



Your Ref: 16/16/16/VC10/225064

Date: 13th March 2018

Our Ref: CS1/LPC18004267/T1qbs2

M/s Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555
(The Motor Claims Department)

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:
XD 5222M**

INSURED VEHICLE: NBV 3398

ACCIDENT DATE: 19/10/2016

We thank you for your instruction on 06/03/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of XD 5222M from M/s Automotive Appraiser and Surveying Services.
- b) Colour damaged vehicle photographs of XD 5222M.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: XD 5222M
Make & Model	: Isuzu CYZ52K
Year of Registration	: 2011
Chassis Number	: JALFXZ77ME7000149
Engine Capacity	: 15,681 cc
2. We recommend that the repairs of the entire damage require about 17 (Seventeen) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.