

ASS. REC. BY:

REF: CS/MSH18004271 / Rthbez Special Instruction:

Surveyor: Rasul
MuhamadASSIGNMENT (Office)From (Person): Jasmine Lok of MSH Date/Time: 06032018 10:08am

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SHB 8331L Insured: FBB 6774Bat Workshop m/s Komoco Motors Tel: 6773 5598of 253 Alexandra Rd #01-01Policy No: MSD/VMT/17-362140 Claim No: MSC/V/18-000334

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 03032018
(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement: _____

Date/Time: 06032018 1143am Person Contacted: Gany Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SHB 8331L - CS/TP17010676/H14h352</u>
	<u>FBB 6774B - x</u>
	<u>Part by Part \$4204.08, 7days. (Red: '387.06', 24%)</u>

49784

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SHB 8331L

at Workshop m/s

Korocco

of

ALEXANDRA

Insured:

msih / my

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time | Action / Instruction

Veh No:

SHB 8331L

Yr Regn:

2016, SEP

Type: M.Car / M.Cycle / Bus / Van / Lorry / ☒ Taxi / Prime Mover /

Truck / Trailer or

Make:

HYUNDAI I30 1.6 TCI c.c. / 1582

Colour:

GREEN

A/C: Insured / Std / NI / NA

Sp. Reading

173281

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

TMAD28 / UVHS 121505

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size:

F:

195/55R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

MAXXIS

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

02/03/18

D.O.I.

06/03/18

Survey held at

Korocco

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

REAR N/S REAR

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 04 JUN 2018

Date/Time, File Pass to?



Preli. Report



Final Report

14/6 Typist
Date/Time, File Return to?

2)

Report Format:

Lump Sum / B.I. (\$) TP 4204.08

Days Of Repair: 7

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee:



Site Insp (\$



Interview (\$



Tech. Insp (\$



Weekend (\$

S + RS. \$

Photos

Others

TOTAL

200

10

210




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18004271/R1tb		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 06-03-2018		
		Code : MSG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	FBB 6774B	Veh. Inspected	SHB 8331L	
Policy No.	MSD/MT/17-362140	Coverage (\$)	0.00	
Claim No.	MSC/V/18/000334	Excess (\$)	0.00	
Assign From	MERIMEN (JASMINE LOK)	Assign Date	06/03/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	03/03/2018	Inspection Date	06/03/2018	
Survey held at	KOMOCO MOTORS PTE LTD 253 ALEXANDRA ROAD #01-01 SINGAPORE 159936.			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Mar 2018		06 Mar 2018 10:08 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	TAZOL HANIF BIN TAZOL ARUS, ID: S2196142F		
Main Claimant:	PREMIER TAXIS PTE LTD		
Vehicle Reg. No.:	SHB8331L	Date of Loss:	03/03/2018 00:00 - :59
Claim Type:	TP / MSC/V/18-000334	Policy/Cover Note No.:	MSD/VMT/17-362140 (Third Party Only) Coverage: 25/05/2017 - 24/06/2048
Vehicle Reg. No. (Insured):	FB86774B	Policy No. (Claimant):	
		Excess:	
Repairer:	Komoco Motors Pte Ltd (Bukit Merah) 253 Alexandra Road #01-01, 159936 Bukit Merah - Tel: 64735588		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 07/03/2018]		
Adj Asg. Remarks:	ON WP Please request Mr Henry Ng to survey.		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/03/2018 12:23
Date Of Accident	02/03/2018 16:00
Exact Location Of Accident	AYE - CLEMENTI (NEARBY LOWER DELTA ROAD EXIT)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB8331L
Insured/Policyholder	
Name Of Registered Owner	PREMIER TAXIS PTE LTD
Co Reg No	200304975H
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62148880

Vehicle Particulars

Manufacturer	HYUNDAI
Model	I30 (FD)-1.6 DOHC (A)
Exact Purpose for which vehicle was being used at time of accident	HIRED & REWARDS
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	5095103893
Cover Note Number	

Driver

Name of Driver	NG WEE LEE (HUANG WEILI)
NRIC No	S7331825D
Date Of Birth	01/09/1973
Occupation	OUTDOOR
Date Of Driving Pass	25/02/1993
Driving Experience	25 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96339112
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 637D #18-385 PUNGGOL DRIVE
Postcode	824637
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : PAX IN THE FRONT SEAT - CHINESE GENDER: : MALE
Passenger 2	NAME: : PAX IN THE REAR SEAT - CHINESE GENDER: : FEMALE
Passenger 3	NAME: : PAX IN THE REAR SEAT - CHINESE / CHILD GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	PUNGGOL N.P.C
Police Station Address	ROAD: 21A TEBING LANE , POSTCODE: 828837 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

VEH. A - 3 PAX VEH. B - NO PILLION

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

Details of Witness 1

Name	KELVIN LEE - PAX IN VEH. A
Phone Number	
Email Address	

Details of Witness 2

Name MR ABDUL HADI - DRIVER OF VEH. C
Phone Number
Email Address

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number FBB6774B
Vehicle Make/Model/Colour M/CYCLE
Details Of Properties VEH. B
Vehicle Category MOTORCYCLE
Name of Driver TAZOL HANIF BIN TAZOL ARUS
NRIC/Passport Number S2196142F
Contact Number 91341707
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver) 1

DETAILS OF INJURED PERSON 1

Name NG WEE LEE - DRIVER OF VEH. A
Approximate Age
Injuries Sustain FELT UNWELL, WENT TO KPTH FOR TREATMENT & HAD 3 DAYS MC
Injured person in which vehicle? SHB8331L
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

DETAILS OF INJURED PERSON 2

Name TAZOL HANIF BIN TAZOL ARUS - RIDER OF VEH. B
Approximate Age
Injuries Sustain LEG & HAND INJURY
Injured person in which vehicle? FBB6774B
Were seat belts worn?
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

DETAILS OF INJURED PERSON 3

Name FEMALE CHINESE/CHILD - PAX IN VEH. A
Approximate Age
Injuries Sustain HEAD PAIN - WENT TO HOSPITAL FOR TREATMENT
Injured person in which vehicle? SHB8331L
Were seat belts worn?
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature (If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

A: SHB 8331L

B: FBB 6774B

C: WITNESS

* REFER TO ATTACH POLICE REPORT.

* VIDEO FOOTAGE CAPTURED

* SCENE PHOTOS TAKEN

* VEHICLE A HAD DAMAGES ON
REAR LEFT PORTION & REAR
WINDSHIELD DAMAGED AS WELL.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20180303/2045

Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-6049999

1 of 3

Report No. T/20180303/2045

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 03/03/2018 11:53	Vide Report No.:	Station Diary No.: 46
--	------------------	--------------------------

Informant's Particulars

Name of Informant: NG WEE LEE			Address: APT BLK 637D PUNGGOL DRIVE #18-385 SINGAPORE 824637		
ID Type / ID No.: NRIC NO / S7331825D			Contact No.: Home/Office: Mobile: 96339112		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 44	Date of Birth: 01/09/1973	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Taxi driver			Driving Licence Information: Class: 2B,3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 02/03/2018 16:00	Type of Location: Straight Road
Location: Along Road 1 Traveling Toward Road 2 AYER RAJAH EXPRESSWAY CLEMENTI ROAD Along AYE towards Clementi Road near exit 3 at the extreme right lane				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBB6774B	Motorcycle	YAMAHA	X-1R	Black	Slightly Damaged	0
SHB8331L	Car	HYUNDAI	I30 GDH 1.6 TCI 5DR DCT	Silver	Slightly Damaged	3



**SINGAPORE
POLICE FORCE**



T/20180303/2045

Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-6049999

2 of 3

Report No. T/20180303/2045

CONTINUATION OF REPORT

Brief Details.

On 2/3/2018 at about 1600hrs, I was driving my vehicle SHB8331L along Ayer Rajah Expressway towards Clementi Road at the extreme right lane near exit 3.

Suddenly, a vehicle in front of me make a sudden brake. I also applied brake and almost came to a stationary stop and the vehicle in front of me continue moving off. Suddenly, I felt a huge impact from the left rear of my vehicle and my rear windscreen had shattered as such I made a stationary stop and check with my passenger if they are alright. My passenger informs that they are alright however their daughter had hit against the front chair but she is still alright. I then informed them that they can visit the doctor if they are not feeling well and they acknowledge.

I then stepped out of my vehicle and made a check and I discovered that there's a motorcycle FBB6774B on the road near to the left rear side of my vehicle. The rider was sitting on the road and members of public came to assist him to the road divider and let him sit at the grass patch area. There's an officer who is around the area came to assist namely Ng Beifeng T07354, 65476445. She assisted by calling ambulance and directing traffic.

The officer asked me to engage another taxi from the company for my passenger as such I complied however was inform that they cannot send a taxi to pick up someone at the expressway. As such I ask for a favour from a member of public namely Abdul Hadi. \$92309467, SJP3942J and he assisted me to send my passenger out of the expressway.

Shortly ambulance and LTA enforcer came, the paramedics went to the rider and made a check and wanted to convey rider to hospital however the rider refused. We managed to exchange our particulars. There are damages at the rear of my vehicle. After the LTA enforcer have settle their issue, I asked permission from them if I can move my vehicle and I was told by them to drive off my vehicle out of the expressway and engage a tow truck as they worried that the expressway will be congested. As such I drove to Blk 111 Bukit Purmei Road, open space carpark and engaged a tow truck.

The tow truck came shortly, towed my vehicle and I took a taxi to my mother's place to take my private vehicle to Khoo Teck Puat Hospital to make a check as I felt sore at my neck area. I made a check at Khoo Teck Puat hospital and I was entiled with a total of 3 days of medical leave from 02/03/2018 to 04/03/2018. I have the CCTV footage of the accident.

My passenger details- Kelvin Lee, 98631931
Rider details- Tazol Hanif Bin Tazol Arus, 91341707



**SINGAPORE
POLICE FORCE**



T/20180303/2045

Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-6049999

3 of 3

Report No. T/20180303/2045

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
F /
Sgt 2 IVIN ONG HONG CHUAN

Signature Of Interpreter:
Not applicable


Officer In Charge Of Case:
TP / GIT /
Sr Staff Sgt MOHAMMAD ABDILLAH BIN PALIL
Contact No.: 65476246

Authentication Stamp
NP168

Signature Of Informant:

Date/Time:
03/03/2018 11:53

Classification Of Case:



Sketch Plan Pg. 6

PREMIER TAXIS	HIRE / RELIEF / SUPER RELIEF
VEHICLE NO.	SHB 8331L
CONTACT NO.	9633 9112
NEW MAILING ADDRESS (if any)	/

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7331825D



Name
NG WEE LEE
(HUANG WEILI)
黄伟利
Race
CHINESE
Date of birth
01-09-1973 M
Country of birth
SINGAPORE



3873601

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: S7331825D
Name:

NG WEE LEE
(HUANG WEILI)

Birth Date: 01 Sep 1973
Issue Date: 19 Oct 2006



3873601



NRIC No: S7331825D

Date of issue
11-02-2005

Address
APT BLK 637D PUNGGOL DRIVE
#18-385
SINGAPORE 824637

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 2B	Motorcycles <= 200 cc	PASS DATE
Class 3	Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver; and other motor vehicles <= 2500kg	26 Aug 2002 25 Feb 1993

NP 428A



Land Transport Authority

VOCATIONAL LICENCE



Licence No: S7331825D

Name: NG WEE LEE

Issue Date: 9/11/2016

Please visit www.lta.gov.sg to check the status of this vocational licence

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

6-Mar-18

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHB 8331 L

1 pc	Emblem I30		\$	27.80	ne -
1 pc	Emblem CRDI		\$	29.40	ne -
1 pc	Emblem Hyundai		\$	29.40	ne -
1 pc	Bootlid lower garnish		\$	362.21	DE -
1 pc	Rear windscreen		\$	778.64	Bro -
1 pc	Rear windscreen moulding		\$	87.00	ne -
1 pc	Rear bumper		\$	811.11	DE -
1 pc	Rear bumper n/s reflector		\$	107.50	SCA -
1 pc	Rear bumper sponge		\$	79.20	? x Sm
1 pc	Rear bumper reinforcement		\$	815.64	? x Sm
1 pc	Rear bumper reinforcement centre		\$	79.20	? x Sm
2 pcs	Rear bumper n/s & o/s side bracket @ \$52.20		\$	104.40	X RHX AN
1 pc	Rear n/s tail lamp		\$	321.30	Bro -
1 pc	Rear n/s reflector		\$	295.10	Bro -
				\$	3,927.90
				\$	1,374.76
				\$	2,553.14

S/NETT

1 set	Rear bumper clips		\$	48.00	ne -
1 set	Reverse sensor		\$	280.00	2000 cut 200
1 set	Tailgate sticker		\$	100.00	ne -
1 pc	Rear n/s fender sticker		\$	60.00	ne -
				\$	50.00
				\$	50.00
				\$	120.00
				\$	80.00
				\$	900.00
				\$	1,200.00
				\$	150.00
				\$	5,591.14

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 Mar 2018		06 Mar 2018 10:08 Edit Adj Rpt	S\$4,204.08 Edit Estimates	S\$4,204.08 View Rpt		Pending for Survey Report Cancel Case

Main		Reference	Claim Details	Documents	Show All
-------------	--	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	TAZOL HANIF BIN TAZOL ARUS, ID: S2196142F		
Main Claimant:	PREMIER TAXIS PTE LTD		
Vehicle Reg. No.:	SHB8331L	Date of Loss:	03/03/2018 00:00 - :59 [17 Months and 24 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MSC/V/18-000334	Policy/Cover Note No.:	MSD/VMT/17-362140 (Third Party Only) Coverage: 25/05/2017 - 24/06/2048
Vehicle Reg. No. (Insured):	FBB6774B	Policy No. (Claimant):	
		Excess:	
Repairer:	Komoco Motors Pte Ltd (Bukit Merah) 253 Alexandra Road #01-01, 159936 Bukit Merah - Tel: 64735588		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Imm.Advice due 07/03/2018]		
Adj Asg. Remarks:	ON WP Please request Mr Henry Ng to survey.		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)



































Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									








Claim Documents

***SHB8331L (MSC/V/18-000334)**
[FBB6774B]

TP

PREMIER TAXIS PTE LTD
Mar 3 2018 12:00AM
[TAZOL HANIF BIN TAZOL ARUS]
Komoco Motors Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports							1 per page		<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)					Thumbnail	Print	
1	27/03/18 17:02	Accident Statement From: SC - Reg. No: FBB6774B, Claimant: TAZOL HANIF BIN TAZOL						Load HTM	
Photos/Images							3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print	
1	04/06/18 11:54	General View						<input checked="" type="checkbox"/>	
2	04/06/18 11:54	General View						<input checked="" type="checkbox"/>	
3	04/06/18 11:54	General View						<input checked="" type="checkbox"/>	
4	04/06/18 11:54	General View						<input checked="" type="checkbox"/>	
5	04/06/18 11:54	General View						<input checked="" type="checkbox"/>	
6	04/06/18 11:54	General View						<input checked="" type="checkbox"/>	
7	04/06/18 11:54	General View						<input checked="" type="checkbox"/>	
8	04/06/18 11:54	General View						<input checked="" type="checkbox"/>	
9	04/06/18 11:54	General View						<input checked="" type="checkbox"/>	
10	04/06/18 11:54	General View						<input checked="" type="checkbox"/>	
11	04/06/18 11:54	General View						<input checked="" type="checkbox"/>	
12	04/06/18 11:54	General View						<input checked="" type="checkbox"/>	
13	04/06/18 11:54	General View						<input checked="" type="checkbox"/>	
14	04/06/18 11:54	General View						<input checked="" type="checkbox"/>	
15	04/06/18 11:54	General View						<input checked="" type="checkbox"/>	
16	04/06/18 11:54	General View						<input checked="" type="checkbox"/>	
17	04/06/18 11:54	General View						<input checked="" type="checkbox"/>	
18	04/06/18 11:54	General View						<input checked="" type="checkbox"/>	
19	04/06/18 11:54	General View						<input checked="" type="checkbox"/>	
20	04/06/18 11:54	General View						<input checked="" type="checkbox"/>	
21	04/06/18 11:54	General View						<input checked="" type="checkbox"/>	
22	04/06/18 11:54	General View						<input checked="" type="checkbox"/>	
23	04/06/18 11:54	General View						<input checked="" type="checkbox"/>	
24	04/06/18 11:54	General View						<input checked="" type="checkbox"/>	
25	04/06/18 11:54	General View						<input checked="" type="checkbox"/>	
26	04/06/18 11:54	General View						<input checked="" type="checkbox"/>	
27	04/06/18 11:54	General View						<input checked="" type="checkbox"/>	
28	04/06/18 11:54	General View						<input checked="" type="checkbox"/>	
29	04/06/18 11:54	General View						<input checked="" type="checkbox"/>	
30	04/06/18 11:54	General View						<input checked="" type="checkbox"/>	
31	04/06/18 11:58	Reinspection Photo						<input checked="" type="checkbox"/>	
32	04/06/18 11:58	Reinspection Photo						<input checked="" type="checkbox"/>	
33	04/06/18 11:58	Reinspection Photo						<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	04/06/18 11:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
35	04/06/18 11:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	04/06/18 11:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	05/03/18 17:52	TP PRI & POLICE REPORT	 Load PDF	
2	06/03/18 09:08	TP NOMINATED OUR AGREED COMMON SURVEYOR - LKK (MR HENRY NG)	 Load PDF	
3	06/03/18 10:07	LOG CARD	 Load PDF	
4	27/03/18 17:02	E-FILE REPORT (SHB8331L) From: SC - Reg. No: FBB6774B, Claimant: TAZOL HANIF BIN TAZOL	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18004271/R1TBE2

Date: 05/06/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMT/17-362140		
Claimant Vehicle No :	SHB8331L	Insured Vehicle No :	FBB6774B		
Date of Loss:	03/03/2018	Nature of Claim:	TP	Claim No:	MSC/V/18-000334

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB8331L	Engine No:	D4FBGZ105488
Make & Model:	HYUNDAI I30 GDH, 1.6 D TCI (M)	Chassis No:	TMAD281UVHJ121505
Reg. Date:	07/09/2016 (Man. Year: 2016)	Odometer:	173281 km
Colour:	Grey		
Engine Capacity:	1582 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Maxxis 5 mm	Rear Left Side:	Maxxis 5 mm
Front Right Side:	Maxxis 5 mm	Rear Right Side:	Maxxis 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,091.13	2,314.08	777.05	25.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,500.00	1,890.00	610.00	24.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,591.13	4,204.08	1,387.05	24.81
+ GST 7.00/7.00% (S\$)	391.38	294.29	97.09	24.81
Nett Amount (S\$)	5,982.51	4,498.37	1,484.14	24.81

INSPECTION

Date of Assignment:	06/03/2018		
Date Inspected:	06/03/2018	Inspected At:	Komoco Motors Pte Ltd (Bukit Merah) 253 Alexandra Road #01-01 Singapore 159936
Estimated Period of Repair:	7.0 days		

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 05 Jun 2018)	
Parts:	N/A	HYUNDAI I30 GDH 1.6 D TCI (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHB8331L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*EMBLEM I30	Necessary	27.80 FL	*27.80 FL
2	1		*EMBLEM CRDI	Necessary	29.40 FL	*29.40 FL
3	1		*EMBLEM HYUNDAI	Necessary	29.40 FL	*29.40 FL
4	1		*BOOTLID LOWER GARNISH	Deformed	362.21 FL	*362.21 FL
5	1		*REAR WINDSCREEN	Broken	778.64 FL	*778.64 FL
6	1		*REAR WINDSCREEN MOULDING	Necessary	87.00 FL	*87.00 FL
7	1		*REAR BUMPER	Deformed	811.11 FL	*811.11 FL
8	1		*REAR BUMPER N/S REFLECTOR	Scratched	107.50 FL	*107.50 FL
9	1		*REAR BUMPER SPONGE	Serviceable	79.20 FL	*- FL
10	1		*REAR BUMPER REINFORCEMENT	Serviceable	815.64 FL	*- FL
11	1		*REAR BUMPER REINFORCEMENT CENTRE	Serviceable	79.20 FL	*- FL
12	1		*REAR BUMPER N/S & O/S SIDE BRACKET	N/S Necessary/O/SNot Necessary	104.40 FL	*52.20 FL
13	1		*REAR N/S TAIL LAMP	Broken	321.30 FL	*321.30 FL
14	1		*REAR N/S REFLECTOR	Broken	295.10 FL	*295.10 FL
15	1		*SET REAR BUMPER CLIPS	Necessary	48.00 FS	*48.00 FS
16	1		*SET REVERSE SENSOR	Cut	280.00 FS	*200.00 FS
17	1		*SET TAILGATE STICKER	Necessary	100.00 FS	*100.00 FS
18	1		*REAR N/S FENDER STICKER	Necessary	60.00 FS	*60.00 FS
19	1		*SUNDRY	Necessary	50.00 FS	*20.00 FS
					Sub Total (S\$)	4,465.90 3,329.66
					- List Item Discount on L Items 35.00/35.00% (S\$)	1,374.77 1,015.58
					Total Parts (S\$)	3,091.13 2,314.08

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING FEE	New	50.00	50.00
2	TO DISMANTLE AND REFIT THE REAR WINDSCREEN	New	120.00	120.00
3	TO DISMANTLE AND REPLACE REVERSE SENSOR AND TEST SYSTEM	New	80.00	60.00
4	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS. INCLUDING TO KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE OF THE END PANEL, BOOTLID, REAR N/S FENDER ETC	New	900.00	700.00
5	TO PUTTY AND SPRAY PAINTING ON THE REAR BUMPER, TAILGATE LOWER GARNISH, TAILGATE, END PANEL, REAR N/S FENDER	New	1,200.00	900.00
6	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS	New	150.00	60.00
Gross Labour Cost (S\$)			2,500.00	1,890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >