MCD618030447 / ComfortDelGro Engineering Pte Ltd - Loyang ENTRY DATE & TIME: 05/03/2018 10:48 SUBMITTED BY: Catherine Por Moy Juan

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

$-\Lambda$ CC	DENT	STAI	EMENT
AUU		יחוט	

05/03/2018 10:48 **Date Of Report** 04/03/2018 12:30 **Date Of Accident**

EDGEDALE PLAINS X PUNGGOL PLAINS **Exact Location Of Accident**

SINGAPORE Country/State of Loss

DETAILS OF OWN VEHICLE

SHD3176R Vehicle Registration Number

insured/Policyholder

COMFORT TRANSPORTATION PTE LTD Name Of Registered Owner

199303821R Co Reg No

FLEETSAFETY@CDGTAXI.COM.SG **Email Address**

Mobile Phone No

OFFICE-65508768 Alternative Phone No

Vehicle Particulars

HYUNDAI Manufacturer

140 Model

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

If No. Please state action to be taken

THIRD PARTY

TAXI Vehicle Category

Insurance Company

MS FIRST CAPITAL INSURANCE LTD Name of Insurance Company

THIRD PARTY FIRE AND/OR THEFT Type Of Coverage

YES Fleet Policy

D-18088936MFSH **Policy Number**

Cover Note Number

Driver

LU CHEET OEI Name of Driver S1685385B **NRIC No** 19/07/1965 Date Of Birth OUTDOOR Occupation 23/11/1988

Date Of Driving Pass 29 YEARS AND 3 MONTHS

Driving Experience

MALE Gender

Mobile Number Fax Number Contact Number

LUCHEETOEI@GMAIL.COM **EMail Address**

Address .

310017

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OTHER - TAXI DRIVER

17 20-222 LORONG 7 TOA PAYOH

(Tr reverse)

Vehicle Registration Number of Driver's Own

Vehicle

Postcode

Insurance Company of Driver's Own Vehicle

General Information of the Accident

COLLISION - HEAD TO REAR Type Of Accident

CLEAR Weather Conditions

DRY Road Surface

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by

ambulance?

NO

NO

1

YES Was any other material or property damaged?

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

Number of Passengers (Including Driver)

Details of Police Action

Was the accident reported to the police?

NO

If Yes.Please state which Police Station

Was notice of intended Prosecution given?

NO

if Yes, against whom?

Circumstances of Accident

SEE ATTACH.(TP REVERSE)

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

NO

Was there any audio recorded?

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SJE8907L

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

REAR

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

(ETCH PLAN	
	
	╶╏╘╏╏┋
	╌╂╌╂╌┼╌╃╻╬╌┼╌╅╍╂╌┼╌┼╌┞╌┼╌┞╌┞╌┤
Notes affach	
	
	╌╀╼╁┄┟╌╂╼┨╼╂╌╂╼╂╼╂╌╀╼╂┈┼╸╄┄┼╾┨
┦╒┩╒╃╒╃╒╃╒╏╒╏╒╏╒┋ <u>╒╏╒╃╅┼┼┋</u> ╧ <u>┼┼┼┼┼┼┼┼┼</u>	
	┈┧╌┧╌┧╍┩╌┩╌╃╌╞╌╏╌┪╌ ╁╌ ╏╸╏╸╏╸ ╏╌╏
<u>┇┇┇╃┪┩╃╃╃</u>	╻ ╶┧ ╸ ╏╸╏╸┦╸╂╸┼╺╂┉╃╼┟╌┟╴┼╼╀╌╀╌┞╌╏╌╏
╌╎╌╎╶┩╒╃┈┩┈╏┈╏┈╏┈╏┈╏┈╏┈╏┈╏┈╏┈╏┈╏┈╏┈╏┈╏┈╏┈╏┈	
DESCRIBE CIRCUMSTANCES OF THE ACCIDENT	
On 4 Mark 2019 around 12-30 pm, at the	junction of
On 4 Mary reig around 12-30 pm, at the Edgedale Plains and Panggal Field towards Black 122A	in the smeeting
English of the state of the sta	
Toward Block 16-11	
Refer attachment.	
Me fer attachnien	
	3 Moorthy
DECLARATION	/ cso
I/We declare the foregoing particulars are true in every respect.	N/ Ana
b	111m 5/5/16
COMFORT TRANSPORTATION PTE (1) 5/3/10	hin. St.
Policyholder's Signature CO REC. NO 199303621R Driver's Signature	Reporting Centre Personnel's Signature
Policyholder's Signature Oriver's Signature	Lorand

(If driver is not the noticeholder)

Date & Time

Sketch Plan Pg. 2

Untitled

Incident:
At 4 March 2018 around 12.30pm, at the junction of Edgedale Plains and Punggol Field in the direction towards Block 122A, Edgedale Plains, Motor vehicle SJE8907L (Toyota ALLION) for some reason, suddenly reverse itself and knock onto my taxi SHD3176R.
My front bumper and car plate were damage.

How it happen:
Traffic light was RED at that time. SJE8907L have already stop and my taxi
SHD3176R also stop behind SJE8907L with clearance.
Both vehicle were stopped & waiting for light to turn GREEN. Suddenly I saw the
front vehicle reverse light was ON and brake light when OFF and it start moving
backward.
Before I could horn him, the back of SJE8907L have already hit on the front of my
taxi SHD3176R with a loud bang.

Ask why he suddenly reverse, he told me he wanted to reverse back and wanted to turn left onto Punggol Field.

J= 5/3/18 R Moorthy GSO 43/18









