

15/5/2010

INS. CASE OWNER:

RA
Atney

C53, AXA 1800 4300, R1A352

LKK:

IDAC:

Surveyor:

M301 (WILSON)

DOI:

2/3/18

Date / Time:

2/3/18

Registered in Merimen:

2/3/18 by AXA.

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHB 9928J

Name of Insured:

TRANS. CAR SERVICES P/L

Insured Tel No.:

HP:

Excess Sec II :SS

5,000.00

D.O.A.:

15/01/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

WONG CHIANG GOON

Driver Tel No.:

81012398

(V/L: YES / NO)

Claim No.:

C0470895

Policy No.:

P1680520

Make / Model:

Renault Latitude

Place of Accident:

North Bridge Rd

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

FS 9322R



INSRS:

WSP:

Tel:

Liability:

RMKS:

sg98



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

2/3/18

M3

FS 9322R - X;

SHB 9928J - C1/A1A16015422/KW1392: 10A22/01/18

12/3 Pending Est & PA.

→ to get PIR result from TP.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

12-2-19

PENDING EST. & PIR

CLOSE PRI

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

1/3/18



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/AXA18004300/R1ua3	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811			Date : 06-03-2018	
			Code : AXA2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 9928J		Veh. Inspected	FS 9322R
Policy No.			Coverage (\$)	0.00
Claim No.			Excess (\$)	0.00
Assign From			Assign Date	06/03/2018
2. Vehicle Particulars & Condition				
Make & Model			c.c	0
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer	-		Steering	
Brakes			Modification	
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	15/02/2018		Inspection Date	07/03/2018
Survey held at	SG 98 MOTOR PTE LTD BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 SINGAPORE 569622			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

Midnight/Investigation

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Mar 2018		02 Mar 2018 16:01 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K, Email: CLAIMS@TRANSCAB.COM.SG		
Main Claimant:	ISMAL BIN MAROOM, ID: S1050922Z		
Vehicle Reg. No.:	FS9322R	Date of Loss:	15/02/2018 21:00 - :59
Claim Type:	TP / C0470895	Policy/Cover Note No.:	P1680520 (Third Party Only)
Vehicle Reg. No. (Insured):	SHB9928J	Policy No. (Claimant):	
		Excess:	S\$5,000.00
Repairer:	Sg 98 Motor Pte Ltd (HQ) BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21, 569622 Ang Mo Kio - Tel: 64524898		
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Stacey Ng - 6880 4351]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 13/03/2018]		
Driver/Custodian (Insured):	WONG CHIANG GOON (), NRIC: S0100615J, Tel: +6581012398		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

...CLAIM SUBFOLDER...(Pending for Survey Report)

Midnight/Investigation

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Mar 2018		02 Mar 2018 16:01 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K, Email: CLAIMS@TRANSCAB.COM.SG		
Main Claimant:	ISMAIL BIN MAROOM, ID: S1050922Z		
Vehicle Reg. No.:	FS9322R	Date of Loss:	15/02/2018 21:00 - :59 [73 Months and 16 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / C0470895	Policy/Cover Note No.:	P1680520 (Third Party Only)
Vehicle Reg. No. (Insured):	SHB9928J	Policy No. (Claimant):	
		Excess:	S\$5,000.00
Repairer:	Sg 98 Motor Pte Ltd (HQ) BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21, 569622 Ang Mo Kio - Tel: 64524898		
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Richard Ang]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 13/03/2018]		
Driver/Custodian (Insured):	WONG CHIANG GOON (), NRIC: S0100615J, Tel: +6581012398 Email:		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AXA_SG (27/11/2018): Re: Direct Settlement - Accident Involving SHB9928J (OI : AXA - C0470895) and FS...
- AXA_SG (25/11/2018): Re: Direct Settlement - Accident Involving SHB9928J (OI : AXA - C0470895) and FS...

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***FS9322R (C0470895)**
[SHB9928J]
TP
ISMAIL BIN MAROOM
Feb 15 2018 9:00PM
[TRANS-CAB SERVICES PTE LTD]
Sg 98 Motor Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View [View in Browser](#) ▼

Photos/Images			3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/06/19 15:00	General View	 Load JPG	☒
2	13/06/19 15:00	General View	 Load JPG	☒
3	13/06/19 15:00	General View	 Load JPG	☒
4	13/06/19 15:00	General View	 Load JPG	☒
5	13/06/19 15:00	General View	 Load JPG	☒
6	13/06/19 15:00	General View	 Load JPG	☒
7	13/06/19 15:00	General View	 Load JPG	☒
8	13/06/19 15:00	General View	 Load JPG	☒
9	13/06/19 15:00	General View	 Load JPG	☒
10	13/06/19 15:00	General View	 Load JPG	☒
11	13/06/19 15:00	General View	 Load JPG	☒
12	13/06/19 15:00	General View	 Load JPG	☒
13	13/06/19 15:00	General View	 Load JPG	☒
14	13/06/19 15:00	General View	 Load JPG	☒
15	13/06/19 15:00	General View	 Load JPG	☒
16	13/06/19 15:00	General View	 Load JPG	☒
17	13/06/19 15:00	General View	 Load JPG	☒
18	13/06/19 15:00	General View	 Load JPG	☒
19	13/06/19 15:00	General View	 Load JPG	☒
20	13/06/19 15:00	General View	 Load JPG	☒
21	13/06/19 15:00	General View	 Load JPG	☒
22	13/06/19 15:00	General View	 Load JPG	☒
23	13/06/19 15:00	General View	 Load JPG	☒
24	13/06/19 15:00	General View	 Load JPG	☒
25	13/06/19 15:00	General View	 Load JPG	☒
26	13/06/19 15:00	General View	 Load JPG	☒
27	13/06/19 15:00	General View	 Load JPG	☒
28	13/06/19 15:00	General View	 Load JPG	☒
29	13/06/19 15:00	General View	 Load JPG	☒
30	13/06/19 15:00	General View	 Load JPG	☒
31	13/06/19 15:00	General View	 Load JPG	☒
32	13/06/19 15:00	General View	 Load JPG	☒
33	13/06/19 15:00	General View	 Load JPG	☒
34	13/06/19 15:00	General View	 Load JPG	☒
35	13/06/19 15:00	General View	 Load JPG	☒

Photos/Images			3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	13/06/19 15:00	General View	 Load JPG	☒
37	13/06/19 15:00	General View	 Load JPG	☒
38	13/06/19 15:00	General View	 Load JPG	☒
39	13/06/19 15:00	General View	 Load JPG	☒
40	13/06/19 15:00	General View	 Load JPG	☒
41	13/06/19 15:00	General View	 Load JPG	☒
42	13/06/19 15:00	General View	 Load JPG	☒
43	13/06/19 15:00	General View	 Load JPG	☒
Documentation			1 per page ▼	☒
No	Finalized On	AXA Insurance Pte Ltd (HQ)	Thumbnail	Print
1	02/03/18 11:26	EMAIL_ABS	 Load PDF	
2	02/03/18 11:26	CO CLAIMANT_ABS	 Load PDF	
3	02/03/18 11:26	SHB9928J INSD GIA_ABS	 Load PDF	
4	02/03/18 11:26	FS9322R TP GIA_ABS	 Load PDF	
5	02/03/18 11:31	EMAIL TO WORKSHOP(LIST OF SURVEYOR)_ABS	 Load PDF	
6	02/03/18 14:44	EMAIL FROM WORKSHOP_ABS	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AXA18004300/R1JA3S2**Date:** 27/06/2019REFERENCE

Handling Insurer:	AXA Insurance Pte Ltd	Policy No:	P1680520
Claimant Vehicle No :	FS9322R	Insured Vehicle No :	SHB9928J
Date of Loss:	15/02/2018	Nature of Claim:	TP
		Claim No:	C0470895

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FS9322R	Engine No:	KB210558
Make & Model:	SYM JOYRIDE 200 A, 171cc (A)	Chassis No:	RFGLF18WYBS007300
Reg. Date:	30/12/2011 (Man. Year: 2011)	Odometer:	0 km
Colour:	Black		
Engine Capacity:	172 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	110/90-13	Rear Tyre Size:	130/70-12
Front Left Side:	Michelin 3 mm	Rear Left Side:	Michelin 3 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	02/03/2018	Sg 98 Motor Pte Ltd (HQ) BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 Singapore 569622
Date Inspected:	07/03/2018 Inspected At:	
Estimated Period of Repair:	7.0 days	

Adjuster: MOHD RASUL**Manager:** Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 - \$6,000.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 27 Jun 2019)

Parts: N/A SYM JOYRIDE 200 A 171cc (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for FS9322R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >