

SS REC BY:

REF:

CS3/ASM18004302/MIB^{SP}

Special Instruction:

Surveyor:

Smart Claim

ASSIGNMENT (Office)

From (Person):

Ernest Tay

of

ASM

Date/Time:

15032018 2pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJJ 3096H

Insured:

SGH 8728G

at Workshop m/s

EM-1 Auto

Tel:

9666 6556

of

Blk 8 Sin ming Ind Est #01-68

Policy No:

Claim No:

S8M00A0F

Sum Insured:

Excess:

Make of Veh:

D.O.A.

03032018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time:

05102018 239pm

Person Contacted:

Mr. Chia

Vehicle:

IN/OUT

Date/Time	Action/Instruction (x) Estimate
	SJJ 3096H - CS/ms616024253/Agbm2
	SGH 8728G - x
	Dismantle Part: 09032018
	After repair: 10032018
3/5	Submit PRS report

DUA: 191216

ASSIGNMENT

From: OPC Date: SEP 2008 Vch No: SS3096H Yr Reg: SEP 2008

Estimated Cost: EMI Type: M.Car M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: KIA DICANTO CO: 1086 Colour: RED A/C: Insured / Std / NI / NA

Sp. Reading: 142016 T. Radio: Insured / Std / NI / NA Eng No: KNABA24339T642356

C No: KNABA24339T642356 Gen. Cond: Good / Fair / Poor / Burnt

Steering: Order / Jammed / Leaked / Burnt or Brake: Order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or Tyre Size: F: 165/50R15 R: 165/50R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or FALKEN

Front: 8 mm Rear: 8 mm R.Bal: 8 mm L.Bal: 8 mm

D.O.A: 6/3/2018 Survey held at: 4.04pm

Des. of Damages: Front O/S / NIS / U/C / Rooftop or The U/C / Chassis frame / Body Structure affected due to collision:

CA / REV / REP. / 24 HRS Date: Person Contacted: Vehicle: IN / OUT



(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: Consistent? : Yes or No
IDAC Accident Report: Consistent? : Yes or No
GIA / PR Seen: Consistent? : Yes or No
Est. Repairs: days Res: Yes or No
Lum Sum: % 3 Val: Yes or No

NO ESTIMATE UPON SURVEY. (PRI)

RECEIVED 03 MAY 2018

Date/Time File Pass to: ☐ Preli. Report ☐ Final Report Days Of Repair: 2

Date/Time File Return to: ☐ Add Fee: ☐ Site Insp \$ ☐ Inter. Insp \$ ☐ Tech. Insp \$ ☐ Web. Insp \$

Report Format: Prg Lump Sum / I.B./I.S. Survey Fee: 2 Transportation: 2 Photos: 2 Draw: 2




Service Request Details

Claim

S8M00A0F

Reference

None 

Loss Date

March 3, 2018

Request Date

March 5, 2018

Due Date

March 12, 2018

LKK AUTO CONSULTANTS PTE LTD (TP) ▾

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SJJ3096H

Make

TPVD

05032018 @ 235pm
Mr. Chua veh in
EM-1 Ma.

Primary Contact/Insured

TEO KIM YEOW

BLK 690F WOODLANDS DRIVE 75, #12-02, 736690, Singapore

YAHOO@YAHOO.COM

Claim Handler

TAY Ernest

6568804835

ernest.tay@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/03/2018 13:46
Date Of Accident	03/03/2018 13:45
Exact Location Of Accident	ALONG WOODLANDS AVE 2
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJJ3096H
Insured/Policyholder	
Name Of Registered Owner	SEAN LIAN CHYE
NRIC No	S7310206E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93854687
Alternative Phone No	OFFICE-93854687

Vehicle Particulars

Manufacturer	KIA
Model	-
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN1539411702
Cover Note Number	

Driver

Name of Driver	SEAN LIAN CHYE
NRIC No	S7310206E
Date Of Birth	29/03/1973
Occupation	INDOOR
Date Of Driving Pass	14/10/1996
Driving Experience	21 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93854687
Fax Number	
Contact Number	OFFICE-93854687
EEmail Address	NOEMAIL

Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)


DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SJD2568B
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number GR3375X
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category COMMERCIAL VEHICLE
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling along woodlands ave 2 towards woodlands ave woodlands ave 7 junction woodlands ave 1, on lane 2, Traffic light was Red I slowed down to stop, Vehicle B Follow suit, Suddenly Vehicle C hit onto Vehicle B rear portion & due to the Group Impact Vehicle B move forwards and hit onto my rear portion. I get down my car then notice 4 vehicles involved. I felt my back & Neck pain

[Signature]

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]
Policyholder's Signature
Date & Time:

[Signature]
Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Signature]
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Svy

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0206E
Vehicle Details	
Vehicle No.:	SJJ3096H
Vehicle to be Exported:	Yes
Intended De-registration Date:	06 Mar 2018
Vehicle Make:	KIA
Vehicle Model:	PICANTO 1.1(A)
Primary Colour:	Red
Manufacturing Year:	2008
Engine No.:	G4HG8461210
Chassis No.:	KNABA24339T642356
Maximum Power Output:	47.1 kW (63 bhp)
Open Market Value:	\$7,840.00
Original Registration Date:	09 Sep 2008
First Registration Date:	09 Sep 2008
Transfer Count:	0
Actual ARF Paid:	\$3,341.00
OPC Cash Rebate Details	
OPC Cash Rebate Eligibility:	No
OPC Cash Rebate Eligibility Expiry Date:	-
OPC Cash Rebate Amount:	-
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	08 Sep 2018
PARF Rebate Amount:	\$1,670.00
Intended COE Rebate Details	
COE Expiry Date:	08 Sep 2018
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$0.00
COE Rebate Amount:	\$0.00
Total Rebate Amount:	\$1,670.00

The information contained herein is correct as at 05 Mar 2018

OK



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT			
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: ERNEST TAY		Ref: CS3/ASM18004302/M1bs2 Date: 11-05-2018 Code: ASM	
			
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SGH 8728G	Veh. Inspected	SJJ 3096H
Policy No.		Coverage (\$)	0.00
Claim No.	S8M00A0F	Excess (\$)	0.00
Assign From	SMART CLAIM (ERNEST TAY)	Assign Date	05/03/2018
2. Vehicle Particulars & Condition			
Make & Model	KIA PICANTO	c.c	1086
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	KNABA24339T642356	Colour	RED
Odometer	142016 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	165/50R15	FALKEN	8 mm
L/H Front Tyre	165/50R15	FALKEN	8 mm
R/H Rear Tyre	165/50R15	FALKEN	8 mm
L/H Rear Tyre	165/50R15	FALKEN	8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
5. General Information			
Accident Date	03/03/2018	Inspect Date / Time	06/03/2018 (04:04 PM)
Survey held at	EM-1 AUTO PTE LTD BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C #01-68 SINGAPORE 575643		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

Report Ref No. CS3/ASM18004302/M1bs2

Inspected By



MA CHIN FOOK

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.