

lump sum \$2200 - (Red 3679.70; 62%)

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: GBD2291T Yr Regn: 2014/JulyType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan Cabstar C.O. 2953Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 256706 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JNISC2F2420856.065Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195 R15C HankookR: 155 R13C S/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Hankook

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 06/03/18Survey held at 96 MotorsDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP 1st Cap.

RECEIVED 16 MAR 2018

Date/Time, File Pass to?

1) 16/3 Typist
Date/Time, File Return to?

2) _____

☐ : Preli. Report
☒ : Final Report
Days Of Repair: 3Resurvey No. of Trip: -

Survey Fee:

Transportation:

____ \$ + RS. ____ \$

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)Report Format: TPLump Sum / I.B.I.: (\$ 2200)

140

50

26

216



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18004303/Atd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 06-03-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 9161J	Veh. Inspected	GBD 2291T
Policy No.		Coverage (\$)	0.00
Claim No.	D18001827MFSH	Excess (\$)	0.00
Assign From	CWS (SITHARA)	Assign Date	06/03/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	02/03/2018	Inspection Date	06/03/2018
Survey held at	96 MOTORSPORTS PTE LTD 62/64 KAKI BUKIT AVENUE 6 SINGAPORE 417893 ARK @ KB		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18001827MFSH

Date: 16/3/2018

Our Ref: CS/FCI18004303/Atd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. GBD 2291T.

Please be informed that we had conducted the inspection of the abovementioned vehicle 6/3/2018 at the premises of M/s 96 Motorsports. and have the following to report: -


Workshop Estimate Amount	: S\$ <u>5,879.70.</u>
Revised Estimate Amount	: S\$ <u>2,269.66</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages
at the o/s.

Comments/ Present Status:

Damages Consistent.



Yours faithfully

Adrian

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	05-03-2018	Our Ref No. D18001827MFSH
Accident Date	02-03-2018	Claim Type. Third Party
Insured Vehicle	SHA9161J	Third Party Vehicle. GBD2291T
Survey Location	62 & 64 Kaki Bukit Avenue 6 ARK@KB Singapore 417893	
Contact Person.	ALWYN SOH	
Contact No.	0/ 9021096	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	96 MOTORSPORTS PTE LTD	Attention. NIL
Cc : TP Solicitor	KURU & CO	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/235590)



PRI Documents



Close



PRI Header Details

Claim No	D18001827MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & KURU & C
Workshop Name	96 MOTORSPORTS PTE LTD (Contact Person : ALWYN SOH)	Survey Location & Contact Details	62 & 64 Kaki Bukit Avenue 6 ARK@KB Singapore 41789: Mobile: 9021096 , Phone: 0 , Fax: 0 EmailId: KURULEGAL@YAHOO.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHA9161J	TP Vehicle No	GBD2291T
PRI Recieved Date	05-03-2018 06:35:24 PM	Surveyor Appointed Date	06-03-2018 11:03:39 AM	Surveyor Accept Date	06-03-2018 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	06-03-2018	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Friday, 16 March 2018 3:17 PM
To: Admin-D (LKKAUTO); 'Claim Workflow System'; assignments
Cc: SITHARA@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18001827MFSH/1
Attachments: PRELI ADVISED GBD 2291T.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **GBD 2291T**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 6 March 2018 2:04 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: SITHARA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18001827MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 6 March 2018 11:04 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SITHARA@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18001827MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department

96 motorsports PTE LTD

62 & 64 Kaki Bukit Ave 6, (S) 417893, Ark@KB

Tel: 6702 6996

Fax: 6384 6996

Email: admin@96motorsports.com

JN1562F24Z0856065

Vehicle number: GBD2291T

Vehicle Made & Model: NISSAN CABSTAR

TP 1st cap Denise

Qty	Nett Items	Amount \$
1	Rear sidegate - RH <i>Dented</i>	2,201.60 ✓
1	Rear sidegate lower member <i>Repair</i>	596.50 ✗
2	Rear wheel guards - RH @ 211.40 <i>Dented</i>	422.80 ✓
1	Rear wheel hub shaft <i>3x100</i>	481.90 ✗
1	Rear wheel hub shaft bearing	181.60 ✗
1	Rear sidegate stopper - Rear - RH <i>Not in</i>	48.60 ✗
Sub-total		3,933.00
<i>30%</i> Less 10%		393.30
Total List		3,539.70

Special Nett Items

1	Rear tyre - RH <i>Not in</i>	160.00 ✗
1	Rear wheel rim - RH <i>Best</i>	180.00 ✗
Total Special Nett		340.00

Labour Charges

To remove, refix rear undercarriage	200.00 ✗
To check wheel alignment	120.00 ✗
To re-seal anti-rust	80.00 ✗
To respray painting & etc	800.00 ✗
Panel beating, cut, weld, remove & replacing above parts	800.00 ✗
Total Labour	2,000.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:
Date:

ESTIMATE PARTS & LABOUR GRAND TOTAL \$

5,879.70

total: 2837.08
n/s: 2.21K
03Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18004303/Atd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 19-03-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 9161J	Veh. Inspected	GBD 2291T	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18001827MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	06/03/2018	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN CABSTAR	c.c	2953	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	JN1SC2F24Z0856065	Colour	SILVER	
Odometer	256706	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15C	HANKOOK	6 mm	
L/H Front Tyre	195 R15C	HANKOOK	6 mm	
R/H Rear Tyre	155 R13C	BRIDGESTONE	6 mm	
L/H Rear Tyre	155 R13C	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/03/2018	Inspection Date	06/03/2018	
Survey held at	96 MOTORSPORTS PTE LTD 62/64 KAKI BUKIT AVENUE 6 SINGAPORE 417893 ARK @ KB			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBD 2291T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR SIDEGATE-RH	DENTED	2,201.60	2,201.60
1	REAR SIDEGATE LOWER MEMBER	TO REPAIR SEE LABOUR	596.50	-
2	REAR WHEEL GUARDS-RH @\$211.40	DENTED	422.80	422.80
1	REAR WHEEL HUB SHAFT	NOT NECESSARY	481.90	-
1	REAR WHEEL HUB SHAFT BEARING	NOT NECESSARY	181.60	-
1	REAR SIDEGATE STOPPER-REAR-RH	NOT NECESSARY	48.60	-
	LESS 10% DISCOUNT		-393.30	-
	LESS 30% DISCOUNT		-	-787.32
			3,539.70	1,837.08
SPECIAL NETT ITEMS				
1	REAR TYRE-RH (SN)	NOT NECESSARY	160.00	-
1	REAR WHEEL RIM-RH (SN)	BENT	180.00	120.00
			340.00	120.00
LABOUR				
	TO REMOVE,REFIX REAR UNDERCARRIAGE.	NOT NECESSARY	200.00	-
	TO CHECK WHEEL ALIGNMENT.		120.00	80.00
	TO RE-SEAL ANTI-RUST.	NOT NECESSARY	80.00	-
	TO RESPRAY PAINTING & ETC.		800.00	500.00
	PANEL BEATING,CUT,WELD,REMOVE & REPLACING ABOVE PARTS.INCLUSIVE OF THE REPAIR OF REAR SIDEGATE LOWER MEMBER.		800.00	300.00
			2,000.00	880.00
GRAND TOTAL			5,879.70	2,837.08
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,200.00

Report Ref No. CS/FCI18004303/Atd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.