



SERVICE REQUESTS

MESSAGES

CLAIMS

## ← Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

### General Details

Involving

TPVD UNKNOWN UNKNOWN (SJZ8773U)

Date of Loss

5 March 2018

Time of Loss

4.00

Loss Description

GBF4864S (INSD) C/W SJZ8773U

Comment

### Workshop Details

Total Rebate Amount

25170

Nett Loss Amount

\$10,830.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (TP)

Target Date of Completion \*

11/06/2018



Days of work completion \*

97



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

### Vehicle & Driver Details

Vehicle Registration#

SJZ8773U

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date \*

01/01/2011



Mileage

91664

Age of Vehicle

7

CATEGORY

Manufacturing Year

POLICY INFORMAT...

ASSESSMENT INFO...

2010

### Driver Details

CATEGORY

Driver Name

FNOL INFORMATI...

TBC

CATEGORY

Make

POST SURVEY INF...

POLICY INFORMAT... TPVD UNKNOWN

ASSESSMENT INFO... VOLKSWAGEN

CATEGORY Model

POLICY INFORMAT... UNKNOWN

ASSESSMENT INFO... SCIROCCO 1.4L AT TSI 1372Q5

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT...

ASSESSMENT INFO... WVVZZZ13ZBV016392

CATEGORY Date of Birth

FNOL INFORMATI...

POST SURVEY INF... dd/mm/yyyy 

CATEGORY Age

FNOL INFORMATI... 0

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Education Qualification

FNOL INFORMATI... Other

POST SURVEY INF...

CATEGORY Driving Experience

CATEGORY Engine No

POLICY INFORMAT...

ASSESSMENT INFO...

CAV235700

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO...

1390

CATEGORY Sum Insured

POLICY INFORMAT...

ASSESSMENT INFO...

0

CATEGORY Market Value

POLICY INFORMAT...

ASSESSMENT INFO...

36000

FNOL INFORMATI... 0

POST SURVEY INF...

CATEGORY

Driver License #

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY

License Type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY

License Issue Date

FNOL INFORMATI...

POST SURVEY INF...

dd/mm/yyyy



CATEGORY

License Expiration Date

FNOL INFORMATI...

POST SURVEY INF...

dd/mm/yyyy



CATEGORY

Address

FNOL INFORMATI... Singapore

POST SURVEY INF...

---

CATEGORY Address type

FNOL INFORMATI... Personal Correspondence

POST SURVEY INF...

---

CATEGORY Gender

FNOL INFORMATI... Unknown

POST SURVEY INF...

---

CATEGORY Marital status

FNOL INFORMATI... Unknown

POST SURVEY INF...

---

CATEGORY Identification #

FNOL INFORMATI...

POST SURVEY INF...



SERVICE REQUESTS

MESSAGES

CLAIMS

---



## Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

---

## Detailed Assessment

Inspection Date \*

06/03/2018



Total Loss

Yes No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

235/40R18

## Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes No

Footbrake (Serviceable)

Yes No

Handbrake (Serviceable)

Yes No

Engine Modification

Yes No

Pre-accident condition

Good



## Tyre Condition

Spare wheel

Rear Tyre Size

235/40R18

---

Front left side

PIRELLI6mm

Front right side

PIRELLI6mm

---

Rear left side

PIRELLI6mm

Rear right side

PIRELLI6mm



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

### Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

### Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

 Yes  No

Part Supplied by AXA

Yes No

Save




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT			
AXA INSURANCE PTE LTD		Ref: CS3/ASM18004304/Gd3e2	
8 SHENTON WAY #24-01		Date: 21-05-2018	
AXA TOWERSINGAPORE 068811			
ATTN : LOH CYNTHIA		Code: ASM	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	GBF 4864S	Veh. Inspected	SJZ 8773U
Policy No.		Coverage (\$)	0.00
Claim No.	S8M00A3T	Excess (\$)	0.00
Assign From	LOH CYNTHIA	Assign Date	06/03/2018
2. Vehicle Particulars & Condition			
Make & Model	VOLKSWAGEN SCIROCCO	c.c	1390
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	WWWZZZ13ZBV016392	Colour	WHITE
Odometer	91664 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	235/40 R18	PIRELLI	6 mm
L/H Front Tyre	235/40 R18	PIRELLI	6 mm
R/H Rear Tyre	235/40 R18	PIRELLI	6 mm
L/H Rear Tyre	235/40 R18	PIRELLI	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
5. General Information			
Accident Date	05/03/2018	Inspect Date / Time	06/03/2018 ( 05:00 PM )
Survey held at	2 KAKI BUKIT AVE 2 #01-18		
Repairer	N-51 AUTOMOTIVE PL		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

Report Ref No. CS3/ASM18004304/Gd3e2

Inspected By

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.