

22/03/2002

RES. REC. BY:

REF: C3/EG18004315/Rhd34

Special Instruction:

Surveyor: Rasul ASSIGNMENT (Office)From (Person): Yee Pei Li of EGT Date/Time: 6/3/18 @ 9:03am

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLR1382D Insured: GBE6467Yat Workshop m/s Cycle & Carriage Kia Tel: 6568 4567of 209 Puncak GardensPolicy No: \_\_\_\_\_ Claim No: GBE6467Y/SE/p

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 26/02/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS Wp

H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 9:32am 06/3/18 Person Contacted: COCO Vehicle-IN/OUT OUT

Date/Time	Action/Instruction
	(✓) Estimate
	SLR1382D-X
	GBE6467Y-X
04/4/18 @ 4:42pm	revised to Steve Lim by email.
07/1/19 @ 4:55pm	confirmed with Mrs Loi Kuan Rg #10728.56, 12 days.
	(Red B 4079.17, 29%)

Surveys

REF: E17

62640

## ASSIGNMENT

From: Date: 02042018

Estimated Cost:

OD TP WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLR 1382D

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

COCO

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 12 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLR 1382D Yr Regn: 2017 / DEC

Type: M.Cycle / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MERCEDES BENZ E200 C.C 1991

Colour: BLACK A/C: Insured / Std / NI / NA

Sp. Reading: 622.6 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WDD2130422A100050

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 275/35 R19

R:

BS / DUN / EXNOVA / GS / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 26/02/18

Survey held at

CBL (PG)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 03 JAN 2019

3/1/2019.

Date/Time, File Pass to?

☐

Preli. Report

1)

Date/Time, File Return to?

☐

Final Report

2)

Days Of Repair: 12

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee: 350

Transportation:

S + PS SI

Photos

Others

TOTAL

350

Report Format: TP

Lump Sum / I.B.I. (\$) 10128.56



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS/EGI18004315/R1qd3

5 TEMASEK BOULEVARD  
#04-01 SUNTEC TOWER FIVE  
SINGAPORE 038985

Date : 06-03-2018



Code : EGI

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBE 6467Y	Veh. Inspected	SLR 1382D
Policy No.		Coverage (\$)	0.00
Claim No.	GBE 6467Y/SE/pl	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	06/03/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	26/02/2018	Inspection Date
Survey held at	CYCLE & CARRIAGE KIA PTE LTD 209 PANDAN GARDENS SINGAPORE 609339	

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

## Nivitha (LKK Auto)

---

**From:** Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>  
**Sent:** Tuesday, 6 March 2018 9:03 AM  
**To:** 'admin-d@lkkauto.com'  
**Subject:** OI : GBE6467Y / TP : SLR1382D/LKK / DOA : 26/02/2018  
**Attachments:** SLR1382D - SAS.pdf; SLR1382D - ESTIMATE.pdf; SLR1382D - PRS FORM.pdf

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **CYCLE & CARRIAGE KIA PTE LTD**,

ADDRESS : PLEASE CONFIRM WITH COCO

PERSON TO CONTACT : COCO LU TING @ 6568 4567

ERGO OFFICER-IN-CHARGE : STEVE LIM

***Note: To survey on without prejudice basis. Please note that our insured/insured driver has yet to e-file their SAS for this accident. Obtain estimate and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.***

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via [Survey.Report@ergo.com.sg](mailto:Survey.Report@ergo.com.sg).

Attached are estimate and TP's SAS (**note: reports not to be released to any Third Party**).

Kindly acknowledge receipt of this email.

Thank you.

### Yee Pei Li

Claims Assistant (Motor)  
ERGO Insurance Pte. Ltd.  
5 Temasek Boulevard  
#04-01 Suntec Tower Five  
Singapore 038985  
Tel.: 65 6829 9199 DID: 65 6829 9194  
Website: [www.ergo.com.sg](http://www.ergo.com.sg)

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group) one of the world's leading risk carriers.

Date: 05.03.2018  
 Our Reference: GBE 6467Y/SE/pl  
 Your Reference: SLR 1382D  
 To: DIPLOMAT PARTS

Sent via Fax ☐  
 or ☐  
 Email ☐ coco.lu@cyclecarriage.com.sg

## Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SLR 1382D  
 Insured's Vehicle: GBE 6467Y  
 Date Of Accident: 26.02.2018

We acknowledge receipt of your request for PRS on: 05.03.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked \*.

\* LKK

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPk	JP Knights Pte Ltd	VAC	Vicom Ltd

<input type="checkbox"/>	Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
<input type="checkbox"/>	Your request for inspection does not have your client's GIA report, kindly forward a copy.
<input type="checkbox"/>	We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
<input checked="" type="checkbox"/>	Our Insured's driver has not reported the accident to us to date.
<input checked="" type="checkbox"/>	Others: <u>We are therefore not in a position to discuss on liability at this juncture.</u>

OFFICER-IN-CHARGE - STEVE LIM

Prepared by:	<u>Pei Li</u>	6829 9194	claims@ergo.com.sg
Signature:			FAX : 6829 9247

### Assessor use only:

Assignment Date: \_\_\_\_\_  
 Assignment Time: \_\_\_\_\_

Remarks:

### Workshop use only:

#### Assessor attended workshop on:

Date: \_\_\_\_\_  
 Time: \_\_\_\_\_  
 Inspector: \_\_\_\_\_

☒ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.

Note: Our inspection is on a without admission to liability basis.

## Shiau Chan (LKKAUTO)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Wednesday, 2 January 2019 4:52 PM  
**To:** 'Loi Ai Ting'; Rasul (LKKAUTO)  
**Cc:** Admin A; Admin-D (LKKAUTO); Cheng Jo Jo; Lauro Araos Songcuan Jr  
**Subject:** RE: SLR1382D, DPS WIP: 22305 (finalisation)

Dear Ms Loi,

WITHOUT PREJUDICE

Confirm final fig \$10,128.56 before GST and 12 repair days.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Loi Ai Ting <aiting.loi@cyclecarriage.com.sg>  
**Sent:** Tuesday, 12 June 2018 9:28 AM  
**To:** Rasul (LKKAUTO) <Rasul@lkkauto.com>  
**Cc:** Admin A <admin-a@lkkauto.com>; Admin-D (LKKAUTO) <admin-d@lkkauto.com>; Cheng Jo Jo <jojo.cheng@cyclecarriage.com.sg>; Lauro Araos Songcuan Jr <lauro.songcuan@cyclecarriage.com.sg>  
**Subject:** RE: SLR1382D, DPS WIP: 22305 (finalisation)

Hi, Rasul,

Can we confirm finalised amount at \$10,837.56?

Thanks.

Regards,  
Loi

---

**From:** Loi Ai Ting  
**Sent:** Wednesday, 30 May, 2018 9:55 AM  
**To:** 'Rasul (LKKAUTO)'  
**Cc:** Admin A; Admin-D (LKKAUTO); Cheng Jo Jo; Lauro Araos Songcuan Jr  
**Subject:** SLR1382D, DPS WIP: 22305 (finalisation)

Hi, Rasul,

Kindly confirm finalised amount at \$10,837.56.

Thanks.

Regards,  
Loi

## Shiau Chan (LKKAUTO)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Wednesday, 4 April 2018 11:42 AM  
**To:** 'Survey Report (ERGO Insurance Pte. Ltd.); assignments; 'Steve Lim'  
**Cc:** SUR  
**Subject:** RE: GBE6467Y / TP : SLR1382D/LKK / DOA : 26/02/2018  
**Attachments:** CSEGI18004315R1qd3.pdf

Dear Steve,

Enclosed herewith preliminary advice of SLR 1382D.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO)  
**Sent:** Tuesday, 6 March 2018 12:14 PM  
**To:** 'Survey Report (ERGO Insurance Pte. Ltd.)' <[Survey.Report@ergo.com.sg](mailto:Survey.Report@ergo.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: GBE6467Y / TP : SLR1382D/LKK / DOA : 26/02/2018

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]  
**Sent:** Tuesday, 6 March 2018 9:03 AM  
**To:** 'admin-d@lkkauto.com' <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>  
**Subject:** OI : GBE6467Y / TP : SLR1382D/LKK / DOA : 26/02/2018

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **CYCLE & CARRIAGE KIA PTE LTD**,

ADDRESS : PLEASE CONFIRM WITH COCO



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: GBE 6467Y/SE/pl

Date: 04<sup>th</sup> April 2018

Our Ref: CS/EG118004315/R1qd3

Without Prejudice

The Motor Claims Department  
ERGO Insurance Pte Ltd

Attn: Pei Li

Dear Sirs/Mdm

**PRELIMINARY ADVICE OF VEHICLE NO. SLR 1382D .**


We thank you for the instruction on 06/03/2018.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 02/04/2018 at the premises of M/s CYCLE & CARRIAGE and have the following to report:-

Workshop Estimate Amount	: S\$ <u>13,857.73</u> .
Revised Estimate Amount	: S\$ <u>10,280.45</u> .
"Check" Items Amount	: S\$ <u>2,947.28</u> .
Market Value	: S\$ <u>-</u> .
Salvage Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages at the o/s rear portion.



Comments/ Present Status:

Damages consistent.

Days of repair: 12 days.

We have NOT authorise repair.

Yours faithfully

Rasul  
Automotive Assessor



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	26/02/2018 18:41
Date Of Accident	26/02/2018 07:25
Exact Location Of Accident	T-JUNCTION OF MARINA BOULEVARD & MARINA VIEW LINK
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLR1382D
<b>Insured/Policyholder</b>	
Name Of Registered Owner	KOH ENG TEH (GAO RONGDI)
NRIC No	S7406264D
Email Address	ENGTEHKOH@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98395895
Alternative Phone No	OTHERS-98395895

### Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	E200
Exact Purpose for which vehicle was being used at time of accident	RECREATION
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5096388229
Cover Note Number	

### Driver

Name of Driver	KOH ENG TEH (GAO RONGDI)
NRIC No	S7406264D
Date Of Birth	24/02/1974
Occupation	INDOOR
Date Of Driving Pass	16/07/1992
Driving Experience	25 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98395895
Fax Number	
Contact Number	OTHERS-98395895
EMail Address	ENGTEHKOH@GMAIL.COM

Address	BLK 314B #11-129 ANCHORVALE LINK
Postcode	542314
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	EMAIL TO MOTORVIDEO@INCOME.COM.SG
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBE6467Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	PEH LAY HOCK, ALBERT
NRIC/Passport Number	S7305127D
Contact Number	90668682
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 26/02/2018  
1200HRS

Driver's Signature


(If driver is not the policyholder)  
Date & Time: 26/02/2018  
1200HRS

Reporting Centre Personnel's Signature

Name: Simon Sulcumae  
NRIC/FIN No.: S8823603C

# Sketch Plan #2

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the 26<sup>th</sup> FEBRUARY 2018, at about 7.27HRS

I was driving my vehicle SLR1382D along marina Boulevard towards MCE. A vehicle, GBE6467Y came out of marina view LINK and collided into my vehicle. The impact point was on the front left bumper of GBE6467Y and Rear right for SLR1382D.

No one was injured and I plan to claim against the other party.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 26/02/2018  
12.00HRS

Driver's Signature

(If driver is not the policyholder)  
Date & Time: 26/02/2018  
12.00HRS

Reporting Centre Personnel's Signature

Name: Sumon Sukumar  
NRIC/FIN No: S8823603C



## REPAIR / ACCIDENT QUOTATION

DATE : 1/3/2018  
OWNER NAME : KOH ENG THE  
REGN NO : SLR1382D  
MODEL : MERC E200  
CHASSIS NO : WDD2130422A100050  
REGN DATE : 11-Dec-17

### MATERIALS:-

PART DESCRIPTION		S\$
1 REAR DOOR RH (A2137300205)	1740.56	2,175.70 <del>pt</del> ✓
2 COVER STRIP RR DOOR RH (A2137300202)	22.48	28.10 <del>ne</del> ✓
3 ORNAMENTAL MOULDING (A2136900487)	81.20	101.50 <del>ne</del> ✓
4 DEFLECTOR STRIP (A2136900662)	22.99	28.74 <del>ne</del> ✓
5 COVER STRIP (A2137300402)	27.44	34.30 <del>ne</del> ✓
6 CIRCUMFERENTIAL DOOR SEAL (A2047271187)	324.58	280.72 <del>ne</del> ✓
7 FIXED WINDOW RH (A2137300255)	112.30	140.37 <del>ne</del> ✓ photo
8 WINDOW GUIDE RAIL (2137357400)	139.40	174.87 ? ✓ DD
9 ORNAMENTAL TRIM (A2136900680)	193.62	217.02 <del>ne</del> ✓
10 REAR FENDER RH (A2136302602)	1709.91	2,137.39 <del>pt</del> ✓
11 WHEEL HOUSE COVER RH (A2136909204)	144.22	908.79 ? ✓ DIS
12 REAR WINDSCREEN MOULDING BOTTOM (A2137250800)	28.99	36.24 <del>ne</del> ✓
13 WHEEL CARRIER (A2133503205)		1,613.62 ? ✓ NN
14 RIM (A21340121007X21)	1550.37	1,550.37 <del>scd</del> ✓

### TOTAL MATERIALS

9,427.73

### LABOUR

DESCRIPTION		S\$
1 TO RENEW REAR DOOR RH, REAR FENDER RH, REPAIR REAR BUMPER, SIDE SILL RH	1 day 4 day labour 1 day = 350	2,100.00 <del>1900</del> 1700
2 TO REMOVE & INSTALL REAR WINDSCREEN		120.00 ✓
3 CHECK WIRING AND ELECTRICAL SYSTEM		20.00 ✓
4 SEALANT FOR REAR WINDSCREEN		60.00 40 ✓
5 TO SPRAY PAINT FOR REAR BUMPER, REAR FENDER RH, REAR DOOR RH, SIDE SILL RH		1,000.00 800 ✓

- 6 TO REMOVE & INSTALL FUEL TANK TO FACILITATE REPAIR
- 7 TO TRANSFER DOOR TRIMS AND GLASS
- 8 TO APPLY SEALANT FOR ACCIDENT PORTION
- 9 TO TRANSFER NEW RIM TO TYRE
- 11 TO CONDUCT DIAGNOSTIC CHECK FOR THE CAR SYSTEM
- 12 TO RENEW REAR UNDER CARRIAGE, remove & install exhaust system, rear cross member
- 13 To Conduct Computerize Full Wheel Alignment
- 14 Sundry

~~350.00~~ 300 *too high*  
~~160.00~~ 120 *100*  
~~80.00~~ 60  
~~30.00~~  
~~120.00~~  
~~250.00~~ 150? *600*  
~~120.00~~ *500*  
~~20.00~~

**TOTAL LABOUR**

**4,430.00**

**GRAND TOTAL**

**13,857.73**

Prepare By : COCO LU

Survey by : \_\_\_\_\_ Date: \_\_\_\_\_

*14207.73*

Authorised / Not Authorised

THE ABOVE IS ONLY BASED ON OUR PREMILINARY INSPECTION , IN THE PROCESS OF SUCH REPAIR ADDITIONAL WORK OR WORKS OR PARTS MAY BE REQUIRE. PART PRICE SUBJECT TO CHANGE WITHOUT PRIOR NOTICE.

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SURVEYOR NAME : Rame - Hp 2000068

SURVEYOR SIGNATURE : [Signature]

DATE : 02/04/18 @ 1650

REMARKS : 12 days

Resy b & paint

*14207.73*



## Diplomat Parts Pte Ltd

VEHICLE NO : SLR 1382 D  
MODEL : MERCEDES E200 AMG AUTO  
WIP : 22305

Material	:	\$	<u>5,978.56</u>
Labour	:	\$	<u>4,150.00</u>
Sub-Total	:	\$	<u>10,128.56</u>
	:		
Less Excess	:	\$	<u>-</u>
Total	:	\$	<u>10,128.56</u>
GST 7%	:	\$	<u>709.00</u>
Grand Total	:	\$	<u>10,837.56</u>
Finalise By/Date	:		<u>LOI / 30/05/2018</u>

☒ REVERT BACK WITHIN 7 DAYS,  
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 12 WORKING DAYS + 4 Days ( 2 ) Weekends  
+ 0 Days (      ) Public Holiday  
TOTAL DAYS REPAIR TOOK = 16

☒ TP claim ERGO GBE6467Y

☒ Claim GIA / LTA fee \$ 2.00

☒ Claim Loss ☐ Use ☒ Rental

☐ Claim Medical Fee / Others \$ -



Diplomat Parts Pte. Ltd.

Company Reg No. 199400304H  
GST Reg No. MR-8500111-X

## PRO-FORMA INVOICE

**THIS IS NOT AN OFFICIAL TAX INVOICE**

Invoice Name &amp; Address

Owner Name &amp; Vehicle Info

ERGO INSURANCE PTE LTD  
MOTOR CLAIM DEPARTMENT  
5 TEMASEK BOULEVARD  
#04-01 SUNTEC TOWER FIVE  
SINGAPORE 038985

Contact No 68299199

Reg No/Reg Date SLR1382D / 11/12/2017  
Date In/Mileage 02/04/2018/ 125  
Chassis No \*WDD2130422A100050  
Engine No 27492030809260  
Make/Model E200 AMG AUTO

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
REX00002	Credit	30/05/2018/ 09:42	TLC	260 / AiTing	22305			
Description of Goods / Services				Qty	Unit Price	Disc%	Amount	
E	PNT88000	TO RENEW REAR DOOR RH, REAR FENDER RH, REPAIR REAR BUMPER SIDE SILL RH						✓ 1800.00
E	PNT88000	TO REMOVE & INSTALL REAR WINDSCREEN						✓ 120.00
M	SUNDRY	SEALANT FOR REAR WINDSCREEN						✓ 40.00
E	PNT98000	TO SPRAY PAINT FOR REAR BUMPER, REAR FENDER RH, REAR DOOR RH SIDE SILL RH						✓ 800.00
A	54900099	TO REMOVE & INSTALL FUEL TANK TO FACILITATE REPAIR						✓ 300.00
E	PNT88000	TO TRANSFER DOOR TRIMS AND GLASS						✓ 120.00
M	SUNDRY	TO APPLY SEALANT FOR ACCIDENT PORTION						✓ 60.00
M	SUNDRY	Sundry						✓ 20.00
A	54900099	TO CHECK WIRING & ELECTRICAL SYSTEM						✓ 20.00
A	54900099	TO CONDUCT DIAGNOSTIC CHECK FOR THE CAR SYSTEM						✓ 120.00
A	54900099	RENEW REAR UNDER CARRIAGE, REMOVE & INSTALL EXHAUST SYSTEM REAR CROSS MEMBER						? 600.00
S	SPECIALISTJOB	LABOUR TO TRANSFER ONE PC TYRE WITH VALVE SUPPLY						✓ 30.00
A	WHEELALIGNMENTBP	CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT						✓ 120.00
X	MA213 730 02 05	REAR DOOR	1.00	✓	2175.70	20.00	1740.56	
X	MA213 690 04 87	ORNAMENTAL MOLDING	1.00	✓	101.50	20.00	81.20	

This is not an official tax invoice. This is a computer generated document, no signature is required.





Diplomat Parts Pte. Ltd.

Company Reg No. 196400304H  
SST Reg No. MR-8500111-X

## PRO-FORMA INVOICE

**THIS IS NOT AN OFFICIAL TAX INVOICE**

Invoice Name &amp; Address

Owner Name &amp; Vehicle Info

ERGO INSURANCE PTE LTD  
MOTOR CLAIM DEPARTMENT  
5 TEMASEK BOULEVARD  
#04-01 SUNTEC TOWER FIVE  
SINGAPORE 038985

Contact No 68299199

Reg No/Reg Date SLR1382D / 11/12/2017  
Date In/Mileage 02/04/2018/ 125  
Chassis No \*WDD2130422A100050  
Engine No 27492030809260  
Make/Model E200 AMG AUTO

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
REX00002	Credit	30/05/2018/ 09:42	TLC	260 / AiTing	22305			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
X	MA204 727 11 87				1.00	✓ 280.72	20.00	224.58
	CIRCUMFERENTIAL DOOR SEAL							
X	MA213 730 02 55				1.00	✓ 140.37	20.00	112.30
	FIXED WINDOW							
X	MA213 735 74 00				1.00	? 174.87	20.00	139.90
	WINDOW GUIDE RAIL							
X	MA213 690 06 80				1.00	✓ 217.02	20.00	173.62
	ORNAMENTAL TRIM							
X	MA213 630 26 02				1.00	✓ 2137.39	20.00	1709.91
	SIDEWALL PANELING							
X	MA213 690 92 04				1.00	? 180.27	20.00	144.22
	WHEEL HOUSE COVERING							
X	MA213 725 08 00				1.00	✓ 36.24	20.00	28.99
	ELASTOMER-MOLDED SEAL							
X	MA213 401 21 00/ 7X21				1.00	✓ 1550.37	00.00	1550.37
	SPOKED WHEEL							
X	MA213 730 02 02				1.00	✓ 28.10	20.00	22.48
	COVER STRIP							
X	MA213 690 06 62				1.00	✓ 28.74	20.00	22.99
	DEFLECTOR STRIP							
X	MA213 730 04 02				1.00	✓ 34.30	20.00	27.44
	COVER STRIP							
Z	TEXT							
	TP CLAIM ERGO GBE6467Y							
	DOA : 26.02.18							
	SURVEYOR RASUL LKK 02.04.18							

Parts	5,978.56				
Labour	4,000.00				
Standard Menu	0.00				
Specialist Job	30.00				
Others(Lub,etc)	0.00				
Sundry	120.00				
Total(w/o GST)	10,128.56				
		7% GST on	10128.56	Nett	10,128.56
					709.00
				Total Payable	10,837.56

This is not an official tax invoice. This is a computer generated document, no signature is required.

209 Pandan Gardens, Singapore 609339 Tel: (65) 6568 4558 Fax: (65) 6567 5258




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD			Ref : CS/EG18004315/R1qd3e2	
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985			Date : 03-01-2019	
			Code : EGI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	GBE 6467Y	Veh. Inspected	SLR 1382D	
Policy No.		Coverage (\$)	0.00	
Claim No.	GBE6467Y/SE/pl	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	06/03/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	MERCEDES BENZ E200	c.c	1991	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	WDD2130422A100050	Colour	BLACK	
Odometer	6226	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	275/35 R19	GOODYEAR	6 mm	
L/H Front Tyre	275/35 R19	GOODYEAR	6 mm	
R/H Rear Tyre	275/35 R19	GOODYEAR	6 mm	
L/H Rear Tyre	275/35 R19	GOODYEAR	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	26/02/2018	Inspection Date	02/04/2018	
Survey held at	CYCLE & CARRIAGE KIA PTE LTD 209 PANDAN GARDENS SINGAPORE 609339			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 1382D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR DOOR RH (A2137300205)	BENT	2,175.70	1,740.56
1	COVER STRIP RR DOOR RH (A2137300202)	NECESSARY	28.10	22.48
1	ORNAMENTAL MOULDING (A2136900487)	NECESSARY	101.50	81.20
1	DEFLECTOR STRIP (A2136900662)	NECESSARY	28.74	22.99
1	COVER STRIP (A2137300402)	NECESSARY	34.30	27.44
1	CIRUMFERENTIAL DOOR SEAL (A2047271187)	NECESSARY	280.72	224.58
1	FIXED WINDOW RH (A2137300255)	NECESSARY	140.37	112.30
1	WINDOW GUIDE RAIL (2137357400)	DENTED	174.87	139.90
1	ORNAMENTAL TRIM (A2136900680)	NECESSARY	217.02	173.62
1	REAR FENDER RH (A2136302602)	BENT	2,137.39	1,709.91
1	WHEEL HOUSE COVER RH (A2136909204)	DISTORTED	908.79	144.22
1	REAR WINDSCREEN MOULDING BOTTOM (A2137250800)	NECESSARY	36.24	28.99
1	WHEEL CARRIER (A2133503205)	NOT NECESSARY	1,613.62	-
1	RIM (A21340121007X21)	SCRATCHED	1,550.37	1,550.37
			9,427.73	5,978.56
<b>SPECIAL NETT ITEMS</b>				
1	SUNDRY (SN)	NECESSARY	20.00	20.00
			20.00	20.00
<b>LABOUR</b>				
	TO RENEW REAR DOOR RH, REAR FENDER RH, REPAIR REAR BUMPER, SIDE SILL RH.		2,100.00	1,800.00
	TO REMOVE & INSTALL REAR WINDSCREEN.		120.00	120.00
	CHECK WIRING AND ELECTRICAL SYSTEM.		20.00	20.00
	SEALANT FOR REAR WINDSCREEN.		60.00	40.00
	TO SPRAY PAINT FOR REAR BUMPER, REAR FENDER RH, REAR DOOR RH, SIDE SILL RH.		1,000.00	800.00
	TO REMOVE & INSTALL FUEL TANK TO FACILITATE REPAIR.		350.00	300.00
	TO TRANSFER DOOR TRIMS AND GLASS.		160.00	120.00
	TO APPLY SEALANT FOR ACCIDENT PORTION.		80.00	60.00
	TO TRANSFER NEW RIM TO TYRE.		30.00	30.00

Report Ref No. CS/EGI18004315/R1qd3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CONDUCT DIAGNOSTIC CHECK FOR THE CAR SYSTEM.		120.00	120.00
	TO RENEW REAR UNDER CARRIAGE, REMOVE & INSTALL EXHAUST SYSTEM, REAR CROSSMEMBER.		600.00	600.00
	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT.		120.00	120.00
			4,760.00	4,130.00
GRAND TOTAL			14,207.73	10,128.56

RECOMMENDED COST OF REPAIRS				10,128.56
-----------------------------	--	--	--	-----------

Report Ref No. CS/EGI18004315/R1qd3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.