

ASS. REC. BY:

REF: CS/FCI18004323/Avd3n2 Special Instruction:

Surveyor:

CWS

Adrian

ASSIGNMENT (Office)

From (Person):

Lucene jaw

of

FCI

Date/Time: 23/2/18 @ 4:07pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLK 7555 U

Insured:

SHB 3389 D

at Workshop m/s

MCS Garage

Tel:

92700917

of

10 Kaki Bkt Rd 2 #03-25

Policy No:

Claim No:

D18001563 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 15/02/2018

CA / REV / REP. / REV 24 HRS

lwp

H.O.D. Endorsement:

Date/Time:

4:13pm 06/3/18

Person Contacted:

Kendrick

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLK 7555 U - X

SHB 3389 D -

7/3/18

Rec file

7/3/18

Informed FCI pending est from repairer by email

16/3/18

Adrian confirmed LS \$1500 (Red 2796.91, 65%)

19/3/18

Email preli revised to FCI

REF:

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SUC755SU Yr Regn: 2008 AugustType: M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi RS4 A4 C.C. 3R7Colour: Black A/C: Insured / Std / NI / NASp. Reading: 180580 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WAUZZ28K99A061424Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 275/50R19R: 275/50R19BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. \_\_\_\_\_ D.O.I. 28/02/18Survey held at 9 MCS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP 1st Cap.Note: MV: 30K (EST)LTA: 25.5KNett: 4.5K

RECEIVED 19 MAR 2018

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2) 19/3 - typistReport Format: CWSLump Sum / I.B.I: (\$) 1500/-Days Of Repair: 2Resurvey No. of Trip: 1Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation:

) S+RS: \$

) Photos

) Others

TOTAL

135

50

50

32

267

## Survey Department Check List (Case Handler)

Reference No.: CS/FCI/8004323/Avd3  
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

**Admin (** ): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

| (1) Office Assign Form |                                       | Y-Date | N-Date | Y-Date | N-Date |
|------------------------|---------------------------------------|--------|--------|--------|--------|
| C                      | Reference No.                         | ✓      |        |        |        |
| C                      | Customer Code                         |        |        |        |        |
| N                      | Assign From                           |        |        |        |        |
| C                      | Assign Date                           | ✓      |        |        |        |
| C                      | Veh No (Inspected)                    | ✓      |        |        |        |
| C                      | Veh No (Insured)                      | ✓      |        |        |        |
| C                      | D.O.A                                 | ✓      |        |        |        |
| C                      | Policy No                             |        |        |        |        |
| C                      | Claim No                              | ✓      |        |        |        |
| C                      | Insurance Authorisation (CA /REV/REP) |        |        |        |        |
| C                      | Report Type                           | ✓      |        |        |        |
| C                      | Weekend Charges                       |        |        |        |        |
| N                      | Survey held at/Repairer               | ✓      |        |        |        |
| C                      | Excess                                |        |        |        |        |

**Surveyor (** ): Case handler to make sure the surveyor completed all required information.

| (1) Assignment Form |                        | Y-Date | N-Date | Y-Date | N-Date |
|---------------------|------------------------|--------|--------|--------|--------|
| C                   | Vehicle No             | ✓      |        |        |        |
| C                   | Regn Month/Year        | ✓      |        |        |        |
| N                   | Vehicle Type           | ✓      |        |        |        |
| N                   | Make & Model           | ✓      |        |        |        |
| C                   | Engine Capacity. (C.C) | ✓      |        |        |        |
| N                   | Colour                 | ✓      |        |        |        |
| C                   | Odometer. (Sp.Reading) | ✓      |        |        |        |
| C                   | Chassis No             | ✓      |        |        |        |
| N                   | General Condition      | ✓      |        |        |        |
| N                   | Steering               | ✓      |        |        |        |
| N                   | Brake                  | ✓      |        |        |        |
| N                   | Modification (Modi)    | ✓      |        |        |        |
| C                   | Tyre Size              | ✓      |        |        |        |
| N                   | Tyre Make              | ✓      |        |        |        |
| C                   | Tyre Balance           | ✓      |        |        |        |
| C                   | Date of Inspection     | ✓      |        |        |        |
| N                   | Survey held            | ✓      |        |        |        |
| N                   | Des.of Damages         | ✓      |        |        |        |

### (2) System - (Views/Merimen)

|   |                                      |   |  |  |  |
|---|--------------------------------------|---|--|--|--|
| C | Damaged Vehicle Photographs Uploaded | ✓ |  |  |  |
|---|--------------------------------------|---|--|--|--|

### (3) Workshop Estimate/Assignment Form

|   |                                               |   |  |  |  |
|---|-----------------------------------------------|---|--|--|--|
| N | ALL Parts condition                           | ✓ |  |  |  |
| C | Market Value for OD cases                     |   |  |  |  |
| C | Estimate Repair Cost for PRI (RSI, TMI, MSIG) |   |  |  |  |
| C | Days of repair                                | ✓ |  |  |  |
| C | Finalised Amount                              |   |  |  |  |
| C | Re-inspection Cases to Finalize within 5 Days | ✓ |  |  |  |

### (4) System - (Views/Merimen)

|   |                         |   |  |  |  |
|---|-------------------------|---|--|--|--|
| C | Resurvey photo Uploaded | ✓ |  |  |  |
|---|-------------------------|---|--|--|--|

Check By: VERON 19/3/18  
Case Handler Date

\*C: Critical \*N: Non-Critical

21/05/2014



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                         |                                                                                    |                 |                           |                                                                                     |
|-------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------|-----------------|---------------------------|-------------------------------------------------------------------------------------|
| FIRST CAPITAL INSURANCE LTD                                                                                                               |                                                                                    |                 | Ref : CS/FCI18004323/Avd3 |                                                                                     |
| 36 ROBINSON ROAD<br>#16-01 CITY HOUSES SINGAPORE 068877                                                                                   |                                                                                    |                 | Date : 06-03-2018         |  |
|                                                                                                                                           |                                                                                    |                 | Code : FCI2               |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                         |                                                                                    |                 |                           |                                                                                     |
| Insured Veh.                                                                                                                              | SHB 3389D                                                                          | Veh. Inspected  | SLK 7555U                 |                                                                                     |
| Policy No.                                                                                                                                |                                                                                    | Coverage (\$)   | 0.00                      |                                                                                     |
| Claim No.                                                                                                                                 | D18001563MFSH                                                                      | Excess (\$)     | 0.00                      |                                                                                     |
| Assign From                                                                                                                               | CWS (LURENE JAW)                                                                   | Assign Date     | 06/03/2018                |                                                                                     |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                             |                                                                                    |                 |                           |                                                                                     |
| Make & Model                                                                                                                              |                                                                                    | c.c             | 0                         |                                                                                     |
| Engine No.                                                                                                                                | HIDDEN                                                                             | Year of Reg.    |                           |                                                                                     |
| Chassis No.                                                                                                                               |                                                                                    | Colour          |                           |                                                                                     |
| Odometer                                                                                                                                  | -                                                                                  | Steering        |                           |                                                                                     |
| Brakes                                                                                                                                    |                                                                                    | Modification    |                           |                                                                                     |
| General                                                                                                                                   |                                                                                    |                 |                           |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                             |                                                                                    |                 |                           |                                                                                     |
|                                                                                                                                           | Size                                                                               | Make            | Balance                   |                                                                                     |
| R/H Front Tyre                                                                                                                            |                                                                                    |                 | mm                        |                                                                                     |
| L/H Front Tyre                                                                                                                            |                                                                                    |                 | mm                        |                                                                                     |
| R/H Rear Tyre                                                                                                                             |                                                                                    |                 | mm                        |                                                                                     |
| L/H Rear Tyre                                                                                                                             |                                                                                    |                 | mm                        |                                                                                     |
| <b>4. Description of Damages</b>                                                                                                          |                                                                                    |                 |                           |                                                                                     |
|                                                                                                                                           |                                                                                    |                 |                           |                                                                                     |
| <b>5. General Information</b>                                                                                                             |                                                                                    |                 |                           |                                                                                     |
| Accident Date                                                                                                                             | 15/02/2018                                                                         | Inspection Date | 06/03/2018                |                                                                                     |
| Survey held at                                                                                                                            | MCS GARAGE<br>10 KAKI BUKIT ROAD 2<br>#03-25 FIRST EAST CENTRE<br>SINGAPORE 417868 |                 |                           |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                        |                                                                                    |                 |                           |                                                                                     |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                    |                 |                           |                                                                                     |



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18001563MFSH  
Our ref: CS/FCI18004323/Avd3

Date : 19/3/2018

The Motor Claims Department  
M/s FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

**INITIAL INSPECTION REPORT OF VEHICLE NO. SLK 7555U**


We thank you for your instruction on 23/2/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 28/2/2017 at the premises of M/s MCS GARAGE and have the following to report:-

|                          |               |
|--------------------------|---------------|
| Workshop Estimate Amount | : S\$4,296.91 |
| Revised Estimate Amount  | : S\$1,949.08 |
| "Check" Items Amount     | : S\$         |
| Market Value             | : S\$         |
| LTA Reimbursement Value  | : S\$         |
| Nett Value               | : S\$         |

**Description of Damage:**

The vehicle sustained damages at the front o/s portion.



**Comments/Present Status:**

Damages Consistent

Yours faithfully,

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A.M.MATAI

Licensed Appraiser

**MOTOR SURVEY ASSIGNMENT**

|                           |                                               |                                      |
|---------------------------|-----------------------------------------------|--------------------------------------|
| <b>Date</b>               | 22-02-2018                                    | <b>Our Ref No.</b> D18001563MFSH     |
| <b>Accident Date</b>      | 15-02-2018                                    | <b>Claim Type.</b> Third Party       |
| <b>Insured Vehicle</b>    | SHB3389D                                      | <b>Third Party Vehicle.</b> SLK7555U |
| <b>Survey Location</b>    | 10 KAKI BUKIT ROAD 2 #03-25 FIRST EAST CENTRE |                                      |
| <b>Contact Person.</b>    | MR KENDRICK/ AH HOCK                          |                                      |
| <b>Contact No.</b>        | 82857623/ 92700917                            | <b>Fax No.</b> 0                     |
| <b>Survey Type</b>        | WITHOUT PREJUDICE:                            |                                      |
| <b>Appointed Surveyor</b> | LKK AUTO CONSULTANTS PTE LTD                  |                                      |
| <b>Contact Person</b>     | NA                                            | <b>Fax No.</b> 68416315              |
| <b>Contact Number.</b>    | NA                                            |                                      |

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

|                          |                |                                |
|--------------------------|----------------|--------------------------------|
| <b>Cc : Workshop</b>     | MCS GARAGE     | <b>Attention.</b> NIL          |
| <b>Cc : TP Solicitor</b> | VISION LAW LLC | <b>TP Solicitor Fax No.</b> NA |
| <b>Officer Incharge</b>  | LURENE         |                                |

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/235253)



PRI Documents



Close X

## PRI Header Details

|                          |                                                       |                                              |                                                                                                                                                                |                                 |              |
|--------------------------|-------------------------------------------------------|----------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------|--------------|
| <b>Claim No</b>          | D18001563MFSH                                         | <b>Policy No</b>                             | D-18088937MFSH                                                                                                                                                 | <b>Claimant S.No &amp; Name</b> | 1 & VISION L |
| <b>Workshop Name</b>     | MCS GARAGE<br>(Contact Person : MR KENDRICK/ AH HOCK) | <b>Survey Location &amp; Contact Details</b> | 10 KAKI BUKIT ROAD 2 #03-25 FIRST EAST CENTRE<br><b>Mobile:</b> 92700917 , <b>Phone:</b> 82857623 , <b>Fax:</b> 0<br><b>EmailId:</b> CT-ADMIN@VISIONLAWLLC.COM |                                 |              |
| <b>Our Surveyor</b>      | LKK AUTO CONSULTANTS PTE LTD                          | <b>Instructions To Surveyor</b>              | WITHOUT PREJUDICE:                                                                                                                                             |                                 |              |
| <b>Insured Name</b>      | CITYCAB PTE LTD                                       | <b>Insured Vehicle No</b>                    | SHB3389D                                                                                                                                                       | <b>TP Vehicle No</b>            | SLK7555U     |
| <b>PRI Recieved Date</b> | 22-02-2018 06:32:57 PM                                | <b>Surveyor Appointed Date</b>               | 23-02-2018 04:06:19 PM                                                                                                                                         | <b>Surveyor Accept Date</b>     | 06-03-2018 0 |

## Survey Report Upload

|                                    |  |                             |            |                                |                                            |
|------------------------------------|--|-----------------------------|------------|--------------------------------|--------------------------------------------|
| <b>Surveyor Inspection Date *:</b> |  | <b>Surveyor Report Date</b> | 06-03-2018 | <b>Upload Survey Report *:</b> | <input type="button" value="Choose File"/> |
|------------------------------------|--|-----------------------------|------------|--------------------------------|--------------------------------------------|

## Vehicle Particulars

|                  |                      |                       |                       |                |                      |
|------------------|----------------------|-----------------------|-----------------------|----------------|----------------------|
| <b>Make</b>      | Please Select Make ▾ | <b>Model</b>          | Please Select Model ▾ | <b>Year</b>    | Select Year ▾        |
| <b>Chasis No</b> | <input type="text"/> | <b>Engine No</b>      | <input type="text"/>  | <b>Mileage</b> | <input type="text"/> |
| <b>Color</b>     | <input type="text"/> | <b>Cubic Capacity</b> | <input type="text"/>  |                |                      |

## Multiple Documents Upload

File Name

Action

## Surveyor Job Remarks

|                |                      |                                     |
|----------------|----------------------|-------------------------------------|
| <b>Remarks</b> | <input type="text"/> | <input type="button" value="Save"/> |
|----------------|----------------------|-------------------------------------|

## Veron Chen (LKKAUTO)

---

**From:** Veron Chen (LKKAUTO)  
**Sent:** Monday, 19 March 2018 12:10 PM  
**To:** 'Claim Workflow System'  
**Cc:** SUR; 'LURENEJAW@MSFIRSTCAPITAL.COM.SG'  
**Subject:** RE: SURVEY ASSESSMENT - D18001563MFSH/1, SLK 7555U  
**Attachments:** SLK 7555U PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SLK 7555U  
Date of survey: 28/2/2018  
Number of days: 2 days

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Veron Chen (LKKAUTO)  
**Sent:** Wednesday, 7 March 2018 3:52 PM  
**To:** 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>  
**Cc:** SUR <sur@lkkauto.com>; LURENEJAW@MSFIRSTCAPITAL.COM.SG  
**Subject:** RE: SURVEY ASSESSMENT - D18001563MFSH/1, SLK 7555U

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SLK 7555U on 28/2/2018.

We are pending estimate from repairer.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO)  
**Sent:** Wednesday, 7 March 2018 3:47 PM  
**To:** Veron Chen (LKKAUTO) <veronchen@lkkauto.com>  
**Subject:** FW: SURVEY ASSESSMENT - D18001563MFSH/1

Best Regards,

**Catherine Chong** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]

**Sent:** Friday, 23 February, 2018 4:07 PM

**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)

**Cc:** [CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG](mailto:CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG); [LURENEJAW@MSFIRSTCAPITAL.COM.SG](mailto:LURENEJAW@MSFIRSTCAPITAL.COM.SG)

**Subject:** PRI: SURVEY ASSESSMENT - D18001563MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

**PS: This is a system generated mail. Please do not reply to this mail.**

**Veron Chen (LKKAUTO)**

---

**From:** Veron Chen (LKKAUTO)  
**Sent:** Wednesday, 7 March 2018 3:52 PM  
**To:** 'Claim Workflow System'  
**Cc:** SUR; LURENEJAW@MSFIRSTCAPITAL.COM.SG  
**Subject:** RE: SURVEY ASSESSMENT - D18001563MFSH/1, SLK 7555U

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SLK 7555U on 28/2/2018.

We are pending estimate from repairer.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO)  
**Sent:** Wednesday, 7 March 2018 3:47 PM  
**To:** Veron Chen (LKKAUTO) <veronchen@lkkauto.com>  
**Subject:** FW: SURVEY ASSESSMENT - D18001563MFSH/1

Best Regards,

**Catherine Chong** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]  
**Sent:** Friday, 23 February, 2018 4:07 PM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** [CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG](mailto:CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG); [LURENEJAW@MSFIRSTCAPITAL.COM.SG](mailto:LURENEJAW@MSFIRSTCAPITAL.COM.SG)  
**Subject:** PRI: SURVEY ASSESSMENT - D18001563MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,  
Admin Team  
Claim Workflow System

Motor Claims Department  
MS First Capital Insurance Limited  
Tel : 6507 3848  
Fax : 6507 3849

**PS: This is a system generated mail. Please do not reply to this mail.**

## Enquire PARF/COE Rebate for Registered Vehicle

|                                |                                          |
|--------------------------------|------------------------------------------|
| Vehicle Owner Particulars      |                                          |
| Owner ID Type:                 | Singapore NRIC                           |
| Owner ID:                      | 6526D                                    |
| Vehicle Details                |                                          |
| Vehicle No.:                   | SLK7555U                                 |
| Vehicle to be Exported:        | Yes                                      |
| Intended De-registration Date: | 28 Feb 2018                              |
| Vehicle Make:                  | AUDI                                     |
| Vehicle Model:                 | A4 3.2 FSI QU S-LINE AT ABS D/AB HID 4DR |
| Primary Colour:                | Black                                    |
| Manufacturing Year:            | 2008                                     |
| Engine No.:                    | CAL016201                                |
| Chassis No.:                   | WAUZZZ8K99A061424                        |
| Maximum Power Output:          | 195.0 kW (261 bhp)                       |
| Open Market Value:             | \$49,762.00                              |
| Original Registration Date:    | 29 Aug 2008                              |
| First Registration Date:       | 29 Aug 2008                              |
| Transfer Count:                | 3                                        |
| Actual ARF Paid:               | \$49,762.00                              |
| Intended PARF Rebate Details   |                                          |
| PARF Eligibility:              | Yes                                      |
| PARF Eligibility Expiry Date:  | 28 Aug 2018                              |
| PARF Rebate Amount:            | \$24,881.00                              |
| Intended COE Rebate Details    |                                          |
| COE Expiry Date:               | 28 Aug 2018                              |
| COE Category:                  | E - Open Category                        |
| COE Period(Years):             | 10                                       |
| QP Paid:                       | \$14,101.00                              |
| COE Rebate Amount:             | \$634.00                                 |
| <b>Total Rebate Amount:</b>    | <b>\$25,515.00</b>                       |

The information contained herein is correct as at 28 Feb 2018

OK

## Cheap Car Insurance Renewal

Is your car insurance expiring soon?

Receive best quotations from multiple insurers in as little as 2 hours.

### Post an Advertisement

Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

New 5 Year Coe Renewal Honda Stream 1.8A



\$2800 Downpayment Monthly  
From \$668 Onwards. Lowest  
3.68%APR. All GV Cars Financing  
GV Credit Pte Ltd [StarAd](#)



Browse by Category ▼

Sort by Date Posted ▼

20 results/page ▼

4 vehicles

Audi A4

Advanced Search

|                                                                                                                                                                                                               | Make    | Model                             | Price    | Depreciation | Reg Date    | Eng Cap  | Mileage    | Veh Type | Status    |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------|-----------------------------------|----------|--------------|-------------|----------|------------|----------|-----------|
| <b>Search Selection</b>                                                                                                                                                                                       | Audi A4 |                                   | Any      | Any          | 2008        | Any      | Any        | Any      | Available |
|                                                                                                                                                                                                               | Audi A4 | Cabriolet 1.8T MU (New 10-yr COE) | \$90,800 | \$9,080 /yr  | 30-Apr-2008 | 1,781 cc | 81,000 km  | Sports   | Available |
| Genuine Low Mileage, 1st Owner Had It For 8.5 Years And Rarely Used. Price For 10 Years COE At \$90,800. Low Depreciation Of \$9K Only! New Aircon System, Very Well Maintained.                              |         |                                   |          |              |             |          |            |          |           |
| Posted: 27-Jan-2018 Tags: 2008 Audi A4, Audi A4, Audi, A4, Used Audi                                                                                                                                          |         |                                   |          |              |             |          |            |          |           |
|                                                                                                                                                                                                               | Audi A4 | Cabriolet 2.0A TFSI S-Line        | \$36,800 | N.A          | 27-Jun-2008 | 1,984 cc | -          | Sports   | Available |
| Option To Buy With New 10 Years COE. It Is Right Time To Own A Audi Soft Top Cabriolet Now! Beautiful White Colour With Red Interior, Accident Free, High PARF Rebate, Regular Servicing, Very Well Main...   |         |                                   |          |              |             |          |            |          |           |
| Eurosport Auto                                                                                                                                                                                                |         |                                   |          |              |             |          |            |          |           |
| Posted: 22-Feb-2018 Tags: 2008 Audi A4, Audi A4, Audi, A4, Used Audi                                                                                                                                          |         |                                   |          |              |             |          |            |          |           |
|                                                                                                                                                                                                               | Audi A4 | 1.8A TFSI MU                      | \$26,888 | \$15,870 /yr | 23-Sep-2008 | 1,798 cc | -          | Luxury   | Available |
| AA Trust Certified Quality Pre-Owned Vehicle! Great Deal! Guarantee Buy Back At \$21k! Only \$5888 For 7 Months Drive! Extremely Well Maintained Interior And Exterior! View It To Believe It! Flexible Ba... |         |                                   |          |              |             |          |            |          |           |
| AA Trust Automotive                                                                                                                                                                                           |         |                                   |          |              |             |          |            |          |           |
| Posted: 19-Feb-2018 Tags: 2008 Audi A4, Audi A4, Audi, A4, Used Audi                                                                                                                                          |         |                                   |          |              |             |          |            |          |           |
|                                                                                                                                                                                                               | Audi A4 | 1.8A TFSI MU S-Line               | \$31,500 | \$15,410 /yr | 11-Dec-2008 | 1,798 cc | 165,830 km | Luxury   | Available |
| Beautiful Interior And Exterior, Most Of The Faulty Parts Replace With Workshop Receipt Support, Powerful Air Conditioning, Accidental Free, Please Call And Make Appointment To View, No Agent Please.       |         |                                   |          |              |             |          |            |          |           |
| Posted: 10-Feb-2018 Tags: 2008 Audi A4, Audi A4, Audi, A4, Used Audi                                                                                                                                          |         |                                   |          |              |             |          |            |          |           |

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or station wagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used Audi A4, Audi A4 Singapore, used Audi A4 Singapore, used Audi A4, used vehicles Singapore or even buy used Audi A4 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

- Home
- New Car
- Used Car
- Sell Car
- Motor
- Product
- Article
- Forum

- About Us
- Careers
- Contact Us
- Sitemap

# MCS Garage

10 Kaki Bukit Road 2 #03-25, First East Centre Singapore 471868

Tel: 9270 0917 / 6538 4322

Vehicle number: SLK7555U

TP1st Cap. reason

Vehicle Made & Model: AUDI A4

| Qty               | List Items                   | Amount \$       |
|-------------------|------------------------------|-----------------|
| 1                 | Front bumper <i>del</i>      | 1,543.43 ✓      |
| 1                 | Front bumper fog lamp - RH   | 281.92 *        |
| 1                 | Front bumper fog lamp cover  | 110.42 *        |
| 1                 | Front bumper PDC sensor      | 313.75 ✓        |
| 1                 | Front bumper sponge          | 140.65 *        |
| 1                 | Front bumper side guide - RH | 55.60 ✓         |
| 1                 | Front bumper reinforcement   | 761.50 *        |
| <b>Sub-total</b>  |                              | <b>3,207.27</b> |
| <b>Less 5%</b>    |                              | <b>160.36</b>   |
| <b>Total List</b> |                              | <b>3,046.91</b> |

## Labour charges

To check front wiring

To respray painting and etc

Panel beating, cut, weld remove & replacing above parts

**Total Labour** 1,250.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 1948.07

2/s: 1512

02 Days

**ESTIMATE PARTS AND LABOUR GRAND TOTAL \$ 4,296.91**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                                                                      |                                                                                    |                 |                             |                                                                                     |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------|-----------------|-----------------------------|-------------------------------------------------------------------------------------|
| FIRST CAPITAL INSURANCE LTD                                                                                                                                                            |                                                                                    |                 | Ref : CS/FCI18004323/Avd3n2 |                                                                                     |
| 36 ROBINSON ROAD<br>#16-01 CITY HOUSESINGAPORE 068877                                                                                                                                  |                                                                                    |                 | Date : 20-03-2018           |  |
|                                                                                                                                                                                        |                                                                                    |                 | Code : FCI2                 |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                                                                      |                                                                                    |                 |                             |                                                                                     |
| Insured Veh.                                                                                                                                                                           | SHB 3389D                                                                          | Veh. Inspected  | SLK 7555U                   |                                                                                     |
| Policy No.                                                                                                                                                                             | D-18088937MFSH                                                                     | Coverage (\$)   | 0.00                        |                                                                                     |
| Claim No.                                                                                                                                                                              | D18001563MFSH                                                                      | Excess (\$)     | 0.00                        |                                                                                     |
| Assign From                                                                                                                                                                            | LURENE                                                                             | Assign Date     | 23/02/2018                  |                                                                                     |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                                                                          |                                                                                    |                 |                             |                                                                                     |
| Make & Model                                                                                                                                                                           | AUDI A4                                                                            | c.c             | 3197                        |                                                                                     |
| Engine No.                                                                                                                                                                             | HIDDEN                                                                             | Year of Reg.    | 2008                        |                                                                                     |
| Chassis No.                                                                                                                                                                            | WAUZZZ8K99A061424                                                                  | Colour          | BLACK                       |                                                                                     |
| Odometer                                                                                                                                                                               | 180580                                                                             | Steering        | IN ORDER                    |                                                                                     |
| Brakes                                                                                                                                                                                 | IN ORDER                                                                           | Modification    | SPORTS RIM                  |                                                                                     |
| General                                                                                                                                                                                | GOOD                                                                               |                 |                             |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                                                                          |                                                                                    |                 |                             |                                                                                     |
|                                                                                                                                                                                        | Size                                                                               | Make            | Balance                     |                                                                                     |
| R/H Front Tyre                                                                                                                                                                         | 275/50 R19                                                                         | MICHELIN        | 6 mm                        |                                                                                     |
| L/H Front Tyre                                                                                                                                                                         | 275/50 R19                                                                         | MICHELIN        | 6 mm                        |                                                                                     |
| R/H Rear Tyre                                                                                                                                                                          | 275/50 R19                                                                         | MICHELIN        | 6 mm                        |                                                                                     |
| L/H Rear Tyre                                                                                                                                                                          | 275/50 R19                                                                         | MICHELIN        | 6 mm                        |                                                                                     |
| <b>4. Description of Damages</b>                                                                                                                                                       |                                                                                    |                 |                             |                                                                                     |
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.<br>DAMAGES SEE DETAILS.                                                                                                        |                                                                                    |                 |                             |                                                                                     |
| <b>5. General Information</b>                                                                                                                                                          |                                                                                    |                 |                             |                                                                                     |
| Accident Date                                                                                                                                                                          | 15/02/2018                                                                         | Inspection Date | 28/02/2018                  |                                                                                     |
| Survey held at                                                                                                                                                                         | MCS GARAGE<br>10 KAKI BUKIT ROAD 2<br>#03-25 FIRST EAST CENTRE<br>SINGAPORE 417868 |                 |                             |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                                                                     |                                                                                    |                 |                             |                                                                                     |
| A) DAMAGES CONSISTENT TO ACCIDENT REPORT.<br>B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                    |                 |                             |                                                                                     |
| <b>5b. Estimate Days of Repair</b>                                                                                                                                                     |                                                                                    |                 |                             |                                                                                     |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                                                                    |                                                                                    | 2 Working Days  |                             |                                                                                     |



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLK 7555U

| Qty | Description of Parts                                                        | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|-----------------------------------------------------------------------------|---------------|---------------------------|-------------------|
|     | <b>REPLACEMENT OF PARTS</b>                                                 |               |                           |                   |
| 1   | FRONT BUMPER                                                                | DEFORMED      | 1,543.43                  | 1,543.43          |
| 1   | FRONT BUMPER FOG LAMP-RH                                                    | NOT NECESSARY | 281.92                    | -                 |
| 1   | FRONT BUMPER FOG LAMP COVER                                                 | NOT NECESSARY | 110.42                    | -                 |
| 1   | FRONT BUMPER PDC SENSOR                                                     | NOT NECESSARY | 313.75                    | -                 |
| 1   | FRONT BUMPER SPONGE                                                         | NOT NECESSARY | 140.65                    | -                 |
| 1   | FRONT BUMPER SIDE GUIDE-RH                                                  | NECESSARY     | 55.60                     | 55.60             |
| 1   | FRONT BUMPER REINFORCEMENT                                                  | NOT NECESSARY | 761.50                    | -                 |
|     | LESS 5% DISCOUNT                                                            |               | -160.36                   | -79.95            |
|     |                                                                             |               | 3,046.91                  | 1,519.08          |
|     | <b>LABOUR</b>                                                               |               |                           |                   |
|     | TO CHECK FRONT WIRING.                                                      |               | 50.00                     | 30.00             |
|     | TO RESPRAY PAINTING AND ETC.                                                |               | 600.00                    | 200.00            |
|     | PANEL BEATING,CUT,WELD REMOVE & REPLACING ABOVE PARTS.                      |               | 600.00                    | 200.00            |
|     |                                                                             |               | 1,250.00                  | 430.00            |
|     | <b>GRAND TOTAL</b>                                                          |               | <b>4,296.91</b>           | <b>1,949.08</b>   |
|     | <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b> |               |                           | <b>1,500.00</b>   |

Report Ref No. CS/FCI18004323/Avd3n2

MARKET VALUE: \$30,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$25,500.00=NETT VALUE: \$4,500.00

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.