

100000

NS CASE OWNER:

MAIS

Justin

CC 4 / LCR18004330 / U P 13

03

LKK

IDAC:

Surveyor:

MARCUS

DOI:

06/03/18

Date / Time:

05/03/18

Registered in Merimen:

06/03/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLM 2849U

Claim No.:

66047586205G

Name of Insured:

LCR

Policy No.:

Insured Tel No.:

HP:

Make / Model:

TOYOTA PRIUS HYBRID - 1.8 (A)

Excess Sec II :SS

D.O.A.:

24/02/18

Place of Accident:

MAULMEIN RD TOWARDS THOMSON RD

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO Driver Name / Age: ONG Soon Kee

Driver Tel No.:

(VA / YES / NO)

OI GIA REPORT YES / NO TP GIA REPORT YES / NO

Insured Liability:

% Final ? Yes / No

FGI 72742



INSRS:

WSP: Erofa Motor Trading

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

07/03/18 (HT)

FGI 72742 - X / SLM 2849U - X

13/3/18

TP report: Old made U-turn & collided on other motorbike.

Old report: He made U-turn, TP jammed brake & skidded. No contact b/w both vehicles.

5/4/18

File pass to Marcus to find out on CTR

16/6/18

Pending PIR

26/2/19

Rec'd email from MAR: sum up.

27/2/19

File -> not been de cler

STAGE

DATE / PIC

Non-Reporting hr (1st):

Non-Reporting hr (2nd):

Non-Reporting hr (Final):

Notification hr (if non-pickup):

Call OI:

After call hr to OI:

15/2/18

Documentation Check List: Handler Typist

Notification hr (if non-pickup)

After call hr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

50

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

SS

Loss of Rental (LOR):

SS

(days)

Loss of Use (LOU):

SS

(S

x

days)

Loss of Income (LOI):

SS

(S

x

days)

LOR only LOR + LOU

SS

LOR + LO

SS

LOR + LO

SS

LOR + LO

SS

LOR + LO

SS

LOR + LO

SS

LOR + LO

SS

LOR + LO

SS

LOR + LO

SS

LOR + LO

SS

LOR + LO

SS

LOR + LO

SS

LOR + LO

SS

LOR + LO

SS

GIA/LTA Search

SS

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

27/5/19

TP

#25012

TOTAL:

SS

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

Name 1:

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC4/LCR18004330/Ups3	
78 SHENTON WAY #08-16 CHARTIS BUILDINGS SINGAPORE 079120		Date : 06-03-2018	
		Code : LCR	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLM 2849U	Veh. Inspected	FBJ 7374Z
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	06/03/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	24/02/2018	Inspection Date	06/03/2018
Survey held at	EROFIA MOTOR TRADING PTE LTD 1 KAKI BUKIT AVENUE 6 #02-62 SINGAPORE 417883		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1812E
Vehicle Details	
Vehicle No.:	FBJ7374Z
Vehicle to be Exported:	No
Intended De-registration Date:	06 Mar 2018
Vehicle Make:	YAMAHA
Vehicle Model:	FINO 115 I
Primary Colour:	Black
Manufacturing Year:	2013
Engine No.:	E3K3E406219
Chassis No.:	MLESE701111406219
Maximum Power Output:	-
Open Market Value:	\$1,588.00
Original Registration Date:	23 Sep 2014
First Registration Date:	23 Sep 2014
Transfer Count:	1
Actual ARF Paid:	\$239.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	22 Sep 2024
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$4,453.00
COE Rebate Amount:	\$2,914.00
Total Rebate Amount:	\$2,914.00

The information contained herein is correct as at 06 Mar 2018

OK

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

AIG

Name : Chan Lai Come

Accident Date : 24-Feb-18

Vehicle No : FBJ 7374 Z

Vehicle Model : Yamaha Fino

Estimated Repair Costs

Qty	Description	Amount S(\$)
	<u>List Items</u>	
1	Front fender	\$ 85.00 ✓
2	Fork inner tubes	\$ 160.00 ✓
2	Fork outer tubes	\$ 180.00 ✓
1	Fork under bracket	\$ 145.00 ✓
1	Front brake disc	\$ 115.00 ✓
1	Front rim shaft	\$ 38.00 ✓
1	Front rim	\$ 280.00 ✓
1	Front rim spook (1 set)	\$ 60.00 ✓
1	Front signal -L/H	\$ 70.00 ✓
1	Handle bar	\$ 138.00 ✓
1	Handle bar end	\$ 28.00 ✓
1	Brake lever (1 set)	\$ 68.00 ✓
1	Side mirror (1 set)	\$ 120.00 ✓
1	Front cowling	\$ 198.00 ✓
1	Front cowling inner panel	\$ 108.00 ✓
1	Front lower cowling	\$ 80.00 ✓
1	Lower cowling	\$ 95.00 ✓
1	Front footstep panel	\$ 116.00 ✓
1	Passenger footrest (1 set)	\$ 98.00 ✓
1	Main stand	\$ 85.00 ✓
1	Side stand	\$ 70.00 ✓
1	Kick starter	\$ 105.00 ✓
1	Crankcase cover	\$ 250.00 ✓
1	Rear signal -L/H	\$ 65.00 ✓
1	Rear fender	\$ 105.00 ✓
1	Rear tailboard -L/H	\$ 138.00 ✓
		\$ 3,000.00
	Less 10%	\$ 300.00
		\$ 2,700.00

Not Adjust
2/5 2150
5 day
6/3/18
To be paid After repair

1379
1241.1

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

Name : Chan Lai Come

Accident Date : 24-Feb-18

Vehicle No : FBJ 7374 Z

Vehicle Model : Yamaha Fino

Estimated Repair Costs

Special Nett Items

2	Fork oils	\$	ner	30.00	—
2	Fork oil seals	\$	ner	56.00	—
1	Steering cone (1 set)	\$	ner	75.00	—
1	Rear box	\$	ner	180.00	—
1	Rear box bracket	\$	ner	100.00	—
1	ERP IU	\$	ner	170.00	165
1	Helmet	\$	ner	95.00	80
1	"FINO" emblem	\$	ner	80.00	✓
				\$	786.00

<u>S/No.</u>	<u>Labour</u>				
1	To provide towing service.	\$		45.00	35
2	To check wiring and reset headlamp focusing.	\$	11	80.00	x
3	To provide labour.	\$		480.00	300
4	To respray painting.	\$		500.00	350
				\$	1,105.00

Grand Total \$ 4,591.00

Dollars: Four Thousand Five Hundred And Ninety-One Only.

EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Tuesday, 13 March 2018 8:18 AM
To: 'Eileen, May Hwee Yap'
Subject: ACCIDENT INVOLVING SLM 2849U(AIG) & FBJ 7374Z ON 24/02/2018

Your Ref: **SLM 2849U**
Our Ref: CC4/LCR18004330/Ups3

Dear Sir/Madam,

ACCIDENT INVOLVING SLM 2849U(AIG) & FBJ 7374Z ON 24/02/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

We have received a claim from FBJ 7374Z against your insurance policy.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

If you have evidence/information to prove that we should not settle the third party claim, kindly let us have them in writing within the next 10 days i.e. by **24/03/2018**, after we shall proceed with negotiation with Third Party claimant on the without prejudice basis and any settlement should not bind any claims whatsoever by you/your driver against the other party's insurer arising from this particular accident.

Please call us if you have further queries.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Hsiao Tong (LKKAUTO)

From: Hsiao Tong (LKKAUTO)
Sent: Saturday, 16 June 2018 9:46 AM
To: 'erofia@singnet.com.sg'
Subject: <Request for PIR> Your Ref: FBJ 7374Z *Our Ref: CC4/LCR18004330/Upa3
[ACCIDENT INVOLVING SLM 2849U(AIG) & FBJ 7374Z ON 24/02/2018]

Your Ref: **FBJ 7374Z**
Our Ref: CC4/LCR18004330/Upa3

Without Prejudice

Dear Sir/Madam,

ACCIDENT INVOLVING SLM 2849U(AIG) & FBJ 7374Z ON 24/02/2018

We refer to the above matter.

Please be informed that liability is unclear as our insured driver reported that your client jammed brake and skidded. There was no contact between his car and your client motorbike. Kindly refer to the below police report for your easy reference.

Brief Details.

On 24/02/2018 at about 2.30pm, I was driving my vehicle along Balestier Road towards Moulin Road. My vehicle bearing plate number SLM2849U. While driving at the location, I wanted to make a U-Turn at the U-Turn point located before any traffic light junction.

I had made a check on the opposite road and observed that the road is clear. As such, I did a U-Turn. While doing a U-Turn, I realised a vehicle with plate number FBJ7374Z, was almost beside my vehicle, in the same lane. She did a jam brake in order to avoid a collision and due to that, she skidded off.

I then stopped my vehicle and assisted her. The motorcyclist was conveyed by an ambulance as she was injured. Traffic police attended to us with reference E/20180224/0122 under TP SIO Zayid with contact number: 65476394. No government property damaged.

We would like to request a copy of Police Investigation Result (if any) for our necessary action.

We will get back to you once we hear from you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Hsiao Tong (LKKAUTO)

From: Mavis, Chew <Chew.Mavis@aig.com>
Sent: Tuesday, 26 February 2019 10:34 AM
To: Hsiao Tong (LKKAUTO); Admin A; Admin-D (LKKAUTO); Joy Irene (LKKAUTO)
Subject: #6467401702SG003#023# << AIG ref | Veh: DCW8742, DOA: 09/07/18

Hi LKK

You were the appointed SJE for this matter. We have received LOD from Roy & Partners, kindly upload your photo/survey report/invoice in Merimen soonest possible, thank you.

Best Regards,
Ms. Mavis Chew
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd.

AIG Building, 78 Shenton Way, #08-16, Singapore 079120
Tel +(65) 6419 1970
chew.mavis@aig.com | www.aig.sg



AIG Asia Pacific won General Insurance Company of the Year at the 22nd Asia Insurance Industry Awards.
[Click here to find out more.](#)

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Feb 2018 Edit Reg		05 Mar 2018 00:00 Edit Adj Rpt	S\$2,150.00 Edit Estimates	S\$2,150.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: LCRF PTE LTD , Co. Reg. No.: 201604597K									
Main Claimant: CHAN LAI COME , ID: 57771812E									
Vehicle Reg. No.: FBJ7374Z		Date of Loss: 24/02/2018 00:00 - :59 [41 Months and 1 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 6604758620SG		Policy/Cover Note No.: 0999994774 (Comprehensive)							
Vehicle Reg. No. (Insured): SLM2849U		Policy No. (Claimant): AN3159259							
		Excess:							
Repairer: Erofia Motor Trading Pte Ltd - (kaki Bukit) (HQ) 1 Kaki Bukit Avenue 6, #02-62 AutoBay @ Kaki Bukit, 417883 Kaki Bukit - Tel: 67527740 / 90696165									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Wong, Justin] Justin.Wong@aig.com									
Claimant's Insurer: AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 15/03/2018]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FBJ7374Z (6604758620SG)
[SLM2849U]

TP

CHAN LAI COME

Feb 24 2018 12:00AM









































[LCRF PTE LTD]

Erofia Motor Trading Pte Ltd - (kaki Bukit)

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser	
------------------	--	---------------	--------------------	--------------	--------------	--	--

Assessment Reports					1 per page v	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print	
1	08/03/18 14:32	Accident Statement <small>From: SC - Reg. No: SLM2849U, Claimant: LCRF PTE LTD</small>		Load HTM		

Photos/Images					3 per page v	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	06/03/18 18:43	General View		Load JPG	<input checked="" type="checkbox"/>	
2	06/03/18 18:43	General View		Load JPG	<input checked="" type="checkbox"/>	
3	06/03/18 18:43	General View		Load JPG	<input checked="" type="checkbox"/>	
4	06/03/18 18:43	General View		Load JPG	<input checked="" type="checkbox"/>	
5	06/03/18 18:43	General View		Load JPG	<input checked="" type="checkbox"/>	
6	06/03/18 18:43	General View		Load JPG	<input checked="" type="checkbox"/>	
7	06/03/18 18:43	General View		Load JPG	<input checked="" type="checkbox"/>	
8	06/03/18 18:43	General View		Load JPG	<input checked="" type="checkbox"/>	
9	06/03/18 18:43	General View		Load JPG	<input checked="" type="checkbox"/>	
10	06/03/18 18:43	General View		Load JPG	<input checked="" type="checkbox"/>	
11	06/03/18 18:43	General View		Load JPG	<input checked="" type="checkbox"/>	
12	06/03/18 18:43	General View		Load JPG	<input checked="" type="checkbox"/>	
13	06/03/18 18:43	General View		Load JPG	<input checked="" type="checkbox"/>	
14	06/03/18 18:43	General View		Load JPG	<input checked="" type="checkbox"/>	
15	06/03/18 18:43	General View		Load JPG	<input checked="" type="checkbox"/>	
16	06/03/18 18:43	General View		Load JPG	<input checked="" type="checkbox"/>	
17	06/03/18 18:43	General View		Load JPG	<input checked="" type="checkbox"/>	
18	06/03/18 18:43	General View		Load JPG	<input checked="" type="checkbox"/>	
19	06/03/18 18:43	General View		Load JPG	<input checked="" type="checkbox"/>	
20	06/03/18 18:43	General View		Load JPG	<input checked="" type="checkbox"/>	
21	06/03/18 18:43	General View		Load JPG	<input checked="" type="checkbox"/>	
22	06/03/18 18:43	General View		Load JPG	<input checked="" type="checkbox"/>	
23	06/03/18 18:43	General View		Load JPG	<input checked="" type="checkbox"/>	
24	06/03/18 18:43	General View		Load JPG	<input checked="" type="checkbox"/>	
25	06/03/18 18:43	General View		Load JPG	<input checked="" type="checkbox"/>	
26	06/03/18 18:43	General View		Load JPG	<input checked="" type="checkbox"/>	
27	06/03/18 18:43	General View		Load JPG	<input checked="" type="checkbox"/>	
28	06/03/18 18:43	General View		Load JPG	<input checked="" type="checkbox"/>	
29	06/03/18 18:43	General View		Load JPG	<input checked="" type="checkbox"/>	
30	06/03/18 18:43	General View		Load JPG	<input checked="" type="checkbox"/>	
31	06/03/18 18:43	General View		Load JPG	<input checked="" type="checkbox"/>	
32	06/03/18 18:43	General View		Load JPG	<input checked="" type="checkbox"/>	
33	06/03/18 18:43	General View		Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
34	06/03/18 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
35	06/03/18 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
36	06/03/18 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
37	06/03/18 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
38	06/03/18 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
39	06/03/18 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
40	06/03/18 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
41	06/03/18 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
42	06/03/18 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
43	06/03/18 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
44	06/03/18 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
45	06/03/18 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
46	06/03/18 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
47	06/03/18 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
48	06/03/18 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
49	06/03/18 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
50	06/03/18 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
51	06/03/18 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
52	06/03/18 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
53	06/03/18 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
54	06/03/18 18:44	General View	 Load JPG	<input checked="" type="checkbox"/>
55	06/03/18 18:44	General View	 Load JPG	<input checked="" type="checkbox"/>
56	06/03/18 18:44	General View	 Load JPG	<input checked="" type="checkbox"/>
57	06/03/18 18:44	General View	 Load JPG	<input checked="" type="checkbox"/>
58	06/03/18 18:44	General View	 Load JPG	<input checked="" type="checkbox"/>
59	06/03/18 18:44	General View	 Load JPG	<input checked="" type="checkbox"/>
60	12/06/18 09:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	12/06/18 09:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	12/06/18 09:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	12/06/18 09:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	12/06/18 09:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	12/06/18 09:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	12/06/18 09:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	12/06/18 09:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/03/18 17:56	EMAIL FROM LAWYER DD 05.03.2018	 Load PDF	
2	06/03/18 17:56	ACKNOWLEDGEMENT EMAIL TO AIG DD 05.03.2018	 Load PDF	
3	06/03/18 17:56	LAWYER FORM	 Load PDF	
4	08/03/18 11:53	TP GIA REPORT 1	 Load PDF	
5	08/03/18 11:53	TP GIA REPORT 2	 Load PDF	
6	08/03/18 11:53	TP ESTIMATE- MARKED	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/LCR18004330/UPA3Q2

Date: 06/06/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994774
Claimant Vehicle FBJ7374Z **Insured Vehicle No :** SLM2849U
No :
 Date of Loss: 24/02/2018 Nature of Claim: TP Claim No: 6604758620SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBJ7374Z**
 Make & Model: YAMAHA FINO, 114cc (A) Engine No: E3K3E406219
 Reg. Date: 23/09/2014 (Man. Year: 2013) Chassis No: MLESE701111406219
 Colour: Black/White Odometer: 16989 km
 Engine Capacity: 114 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 80-90-14 Rear Tyre Size: 80-90-14
 Front Left Side: Dunlop 8 mm Rear Left Side: Dunlop 8 mm
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,486.00	2,007.10	1,478.90	42.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,105.00	685.00	420.00	38.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,591.00	2,692.10	1,898.90	41.36
Approved Total (Overridden) (S\$)		2,150.00		
Nett Amount (S\$)	4,591.00	2,150.00	2,441.00	53.17
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 05/03/2018
 Date Inspected: 06/03/2018 Inspected At: Erofia Motor Trading Pte Ltd - (kaki Bukit) (HQ)
 1 Kaki Bukit Avenue 6, #02-62 AutoBay @ Kaki Bukit
 Singapore 417883
 Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Cut	85.00 FL	*85.00 FL
2	2		*FORK INNER TUBES	Repair	160.00 FL	*- FL
3	2		*FORK OUTER TUBES	Repair	180.00 FL	*- FL
4	1		*FORK UNDER BRACKET	Not Necessary	145.00 FL	*- FL
5	1		*FRONT BRAKE DISC	Not Necessary	115.00 FL	*- FL
6	1		*FRONT RIM SHAFT	Not Necessary	38.00 FL	*- FL
7	1		*FRONT RIM	Not Necessary	280.00 FL	*- FL
8	1		*SET FRONT RIM SPOOKY	Not Necessary	60.00 FL	*- FL
9	1		*FRONT SIGNAL -L/H	Cut	70.00 FL	*70.00 FL
10	1		*HANDLE BAR	Bent	138.00 FL	*138.00 FL
11	1		*HANDLE BAR END	Scratched	28.00 FL	*28.00 FL
12	1		*SET BRAKE LEVER	Scratched	68.00 FL	*68.00 FL
13	1		*SET SIDE MIRROR	Cut	120.00 FL	*120.00 FL
14	1		*FRONT COWLING	Cut	198.00 FL	*198.00 FL
15	1		*FRONT COWLING INNER PANEL	Cracked	108.00 FL	*108.00 FL
16	1		*FRONT LOWER COWLING	Cut	80.00 FL	*80.00 FL
17	1		*LOWER COWLING	Cut	95.00 FL	*95.00 FL
18	1		*FRONT FOOTSTEP PANEL	Cut	116.00 FL	*116.00 FL
19	1		*SET PASSENGER FOOTREST	Cut	98.00 FL	*98.00 FL
20	1		*MAIN STAND	Repair	85.00 FL	*- FL
21	1		*SIDE STAND	Cut	70.00 FL	*70.00 FL
22	1		*KICK STARTER	Cut	105.00 FL	*105.00 FL
23	1		*CRANKCASE COVER	Repair	250.00 FL	*- FL
24	1		*REAR SIGNAL -L/H	Serviceable	65.00 FL	*- FL
25	1		*REAR FENDER	Repair	105.00 FL	*- FL
26	1		*REAR TAILBOARD -L/H	Not Necessary	138.00 FL	*- FL
27	2		*FORK OILS	Necessary	30.00 FS	*30.00 FS
28	2		*FORK OIL SEALS	Necessary	56.00 FS	*56.00 FS
29	1		*SET STEERING CONE	Necessary	75.00 FS	*75.00 FS
30	1		*REAR BOX	Cut	180.00 FS	*180.00 FS
31	1		*REAR BOX BRACKET	Bent	100.00 FS	*100.00 FS
32	1		*ERP IU	Cut	170.00 FS	*165.00 FS
33	1		*HELMET	Deep Cut	95.00 FS	*80.00 FS
34	1		*FINO EMBLEM	Necessary	80.00 FS	*80.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,786.00	2,145.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	300.00	137.90
Total Parts (\$\$)	3,486.00	2,007.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PROVIDE TOWING SERVICE	New	45.00	35.00
2	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
3	TO PROVIDE LABOUR	New	480.00	300.00
4	TO RESPRAY PAINTING	New	500.00	350.00
Gross Labour Cost (\$\$)			1,105.00	685.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >