

U.S. CASE OWNER:

NATALIE

CC3 / III1800

4371, G W39

LKK:

IDAC:

Surveyor:

XGQ

DOI:

ASSIGNMENT

26/08/18

Date / Time:

6/7/18

Registered in Merimen:

6/7/18

Pre-assign / CCU / FTE:

SHC 1544E



Insured Vehicle No.:

LTP

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

2/7/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: CHAN SIEW

KHONH

OI GIA REPORT: YES / NO: TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L) YES / NO

Insured Liability: %

Final ? Yes / No

SJK 981AB



INSRS:

WSP:

Tel:

Liability:

RMKS:

performance



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time	STAGE	DATE / PIC
8/7/18	Non-Reporting ltr (1st)	
	Non-Reporting ltr (2nd)	
	Non-Reporting ltr (Final)	
	Notification ltr (if non-pickup)	
	Call OI:	
	After call ltr to OI:	
9/8/18	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	
	After call ltr to OI:	
	Authorisation To Act:	
	Release Voucher:	
	Final Repair Bill:	
	Car Rental Invoice:	
	Towing Invoice:	
	LTA / GIA:	
	Medical Bill:	
	PIR:	
	Mandate/Reject Instruction:	
	LOD:	
	Payment Breakdown Form:	
	Post-Repair Photos:	
	Others:	
PRELIMINARY ADVICE	Date/Time:	Send By:
FINALIZATION	Date/Time:	Confirm with:
Repair Cost: P/P	SS 4,474.40 / 3 days	Reduction: 25 %
FINAL SETTLEMENT	Date/Time: 08/08/18	Confirm with: CAROLINE
Final Liability:	SS 100 (Agreed / Assessed)	BOLA S/N No.: NIL
Repair Cost: (W/GST)	SS 4,787.61	
Loss of Rental (LOR):	SS — (days)	
Loss of Use (LOU):	SS 150.00 x 3 days	
Loss of Income (LOI):	SS — (5 x days)	
LOR only <input type="checkbox"/> LOU only <input checked="" type="checkbox"/>	LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/> (Tick only one)	
GIA/LTA Search	SS —	
Medical	SS —	
Disbursement:	SS — (e.g. Tow/ Independent)	
Legal Cost	SS —	
Total:	SS 4,937.61	Global Sum SS: —
FINAL PAYMENT	Date/Time:	Confirm with:
Payee 1:	SS 4,937.61	Name 1: PERFORMANCE MOTORS LIMITED
Payee 2: (Strike if N.A.)	SS —	Name 2: —
Payee 3: (Strike if N.A.)	SS —	Name 3: —



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL		Ref : CC3/III18004331/hb3		
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 06-03-2018		
		Code : III2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 1544E	Veh. Inspected	SJX 9819B	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	06/03/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	02/03/2018	Inspection Date		
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401539W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64767770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190538 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



Sending Shm & repair
26/3/2018 morning

GST REG. NO : M2 - 0020081 - X

ESTIMATE

06 MAR 2018

Estimate No. : b1 46130
Date Estimated : 06/03/2018
Prepared By : Chua Kee Sin

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -

Lee Kong Meng
Blk 627 Senja Road
#27-174
Singapore
Singapore 670627

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJX9819B	VN76310	28/07/2010	X1 sDrive18i	0

DESCRIPTION

Replace rear bumper and remove attachment etc include knock on accident dent

VALUE

1275 1,700.00

Spray painting rear bumper

934 1,038.00

To check steering geometry and conduct wheel alignment according to BMW specification (1X)

? 531.00 X

To replace tyre and wheel rim including balancing. (1x) right rear

80 94.00 -

Sundries. *NN*

4080 150.00 -

Total Labour 1: 3,513.00

DESCRIPTION

ALLOY RIM 71/2Jx17 VSPOKE 318 *- Act*
HUB CAP WITH CHROME EDGE (BMW) *X*
RR BUMPER CTR GUIDE *X*
RR BUMPER LOWER COVERING *X*
RR BUMPER RH GUIDE *?*
RR BUMPER (PRIMED) *- Act*
RR BUMPER BOTTOM (XLINE/PDC) *- SDR*
RR RH WHEEL ARCH COVER *- SDR*
EXPANDING RIVET *- 4ml*
EXPANDING RIVET *- 4ml*
RR BUMPER RH REFLECTOR *X NN*

QTY PRIC VALUE

1	778.55	778.55
1	24.30	24.30
1	61.35	61.35
1	31.45	31.45
1	56.95	56.95
1	831.40	831.40
1	322.35	322.35
1	146.10	146.10
10	1.35	13.50
2	1.35	2.70
1	35.20	35.20

Total Parts : 2,303.85

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401555W GST Reg. No M2-0020081-X



203, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kempong Arang Road
East Coast Centre
Singapore 478180
Tel. 63190888 (AfterSales)
Fax. 63445773

115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190828 (AfterSales)
63190833/535 (Motorrad)
Fax. 64796401 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 46130
Date Estimated : 06/03/2018
Prepared By : Chua Kee Sin

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJX9819B	VN76310	28/07/2010	X1 sDrive18i	0

LPR Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

before paint photos.

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date&Time 26/3/18 Excess S\$ _____

Surveyor's Name Gua Qi-p Sign _____

Surveyor's Tel 82880282 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No _____

Surveyor's E-mail _____

No. of Working Days Recommend 3

Labour 1	:	3,513.00
Parts	:	2,303.85
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	407.18
Grand Total	:	6,224.03

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

5,816.00

Performance Motors Limited

A member of the Sino Dairy Group
Co. Reg. No. 197401559W. GST Reg. No. M2 002081-X



FINAL REPORT

Estimate No. : b1 46130
Date Estimated : 06/03/2018
Prepared By : Chua Kee Sin

Page No. :

REPAIR FOR -
Lee Kong Meng
Blk 627 Senja Road
#27-174
Singapore
Singapore 670627

- ACCOUNT - 219
India Int'l Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEASE
SJX9819B	VN76310	28/07/2010	X1 sDrive18i	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace rear bumper and attachments, rear RH wheel arch cover include knocking out dents caused by the accident	1275.00		1,275.00	
To spray paint rear bumper	934.00		934.00	
To replace rear RH wheel rim include balancing (1x)	80.00		80.00	
Sundries	80.00		80.00	

DESCRIPTION	INIT PRICE	QTY	DISC. %	NETT
ALLOY RIM 71/2Jx17 VSPOKE 318	778.55	1.00		778.55
RR BUMPER (PRIMED)	831.40	1.00		831.40
RR BUMPER BOTTOM (XLINE/PDC)	322.35	1.00		322.35
RR RH WHEEL ARCH COVER	146.10	1.00		146.10
EXPANDING RIVET	1.35	20.00		27.00

SUPPLEMENTARY ITEMS

Total Labour :	2,369.00
Total Parts :	2,105.40
Total Labour & Parts :	4,474.40
Deduction for Excess :	0.00
Total Repair Costs less Excess:	4,474.40
GST @7%:	313.21
Grand Total :	4,787.61

Vic (LKKAUTO)

From: Asher Sng (LKKAUTO)
Sent: Monday, 21 May, 2018 3:46 PM
To: PBSP, Vic (LKKAUTO)
Cc: Guo Qiang (LKKAUTO)
Subject: FW: FINAL REPORT / SJX9819B
Attachments: Final Report SJX9819B.pdf

Without Prejudice

Hi Caronline,

We refer to the email below.

The case handler for this case is Vic.

Hi Vic,

FYNA.

Thank You.

Best Regards,
Asher Sng | Case Handler
LKK Auto Consultants Pte Ltd
phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1,
#02-25 | S(408933)

-----Original Message-----

From: PBSP [mailto:pml-pbsp@simedarby.com.sg]
Sent: Monday, 21 May 2018 3:32 PM
To: Guo Qiang (LKKAUTO) <GuoQiang@lkkauto.com>; Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>
Subject: FINAL REPORT / SJX9819B

Dear Sirs

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 2,369.00
Total Parts : 2,105.40
Total Labour & Parts : 4,474.40

Repair days: 3

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4141F
Vehicle Details	
Vehicle No.:	SJX9819B
Vehicle to be Exported:	No
Intended De-registration Date:	29 Mar 2018
Vehicle Make:	B.M.W.
Vehicle Model:	X1 SDRIVE18i AT D/AB 2WD 5DR GAS/D SR
Primary Colour:	Black
Manufacturing Year:	2010
Engine No.:	A824I751N46B20BD
Chassis No.:	WBAVL32050VN76310
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$28,525.00
Original Registration Date:	28 Jul 2010
First Registration Date:	28 Jul 2010
Transfer Count:	1
Actual ARF Paid:	\$28,525.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Jul 2020
PARF Rebate Amount:	\$17,115.00
Intended COE Rebate Details	
COE Expiry Date:	27 Jul 2020
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$39,911.00
COE Rebate Amount:	\$9,280.00
Total Rebate Amount:	\$26,395.00

The information contained herein is correct as at 29 Mar 2018

OK

Print Received Message

This mail is associated with :

***SJX9819B (MCT18030086)
[SHC1544E]**

TP

LEE KONG MENG

Mar 2 2018 2:00PM

[COMFORT TRANSPORTATION PTE LTD]

Performance Motors Limited

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 07/08/2018 11:22 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$4937.61) - SJX9819B - Claim Handler: NATALIE LEE

Approved:4937.61:.



nh h

India Int'l Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711
Attention: Motor Claims

"Without Prejudice"

Your Ref :

Our Ref :

Date :

Subject :

10 July 2018

ACCIDENT INVOLVING VEHICLES SJX9819B & SHC1544E ON 02.03.2018

Dear Sirs

We refer to the above matter.

The accident was caused solely by the negligence on the part of your insured. As a result of the said accident, our client has suffered losses which are set out hereunder as follows:-

Cost of repair	:	S\$	4787.61
Loss of use	:	S\$	150.00 (S\$ 50.00 x 3 days)
Total	:	S\$	4937.61

A copy of each of the following supporting documents is enclosed:

1. Copy of Accident Report
2. Copy of Final Repair bill
3. Copy of Certificate of Insurance
4. Copy of Identification Card & Driving License
5. Copy of Letter of Authorisation

Please note that you or your insured should send us an acknowledgement of receipt of this letter within fourteen (14) days from the date of this letter, failing which our client will have no alternative but to commence legal proceedings against you without any further notice to you or your insured.

Should you have a counterclaim against our client arising out of the accident, you are also required to send a letter giving full particulars of the counterclaim together with all relevant supporting documents within eight (8) weeks of your receipt of this letter.

For any correspondence, please contact Ms Caroline Tan at 6319-0174 / Fax. 6479-4601 or email to pml-pbsp@sime-darby.com.sg.

Yours sincerely

Teng Wai Khan
Customer Service Manager, Body & Paint

Performance Motors
Limited
1800-Call-BMW
(1800-2255-269)
www.pml.com.sg

303 Alexandra Road
Sime Darby
Performance Centre
Singapore 159941
Tel Sales 6319 0100
Tel AfterSales
6319 0111
Fax 6474 7770

315 Alexandra Road
#01-01
Sime Darby
Business Centre
Singapore 159944
Tel Sales 6319 0511
Tel AfterSales
6319 0527
Fax 6479 6624

280
Kampong Arang Rd
East Coast Centre
Singapore 438180
Tel AfterSales
6319 0888
Fax 6344 1332

Registered office
305 Alexandra Road
#02-01
Vantage
Automotive Centre
Singapore 159942

Co. Reg. No:
197401599W

Performance Motors Limited

A member of the Sime Darby Group



LETTER OF AUTHORISATION

ACCIDENT INVOLVING SJX9819B & SHG1544E ON 02/3/18.


I, LEE KONG MENG owner of Vehicle Registration No. SJX 9819B
hereby authorise **Performance Motors Limited** to submit, correspond, negotiate and
settle my claim for cost of repair and/or uninsured losses arising from the above accident.

I further authorise **Performance Motors Limited** to execute, sign, seal and deliver all
documents whatsoever in relation to this matter and to accept and receive any payment
due to me in respect of my claim above.

I hereby declare that all acts and documents done by virtue of this Letter of Authorisation
on my behalf shall be good valid and effectual to all intents and purposes whatsoever as if
the same had been done or executed by me in person.


I further confirm that the acceptance by **Performance Motors Limited** of the settlement
amount in respect of such claim shall constitute the full discharge of my claim in respect of
such loss and damage.

Signed by:


Name: _____ (Date) _____
NRIC No.: _____

In the presence of:

CHUA KEE SIN
Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941


6/5/2018
16 06 hrs

Name: _____ (Date) _____
NRIC No.: _____

EXPRESS SETTLEMENT

DISCHARGE VOUCHER

III-Direct Settlement (PODS)

India Ref: MC18030086
 Claimant Ref: 65X9819B

We/I, PERFORMANCE MOTORS LIMITED ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of Surveyor) with respect to the amount claimed for S\$ 4,787.61 (repair cost), S\$ 180.00 (loss of use/rental), S\$ — (search fee), vehicle no. 65X9819B that was damaged pursuant to the accident which occurred on 02/08/18 (date) at 466 HOUGANG AVE 8 CP (location) involving vehicle no. SAC1544E (insured vehicle). This is pursuant to the inspection conducted on 26/08/18 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner LEE KONG HONG & PARTN LEE KONG HONG ("the third party claimant") of vehicle no. 65X9819B to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to 65X9819B (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 4,967.61 to PERFORMANCE MOTORS LIMITED

Dated this 08 day of 08 2018

CLAIMANT:

Signature:

Name:

NRIC:

Address:

Nationality:

Occupation:

CHUA KEE SIN
 Performance Motors Limited
 303 Alexandra Road
 Sims Dairy Performance Centre
 Singapore 159941
 Signed by "the workshop" (with chop)

WITNESS:

Signature:

Name:

NRIC:

Address:

Nationality:

Occupation:

XGQ
 Signed by appointed Surveyor

LKK AUTO CONSULTANTS PTE LTD

199607196R

51 UBI AVE 1, PAYA UBI INDUSTRIAL PARK

#02-25 SINGAPORE 408933

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159943
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

380, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



SERVICE TAX INVOICE

Repair Order No. : B1 1253912

Date IN : 26/03/2018

Cust. Svc. Advisor: Chua Kee Sin

Page No. : 1 of 2

Invoice Number : 1976531 / WSB

Invoice Date : 18/06/2018

Payment Terms : 30 Days From Invoice

Invoice By : Sharon Heng

- CUSTOMER INFORMATION -

Mr Lee Kong Meng
Blk 627 Senja Road
#27-174
Singapore
Singapore 670627

- INVOICE TO - 219

India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

REGN. NO.
SJX9819B

CHASSIS NO.
VN76310

REGN. DATE
28/07/2010

MODEL
X1 SDRIVE18I

MILEAGE
1253912

- - - - LABOUR 1 - - - -

To replace rear bumper and attachments including to
remove and install body parts in order to carry out painting
job.

To respray rear bumper.

To replace rear right wheel rim including balancing.

Sundries.

INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT.

DATE OF ACCIDENT : 2.3.2018. 3RD PARTY CAR : SHC1544E.

YOUR REF NO : NIL.

VEHICLE WAS SURVEYED BY MR GUO QIANG FROM LKK AUTO
CONSULTANTS PTE LTD ON 26.3.2018. AUTHORISED REPAIR
BY MR VIC ALPEH FROM LKK ON 19.3.2018 VIA E-MAIL.

PROPOSE LOSS OF USE = \$50X3. THE AMOUNT IS SUBJECTED
TO INSURANCE COMPANY CONFIRMATION.

NETT

1,275.00

934.00

80.00

80.00

0.00

0.00

Total Labour 1: 2,369.00

- - - - PARTS - - - -

RR BUMPER (PRIMED)

RR BUMPER BOTTOM (XLINE/PDC)

EXPANDING RIVET

RR RH WHEEL ARCH COVER

ALLOY RIM 71/2Jx17 VSPOKE 318

Qty	Retail Price
1	831.40
1	322.35
20	1.35
1	146.10
1	778.55

NETT

831.40

322.35

27.00

146.10

778.55

Total Parts : 2,105.40

- - - - LABOUR 2 - - - -

NETT

0.00

Total Labour 2: 0.00

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020002-X



301, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190668 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

SERVICE TAX INVOICE

Repair Order No. : **B1 1253912**

Date IN : **26/03/2018**

Cust. Svc. Advisor: **Chua Kee Sin**

Page No. : **2 of 2**

Invoice Number : **1976531 / WSB**

Invoice Date : **18/06/2018**

Payment Terms : **30 Days From Invoice**

Invoice By : **Sharon Heng**

Labour Charges : **2,289.00**
Parts Charges : **2,105.40**
Lubricant/Misc : **80.00**

Total Labour & Parts Charges	: S\$	4,474.40
Less Insurance Excess	: S\$	0.00
Invoice Total Amount Exclude GST	: S\$	4,474.40
GST @ 7%	: S\$	313.21
Invoice Total Amount Include GST	: S\$	4,787.61

Computer generated invoice. No signature is required.

Amount Payable Include GST : **S\$ 4,787.61**

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.



...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Mar 2018 Edit Reg		26 Mar 2018 00:00 Edit Adj Rpt	S\$4,474.40 Edit Estimates	S\$4,474.40 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R								
Main Claimant:	LEE KONG MENG, ID: 57124141F								
Vehicle Reg. No.:	SJX9819B	Date of Loss:	02/03/2018 14:00 - :59 [91 Months and 2 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT18030086	Policy/Cover Note No.:	MCOM0016						
Vehicle Reg. No. (Insured):	SHC1544E	Policy No. (Claimant):	GA098263						
		Excess:							
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by NATALIE LEE - 63476100 ext 243]								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 15/03/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> III_SG (07/06/2018): Alert - Adj Mandate Approved (S\$4937.61) - SJX9819B - Claim Handler: NATALIE LEE III_SG (15/03/2018): Alert - Adj Mandate Approved (S\$0.00) - SJX9819B - Claim Handler: NATALIE LEE III_SG (15/03/2018): Alert - Adj Mandate Maintained - SJX9819B - Claim Handler: NATALIE LEE 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJX9819B (MCT18030086)
[SHC1544E]
TP
LEE KONG MENG
Mar 2 2018 2:00PM
[COMFORT TRANSPORTATION PTE LTD]
Performance Motors Limited

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	15/03/18 10:45	Video - Accident	Load MP4	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	22/05/18 13:19	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
2	22/05/18 13:19	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
3	22/05/18 13:19	General View	Load JPG	<input checked="" type="checkbox"/>
4	22/05/18 13:19	General View	Load JPG	<input checked="" type="checkbox"/>
5	22/05/18 13:19	General View	Load JPG	<input checked="" type="checkbox"/>
6	22/05/18 13:19	General View	Load JPG	<input checked="" type="checkbox"/>
7	22/05/18 13:19	General View	Load JPG	<input checked="" type="checkbox"/>
8	22/05/18 13:19	General View	Load JPG	<input checked="" type="checkbox"/>
9	22/05/18 13:19	General View	Load JPG	<input checked="" type="checkbox"/>
10	22/05/18 13:19	General View	Load JPG	<input checked="" type="checkbox"/>
11	22/05/18 13:19	General View	Load JPG	<input checked="" type="checkbox"/>
12	22/05/18 13:19	General View	Load JPG	<input checked="" type="checkbox"/>
13	22/05/18 13:19	General View	Load JPG	<input checked="" type="checkbox"/>
14	22/05/18 13:19	General View	Load JPG	<input checked="" type="checkbox"/>
15	22/05/18 13:19	General View	Load JPG	<input checked="" type="checkbox"/>
16	22/05/18 13:19	General View	Load JPG	<input checked="" type="checkbox"/>
17	22/05/18 13:19	General View	Load JPG	<input checked="" type="checkbox"/>
18	22/05/18 13:19	General View	Load JPG	<input checked="" type="checkbox"/>
19	22/05/18 13:19	General View	Load JPG	<input checked="" type="checkbox"/>
20	22/05/18 13:19	General View	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/03/18 18:09	TP EST & GIA REPORT	Load PDF	
2	29/03/18 15:42	TP ESTIMATE- MARKED	Load PDF	
3	27/07/18 12:09	WORKSHOP INVOICE	Load PDF	
4	27/07/18 12:09	LOD	Load PDF	
5	14/08/18 15:59	DISCHARGE VOUCHER	Load PDF	
6	14/08/18 15:59	AUTHORISATION TO ACT FORM	Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	07/03/18 08:48	Singapore Accident Statement	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
----------------------------	-----------------------	----------------------	-----------------------

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No.199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/III18004331/GHB3Q2

Date: 14/08/2018

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0016
Claimant Vehicle No :	SJX9819B	Insured Vehicle No :	SHC1544E
Date of Loss:	02/03/2018	Nature of Claim:	TP
		Claim No:	MCT18030086

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJX9819B		
Make & Model:	BMW X1 SDRIVE18I, 2.0 D/AB 2WD 5DR GAS/D SR (A)	Engine No:	A824I751N46B20BD
Reg. Date:	28/07/2010 (Man. Year: 2010)	Chassis No:	WBAVL32050VN76310
Colour:	Black	Odometer:	83606 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,467.35	2,185.40	281.95	11.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,363.00	2,289.00	1,074.00	31.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,830.35	4,474.40	1,355.95	23.26
+ GST 7.00/7.00% (S\$)	408.12	313.21	94.91	23.26
Nett Amount (S\$)	6,238.47	4,787.61	1,450.86	23.26
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
Nett Liability (S\$)		4,937.61		

INSPECTION

Date of Assignment:	26/03/2018	
Date Inspected:	26/03/2018 Inspected At:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941
Estimated Period of Repair:	3.0 days	

Adjuster: XING GUO QIANG**Manager:** VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Jul 2018)
Parts:	M1-SUV	BMW X1 SDRIVE18I 2.0 D/AB 2WD 5DR GAS/D SR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJX9819B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*80.00 FS
2	1		*ALLOY RIM 71/2JX17 VSPOKE 318	Cut	778.55 FS	*778.55 FS
3	1		*HUB CAP WITH CHROME EDGE (BMW)	Not Necessary	24.30 FS	*- FS
4	1		*RR BUMPER CTR GUIDE	Not Necessary	61.35 FS	*- FS
5	1		*RR BUMPER LOWER COVERING	Not Necessary	31.45 FS	*- FS
6	1		*RR BUMPER RH GUIDE	Not Necessary	56.95 FS	*- FS
7	1		*RR BUMPER (PRIMED)	Cut	831.40 FS	*831.40 FS
8	1		*RR BUMPER BOTTOM (XLINE/PDC)	Scratched	322.35 FS	*322.35 FS
9	1		*RR RH WHEEL ARCH COVER	Scratched	146.10 FS	*146.10 FS
10	10		*EXPANDING RIVET)	Necessary	27.00 FS	*27.00 FS
11	1		*EXPANDING RIVET)	Necessary	2.70 FS	*- FS
12	1		*RR BUMPER RH REFLECTOR	Not Necessary	35.20 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	2,467.35	2,185.40
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REPLACE REAR BUMPER AND REMOVE ATTACHMENT ETC INCLUDE KNOCK ON ACCIDENT DENT	New	1,700.00	1,275.00
2	SPRAY PAINTING REAR BUMPER	New	1,038.00	934.00
3	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT ACCORDING TO BMW SPECIFICATION	New	531.00	0.00
4	TO REPLACE TYRE AND WHEEL RIM INCLUDING BALANCING RIGHT REAR	New	94.00	80.00
Gross Labour Cost (S\$)			3,363.00	2,289.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >