

15/02/2018

INS CASE OWNER:

Cynthia

CC 4/AXA18004247 / P1 b3 jf3

LKK:

IDAC:

Surveyor:

KAWI

DOI:

ASSIGNMENT

X/1/18

Date / Time:

06/03/18

Registered in Merimen:

0605/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHD 9722A

Claim No.:

C0471904

Name of Insured:

TRANS - CAR SERVICES PTE LTD

Policy No.:

PL680520

Insured Tel No.:

HP:

Make / Model:

RENAULT LATITUDE - 2.0 DCI AUTO DIA8

Excess Sec II :\$5

5,002.00

D.O.A.:

26/02/18

Place of Accident:

JBR (A) BUKET PANTANG RD TOWARDS BUKIT

Is driver the owner?

(YES / NO)

Nature of Accident:

PANTANG RING RD

If NO, Driver Name / Age: LGE CHOR HOCK

OI GIA REPORT YES / NO : TP GIA REPORT YES / NO

Driver Tel No.:

9147 4498

(V/L: YES / NO)

Insured Liability:

Final ? Yes / No

GBC 6856T



INSRS:

WSP: Ban Choon

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

07/03/18 (joy)

26-7-18

FUR MANDATE

RECEIVED 16 OCT 2018

STAGE

DATE / PIC

Non-Reporting 1st (1st):

Non-Reporting 1st (2nd):

Non-Reporting 1st (Final):

Notification 1st (if non-pickup):

Call OI:

After call 1st to OI:

8-5-18 JOY

Documentation Check List: Handler Typist

Notification 1st (if non-pickup):

After call 1st to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$5

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

27

Repair Cost:

G51

\$5

2,568.00

Loss of Rental (LOR):

\$5

1 days

Loss of Use (LOU):

\$5

400 (\$ 80 x 5 days)

Loss of Income (LOI):

\$5

- (\$ x days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LO ☐

(Tick only one)

GIA/LTA Search:

\$5

7.45

Medical:

\$5

Disbursement:

\$5

(e.g. Tow/ Independent)

Legal Cost:

\$5

Total:

\$5

2,975.45

Global Sum \$5:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$5

2,975.45

Name 1:

BAN CHON MOTOR WORKS

Payee 2: (Strike if N.A.)

\$5

X

Name 2:

X

Payee 3: (Strike if N.A.)

\$5

Name 3:

X

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

OI HIT TP FROM  
REAR 16/10/18





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/AXA18004347/R1js3

8 SHENTON WAY #24-01  
AXA TOWERS SINGAPORE 068811

Date : 06-03-2018



Code : AXA2

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 9722A	Veh. Inspected	GBC 6856T
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	06/03/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages


--

## 5. General Information

Accident Date	26/02/2018	Inspection Date	07/03/2018
Survey held at	BAN CHOON MOTOR WORKS 3 PIONEER ROAD NORTH #01-14/15 SINGAPORE 628457		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---



# 萬春摩托 BAN CHOON MOTOR WORKS

Blk 3, Pioneer Road North #01-14/15 Singapore 628457

Tel: 6264 1191 Fax: 6261 1324

E-mail: benchoon@singnet.com.sg

Business Reg / GST Reg. No. 35191500A

377A T35 / 2013

EST/QUOTE NO. SQ000118

AXA Insurance Singapore Pte Ltd

8 Shenton Way

B1-01 AXA Tower

Singapore 068811

ATTENTION:

CONTACT: -

FAX NO:

DATE : 05/03/2018  
ACCIDENT DATE : 26/02/2018  
VEHICLE NO : GBC 6856 T  
CHASSIS/ENG.NO : 67766633  
VEHICLE MODEL : TOYOTA DYNA  
CLAIM NO : TP  
POLICY NO : -  
REMARK : TP - SHD 9722 A

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
------	-----	------	-------------	-------	--------	-------------	-----------

<b>** LIST PRICE **</b>							
1	1		Taillamps	240.20	25	180.15 RH-JC	360.30
SUB-TOTAL:							360.30

<b>** SPECIAL NETT PRICE **</b>							
1	2		Tail boards	1,200.00		price? 10-40	2,400.00
2	1		70 km/h sticker	20.00		20.00	20.00
3	1		Rear number plate	35.00		35.00	35.00
SUB-TOTAL							2,455.00

## \*\* WORK LABOUR \*\*

To knocking and straightening of all necessary damaged parts.

To changing of the above parts.

To putty and spray painting on accident damaged parts.

	SUB-TOTAL	2,455.00
Rate		
hp 900 10068		
5 days		
h/s		
	0.00	0.00
	480.00	400 <del>480.00</del>
	500.00	400 <del>500.00</del>
	SUB-TOTAL	980.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:  
Date:


PAGE: 1 of 1

07/03/18 @ 1455  
Resurvey after repair  
4/5-2,400  
5 days  
SUB-TOTAL: S\$ 3,795.30  
3035.15  
2428.12

ON BEHALF OF BAN CHOON MOTOR WORKSHOP

E & O E

ALL PRICES SUBJECT TO 7% GST



萬 春 摩 哆

## BAN CHOON MOTOR WORKS

Blk 3, Pioneer Road North #01-14/15 Singapore 628457

Tel: 6264 1191 Fax: 6261 1324

E-mail: banchoon@singnet.com.sg

Business Reg./GST Reg. No. 35191500A

EST/QUOTE NO. SQ000118

AXA Insurance Singapore Pte Ltd  
8 Shenton Way  
B1-01 AXA Tower  
Singapore 068811  
ATTENTION:  
CONTACT: -

FAX NO:

DATE : 05/03/2018  
ACCIDENT DATE : 26/02/2018  
VEHICLE NO : GBC 6856 T  
CHASSIS/ENG.NO : 67766633  
VEHICLE MODEL : TOYOTA DYNA  
CLAIM NO : TP  
POLICY NO : -  
REMARK : TP - SHD 9722 A

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
------	-----	------	-------------	-------	--------	-------------	-----------

<b>** LIST PRICE **</b>							
1	1		Taillamps	240.20	25	180.15	360.30

SUB-TOTAL: 360.30

<b>** SPECIAL NETT PRICE **</b>							
1	2		Tail boards	1,200.00		1,200.00	2,400.00
2	1		70 km/h sticker	20.00		20.00	20.00
3	1		Rear number plate	35.00		35.00	35.00

SUB-TOTAL: 2,455.00

**\*\* WORK LABOUR \*\***

To knocking and straightening of all necessary damaged parts.

To changing of the above parts.

To putty and spray painting on accident damaged parts.

0.00 0.00

480.00 480.00

500.00 500.00

SUB-TOTAL: 980.00

**LIK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PAGE: 1 of 1

SUB-TOTAL: S\$ 3,795.30

PERLIN

ON BEHALF OF BAN CHOON MOTOR WORKSHOP

E &amp; O E

ALL PRICES SUBJECT TO 7% GST



# BAN CHOON MOTOR WORKS

Blk 3, Pioneer Road North #01-14/15 Singapore 628457

Tel: 6264 1191 Fax: 6261 1324

E-mail: banchoon@singnet.com.sg

Business Reg./GST Reg. No. 351915/00A

EST/QUOTE NO. SQ000118

AXA Insurance Singapore Pte Ltd

8 Shenton Way

B1-01 AXA Tower

Singapore 068811

ATTENTION :

CONTACT : -

FAX NO:

DATE : 05/03/2018  
ACCIDENT DATE : 26/02/2018  
VEHICLE NO : GBC 6856 T  
CHASSIS/ENG.NO : 67766633  
VEHICLE MODEL : TOYOTA DYNA  
CLAIM NO : TP  
POLICY NO : -  
REMARK : TP - SHD 9722 A

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
------	-----	------	-------------	-------	--------	-------------	-----------

## \*\* LIST PRICE \*\*

1	1		Taillamps	240.20	25	180.15 RH-Jua	360.30 X LH
---	---	--	-----------	--------	----	---------------	-------------

SUB-TOTAL: 360.30

## \*\* SPECIAL NETT PRICE \*\*

1	2		Tail boards	1,200.00	price?	1,200.00	2,400.00
2	1		70 km/h sticker	20.00		20.00	20.00
3	1		Rear number plate	35.00		35.00	35.00

SUB-TOTAL 2,455.00

## \*\* WORK LABOUR \*\*

To knocking and straightening of all necessary damaged parts.

To changing of the above parts.

To putty and spray painting on accident damaged parts.

Repair  
Hq 900 10068  
5 days  
L/S  
07/03/18 @ 1455  
Resurvey after repair

	0.00	0.00
	480.00	400 480.00
	500.00	400 500.00

SUB-TOTAL 980.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

PERLIN  
Signature:  
Date:

PAGE: 1 of 1

SUB-TOTAL : S\$ 3,795.30

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AXA Insurance Pte Ltd  
8 Shenton Way #24-01  
AXA Tower  
Singapore 068811

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Cynthia Loh

Date: 09 Mar 2018

**Preliminary Advice**

Insured Vehicle No	: SHD9722A	Accident Date	: 26/02/2018
TP Vehicle No	: GBC6856T	Assignment Date	: 05/03/2018
Make	: TOYOTA DYNA 150	Est. Duration of Repair	: 5 days
Date of Inspection	: 07/03/2018		
Inspection At	: Ban Choon Motor Works (HQ) Blk 3 Pioneer Road North #01-15 Singapore 628457		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages .....rear O/S..... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,795.30
Revised Amount	:S\$	3,390.11
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,390.11

Lump Sum Repair	:S\$
-----------------	------

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : We have not authorized repairs.

## Print Received Message

This mail is associated with :

**\*GBC6856T (C0471904)**  
**[SHD9722A]**

TP

K G FOOD PTE LTD

Feb 26 2018 4:00AM

[TRANS-CAB SERVICES PTE LTD]

Ban Choon Motor Works

**From** AXA Insurance Pte Ltd (HQ) (AXA\_SG), sent on 02/10/2018 23:06 PM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$2975.45) - GBC6856T - Claim Handler: Richard Ang

Approved:2975.45.



AXA Insurance Spore Pte Ltd

Attn: Motor Claims Dept

Dear Sir/ Madam

ACCIDENT INVOLVING VEHICLE NO SHD 9722A & GBC 6856T  
ALONG Bukit Panjang Rd X Bukit Panjang ON 26/2/18  
Ring Road

We understand that you are the insurer of SHD 9722A vehicle.

I/We wish to inform you that my/our vehicle GBC 6856T have been completed repairs to my/our satisfaction by M/s Ben Chuan Motor Works. I/We therefore propose to claim from you as follows:

1.	Cost of Repairs	SS <u>2568.00</u>
2.	Loss of Use/Rental (SS <u>80</u> x <u>5</u> days)	SS <u>400.00</u>
3.	LTA Search Fee/GIA Reports	SS <u>7.45</u>
	<b>TOTAL</b>	SS <u>2975.45</u>

Please let us have your reply soonest possible.

Thank you.

Yours faithfully



**Joy Irene (LKKAuto)**

---

**From:** Joy Irene (LKKAuto)  
**Sent:** Tuesday, 8 May 2018 5:14 PM  
**To:** 'claims@transcab.com.sg'  
**Cc:** 'carrisalee@ava-ins.com'; 'icewong@ava-ins.com'; 'ireneng@ava-ins.com'; 'foonghon@ava-ins.com'; Admin A  
**Subject:** ACCIDENT INVOLVING SHD 9722A & GBC 6856T ALONG BUKIT PANJANG ROAD ON 26/02/2018

**Transcab Taxi**  
Singapore

Dear Sir/Madam,

OUR REF : CC4/AXA18004347/R1js3  
YOUR REF : P1680520 (SHD 9722A)

**ACCIDENT INVOLVING SHD 9722A & GBC 6856T ALONG BUKIT PANJANG ROAD ON 26/02/2018**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from **BAN CHOON MOTOR WORKS** acting on behalf of the owner of GBC 6856T against your motor insurance policy.

Based on the accident report and accident scenario, we are of the opinion that liability is not to our favour. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

We also wish to advise that there is an excess of **S\$5,000.00** attached with Third Party Claims. Please be informed that you shall be liable for the excess following any settlement of the third party claim.

AXA shall keep you informed of the third party claim settlement and thereafter kindly let AXA have the excess payment in your cheque payable to "AXA Insurance Pte Ltd". Please indicate your vehicle registration number and the date of accident on the back of the cheque.

Notwithstanding the excess being applied and/or received by AXA for the above subject matter, AXA expressly reserves all their rights under the policy to refund the excess payment in the event that there arises any known policy breach and or exclusion material to coverage.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 10 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by AXA.

Your full co-operation in the handling of the claim is required and kindly submit the following **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (if any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim.

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without our prior knowledge and consent. If you receive any correspondence or legal document such as a Writ of Summons in connection with this accident, please forward it to us immediately. You may email it to [cst@axa.com.sg](mailto:cst@axa.com.sg) / [joyirene@lkkauto.com](mailto:joyirene@lkkauto.com) or deliver it by hand to our Customer Care Centre.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorized driver may have committed.

In the event of receiving and handling of any third party injury claim(s), we shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact our Claims Service Team at 1800-880 4888 at our operating hours 9:00am to 5:30pm (press 1 for GI and option 3 for claims) or [cst@axa.com.sg](mailto:cst@axa.com.sg) / [joyirene@lkkauto.com](mailto:joyirene@lkkauto.com). Please quote our claim reference when you contact us that we can assist you more effectively.

Thank you.

Best Regards,  
Joy Irene | Case Handler  
LKK Auto Consultants Pte Ltd  
DID: 6841-2409 | email: [joyirene@lkkauto.com](mailto:joyirene@lkkauto.com) | Fax: 6741-4108  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

## AUTHORIZATION TO ACT

We  
I, KG Food Pte Ltd ("the third party  
claimant")  
of \_\_\_\_\_ (address),  
owner of GBC 6856T (vehicle no.) hereby authorize  
Ban Choon Motor Works  
("The workshop") to act for me with respect to my claim for  
repair costs and/or rental and/or loss of use ("claim") for my  
Vehicle No. GBC 6856T that was damaged pursuant to the  
accident which occurred on 26/2/18 (date) along Bukit  
Panjang Rd x Bukit Panjang Ring Road (location)  
involving Vehicle No/s SHD 9722A & GBC 6856T  
("The accident").

I further authorize the workshop to settle my above mentioned  
claim in a manner that they deem fit and the workshop is further  
authorized to receive payment further to settlement of my claim  
with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach  
on my behalf is on a without prejudice and without admission of  
liability basis insofar as the driver/owner/insurers of the  
other vehicle/s is concerned.

Dated this 13 day of Mar (month) 20 18 (year)



[Signature]

Signed by "the third party claimant"



[Signature]

Signed by "the workshop"



redefining / insurance

CLAIM REF : C0471904  
INSURED : TRANS-CAB SERVICES PTE LTD

DISCHARGE VOUCHER

We/I K G FOOD PTE LTD Co. Reg. No.: 200107765H hereby agree to accept the sum of dollars TWO THOUSAND NINE HUNDRED SEVENTY FIVE AND CENTS FORTY FIVE ONLY (S\$ 2,975.45) paid to us/me by AXA INSURANCE PTE LTD as full and final settlement of all claims of whatever kind including damages for personal injuries and damages to property that we/I may have against the said AXA INSURANCE PTE LTD or their Insured or the driver of motor vehicle no. [SHD 9722A] as a result of an accident along [BUKIT PANJANG RD/BUKIT PANJANG RING RD] on [26/02/2018] of which we/I were/was the driver/ owner/ hirer/ passenger/rider/pillion/ insurer of motor vehicle no. [GBC 6856T].

We/I hereby declare that the said insurer or owner and/or driver of insured vehicle shall not be liable for any further claim(s) whatsoever and whosoever present or future that we/I may have against the said Insurer, owner and/or driver of vehicle no. [SHD 9722A] in connection directly or indirectly with the said accident and give our/my full and final discharge.

We/I hereby declare that we/I are/am the person(s) entitled to receive the above settlement and hereby undertake to indemnify AXA INSURANCE PTE LTD against any claim made or to be made in respect of this settlement.

It is understood and agreed that payment herein is made without admission of liability whatsoever on the part of the said Insurer, owner and/or driver of vehicle no. [SHD 9722A]

Dated this 9th day of October 2018

Claimant's Signature : K G FOOD PTE LTD

NRIC. No./Co. Stamp : Co. Reg. No.: 200107765H

Occupation/ Business :

Address :

Telephone No. :

Witness's Name :

Witness's Signature :

Witness's NRIC No. :

AXA Insurance Pte Ltd (Company Reg. No. 190003512M)  
8 Shenton Way, #24-01 AXA Tower, Singapore 068811  
Customer Centre #B1-01  
Tel: +65 6880 4888 Fax: +65 6338 2522 Website: www.axa.com.sg



萬 春 摩 哆

# BAN CHOON MOTOR WORKS

Blk 3, Pioneer Road North #01-14/15 Singapore 628457

Tel: 6264 1191 Fax: 6261 1324

E-mail: banchoon@singnet.com.sg

Business Reg./GST Reg. No. 351915/00A

**GST Regn No: 351915/00A**

## TAX INVOICE

26/07/2018

AXA Insurance Singapore Pte Ltd  
8 Shenton Way B1-01 AXA Tower  
Singapore 068811

Attn: Motor Claims Dept.

Dear Sirs/Madam

FINAL BILL FOR REPAIRS OF VEHICLE NO: GBC 6856 T

MODEL: TOYOTA DYNA

DATE OF ACCIDENT: 26/02/2018

YOUR INSURED VEHICLE NO. SHD 9722 A

Supplying of spare parts, knocking and spray painting on  
accident damaged parts.

LUMP SUM

\$ 2,400.00

Add: GST @ 7%

168.00

\$ 2,568.00

Yours faithfully,

*Polindag*



Land Transport Authority  
10 Sin Ming Drive  
Singapore 575701  
GST Registration No. : M4-0006529-2

Print Date/Time : 05 Mar 2018 / 10:28:48

Receipt Date/Time : 05 Mar 2018 / 10:28:48

### Tax Invoice/Receipt

Receipt No. : ITNET-00000-180305-000500

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SHD9722A				
As at 26 Feb 2018/10:20:00				
Insurance Co: AXA INSURANCE PTE LTD				
1	Insurance Enquiry - SHD9722A			
	Enquiry Fee	7.00	0.49	7.49
	20180305102754910360			
	Sub-Total	7.00	0.49	7.49
	Total Before Rounding	7.00	0.49	7.49
	Rounding Difference			0.04
	Total Amount Payable			7.45
Paid By				
	20180305102805709	Direct Debit: eNETS Debit (Internet Banking)		7.45
	Total			7.45
	Cash Change			0.00
	Tendered Amount			7.45
	Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

## Vehicle Insurance Particulars Result

Vehicle No.	Incident Date/Time	Insurance Company Name
SHD9722A	26 Feb 2018 / 10:20:00	AXA INSURANCE PTE LTD

[Print](#)   [OK](#)   [Save as PDF](#)



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement




CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Mar 2018		05 Mar 2018 18:14 <a href="#">Edit Adj Rpt</a>	<b>S\$2,400.00</b> <a href="#">Edit Estimates</a>	<b>S\$2,400.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured: <b>TRANS-CAB SERVICES PTE LTD</b> , Co. Reg. No.: 200303878K, Email: CLAIMS@TRANSCAB.COM.SG									
Main Claimant: <b>K G FOOD PTE LTD</b> , Co. Reg. No.: 200107765H									
Vehicle Reg. No.:	<b>GBC6856T</b>	Date of Loss:	26/02/2018 04:00 - :59 [55 Months and 30 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / C0471904</b>	Policy/Cover Note No.:	P1680520 (Third Party Only)						
Vehicle Reg. No. (Insured):	<b>SHD9722A</b>	Policy No. (Claimant):	8-V0008119-MVA-E001						
		Excess:	S\$5,000.00						
Repairer:	<b>Ban Choon Motor Works (HQ)</b> Bldg 3 Pioneer Road North #01-15, 628457 Jurong West - Tel: 62641191								
Handling Insurer:	<b>AXA Insurance Pte Ltd (HQ)</b> - Tel: 6338 7288 ... [Handled by <b>Richard Ang</b> ]								
Claimant's Insurer:	<b>QBE Insurance (Singapore) Pte Ltd (HQ)</b> - Tel: 62246633								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD RASUL</b> ] ... [Final Rpt due 14/03/2018]								
Driver/Custodian (Insured):	LEE CHOR HOCK (J), NRIC: S1332287B, Tel: +6591474498								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>AXA_SG (02/10/2018): <b>Alert - Adj Mandate Approved (S\$2975.45) - GBC6856T - Claim Handler: Richard Ang</b></li> <li>AXA_SG (05/03/2018): <b>New TP Assignment - C0471904/P1680520</b></li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*GBC6856T (C0471904)  
[SHD9722A]  
TP  
K G FOOD PTE LTD  
Feb 26 2018 4:00AM  
[TRANS-CAB SERVICES PTE LTD]  
Ban Choon Motor Works

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page		<input checked="" type="checkbox"/>			
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print				
1	(Draft)	Third Party Express Settlement – Payment Breakdown												1	Edit					
Assessment Reports															1 per page		<input checked="" type="checkbox"/>			
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print				
1	09/03/18 15:29	Adjuster Immediate Advice												1	Load HTML					
Photos/Images															3 per page		<input checked="" type="checkbox"/>			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print				
1	26/07/18 11:50	General View												1	Load JPG		<input checked="" type="checkbox"/>			
2	26/07/18 11:50	General View												1	Load JPG		<input checked="" type="checkbox"/>			
3	26/07/18 11:50	General View												1	Load JPG		<input checked="" type="checkbox"/>			
4	26/07/18 11:50	General View												1	Load JPG		<input checked="" type="checkbox"/>			
5	26/07/18 11:50	General View												1	Load JPG		<input checked="" type="checkbox"/>			
6	26/07/18 11:50	General View												1	Load JPG		<input checked="" type="checkbox"/>			
7	26/07/18 11:50	General View												1	Load JPG		<input checked="" type="checkbox"/>			
8	26/07/18 11:50	General View												1	Load JPG		<input checked="" type="checkbox"/>			
9	26/07/18 11:50	General View												1	Load JPG		<input checked="" type="checkbox"/>			
10	26/07/18 11:50	General View												1	Load JPG		<input checked="" type="checkbox"/>			
11	26/07/18 11:50	General View												1	Load JPG		<input checked="" type="checkbox"/>			
12	26/07/18 11:50	General View												1	Load JPG		<input checked="" type="checkbox"/>			
13	26/07/18 11:50	General View												1	Load JPG		<input checked="" type="checkbox"/>			
14	26/07/18 11:50	General View												1	Load JPG		<input checked="" type="checkbox"/>			
15	26/07/18 11:50	General View												1	Load JPG		<input checked="" type="checkbox"/>			
16	26/07/18 11:50	General View												1	Load JPG		<input checked="" type="checkbox"/>			
17	26/07/18 11:50	General View												1	Load JPG		<input checked="" type="checkbox"/>			
18	26/07/18 11:50	General View												1	Load JPG		<input checked="" type="checkbox"/>			
19	26/07/18 11:50	General View												1	Load JPG		<input checked="" type="checkbox"/>			
20	26/07/18 11:50	General View												1	Load JPG		<input checked="" type="checkbox"/>			
21	26/07/18 11:50	General View												1	Load JPG		<input checked="" type="checkbox"/>			
22	26/07/18 11:50	General View												1	Load JPG		<input checked="" type="checkbox"/>			
23	26/07/18 11:50	General View												1	Load JPG		<input checked="" type="checkbox"/>			
24	26/07/18 11:50	General View												1	Load JPG		<input checked="" type="checkbox"/>			
25	26/07/18 11:50	General View												1	Load JPG		<input checked="" type="checkbox"/>			
26	26/07/18 11:50	General View												1	Load JPG		<input checked="" type="checkbox"/>			
27	26/07/18 11:50	General View												1	Load JPG		<input checked="" type="checkbox"/>			
28	26/07/18 11:50	General View												1	Load JPG		<input checked="" type="checkbox"/>			
29	26/07/18 11:50	General View												1	Load JPG		<input checked="" type="checkbox"/>			
30	26/07/18 11:50	General View												1	Load JPG		<input checked="" type="checkbox"/>			

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
31	26/07/18 11:50	General View	 Load JPG	<input checked="" type="checkbox"/>
32	26/07/18 11:50	General View	 Load JPG	<input checked="" type="checkbox"/>
33	26/07/18 11:50	General View	 Load JPG	<input checked="" type="checkbox"/>
34	26/07/18 11:50	General View	 Load JPG	<input checked="" type="checkbox"/>
35	26/07/18 11:50	General View	 Load JPG	<input checked="" type="checkbox"/>
36	26/07/18 11:50	General View	 Load JPG	<input checked="" type="checkbox"/>
37	26/07/18 11:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	26/07/18 11:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	26/07/18 11:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AXA Insurance Pte Ltd (HQ)	Thumbnail	Print
1	05/03/18 12:03	EMAIL_ABS	 Load PDF	
2	05/03/18 12:03	ESTIMATE_ABS	 Load PDF	
3	05/03/18 12:03	GBC6856T TP GIA_ABS	 Load PDF	
4	05/03/18 12:03	SHD9722A INSD GIA_ABS	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/03/18 09:01	TP ESTIMATE- MARKED	 Load PDF	
2	26/07/18 11:56	IA - FOR QUANTUM MANDATE	 Load PDF	
3	26/07/18 12:05	LOD	 Load PDF	
4	27/07/18 14:56	LTA SEARCH	 Load PDF	
5	27/07/18 14:56	LETTER TO OI	 Load PDF	
6	16/10/18 15:01	WORKSHOP INVOICE	 Load PDF	
7	16/10/18 15:01	AUTHORISATION TO ACT FORM	 Load PDF	
8	16/10/18 15:01	DISCHARGE VOUCHER	 Load PDF	
9	16/10/18 15:01	LOD	 Load PDF	

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	<a href="#">Reset</a>	<a href="#">Save</a>	<a href="#">Print</a>
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SHD9722A (Insd veh)	Model:	TOYOTA DYNA 150 3.0 D (M)
	GBC6856T (TP veh)		
Date of Accident:	26/02/2018		

Global Sum Settlement	: [ ] Yes	: [ X ] No	
Repair Estimate	: \$	4,060.97	
Final Repair Cost	: \$	2,568.00	
Loss of Use	: \$	400.00	5.00 days at \$80.00 per day
Rental (If any)	: \$	0.00	days
LTA / GIA Search Fee	: \$	7.45	
Others:	: \$	0.00	
	: \$		
Final Settlement Sum	: \$	2,975.45	

**Is Third Party Workshop GIA Registered?** [ ] YES [ X ] NO (Kindly indicate below)

**A) For Non GIA Registered Workshop:** Agreed Liability \_\_\_\_ 100 \_\_\_\_ (%)

**B) For GIA Registered Workshop:** BOLA Applicable: Yes/ No BOLA Scenario No: \_\_\_\_

BOLA Liability: \_\_\_\_ (%) Assessed Liability (\*): \_\_\_\_ (%)

*\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks \_\_\_\_\_

Payment Instruction: Payee's Breakdown			
1)	Ban Choon Motor Works	: \$	2,975.45
2)		: \$	
3)		: \$	

JOANNE LEE KHANG MIN

16 Oct  
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

## LKK Auto Consultants Pte Ltd (Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AXA18004347/R1JB3Q2  
Date: 16/10/2018

## REFERENCE

Handling Insurer:	AXA Insurance Pte Ltd	Policy No:	P1680520
Claimant Vehicle No :	GBC6856T	Insured Vehicle No :	SHD9722A
Date of Loss:	26/02/2018	Nature of Claim:	TP
		Claim No:	C0471904

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	<b>GBC6856T</b>		
Make & Model:	TOYOTA DYNA 150, 3.0 D (M)	Engine No:	1KD2296967
Reg. Date:	27/06/2013 (Man. Year: 2013)	Chassis No:	JTFAT35Y80K202351
Colour:	White	Odometer:	196561 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	195/75 R15	Rear Tyre Size:	155 R12C
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,815.30	2,235.15	580.15	20.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	980.00	800.00	180.00	18.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>3,795.30</b>	<b>3,035.15</b>	<b>760.15</b>	<b>20.03</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,400.00</b>		
(S\$)	3,795.30	2,400.00	1,395.30	36.76
<b>+ GST 7.00/7.00% (S\$)</b>	265.67	168.00	97.67	36.76
<b>Nett Amount (S\$)</b>	<b>4,060.97</b>	<b>2,568.00</b>	<b>1,492.97</b>	<b>36.76</b>
<b>+ Loss of Use (5.0 x S\$80.00/day) (S\$)</b>		400.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>2,975.45</b>		

## INSPECTION

Date of Assignment:	05/03/2018		
Date Inspected:	07/03/2018	Inspected At:	Ban Choon Motor Works (HQ) Blk 3 Pioneer Road North #01-15 Singapore 628457

Estimated Period of Repair: 5.0 days

---

**Adjuster:** MOHD RASUL

**Manager:** Joy Irene Bascao

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 27 Jul 2018)	
<b>Parts:</b>	N/A	TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBC6856T)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILLAMPS (CONSISTENT)	O/S Scratched	480.40 FL	*240.20 FL
2	1		*TAIL BOARDS (CONSISTENT)	Bent	2,400.00 FS	*2,000.00 FS
3	1		*70KM/H STICKER (CONSISTENT)	Necessary	20.00 FS	*20.00 FS
4	1		*REAR NUMBER PLATE (CONSISTENT)	Bent	35.00 FS	*35.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>2,935.40</b>	<b>2,295.20</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	<b>120.10</b>	<b>60.05</b>
<b>Total Parts (\$\$)</b>	<b>2,815.30</b>	<b>2,235.15</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO KNOCKING AND STRAIGHTEN OF ALL NECESSARY DAMAGED PARTS TO CHANGING OF THE ABOVE PARTS	New	480.00	400.00
2	TO PUTTY AND SPRAY PAINTING ON ACCIDENT DAMAGED PARTS	New	500.00	400.00
Gross Labour Cost (\$\$)			980.00	800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >