

BMW Dealer

Performance Motors LimitedA member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

3.4 @ 10.00 an

Survey & repair
- arrange rental car

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

07 MAR 2018

Estimate No.	: b1 46145	Page No. : 1 of 1
Date Estimated	: 06/03/2018	
Prepared By	: Inthiran A/L Thurasamy	

- ESTIMATE REPAIR FOR - Leslie Low Joo Leong (Leslie Liu Yu 11R Marlene Avenue Singapore 554535	- ACCOUNT - 121 AIG Asia Pacific Insurance Pte. Ltd. 78 Shenton Way #08-16 Chartis Building Singapore 079120
---	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLT6668L	5E91261	15/09/2017	216i G TOURER	0

<u>DESCRIPTION</u>	<u>VALUE</u>
To replace rear bumper and attachments.	850 1,275.00
Painting rear bumper.	934 1,038.00
To check electrical wiring systems and lightings at the rear section for proper function.	150 177.00
Sundries.	40 80.00
Total Labour 1:	<u>2,570.00</u>

<u>DESCRIPTION</u>	<u>QTY</u>	<u>PRIC</u>	<u>VALUE</u>
REAR BUMPER PANEL PRIMED (PDC)	1	966.25	R 966.25
SET MOUNTS PDC SENSOR REAR	1	62.95	X 62.95
Total Parts :			<u>1,029.20</u>

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 03/04/18 @ 1405 Excess S\$ _____

Surveyor's Name RASUL Sign _____

Surveyor's Tel 90010068 Authorised Yes / No _____

Authorised Date _____ Time _____

REPAIR PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No _____

Surveyor's E-mail _____

No. of Working Days Recommend 3 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Labour 1 : 2,570.00

Acknowledged by Repairer : 1,029.20

Signature: _____

Date: _____

Excess : 0.00

Total GST @ 7% : 251.94

Grand Total : 3,851.14

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **