

ASS. REC. BY:

REF: CS3/C71800437/M1d3et

Surveyor
Mainmen

MA

ASSIGNMENT (Office)

From (Person):

Chong Boon Sen

of

CTI

Date/Time:

6/3/18 @ 5:11pm

Estimated Cost:

Bill to:

OD / ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No:

SLU83994

Insured:

SJL 7814R

at Workshop m/s:

Jian Her Motors

Tel:

64817221

of

Jalan Isnin

Policy No:

DMPCSN1319631704

Claim No:

SNM18D01140C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

26/2/2018

CA / REV / REP. / REV 24 HRS

w/p

Insp: Blk 5038 AMK Ind Prk 2 #01-105

H.O.D. Endorsement:

Date/Time:

10:05am @ 7/3/18

Person Contacted:

James

Vehicle ☒ IN / OUT

Date/Time

Action/Instruction (4) Estimate

SLU83994-X

SJL 7814R-X

Dismantle: 8/3/2018

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLU 8399U Yr Regn: DEC 2017

Type: MCar M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA CHR cc 1797

Colour: BLUE A/C: Insured / Std / NI / NA

Sp. Reading: 24539. T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ZYX 102083028

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R17

R: _____

BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 8 mm R/Bal: 8 mm

L/Bal: 8 mm L/Bal: 8 mm

D.O.A. 26/2/2018 D.O.I. 7/3/2018

Survey held at: _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

- FRNT NS.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

NO ESTIMATE UPON SURVEY

* Repair Estimate: S\$ 3500 - 4500

* 2 days

RECEIVED 2 JUN 2018

Date/Time: File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

1 \$ + \$5.00

Photos

Other

TOTAL

Report Format :

Lump Sum / I.B.I: \$

Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech. Insp (\$☐ Weekend (\$

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Mar 2018		06 Mar 2018 17:11 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:									
Main Claimant: H.L. CAR RENTAL PTE LTD									
Vehicle Reg. No.:		SLU8399U	Date of Loss:	26/02/2018 00:00 - :59					
Claim Type:		TP / SNM18D01140C02	Policy/Cover Note No.:	DMPCSN1319631704					
Vehicle Reg. No. (Insured):		SJL7814R	Policy No. (Claimant):						
		Excess:	S\$0.00						
Repairer: Lian Her Motors (HQ) 1 JALAN ISNIN, S77939 Ang Mo Kio - Tel: 64817221									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 15/03/2018]									
Adj Asg. Remarks: NO EST, CASE W/O SJE.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
<input type="checkbox"/> ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	4543E
Vehicle Details	
Vehicle No.:	SLU8399U
Vehicle to be Exported:	No
Intended De-registration Date:	02 May 2018
Vehicle Make:	TOYOTA
Vehicle Model:	C-HR HYBRID 1.8S CVT
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	2ZR8222258
Chassis No.:	ZYX102083028
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,403.00
Original Registration Date:	15 Dec 2017
First Registration Date:	15 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Dec 2027
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	14 Dec 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,390.00
COE Rebate Amount:	\$55,183.00
Total Rebate Amount:	\$58,933.00

The information contained herein is correct as at 02 May 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/02/2018 16:20
Date Of Accident	26/02/2018 15:35
Exact Location Of Accident	FARRER RD TWDS QUEENSWAY AYE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLU8399U
Insured/Policyholder	
Name Of Registered Owner	H.L. CAR RENTAL PTE LTD
Co Reg No	201004543E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91828811
Alternative Phone No	OFFICE-91828811

Vehicle Particulars

Manufacturer	TOYOTA
Model	C-HR
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5083403664-01
Cover Note Number	

Driver

Name of Driver	CHIANG WAI MENG (ZHANG WEIMING)
NRIC No	S7514666C
Date Of Birth	11/05/1975
Occupation	OUTDOOR
Date Of Driving Pass	22/11/1996
Driving Experience	21 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91828811
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 152 YUNG HO RD #07-05
Postcode	610152
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : TAN POH LI GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TECK GHEE NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 321 ANG MO KIO STREET 31 , POSTCODE: 560321 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4599999 - FAX NO: 64574478
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT NO. T/20180227/2105.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	PENDING
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJL7814R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


H.L CAR RENTAL PTE LTD

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/Fin No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report no. T/20180227/2105.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

H.L. CAR RENTAL PTE LTD

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name
NSIC 2714 (v)

POLICE REPORT PG 1



**SINGAPORE
POLICE FORCE**



T/20180227/2105

Police Station Of Origin:
Teck Ghee NPP
321 Ang Mo Kio Street 31 SINGAPORE
560321
Tel No: 1800-4599999

1 of 3

Report No: T/20180227/2105

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 27/02/2018 15:15	Video Report No.:	Station Diary No.: 28
--	-------------------	--------------------------

Informant's Particulars

Name of Informant: CHIANG WAI MENG			Address: APT BLK 152 YUNG HO ROAD #07-05 SINGAPORE 610152	
ID Type / ID No.: NRIC NO / S7514666C			Contact No.: Home/Office: Mobile: 91828811	
Nationality: SINGAPORE CITIZEN			Email:	
Sex: Male	Age: 42	Date of Birth: 11/05/1975	Type of Informant: Driver	
Race: Chinese			Language:	Institution / School Name:
Occupation: DRIVER			Driving Licence Information: Class: 2B,3 Date of Expiry:	

General Information of the Accident

Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 26/02/2018 15:35	Type of Location: Straight Road
Location: Along Road 1 Traveling Toward Road 2 FARRER ROAD QUEENSWAY Farrer Road towards Queensway AYE				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume:	
Type of Collision: Between Moving Vehicles - Head To Side			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJL7814R	Car					0
SLU8399U	Car				Slightly Damaged	1

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20180227/2105

2 of 3

Police Station Of Origin:
Teck Ghee NPP
321 Ang Mo Kio Street 31 SINGAPORE
560321
Tel No: 1800-4599999

Report No: T/20180227/2105

CONTINUATION OF REPORT

Driver			
Name	CHIANG WAI MENG	ID No.	S7514666C
Related Vehicle	SLU8399U (Car)	Contact No.	91828811
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On the 26/02/2018 at about 1526hrs, I was driving my vehicle bearing plate number SLU8399U along farrier road towards Queensway AYE. I was driving at the first lane. Another vehicle bearing plate number SJL7814R signaled right with intention of coming into my lane. He then turned into my lane and his right rear knocked into my front left side of the vehicle. He then continued to drive forward. I honked him and high beamed him but he did not stop. As such I came and lodge a police report. Damages to my vehicle is some scratches on the front left side of the vehicle.

B-8
2157601R12

POLICE REPORT PG 3



SINGAPORE
POLICE FORCE



T/20180227/2105

Police Station Of Origin:
Teck Ghee NPP
321 Ang Mo Kio Street 31 SINGAPORE
560321
Tel No: 1800-4599999

3 of 3
Report No: T/20180227/2105

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

F /

Sgt 2 ROY CHONG YU KEONG

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

27/02/2018 15:15

Officer In Charge Of Case:

TP / HRT /

SI TAN LEE HWANG DAWN

Contact No.: 65476215

Classification Of Case:

Authentication Stamp

NP168

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Mar 2018		06 Mar 2018 17:11 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	Co. Reg. No.: -								
Main Claimant:	H.L. CAR RENTAL PTE LTD								
Vehicle Reg. No.:	SLU8399U	Date of Loss:	26/02/2018 00:00 - :59 [2 Months and 11 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D01140C02	Policy/Cover Note No.:	DMPCSN1319631704						
Vehicle Reg. No. (Insured):	SJL7814R	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Lian Her Motors (HQ) Block 5038 Ang Mo Kio Avenue 3, #01-405 Ang Mo Kio Industrial Park 2, 569541 Ang Mo Kio - Tel: 82990599								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MA CHIN FOOK] ... [Final Rpt due 15/03/2018]								
Adj Asg. Remarks:	NO EST, CASE W/O SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• CHINA_TAIPING (07/05/2018): < No subject >									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLU8399U (SNM18D01140C02)**
[SJL7814R]
TP
H.L. CAR RENTAL PTE LTD
Feb 26 2018 12:00AM
[-]
Lian Her Motors

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder		Thumbnail	Print
1	02/05/18 12:28	General View	Load PDF	
2	02/05/18 12:28	Photographs of Damaged Parts	Load PDF	
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
1	06/03/18 17:11	PRS	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI18004371/M1D3E2

Date: 27/06/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN1319631704

Claimant Vehicle
No: SLU8399UInsured Vehicle
No: SJL7814R

Date of Loss: 26/02/2018

Nature of Claim: TP

Claim
No: SNM18D01140C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLU8399U

Make & Model: TOYOTA C-HR HYBRID, 1.8 S CVT (A)

Engine No: 2ZR8222258

Reg. Date: 15/12/2017 (Man. Year: 2017)

Chassis No: ZYX102083028

Colour: Blue

Odometer: 24539 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R17

Rear Tyre Size: 215/60 R17

Front Left Side: Bridgestone 8 mm

Rear Left Side: Bridgestone 8 mm

Front Right Side: Bridgestone 8 mm

Rear Right Side: Bridgestone 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 06/03/2018

Date Inspected: 07/03/2018 Inspected At:

Lian Her Motors (HQ)
Block 5038 Ang Mo Kio Avenue 3, #01-405
Ang Mo Kio Industrial Park 2
Singapore 569541

Estimated Period of Repair: 2.0 days

Adjuster: MA CHIN FOOK

Manager: Nivitha Govindasamy

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,500.00 - \$4,500.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Jun 2018)
Parts:	M1-SUV	TOYOTA C-HR HYBRID 1.8 S CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLU8399U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >