

ASS. REC. BY:

REF: CS3 | SM018001372/R1d3

Special Instruction:

Surveyor: RaisulASSIGNMENT (Office)From (Person): Grace TEO

of

SMO

Date/Time:

7/3/18 @ 10:36am

Estimated Cost:

Bill to:

OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV ☐ CS

To Inspect Vehicle No:

SJG 8410S

Insured:

CB 6868C

at Workshop m/s

AMA Automotive

Tel:

8778 3636

of

36 Toh Guan Rd East # 01-36

Policy No:

Claim No:

CMTD1806971 / GPL

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

02/03/2018CA / REV / REP. / REV 24 HRS ^{1wp}

H.O.D. Endorsement:

Date/Time: 10:40am @ 7/3/18

Person Contacted:

MelvinVehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (X) Estimate
	<u>SJG 8410S-X</u>
	<u>CB 6868C - CC6/AIG16003618/4h63q2</u>
	<u>Dismantle Part: 0903 2018</u>

D.O.A: 19/2/2016

Signature: *[Signature]*


REF:

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To inspect Vehicle No: GSE S36 84108
at Workshop m/s AMA Automotive
of Toll Guan
Insured: Sonyo / TP
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 6 days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: S36 84108 Yr Regn: 1
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: MITSUBUHI LANCER C.C.
Colour: WHITE AC: Insured / Std / NI / NA
Sp. Reading: 297807 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: JMY5RCY2A8U407106
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Mod: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 215/55R17
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front R/Bal. 6 mm
L/Bal. 6 mm
D.O.A. 02/03/18
Rear R/Bal. 6 mm
L/Bal. 6 mm
D.O.I. 07/03/18
Survey held at AMA Automotive
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time | Action / Instruction
\$6,800 - \$8,500

[Signature]
14/04/2018

RECEIVED 05 APR 2018

Date/Time, File Pass to? ☐ : Preli. Report
☐ : Final Report
1) _____
Date/Time, File Return to? _____
2) _____
Report Format : _____
Lump Sum / I.B.I. (\$) _____

Days Of Repair: _____
Resurvey No. of Trip: _____
Survey Fee: _____
Transportation: _____
Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)
TOTAL _____

Nivitha (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Wednesday, 7 March 2018 10:36 AM
To: Alywin; admin-d@lkkauto.com; assignments@lkkauto.com
Cc: Gnoh, Pau Loong
Subject: CMTD1800971/GPL - PRI - ACCIDENT INVOLVING CB6868C & SJG8410S ON 02.03.2018
Attachments: 20180305131842314.pdf

Our Reference: CMTD1800971/GPL
Your Reference: SJG8410S (AY)

Without Prejudice

Date: 7th March 2018

Attention:
M/S CHIA S ARUL LLC

Dear Alywin,

ACCIDENT INVOLVING CB6868C & SJG8410S ON 02.03.2018

We refer to your reply dated 07/03/2018.

We do not agree to your list of surveyors.

As such, we will be appointing our motor surveyor, **LKK AUTO** to conduct the pre-repair survey of your client's vehicle.

The pre-repair survey will include a survey of the vehicle when its damaged parts are being dismantled prior to the commencement of repairs.

We would like our motor surveyor to conduct a post repair inspection once your client's vehicle has been repaired.

The survey is conducted on a without Prejudice basis and without any admission of liability.

Yours faithfully,

Best Regards
Grace Teo
Claims Division
D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Alywin [mailto:alywin@chiaarul.com]

Sent: Wednesday, March 07, 2018 10:19 AM

To: Teo, Grace

Cc: Gnoh, Pau Loong

Subject: RE: CMTD1800971/GPL - PRI - ACCIDENT INVOLVING CB6868C & SJG8410S ON 02.03.2018

Dear All,

We refer to the above matter and to your email below.

Kindly be inform that our client is not agreeable to the list of your surveyor.

We enclosed herewith the list of our client's workshop surveyor for your consideration.

Sincere Appraisal - Mr Dave

SK Auto Consultants - S. Kumanan

Kindly let us have your reply soon.

Please do not hesitate to contact me should you have any queries thereof.

Best regards,

Mr Alywin Yeo

M/s Chia S Arul LLC

151 Chin Swee Road

#03-09 Manhattan House

Singapore 169876

Tel: (65) 6733 4647 Fax: (65) 6733 8183

This e-mail is from M/s Chia S Arul LLC, a firm of Advocates and Solicitors in Singapore, and is intended solely for the named addressee. It contains confidential and /or legally privileged information. If the e-mail has reached you in error, please delete the e-mail immediately and inform us of the error. You may contact us at info@chiaarul.com. Internet communications cannot be guaranteed to be secured or error-free as information could be intercepted, corrupted, lost, arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the context of this message which arise as a result of Internet transmission.

From: Teo, Grace [mailto:grace.teo@sompo.com.sg]

Sent: 05 March, 2018 3:39 PM

To: Alywin

Cc: Gnoh, Pau Loong

Subject: CMTD1800971/GPL - PRI - ACCIDENT INVOLVING CB6868C & SJG8410S ON 02.03.2018

Our Reference: CMTD1800971/GPL

Your Reference: SJG8410S (AY)

Without Prejudice

Date: 5th March 2018

Attention:

M/S CHIA S ARUL LLC

Dear Alywin,

ACCIDENT INVOLVING CB6868C & SJG8410S ON 02.03.2018

We refer to your Notice of Accident dated 5/03/2018.

Please be informed that Gnoh Pau Loong the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Alywin [<mailto:alywin@chiaarul.com>]

Sent: Monday, March 05, 2018 1:20 PM

To: Claims - Motor Survey

Subject: PRI FOR SJG 8410S

Dear All,

We enclosed herewith a copy of PRI for your necessary action.

Please do not hesitate to contact me should you have any queries thereof.

Best regards,

Mr Alywin Yeo

M/s Chia S Arul LLC

151 Chin Swee Road

#03-09 Manhattan House

Singapore 169876

Tel: (65) 6733 4647 Fax: (65) 6733 8183

This e-mail is from M/s Chia S Arul LLC, a firm of Advocates and Solicitors in Singapore, and is intended solely for the named addressee. It contains confidential and /or legally privileged information. If the e-mail has reached you in error, please delete the e-mail immediately and inform us of the error. You may contact us at info@chiaarul.com. Internet communications cannot be guaranteed to be secured or error-free as information could be intercepted, corrupted, lost, arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the context of this message which arise as a result of Internet transmission.

CHIA S ARUL LLC
ADVOCATES & SOLICITORS
UEN 201330709H

ARULCHELVAN S

Our Ref : SJG 8410S (AY)

Your Ref :

5 March 2018

Sompo Insurance Singapore Pte Ltd
50 Raffles Place
#05 - 01 / 06
Singapore Land Tower
Singapore 048623

BY FACSIMILE ONLY
(Fax: 6221 3147)

Dear Sir,

RE: PROPERTY DAMAGE CLAIM
CLAIMANT : SIN-THAI ELECTRONICS
ACCIDENT INVOLVING SJG 8410S & CB 6868C ALONG TAMPINES AVENUE
5 TOWARDS TAMPINES ON 2 MARCH 2018

1. We act for SIN-THAI ELECTRONICS, the owner of motor vehicle no. SJG 8410S, which was involved in the aforesaid accident.
2. We hereby give you **NOTICE** that we are claiming against your insured motor vehicle no. CB 6868C for damages, costs and disbursements as a result of your insured driver's negligence.
3. Kindly let us know if you wish to conduct a pre-repair inspection on our client's motor vehicle at M/s AMA Autocare Pte Ltd at 36 Toh Guan Road East #01 - 36 Singapore 608580 and kindly arrange with Mr. Melvin at 8778 3636.
4. If we do not hear from you within the next **two (2) working days**, we shall advise our client to proceed with their own inspection and repairs.
5. Please reply either by fax at 6733 8183 or by email to alywin@chiaarul.com.

Yours faithfully,

MR ARULCHELVAN S
cc: Client (By Email)

151 CHIN SWEE ROAD • #03-09
MANHATTAN HOUSE • SINGAPORE 169876
TEL : (65) 6733 4647 • FAX : (65) 6733 8183 (not for Service of Court documents)
EMAIL : info@chiaarul.com

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

PRE-REPAIR INSPECTION REPORT

SOMPO INSURANCE SINGAPORE PL

Ref: CS3/SMO18004372/R1d3s2

50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERS SINGAPORE 048623

Date: 05-04-2018



Code: SMO

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	CB 6868C	Veh. Inspected	SJG 8410S
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1800971/GPL	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	07/03/2018


2. Vehicle Particulars & Condition

Make & Model	MITSUBISHI LANCER	c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	JMYSRCY2A8U007106	Colour	WHITE
Odometer	297807 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/55 R17	YOKOHAMA	6 mm
L/H Front Tyre	215/55 R17	YOKOHAMA	6 mm
R/H Rear Tyre	215/55 R17	YOKOHAMA	6 mm
L/H Rear Tyre	215/55 R17	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.	
--	---

5. General Information

Accident Date	02/03/2018	Inspect Date / Time	07/03/2018 (12:11 PM)
Survey held at	AMA AUTOMOTIVE PTE. LTD. 36 TOH GUAN ROAD EAST #03-36 S 608580		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,800-\$8,500

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------

Report Ref No. CS3/SMO18004372/R1d3s2

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.