

ASS. REC. BY:

REF:

CS3 / MSC / 18004373 / Wb5

Special Instruction:

Surveyor:

Wilson

ASSIGNMENT (Office)

From (Person):

Elaine Ngu

of

MSC

Date/Time:

06032018 11:53am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJS 2942A

Insured:

YP 5940Z

at Workshop m/s

Motor Intel Automo

Tel:

9838 3318

of

13 Kaki Bukit Rd 4 #01-20

Policy No:

MSD/VCC/18-00004

Claim No:

MSC/V/18-00019

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

17012018

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time:

07032018 456am

Person Contacted:

Wilson

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SJS 2942A - NS/ INC 18010236 / H143d1
	YP 5940Z - X
	Dismantle Part : 09032018

D.O.A. : 180615

[]

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Jan 2018		06 Mar 2018 11:53 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:

SG SAGAWA AMEROID PTE LTD, Co. Reg. No.: 199100423D

Main Claimant:

CHAN HUA HSING ALVIN, ID: S8103346C

Vehicle Reg. No.:

SJS2942A

Claim Type:

TP / MSC/V/18-000119

Vehicle Reg. No. (Insured):

YP5940Z

Repairer:

- Not Applicable - (-)

Handling Insurer:

MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 07/03/2018]

Driver/Custodian (Insured):

MA CHENGBO (), NRIC: G6327760L, Tel: +6593863380

Adj Asg. Remarks:

M/s Motor Intel Automo Pte Ltd at 13 Kaki Bukit Road 4 #01 - 20 Bartley Biz Centre Singapore 417807 and kindly arrange with Mr Wilson Ong at 8838 3318 and/or Mr Daniel Tan at 9385 8911.

[Created by insurer]

Date of Loss:

17/01/2018 21:00 - :59

Policy/Cover Note No.:

MSD/VCC/18-000004 (Comprehensive)
Coverage: 01/01/2018 - 31/12/2018

Policy No. (Claimant):

Excess:

S\$2,000.00

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

07032018 @ 956am
Wilser veh in

Vehicle No.

SSS 2942A.

Make / Model:

Honda Fit 1.3

Date of Accident

02 Mar 2018

Time of Accident

1715 hrs.

Location of Accident

Junction of Tuas West Rd & Tuas Crescent.
On the way home.

Purpose of Use

Name of Owner

Chan Hua Hsing, Alvin.

NRIC / Business UEN:

S8103346C

Contact No:

HP:

97856132

Home:

63093207

Claim Type:

Own Damage

Third Party

Reporting Only

Private Hire:

Uber / Grab

Insurance Company:

NTUC

Type Of Coverage:

Comprehensive

Third Party

TPFT

Policy No:

5096084351

Name Of Driver: (as above)

No. Of Passenger:

Male:

Female:

NRIC:

S8103546C

Date Of Birth:

31/01/1981

License Pass Date:

20 Feb 2016

Gender:

Male

Female

Occupation:

Service Engineer

Contact No.:

HP: as above

Home:

Address:

Bik 111B, Depot Rd #03-111 S(102111)

Driver Own Vehicle:

Yes

Relationship:

Employee / Relative / Friend

Weather Condition:

Day

Night

Raining

Road Surface:

Dry

Wet

Any Injuries:

Yes, Driver, Chan Hua Hsing

Contact No.:

97856132

Police Report:

Vehicle B No.:

YP 5940Z

No. Of Passenger:

Male:

Female:

Driver / NRIC

WANG DAYONG

Driver Contact:

93858344

Vehicle C:

No. Of Passenger:

Male:

Female:

Driver / NRIC

Driver Contact:

Vehicle D:

No. Of Passenger:

Male:

Female:

Driver / NRIC

Driver Contact:

Vehicle E:

No. Of Passenger:

Male:

Female:

Driver / NRIC

Driver Contact:

Particulars of Workshop:

Tel no: 6281 0087

Person In Charge:

Address:

Email:

Motor Intel Automo Pte. Ltd.


Fax No: 6281 0187

Wilson Ong (HP: 8838 3318)

Bartley Biz Centre, 13 Kaki Bukit Rd 4, #01-20 S(417807)

sales@mia.com.sg

SKETCH PLAN



veh A: SJS 2942A
veh B: YP 5940Z

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

As per police report. T/2018 0303/2054

veh A: SJS 2942A
veh B: YP 5940Z

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



SINGAPORE POLICE FORCE



T/20180303/2054

1 of 3

Police Station Of Origin:
Kampong Java N.P.C
21 Kampong Java Road SINGAPORE
228892
Tel No: 1800-2959999

Report No. T/20180303/2054

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 03/03/2018 12:41	Vide Report No.:	Station Diary No.: 65
--	------------------	--------------------------

Informant's Particulars

Name of Informant: CHAN HUA HSING, ALVIN			Address: APT BLK 111B DEPOT ROAD #03-111 SINGAPORE 102111		
ID Type / ID No.: NRIC NO / S8103346C			Contact No.: Home/Office: 63093207 Mobile: 97856132		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 37	Date of Birth: 31/01/1981	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: SERVICE ENGINEER			Driving Licence Information: Class: 3A Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 02/03/2018 05:15	Type of Location: X-Junction
Location: TUAS WEST ROAD TUAS CRESCENT Cross junction of Tuas West Rd and Tuas Cres				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Dual Carriage Way		Traffic Control: Traffic Light - Working		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJS2942A	Car	HONDA	FIT 1.3G A	Silver	Seriously Damaged	0
YP5940Z	Lorry	MITSUBISHI		Blue	Seriously Damaged	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SJS2942A	NTUC Income Insurance Co-Operative Limited	5096084351	24/11/2017	06/02/2019



**SINGAPORE
POLICE FORCE**



T/20180303/2054

2 of 3

Police Station Of Origin:
Kampong Java N.P.C
21 Kampong Java Road SINGAPORE
228892
Tel No: 1800-2959999

Report No. T/20180303/2054

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver:			
Name	CHAN HUA HSING, ALVIN	ID No.	S8103346C
Related Vehicle	SJS2942A (Car)	Contact No.	63093207
Hospital/Clinic	NOVENA MEDICAL CENTER FAMILY CLINIC	Class of Driving Licence & Expiry Date	Class: 3A Date of Expiry: NIL
Date Treatment	03/03/2018	Date Discharge	NIL
No. of Days granted Medical Leave	07	Degree of Injury	NIL
Driver:			
Name	Wang DaYoung	ID No.	G6758188T
Related Vehicle	NIL	Contact No.	93858344
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: 19/03/2019
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On the 02/03/18 at around 1715hrs, I was driving my car, SJS2942A, at the first lane of Tuas Cres, preparing to turn right into Tuas West Rd. However, upon seeing the red light, I stopped my car before the yellow stop line. At this point in time, the lorry, YP5940Z, behind me bang onto my rear side of the car. The driver of the lorry, Wong Dayoung, came down and told me to settle this issue through the insurance agencies. He also gave me his manager contact details (Steven, 86574255). I went to cantonment yesterday, on the 02/03/18 at about 2200hrs, wanting to make a report. However, I was told to sought for medical attention before lodging a traffic accident report. So, I went down today to Novena Medical Center (10 Sinaran Dr #09-21) and got a 7 days Medical Certificate by Dr Choo Kay Wee from 03/03/18 to 09/03/18.

★



**SINGAPORE
POLICE FORCE**



T/20180303/2054

3 of 3

Report No. T/20180303/2054

Police Station Of Origin:
Kampong Java N.P.C
21 Kampong Java Road SINGAPORE
228892
Tel No: 1800-2959999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

E /

Staff Sgt SEOW HONG DE, XAVIER

Signature Of Interpreter:

Not applicable

*

Officer In Charge Of Case:

TP / AEIT /

Sgt 2 YEO KIA HUAT

Contact No.: 65476325

Signature Of Informant:

Date/Time:

03/03/2018 12:41

Classification Of Case:

Authentication Stamp

NP168



**SINGAPORE
POLICE FORCE**

SN 167

SIGNATURE

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Jan 2018		06 Mar 2018 11:53 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	SG SAGAWA AMEROID PTE LTD, Co. Reg. No.: 199100423D		
Main Claimant:	CHAN HUA HSING ALVIN, ID: S8103346C		
Vehicle Reg. No.:	SJS2942A	Date of Loss:	17/01/2018 21:00 - :59 [101 Months and 10 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MSC/V/18-000119	Policy/Cover Note No.:	MSD/VCC/18-000004 (Comprehensive) Coverage: 01/01/2018 - 31/12/2018
Vehicle Reg. No. (Insured):	YP5940Z	Policy No. (Claimant):	
		Excess:	S\$2,000.00
Repairer:	- Not Applicable - (-)		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Teo Cheng Ming Wilson] ... [Imm.Advice due 07/03/2018]		
Driver/Custodian (Insured):	MA CHENGBO (), NRIC: G6327760L, Tel: +6593863380		
Adj Asg. Remarks:	M/s Motor Intel Automo Pte Ltd at 13 Kaki Bukit Road 4 #01 - 20 Bartley Biz Centre Singapore 417807 and kindly arrange with Mr Wilson Ong at 8838 3318 and/or Mr Daniel Tan at 9385 8911.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJS2942A (MSC/V/18-000119)**
[YP5940Z]

TP

CHAN HUA HSING ALVIN
Jan 17 2018 9:00PM
[SG SAGAWA AMEROID PTE LTD]

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View [View in Browser](#) ▼

Assessment Reports			1 per page ▼	☒
No.	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	06/03/18 09:46	Accident Statement From: SC - Reg. No: YP5940Z, Claimant: SG SAGAWA AMEROID PTE LTD	 Load HTM	

Photos/Images			3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/04/18 16:34	General View	 Load JPG	☒
2	03/04/18 16:34	General View	 Load JPG	☒
3	03/04/18 16:34	General View	 Load JPG	☒
4	03/04/18 16:34	General View	 Load JPG	☒
5	03/04/18 16:34	General View	 Load JPG	☒
6	03/04/18 16:34	General View	 Load JPG	☒
7	03/04/18 16:34	General View	 Load JPG	☒
8	03/04/18 16:34	General View	 Load JPG	☒
9	03/04/18 16:34	General View	 Load JPG	☒
10	03/04/18 16:34	General View	 Load JPG	☒
11	03/04/18 16:34	General View	 Load JPG	☒
12	03/04/18 16:34	General View	 Load JPG	☒
13	03/04/18 16:34	General View	 Load JPG	☒
14	03/04/18 16:34	General View	 Load JPG	☒
15	03/04/18 16:34	General View	 Load JPG	☒
16	03/04/18 16:34	General View	 Load JPG	☒
17	03/04/18 16:34	General View	 Load JPG	☒
18	03/04/18 16:34	General View	 Load JPG	☒
19	03/04/18 16:34	General View	 Load JPG	☒
20	03/04/18 16:34	General View	 Load JPG	☒
21	03/04/18 16:34	General View	 Load JPG	☒
22	03/04/18 16:36	Photographs of Damaged Parts	 Load JPG	☒
23	03/04/18 16:36	Photographs of Damaged Parts	 Load JPG	☒
24	03/04/18 16:36	Photographs of Damaged Parts	 Load JPG	☒
25	03/04/18 16:36	Photographs of Damaged Parts	 Load JPG	☒
26	03/04/18 16:36	Photographs of Damaged Parts	 Load JPG	☒
27	03/04/18 16:36	Photographs of Damaged Parts	 Load JPG	☒
28	03/04/18 16:36	Photographs of Damaged Parts	 Load JPG	☒
29	03/04/18 16:36	Photographs of Damaged Parts	 Load JPG	☒
30	03/04/18 16:36	Photographs of Damaged Parts	 Load JPG	☒
31	03/04/18 16:36	Photographs of Damaged Parts	 Load JPG	☒
32	03/04/18 16:36	Photographs of Damaged Parts	 Load JPG	☒

Assessment Reports			1 per page	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
33	03/04/18 16:36	Photographs of Damaged Parts	 Load JPG	☒
34	03/04/18 16:36	Photographs of Damaged Parts	 Load JPG	☒
35	03/04/18 16:36	Photographs of Damaged Parts	 Load JPG	☒
36	03/04/18 16:36	Photographs of Damaged Parts	 Load JPG	☒
37	03/04/18 16:36	Photographs of Damaged Parts	 Load JPG	☒
38	03/04/18 16:36	Photographs of Damaged Parts	 Load JPG	☒
39	03/04/18 16:36	Photographs of Damaged Parts	 Load JPG	☒
40	03/04/18 16:36	Photographs of Damaged Parts	 Load JPG	☒
41	03/04/18 16:36	Photographs of Damaged Parts	 Load JPG	☒
42	03/04/18 16:36	Photographs of Damaged Parts	 Load JPG	☒
43	03/04/18 16:36	Photographs of Damaged Parts	 Load JPG	☒
44	03/04/18 16:36	Photographs of Damaged Parts	 Load JPG	☒
45	03/04/18 16:36	Photographs of Damaged Parts	 Load JPG	☒
46	03/04/18 16:36	Photographs of Damaged Parts	 Load JPG	☒
47	03/04/18 16:36	Photographs of Damaged Parts	 Load JPG	☒
48	03/04/18 16:36	Photographs of Damaged Parts	 Load JPG	☒
49	03/04/18 16:36	Photographs of Damaged Parts	 Load JPG	☒
50	03/04/18 16:36	Photographs of Damaged Parts	 Load JPG	☒
51	03/04/18 16:36	Photographs of Damaged Parts	 Load JPG	☒
52	03/04/18 16:36	Photographs of Damaged Parts	 Load JPG	☒
53	03/04/18 16:36	Photographs of Damaged Parts	 Load JPG	☒
54	03/04/18 16:36	Photographs of Damaged Parts	 Load JPG	☒
55	03/04/18 16:36	Photographs of Damaged Parts	 Load JPG	☒
56	03/04/18 16:36	Photographs of Damaged Parts	 Load JPG	☒
57	03/04/18 16:36	Photographs of Damaged Parts	 Load JPG	☒
58	03/04/18 16:36	Photographs of Damaged Parts	 Load JPG	☒
59	03/04/18 16:36	Photographs of Damaged Parts	 Load JPG	☒
60	03/04/18 16:36	Photographs of Damaged Parts	 Load JPG	☒
61	03/04/18 16:36	Photographs of Damaged Parts	 Load JPG	☒
62	03/04/18 16:36	Photographs of Damaged Parts	 Load JPG	☒
63	03/04/18 16:36	Photographs of Damaged Parts	 Load JPG	☒
64	03/04/18 16:36	Photographs of Damaged Parts	 Load JPG	☒
65	03/04/18 16:36	Photographs of Damaged Parts	 Load JPG	☒
66	03/04/18 16:36	Photographs of Damaged Parts	 Load JPG	☒
67	03/04/18 16:36	Photographs of Damaged Parts	 Load JPG	☒
68	03/04/18 16:36	Photographs of Damaged Parts	 Load JPG	☒
69	03/04/18 16:36	Photographs of Damaged Parts	 Load JPG	☒
70	03/04/18 16:36	Photographs of Damaged Parts	 Load JPG	☒
71	03/04/18 16:36	Photographs of Damaged Parts	 Load JPG	☒
72	03/04/18 16:36	Photographs of Damaged Parts	 Load JPG	☒
73	03/04/18 16:36	Photographs of Damaged Parts	 Load JPG	☒
74	03/04/18 16:36	Photographs of Damaged Parts	 Load JPG	☒
75	03/04/18 16:36	Photographs of Damaged Parts	 Load JPG	☒
76	03/04/18 16:36	Photographs of Damaged Parts	 Load JPG	☒
77	03/04/18 16:36	Photographs of Damaged Parts	 Load JPG	☒
78	03/04/18 16:36	Photographs of Damaged Parts	 Load JPG	☒
79	03/04/18 16:36	Photographs of Damaged Parts	 Load JPG	☒
80	03/04/18 16:36	Photographs of Damaged Parts	Load JPG	☒

Assessment Reports			1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
81	03/04/18 16:36	Photographs of Damaged Parts	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	06/03/18 09:46	TP SJS2942A GIA REPORT	 Load PDF	
2	06/03/18 11:53	WORKSHOP DETAILS - SJS2942A	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18004373/WBS2
Date: 06/04/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: MSD/VCC/18-000004
Claimant Vehicle No: SJS2942A Insured Vehicle No: YP5940Z
Date of Loss: 17/01/2018 Nature of Claim: TP Claim No: MSC/V/18-000119

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJS2942A Engine No: L13A4085349
Make & Model: HONDA FIT, 1.3 G (A) Chassis No: GE61075936
Reg. Date: 07/08/2009 (Man. Year: 2008) Odometer: 0 km
Colour: Silver
Engine Capacity: 1339 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60R14 Rear Tyre Size: 185/60R14
Front Left Side: Pirelli 3 mm Rear Left Side: Pirelli 3 mm
Front Right Side: Pirelli 3 mm Rear Right Side: Pirelli 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 06/03/2018
Date Inspected: 07/03/2018 Inspected At: Motor Intel Automo
13 Kaki Bukit Road 4 #01-20
Singapore 417807
Estimated Period of Repair: 0.0 days

Adjuster: Teo Cheng Ming Wilson

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

4/6/2018

Adjuster Report

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,800.00 - \$7,800.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Apr 2018)
Parts:	144	HONDA FIT 1.3 G (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJS2942A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >