

22/03/2018

ASS. REC. BY:

REF:

CS3/MSH18004380/WB

Special Instruction:

Surveyor: Wilson

ASSIGNMENT (Office)

From (Person): Chhira Nyuk Rui of MSH Date/Time: 07032018 8:47am

Estimated Cost: Bill to:

OD / TD / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJS 5509Z Insured: SJH 2515H

at Workshop m/s Mutronic motor Tel: 9662 9356

of Blk 160 Sin ming Drive #03-16

Policy No: 78989098 QMX Claim No: 551433

Sum Insured: Excess:

Make of Veh: D.O.A. 05032018
(Client's Record)

CA / REV / REP. / REV 24 HRS Wp1

H.O.D. Endorsement:

Date/Time: 07032018 10am Person Contacted: Ray Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SJS 5509Z - CS/AWA15007543 / Rlvbdl DA: 300415
	SJH 2515H - Y
	Dismantle Part: 08032018
	After repair: 13-032018

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/03/2018 10:48
Date Of Accident	05/03/2018 08:30
Exact Location Of Accident	JALAN JURONG KECHIL
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJS5509Z
Insured/Policyholder	
Name Of Registered Owner	CHUA SHI QUAN, GABRIEL
NRIC No	S8833304G
Email Address	GABBCHUA@GMAIL.COM
Mobile Phone No	(LOCAL) +65-90469225
Alternative Phone No	OTHERS-90469225

Vehicle Particulars

Manufacturer	HONDA
Model	FIT 1.3G

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle?

NO

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A 80451030 QMX
Cover Note Number	

Driver

Name of Driver	CHUA SHI QUAN, GABRIEL
NRIC No	S8833304G
Date Of Birth	06/09/1988
Occupation	INDOOR
Date Of Driving Pass	13/06/2008
Driving Experience	9 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90469225
Fax Number	
Contact Number	OTHERS-90469225
EEmail Address	GABBCHUA@GMAIL.COM

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

(d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.

(e) the information so collected under (d) above may be shared / disclosed:

- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
- (ii) for complying with requirements under any regulations, laws or court orders.

05/03/18, 1030 am

05/03/18, 1030am

Poh Kwee Choo
S6840583A

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	06 Mar 2018		07 Mar 2018 08:47 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	MDM LIM BUAY GEK CYNTHIA, ID: S7736407B		
Main Claimant:	CHUA SHI QUAN, GABRIEL, ID: S8833304G		
Vehicle Reg. No.:	SJS5509Z	Date of Loss:	05/03/2018 08:00 - :59 [102 Months and 12 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 551433	Policy/Cover Note No.:	28989098QMX (Comprehensive) Coverage: 17/07/2017 - 29/07/2018
Vehicle Reg. No. (Insured):	SJH2515H	Policy No. (Claimant):	
		Excess:	S\$700.00
Repairer:	Motronic Motor Works (HQ) BLK 17 SIN MING IND. EST. SEC. A #01-69, 575675 Sin Ming - Tel: 6454 8418 / 9820 9599		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Teo Cheng Ming Wilson] ... [Imm.Advice due 08/03/2018]		
Adj Asg. Remarks:	Please contact MR RAY NG @ 9662 9356 to arrange for survey.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJS5509Z (551433)**
[SJH2515H]

TP

CHUA SHI QUAN, GABRIEL
Mar 5 2018 8:00AM
[MDM LIM BUAY GEK CYNTHIA]
Motronic Motor Works

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Letters/Correspondences

1 per page ▼

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	06/03/18 15:27	Non Reporting Letter to OI	1 Load HTM	

Photos/Images

3 per page ▼

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/04/18 18:39	General View	1 Load JPG	✓
2	05/04/18 18:39	General View	1 Load JPG	✓
3	05/04/18 18:39	General View	1 Load JPG	✓
4	05/04/18 18:39	General View	1 Load JPG	✓
5	05/04/18 18:39	General View	1 Load JPG	✓
6	05/04/18 18:39	General View	1 Load JPG	✓
7	05/04/18 18:39	General View	1 Load JPG	✓
8	05/04/18 18:39	General View	1 Load JPG	✓
9	05/04/18 18:39	General View	1 Load JPG	✓
10	05/04/18 18:39	General View	1 Load JPG	✓
11	05/04/18 18:39	General View	1 Load JPG	✓
12	05/04/18 18:39	General View	1 Load JPG	✓
13	05/04/18 18:39	General View	1 Load JPG	✓
14	05/04/18 18:39	General View	1 Load JPG	✓
15	05/04/18 18:39	General View	1 Load JPG	✓
16	05/04/18 18:39	General View	1 Load JPG	✓
17	05/04/18 18:39	General View	1 Load JPG	✓
18	05/04/18 18:39	General View	1 Load JPG	✓
19	05/04/18 18:39	General View	1 Load JPG	✓
20	05/04/18 18:39	General View	1 Load JPG	✓
21	05/04/18 18:39	General View	1 Load JPG	✓
22	06/04/18 14:36	Photographs of Damaged Parts	1 Load JPG	✓
23	06/04/18 14:36	Photographs of Damaged Parts	1 Load JPG	✓
24	06/04/18 14:36	Photographs of Damaged Parts	1 Load JPG	✓
25	06/04/18 14:36	Photographs of Damaged Parts	1 Load JPG	✓
26	06/04/18 14:36	Photographs of Damaged Parts	1 Load JPG	✓
27	06/04/18 14:36	Photographs of Damaged Parts	1 Load JPG	✓
28	06/04/18 14:36	Photographs of Damaged Parts	1 Load JPG	✓
29	06/04/18 14:36	Photographs of Damaged Parts	1 Load JPG	✓
30	06/04/18 14:36	Photographs of Damaged Parts	1 Load JPG	✓
31	06/04/18 14:36	Photographs of Damaged Parts	1 Load JPG	✓
32	06/04/18 14:36	Photographs of Damaged Parts	1 Load JPG	✓

Letters/Correspondences			1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
33	06/04/18 14:36	Photographs of Damaged Parts		Load JPG ✓
34	06/04/18 14:36	Photographs of Damaged Parts		Load JPG ✓
35	06/04/18 14:36	Photographs of Damaged Parts		Load JPG ✓
36	06/04/18 14:36	Photographs of Damaged Parts		Load JPG ✓
37	06/04/18 14:36	Photographs of Damaged Parts		Load JPG ✓
38	06/04/18 14:36	Photographs of Damaged Parts		Load JPG ✓
39	06/04/18 14:36	Photo After Spray		Load JPG ✓
40	06/04/18 14:36	Photo After Spray		Load JPG ✓
41	06/04/18 14:36	Photo After Spray		Load JPG ✓
42	06/04/18 14:36	Photo After Spray		Load JPG ✓
43	06/04/18 14:36	Photo After Spray		Load JPG ✓
Documentation			1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	06/03/18 15:26	TPD SJS5509Z GIA REPORT		Load PDF
2	07/03/18 08:41	TPD SJS5509Z - SURVEY LISTING & PRI		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18004380/WBS2
 Date: 09/04/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 28989098QMX
 Claimant Vehicle No: SJS5509Z Insured Vehicle No: SJH2515H
 Date of Loss: 05/03/2018 Nature of Claim: TP Claim No: 551433

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJS5509Z Engine No: L13A4229150
 Make & Model: HONDA FIT, 1.3 G (A) Chassis No: GE61208932
 Reg. Date: 21/08/2009 (Man. Year: 2009) Odometer: 108256 km
 Colour: Black
 Engine Capacity: 1339 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55R15 Rear Tyre Size: 195/55R15
 Front Left Side: Pirelli 4 mm Rear Left Side: Pirelli 4 mm
 Front Right Side: Pirelli 4 mm Rear Right Side: Pirelli 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 07/03/2018
 Date Inspected: 07/03/2018 Inspected At: 160 SIN MING DRIVE #03-16
 Estimated Period of Repair: 0.0 days Repairer: Motronic Motor Works (HQ)
 BLK 17 SIN MING IND. EST. SEC. A #01-69
 Singapore 575675

Adjuster: Teo Cheng Ming Wilson

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

4/9/2018

Adjuster Report

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,800.00 - \$5,500.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Apr 2018)
Parts:	144	HONDA FIT 1.3 G (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJS5509Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >