

ASS. REC. BY:

REF: CS/GAT18004383/Gvd34 Special Instruction:

Surveyor: GO

ASSIGNMENT (Office)

From (Person): Rachel Tan

of GAI

Date/Time: 6/3/18 @ 5:07pm

Estimated Cost: _____ Bill to: _____

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKD 7808P

Insured: SLJ 2650R

at Workshop m/s Kan fook Sing

Tel: 6747 9560

of 61 Defu Lane 12

Policy No: _____ Claim No: CLMOMVP000000588

Sum Insured: _____ Excess: _____

Make of Veh: _____ (Client's Record) D.O.A. 23/02/2018

CA / REV / REP. / REV 24 HRS ^{1up?} H.O.D. Endorsement: _____

Date/Time: 10:27am @ 7/3/18 Person Contacted: Margaret Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SKD 7808P - X
	SLJ 2650R - CS/FCI18003693/Utd3 D.O.A: 23/2/18
<u>9/3/18</u>	Email preli revised to Rachel
<u>21/5/18</u>	LS \$ 6250 confirmed by email (Reel 2180, 269)

Survey Department Check List (Case Handler)

Reference No. : CS | GAI | 8004383 | GVCB
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all information created by the assignment team are ACCURATE.

(1) Office Assign Form		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No				
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form		Y-Date	N-Date	Y-Date	N-Date
C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)		Y-Date	N-Date	Y-Date	N-Date
C	Damaged Vehicle Photographs Uploaded	✓			

(3) Workshop Estimate/Assignment Form		Y-Date	N-Date	Y-Date	N-Date
N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)		Y-Date	N-Date	Y-Date	N-Date
C	Resurvey photo Uploaded	✓			

Check By: VERON 21/5/18
Case Handler Date

*C: Critical *N: Non-Critical



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

GREAT AMERICAN INSURANCE COMPANY

Ref : CS/GAI18004383/Gvd3

3 TEMASEK AVENUE
#16-01 CENTENNIAL TOWER
SINGAPORE 039190

Date : 07-03-2018



Code : GAI

1 Policy Particulars - THIRD PARTY CLAIM

Insured Veh.	SLJ 2650R	Veh. Inspected	SKD 7808P
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	RACHEL TAN	Assign Date	07/03/2018

2 Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3 Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4 Description of Damages

--	--

5 General Information

Accident Date	23/02/2018	Inspection Date	07/03/2018
Survey held at	KAN FOOK SING MOTOR WORKSHOP 61 DEFU LANE 12 SINGAPORE 539147		

5a Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Veron Chen (LKKAuto)

From: Tan, Rachel <Rachel.Tan@sg.gaig.com>
Sent: Tuesday, 17 April 2018 9:01 AM
To: Veron Chen (LKKAuto)
Subject: RE: SKD7808P - 3rd party survey v SLJ2650R (GA) on 23 Feb 2018

CLMOMVP000000588

From: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Sent: Tuesday, April 17, 2018 8:29 AM
To: Tan, Rachel <Rachel.Tan@sg.gaig.com>
Cc: SUR <sur@lkkauto.com>
Subject: [External] FW: SKD7808P - 3rd party survey v SLJ2650R (GA) on 23 Feb 2018

Dear Rachel,

Please provide us the claim number.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)
Sent: Friday, 9 March 2018 10:12 AM
To: 'Tan, Rachel' <Rachel.Tan@sg.gaig.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: SKD7808P - 3rd party survey v SLJ2650R (GA) on 23 Feb 2018

Dear Rachel,

Enclosed preliminary revised of vehicle SKD 7808P
Date of survey: 7/3/2018
Number of days:4 days

Kindly provides us the claim number.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 7 March 2018 10:29 AM
To: 'Tan, Rachel' <Rachel.Tan@sg.gaig.com>; assignments <assignments@lkkauto.com>
Cc: assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: SKD7808P - 3rd party survey v SLJ2650R (GA) on 23 Feb 2018

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan, Rachel [<mailto:Rachel.Tan@sg.gaig.com>]
Sent: Tuesday, 6 March 2018 5:07 PM
To: mttan <mttan@kanfs.net>
Cc: LKK Assignments <assignments@lkkauto.com>
Subject: RE: SKD7808P - 3rd party survey v SLJ2650R (GA) on 23 Feb 2018

Without Prejudice

Dear Mr Tan

We will arrange for LKK to conduct Pre-repair inspection.

Regards

Rachel Tan

Executive, Motor Claims, Great American Insurance Company

Tel: 6804 7846

From: mttan [<mailto:mttan@kanfs.net>]
Sent: Tuesday, March 6, 2018 2:44 PM
To: Tan, Rachel <Rachel.Tan@sg.gaig.com>
Subject: SKD7808P - 3rd party survey

Dear Rachel

Kindly arrange for a 3rd party survey for vehicle SKD7808P at 61 Defu Lane 12 SE539147

Documents attached

Detail as follow

our client : SKD7808P

your insured : SLJ2650R

date/time loss : 23/02/18@0650hrs

Thank you

Tan
KFS
67479560

--

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 9 March 2018 10:12 AM
To: 'Tan, Rachel'
Cc: SUR
Subject: RE: SKD7808P - 3rd party survey v SLJ2650R (GA) on 23 Feb 2018
Attachments: SKD 7808P PRELI REVISED.pdf

Dear Rachel,

Enclosed preliminary revised of vehicle SKD 7808P
Date of survey: 7/3/2018
Number of days:4 days

Kindly provides us the claim number.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 7 March 2018 10:29 AM
To: 'Tan, Rachel' <Rachel.Tan@sg.gaig.com>; assignments <assignments@lkkauto.com>
Cc: assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: SKD7808P - 3rd party survey v SLJ2650R (GA) on 23 Feb 2018

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan, Rachel [<mailto:Rachel.Tan@sg.gaig.com>]
Sent: Tuesday, 6 March 2018 5:07 PM
To: mttan <mttan@kanfs.net>
Cc: LKK Assignments <assignments@lkkauto.com>
Subject: RE: SKD7808P - 3rd party survey v SLJ2650R (GA) on 23 Feb 2018

Without Prejudice

Dear Mr Tan

We will arrange for LKK to conduct Pre-repair inspection.

Regards

Rachel Tan

Executive, Motor Claims, Great American Insurance Company

Tel: 6804 7846

From: mttan [mailto:mttan@kanfs.net]

Sent: Tuesday, March 6, 2018 2:44 PM

To: Tan, Rachel <Rachel.Tan@sg.gaig.com>

Subject: SKD7808P - 3rd party survey

Dear Rachel

Kindly arrange for a 3rd party survey for vehicle SKD7808P at 61 Defu Lane 12 SE539147

Documents attached

Detail as follow

our client : SKD7808P

your insured : SLJ2650R

date/time loss : 23/02/18@0650hrs

Thank you

Tan

KFS

67479560

--

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.



Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: PLEASE ADVISED
Our ref: CS/GAI18004383/Gvd3

Date:9/3/2018

The Motor Claims Department
M/s GREAT AMERICAN INSURANCE COMPANY

WITHOUT PREJUDICE

Dear Sir/Madam,


PRELIMINARY ADVICE OF VEHICLE NO.SKD 7808P

We thank you for your instruction on 6/3/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 7/3/2018 at the premises of M/s KAN FOOK SING MOTOR WORKSHOP and have the following to report-

Workshop Estimate Amount	: S\$	<u>8,430.00</u>
Revised Estimate Amount	: S\$	<u>7,870.00</u>
"Check" Items Amount	: S\$	<u> </u>
Market Value	: S\$	<u> </u>
LTA Reimbursement Value	: S\$	<u> </u>
Nett Value	: S\$	<u> </u>

Description of Damage:
The vehicle sustained damages at the front o/s portion.



Comments/Present Status:
Damages Consistent

Yours faithfully,

XING GUO QIANG (HP 8288 0282)
Automobile Assessor

Catherine Chong (LKK Auto)

From: Tan, Rachel <Rachel.Tan@sg.gaig.com>
Sent: Tuesday, 6 March, 2018 5:07 PM
To: mttan
Cc: LKK Assignments
Subject: RE: SKD7808P - 3rd party survey v SLJ2650R (GA) on 23 Feb 2018

Without Prejudice

Dear Mr Tan

We will arrange for LKK to conduct Pre-repair inspection.

Regards
Rachel Tan
Executive, Motor Claims, Great American Insurance Company
Tel: 6804 7846

From: mttan [mailto:mttan@kanfs.net]
Sent: Tuesday, March 6, 2018 2:44 PM
To: Tan, Rachel <Rachel.Tan@sg.gaig.com>
Subject: SKD7808P - 3rd party survey

Dear Rachel

Kindly arrange for a 3rd party survey for vehicle SKD7808P at 61 Defu Lane 12 SE539147

Documents attached

Detail as follow

our client : SKD7808P
your insured : SLJ2650R
date/time loss : 23/02/18@0650hrs

Thank you

Tan
KFS
67479560

--

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

Enquire Transfer Fee

Vehicle Details

Vehicle No.:	SKD7808P
Vehicle Type:	P10 - Passenger Motor Car
Vehicle Attachment 1:	With Sun Roof
Vehicle Scheme:	Normal
Vehicle Make:	AUDI
Vehicle Model:	A8L 4.2 FSI QU (PSR+LED)
Chassis No.:	WAUZZZ4HXBN014346
Propellant:	Petrol
Engine No.:	CDR008073
Engine Capacity:	4163 cc
Maximum Power Output:	273.0 kW (366 bhp)
Maximum Laden Weight:	2535 kg
Unladen Weight:	1885 kg
Year Of Manufacture:	2011
Original Registration Date:	17 Mar 2011
Lifespan Expiry Date:	-
COE Category:	B - Car (1601cc & above)
Quota Premium:	\$72,001.00
COE Expiry Date:	16 Mar 2021
Road Tax Expiry Date:	16 Mar 2018
PARF Eligibility Expiry Date:	16 Mar 2021
Inspection Due Date:	16 Mar 2018
Intended Transfer Date:	08 Mar 2018
CO2 Emission:	-
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-

The current road tax expiry is 16 Mar 2018. You may renew the road tax from 17 Dec 2017 with all pre-requisite(s) fulfilled. If the road tax is renewed after 16 Mar 2018, late renewal fee(s) will be imposed. Please use [Enquire Road Tax Payable](#) to check on the late fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable (From 17 Mar 2018 to 16 Sep 2018)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/02/2018 13:59
Date Of Accident	23/02/2018 06:50
Exact Location Of Accident	JUNCTION OF TAMPINES AVE 5 & AVE 8
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKD7808P
Insured/Policyholder	
Name Of Registered Owner	LIEW KHIM HWA
NRIC No	S1698492B
Email Address	KHIMHWA65@GMAIL.COM
Mobile Phone No	(LOCAL) +65-92378270
Alternative Phone No	OTHERS-92378270

Vehicle Particulars

Manufacturer	AUDI
Model	A8L 4.2 FSI QU (PSR+LED)
Exact Purpose for which vehicle was being used at time of accident	PVT USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN1647501701
Cover Note Number	17/9/17-16/9/18

Driver

Name of Driver	LIEW KHIM HWA
NRIC No	S1698492B
Date Of Birth	07/04/1965
Occupation	INDOOR
Date Of Driving Pass	19/01/1983
Driving Experience	35 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-92378270
Fax Number	
Contact Number	OTHERS-92378270
E Mail Address	KHIMHWA65@GMAIL.COM

Address BLK 941 TAMPINES AVE 5 #10-217
 Postcode 520941
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident SIDE SWIPE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance?
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name WOODLANDS EAST N.P.C
 Police Station Address ROAD: 3 WOODLANDS DRIVE 63 , POSTCODE: 737890 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: - FAX NO:
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER POLICE REPORT

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLJ2650R
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver LEE CHUN LING CHERYL
 NRIC/Passport Number S9019299Z
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SHA4669U
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category TAXI
Name of Driver SIANG KEE SENG
NRIC/Passport Number S0704709F
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SHD3393E
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category TAXI
Name of Driver YEO BOK CHUAN JAMES
NRIC/Passport Number S1333459E
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

VEHICLE NO.: SKD 7808 P
INSURER : CHINA MARINE
DATE & TIME: 23/02/18 6650 HET

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/are be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be based outside of Singapore, for one or more of the above Purposes;
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders;


[Signature]
23-2-18
Policyholder's Signature
Date & Time:

[Signature]
Driver's Signature
(If driver is not the policy holder)
Date & Time:

[Signature] 23-2-18
Reporting Centre Personnel's Signature
Name: [Signature]
NIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Repair by own workshop :
 KAN FOOK SING MOTOR WORK
 61 DE FU LANE 17.

APPROVED BY POLICE REPORT

Note : Please note that your insurer may have 14 days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time: 23-2-18

Driver's Signature
 (If driver is not the policyholder)
 Date & Time

Reporting Centre Personnel's Signature
 Name: [Signature]
 NFIC/RN No.:

Sketches described in form of: Claim Own Policy Claim Third Party Reporting Only
 Claim OD at other workshop

POLICE REPORT



T/20180223/2047

1 of 4

Police Station Of Origin:
Woodlands East N.P.C
3 Woodlands Drive 63 SINGAPORE 737890
Tel No: 1800 7679999

Report No: T/20180223/2047

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 23/02/2018 12.24	Video Report No G/20180223/0084	Station Diary No 98
Name of Informant LIEW KHIM HWA		Address APT BLK 941 TAMPINES AVENUE 5 #10-217 SINGAPORE 520941
ID Type / ID No NRIC NO / S16904023	Contact No Home/Office	Mobile 92378270
Nationality SINGAPORE CITIZEN	Email	
Sex Male	Age 52	Date of Birth 01/01/1966
Race Chinese	Type of Informant Driver	Institution / School Name
Occupation Company director	Language	Date of Expiry
Driving Licence Information Class: 3,4		

Type of Accident	Non Injury Attended by Police	Drink Drives: No	Date/Time of Accident: 23/02/2018 06.50	Type of Location X-Junction
Location: Along Road 1 TAMPINES AVENUE 5				
JUNCTION OF TAMPINES AVENUE 5 AND AVENUE B				
Weather Clear	Road Surface: Dry	Road Speed Limit		
Traffic Flow: Dual Carriage Way	Traffic Control: Traffic Light - Working	Traffic Volume Moderate		
Type of Collision: Between Moving Vehicles - Side Swipe - Opposite Direction			Anyone conveyed by ambulance: No	

SHA4689U	Car		HYUNDAI SONATA	Blue	Slightly Damaged	0
SHD3393F	Car		HYUNDAI	Blue	Seriously Damaged	0
SKD7808P	Car	AUDI	A&L 4 2 FSI QU (PSR+LED)	Beige	Slightly Damaged	0
SLJ2650R	Car		TOYOTA HARRIER	Brown	Seriously Damaged	0

POLICE REPORT



120180223/2047

2 of 4

Police Station Of Origin:
Woodlands East N.P.C.
3 Woodlands Drive #3 SINGAPORE 737890
Tel No: 1800-7879695

Report No: 120180223/2047

CONTINUATION OF REPORT

SKD7808P	CHINA TAIPIING INSURANCE (SINGAPORE) PTE. LTD	DMPCSN:16475017-01	17/09/2017	16/09/2018
----------	---	--------------------	------------	------------

Any Pedestrian Involved: No		Use of Pedestrian Crossing: NA		
No. of Pedestrians Involved: NIL				
Name	HEM HWA	ID No	S1696492B	
Related Vehicle	SKD7808P (Car)	Contact No	97378270	
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3, 4 Date of Expiry: NIL	
Date Treatment	NIL	Date Discharge	NIL	
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL	
Name	LEE CHUN LING CHERYL	ID No	S9019299Z	
Related Vehicle	SHD3393E (Car)	Contact No	97401718	
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL	
Date Treatment	NIL	Date Discharge	NIL	
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL	

Brief Details.

On the 23/02/18 at about 0655 hrs I was along Tampines Ave 5 with my car (SKD7808P), at the junction of Tampines Ave 8. The traffic light was red and I was waiting before the stop line on the second lane.

Along Tampines Ave 8, there were vehicles making a right turn into Tampines Ave 5. All of the sudden, a car (SLJ2630R) that had swiped a taxi (SH44669U) on its left after making a right turn. Due to the fact the driver of (SLJ2630R) reacted by turning to the right and collided into the road barrier and went of over to the opposite side of the road. The car then collided onto the left side of another taxi (SHD3393E) that was behind my car. However, when the said car collided into the barrier, a part of the barrier hit onto the right side of your front bumper.

All the drivers of the vehicles involved stopped and got down to make a check. All drivers including myself did not suffer any visible injuries.

POLICE REPORT



T/20160223/2047

Police Station Of Origin
Woodlands East N.P.C
3 Woodlands Drive 61 SINGAPORE 737890
Tel No. 1800-7678999

3 of 4
Report No. T/20160223/2047

CONTINUATION OF REPORT

My car suffered damages on the front right bumper having dents and scratches. (SLJ2650R) suffered serious damages on the front of the car due to collisions. (SHA4669U) suffered slight damages on the right side of the taxi due to the side swipe. (SHD3393E) suffered damages on the right side of vehicle having dents due to the collision of the said car.

I exchanged particulars with the driver of (SLJ2650R) and took photos of the whole incident. Traffic Police was activated at scene. The Traffic Police officer then took down the particulars of the drivers involved. The officer then instructed me to lodge a traffic accident report.

IO Lim Hong Lee, Tel 65476433

POLICE REPORT



Police Station Of Origin
Woodlands East N.P.C
3 Woodlands Drive 63 SINGAPORE 737890
Tel No: 1800-7679999



T/20180223/2047

4 of 4



Report No: T/20180223/2047

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference

Signature Of Officer Recording The Report J/ MUHAMMAD CAHY BIN AHMAD  Signature	SN 130 Signature Of Informant 
Signature Of Informant Not applicable	Date/Time 23/02/2018 12:24
Officer In Charge Of Case TP / GIT / Staff Sgt MOHAMED HUSNUL TAUFIQ BIN MD YUSOF Contact No: 65478358 Authentication Stamp No: 68	Classification Of Case



簡福星噴多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquater: 61 Defu Lane 12 Singapore 539147
 Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428
 E-mail: ryan@kanfs.net/ patricia@kanfs.net
 Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883
 Tel: (65) 6481 5150 Fax: (65) 6481 8683

GREAT AMERICAN INSURANCE COMPANY
 3 TEMASEK AVENUE
 #16-01 CENTENNIAL TOWER
 SINGAPORE 039190

VEHICLE NO. : SKD7808P
 ACCIDENT DATE : 23-02-2018 06:50
 THIRD PARTY REF. : SLJ2650R

ATTN: GREAT AMERICAN INSURANCE COMPANY

ESTIMATE COST OF REPAIR TO VEICLE SKD7808P AUDI A8L 4.2 FSI QU (PSR+LED)

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after ~~spray painting~~ : 06-03-2018
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	1	FRONT HEADLAMP RH / Cut	3850.00
2	1	FRONT FENDER RH / Blc	600.00
3	1	FRONT BUMPER / Re	1200.00
4	10	FRONT BUMPER CLIP@\$5.00 / Mc	50.00
			<hr/>
			5,700.00
			<hr/>
ADD 20 %			1,140.00
			<hr/>
TOTAL (A)			6,840.00

LABOUR CHARGES

1	1	TO CHECK WIRING SYSTEM	30.00 ✓
2	1	TO REPROGRAMME HEADLAMP	300.00 200
3	1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	580.00 400
4	1	SPRAYPAINTING CHARGES	680.00 400

4 Days.
 part by part.
 before part photos.
 Come quick. 82880282
 07/3/18

TOTAL (D)	1,590.00
ESTIMATE TOTAL	8,430.00



簡福星嘍哆工廠

KAN FOOK SING MOTOR WORKSHOP

Headquater: 61 Defu Lane 12 Singapore 539147
 Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428
 E-mail: ryan@kanfs.net/ patricia@kanfs.net
 Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883
 Tel: (65) 6481 5150 Fax: (65) 6481 8683

GREAT AMERICAN INSURANCE COMPANY
 3 TEMASEK AVENUE
 #16-01 CENTENNIAL TOWER
 SINGAPORE 039190

DATE : 06-03-2018

VEHICLE NO. : SKD7808P
 ACCIDENT DATE : 23-02-2018 06:50
 THIRD PARTY REF. : SLJ2650R

ATTN: GREAT AMERICAN INSURANCE COMPANY

ESTIMATE COST OF REPAIR TO VEHICLE SKD7808P AUDI A8L 4.2 FSI QU (PSR+LED)

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	1	FRONT HEADLAMP RH / <i>Cut</i>	3850.00
2	1	FRONT FENDER RH / <i>huc</i>	600.00
3	1	FRONT BUMPER / <i>pe</i>	1200.00
4	10	FRONT BUMPER CLIP@\$5.00 / <i>huc</i>	50.00
			<hr/>
			5,700.00
			<hr/>
ADD 20 %			1,140.00
TOTAL (A)			6,840.00

LABOUR CHARGES

1	1	TO CHECK WIRING SYSTEM	30.00 ✓
2	1	TO REPROGRAMME HEADLAMP	300.00 <i>200</i>
3	1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	580.00 <i>400</i>
4	1	SPRAYPAINTING CHARGES	680.00 <i>400</i>
			<hr/>
TOTAL (D)			1,590.00 <i>1030</i>
ESTIMATE TOTAL			8,430.00

4 Days.

part by part.

before part photos.

Case Ref. 82880282

07/3/18

Parts \$ 6840.

Labour \$ 1030

\$ 7870

- 20% \$ 1574

\$ 6296.

2/3 \$ 6250/2

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Monday, 21 May 2018 10:17 AM
To: 'mttan'; Guo Qiang (LKKAuto)
Cc: SUR
Subject: RE: SKD7808P - Finalize

Dear Mr Tan,

WITHOUT PREJUDICE

Confirmed Lump sum \$6250.00 @ 4 working days.

Final invoice and all supporting documents sent over to GREAT AMERICAN

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: mttan [mailto:mttan@kanfs.net]
Sent: Wednesday, 25 April 2018 10:09 AM
To: Guo Qiang (LKKAuto) <GuoQiang@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: Fw: SKD7808P - Finalize

Kindly finalize

Thank you

Tan
KFS
67479560

----- Forwarded Message -----

From: "mttan" <mttan@kanfs.net>
To: "Guo Qiang (LKK)" <guoqiang@lkkauto.com>
Cc: "LKK (survey)" <sur@lkkauto.com>
Sent: Sat, 14 Apr 2018 14:45:03 +0800
Subject: Fw: SKD7808P - Finalize

Hi Guo Qiang

Kindly finalise

Thank you

Tan
KFS
67479560

----- Forwarded Message -----

From:"mttan" <mttan@kanfs.net>
To:"Guo Qiang (LKK)" <guoqiang@lkkauto.com>
Sent:Wed, 14 Mar 2018 15:55:03 +0800
Subject:SKD7808P - Finalize

Hi Guo Qiang

Photo and finalize attached

Propose lump sum \$6250-00

Kindly check and revert

Thank you

Tan
KFS
67479560

--

----- End of Forwarded Message -----

--

----- End of Forwarded Message -----

--

Veron Chen (LKKAuto)

From: Nora Khai <nora.khai@premiumauto.com.sg>
Sent: Friday, 18 May 2018 6:01 PM
To: Veron Chen (LKKAuto)
Subject: RE: CHECK PARTS PRICES

Dear Veron,

- 1 FRONT HEADLAMP RH - 9474
- 2 FRONT FENDER RH - 1613
- 3 FRONT BUMPER – 2902

Thank you.

Best regards

Norazima Khairuddin
Claims Manager


Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9827 f. +65 6841 1183

e. nora.khai@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]

Sent: 18 May, 2018 5:41 PM

To: Nora Khai

Subject: RE: CHECK PARTS PRICES

Dear Nora,

- 4 FRONT HEADLAMP RH
- 5 FRONT FENDER RH
- 6 FRONT BUMPER

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Nora Khai [mailto:nora.khai@premiumauto.com.sg]

Sent: Friday, 18 May 2018 5:34 PM

To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>

Subject: RE: CHECK PARTS PRICES

Hi Veron,

Do you have the list?

Thank you.

Best Regards,

Norazima Khairuddin

Claims Manager


Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9827 f. +65 6841 1183

e. nora.khai@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]

Sent: 18 May, 2018 4:31 PM

To: Nora Khai

Subject: FW: CHECK PARTS PRICES

Dear Nora,

Kindly assist to check parts prices

VEHICLE NO SKD 7808P
MODEL: AUDI A8L
YEAR :2011, 4163 cc
CHASSIS NO: WAUZZZ4HXBN014346

Many thanks.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)
Sent: Wednesday, 9 May 2018 2:22 PM
To: 'Nora Khai' <nora.khai@premiumauto.com.sg>
Subject: CHECK PARTS PRICES

Dear Nora,

Kindly assist to check parts prices

VEHICLE NO SKD 7808P
MODEL: AUDI A8L
YEAR :2011, 4163 cc
CHASSIS NO: WAUZZZ4HXBN014346

Many thanks.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

GREAT AMERICAN INSURANCE COMPANY

Ref : CS/GAI18004383/Gvd3e2

3 TEMASEK AVENUE
#16-01 CENTENNIAL TOWER
SINGAPORE 039190

Date : 25-05-2018



Code : GAI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLJ 2650R	Veh. Inspected	SKD 7808P
Policy No.		Coverage (\$)	0.00
Claim No.	CLMOMVP000000588	Excess (\$)	0.00
Assign From	RACHEL TAN	Assign Date	06/03/2018

2. Vehicle Particulars & Condition

Make & Model	AUDI A8L	c.c	4163
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	WAUZZZ4HXBN014346	Colour	BROWN
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	265/40 R20	GOODYEAR	6 mm
L/H Front Tyre	265/40 R20	GOODYEAR	6 mm
R/H Rear Tyre	265/40 R20	GOODYEAR	6 mm
L/H Rear Tyre	265/40 R20	GOODYEAR	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	23/02/2018	Inspection Date	07/03/2018
Survey held at	KAN FOOK SING MOTOR WORKSHOP 61 DEFU LANE 12 SINGAPORE 539147		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKD 7808P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT HEADLAMP RH (WCP)	CUT	3,850.00	3,850.00
1	FRONT FENDER RH (WCP)	BUCKLED	600.00	600.00
1	FRONT BUMPER (WCP)	DEFORMED	1,200.00	1,200.00
10	FRONT BUMPER CLIP @\$5.00 (WCP)	NECESSARY	50.00	50.00
	COST PLUS 20%		1,140.00	1,140.00
			6,840.00	6,840.00
	LABOUR			
	TO CHECK WIRING SYSTEM.		30.00	30.00
	TO REPROGRAMME HEADLAMP		300.00	200.00
	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS.		580.00	400.00
	SPRAY PAINTING CHARGES.		680.00	400.00
			1,590.00	1,030.00
	GRAND TOTAL		8,430.00	7,870.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,250.00

Report Ref No. CS/GAI18004383/Gvd3e2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.