

22/03/2001

ASS. REC. BY:

REF: CS/FCI 18004389/Tird3/

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

Ang Yin Min

of

FCI

Date/Time:

23/2/18 @ 5:06pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLP 3374A

Insured:

SHC 0754Y

at Workshop m/s

Tan Chong Motor

Tel:

64667711

of

913 Bkt Timah Rd

Policy No:

Claim No:

D18001556MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

20/2/2018

CA / REV / REP. / REV 24 HRS / wp

H.O.D. Endorsement:

Date/Time:

4:11pm @ 6/3/18

Person Contacted:

Lawrence

Vehicle IN / OUT

Date/Time

Action/Instruction

(✓)

Estimate

SLP 3374A-X

SHC 754Y-CS/QW09024899/Rcr1

D.O.A: 18/10/2009

22/03/2001

ASS. REC. BY:

REF: CS/FCI 18004389/Tird30

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): Ang Yin Min

of

FCI

Date/Time:

23/2/18 @ 5:06pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLP 3374A

Insured:

SHC 0754Y

at Workshop m/s

Tan Chong Motor

Tel:

64667711

of

913 Bkt Timah Rd

Policy No:

Claim No:

D18001556MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

20/2/2018

CA / REV / REP. / REV 24 HRS / wp

H.O.D. Endorsement:

Date/Time: 4:11pm @ 6/3/18

Person Contacted:

Lawrence

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLP 3374A-X
	SHC 754Y-CS/QW09024899/Rcr
	D.O.A: 18/10/2009

Signature: Tayfer

REF: FCI

ASSIGNMENT

From: _____ Date: 12.03.2018

Estimated Cost: _____

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV

To Inspection Vehicle No: SLP 3374A
at Workshop m/s Tan Chong
of 911 Bukit Timah Rd

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: Lawrence

4pm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLP 3374A Yr Regn: 2016 Feb.

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan Roshan c.c. 1197

Colour: Maroon A/C: Insured / Std / NI / NA

Sp. Reading: 55125 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: SJN FEA J1141583267

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: 6 F: 215/60R17
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Comphentel

Front 6 mm Rear 6 mm
R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 12/3/18 P 1620

Survey held at Tan Chong Bukit Timah

Des. of Damages: Frt / Rear / O/S / NIS / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Final Sig @ 2987.02 (Red. 2175.60, 422)

RECEIVED 16 OCT 2018

Date/Time: File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time: File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: -

Survey Fee:

Transportation:

) S + RS \$

) Photos

) Others

TOTAL

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Report Format: TP

Lump Sum / I.B.I: \$ 2987.02

140

50

38

228



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18004389/T1rd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 07-03-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 754Y	Veh. Inspected	SLP 3374A
Policy No.		Coverage (\$)	0.00
Claim No.	D18001556MFSH	Excess (\$)	0.00
Assign From	CWS (AUNG YIN MIN)	Assign Date	07/03/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	20/02/2018	Inspection Date
Survey held at	TAN CHONG MOTOR SALES PTE LTD 911, BUKIT TIMAH RD, SINGAPORE 589623.	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

MOTOR SURVEY ASSIGNMENT

Date	22-02-2018	Our Ref No. D18001556MFSH
Accident Date	20-02-2018	Claim Type. Third Party
Insured Vehicle	SHC0754Y	Third Party Vehicle. SLP3374A
Survey Location	913 BUKIT TIMAH ROAD	
Contact Person.	LAWRENCE TEO	
Contact No.	64667711/ 67038914	Fax No. 64697472
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TAN CHONG MOTOR SALES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	AUNGYM	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/235246)



PRI Documents



Close



PRI Header Details

Claim No	D18001556MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & TAN CHOI
Workshop Name	TAN CHONG MOTOR SALES PTE LTD (Contact Person : LAWRENCE TEO)	Survey Location & Contact Details	913 BUKIT TIMAH ROAD Mobile: 67038914 , Phone: 64667711 , Fax: 6469747; EmailId: LAWRENCETEO@TANCHONG.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHC0754Y	TP Vehicle No	SLP3374A
PRI Recieved Date	23-02-2018 04:09:37 PM	Surveyor Appointed Date	23-02-2018 05:06:16 PM	Surveyor Accept Date	07-03-2018 1

Survey Report Upload

Surveyor Inspection Date *:	<input type="text"/>	Surveyor Report Date	07-03-2018	Upload Survey Report *:	<input type="button" value="Choose File"/>
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	<input type="text" value="Please Select Make"/>	Model	<input type="text" value="Please Select Model"/>	Year	<input type="text" value="Select Year"/>
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6663E
Vehicle Details	
Vehicle No.:	SLP3374A
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Oct 2018
Vehicle Make:	NISSAN
Vehicle Model:	QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR
Primary Colour:	Purple
Manufacturing Year:	2015
Engine No.:	HRA2233358A
Chassis No.:	SJNFEAJ11U1583267
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$18,454.00
Original Registration Date:	24 Feb 2016
First Registration Date:	24 Feb 2016
Transfer Count:	1
Actual ARF Paid:	\$13,454.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Feb 2026
PARF Rebate Amount:	\$10,090.00
Intended COE Rebate Details	
COE Expiry Date:	23 Feb 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$43,000.00
COE Rebate Amount:	\$31,622.00
Total Rebate Amount:	\$41,712.00

The information contained herein is correct as at 16 Oct 2018

OK

Somp

S/C

MTC318025228 / Tan Chong Motor Sales Pte Ltd - Bukit Timah
 ENTRY DATE & TIME: 21/02/2018 16:15
 SUBMITTED BY: Nuraizah Binte Osman

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	21/02/2018 16:15
Date Of Accident	20/02/2018 20:50
Exact Location Of Accident	CARPARK BLK 190 LOR 6 TOA PAYOH
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLP3374A
Insured/Policyholder	
Name Of Registered Owner	AZHARIE BIN MOHAMED MUDAKIR
NRIC No	S7436663E
Email Address	AZHARIE.MUDAKIR@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96901190
Alternative Phone No	OTHERS-96901190
Vehicle Particulars	
Manufacturer	NISSAN
Model	QASHQAI-1.2 DIG-T (J11) (A)
Exact Purpose for which vehicle was being used at time of accident	PERSONAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D17MTPV01009804
Cover Note Number	
Driver	
Name of Driver	AZHARIE BIN MOHAMED MUDAKIR
NRIC No	S7436663E
Date Of Birth	09/11/1974
Occupation	INDOOR
Date Of Driving Pass	06/12/1994
Driving Experience	23 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96901190
Fax Number	
Contact Number	OTHERS-96901190
EMail Address	AZHARIE.MUDAKIR@GMAIL.COM

Address	BLK 139B LORONG 1 TOA PAYOH #04-52
Postcode	312139
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PERSONAL

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC754Y
Vehicle Make/Model/Colour	HYUNDAI
Details Of Properties	FRONT BUMPER AND NUMBER PLATE
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	


SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time: 21/02/2018
@ 1600hrs.

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: NURA NAH OSMAN
NRIC/FIN No.:

SKEETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 20th February 2018 at about 20:50hrs, I was driving my vehicle SLP3374A behind Blk. 190 Lor 6 Tua Paoh in the public carpark. As I passed an intersection just behind Blk. 178 Tua Paoh Central, I felt a knock on my left rear side. I then proceeded to stop and noted that a taxi SHC754Y had knocked onto my left rear side of my car. My car left rear side suffered scratches and the left rear tyre guard came off. There were also scratches on the rims of my left rear tyre. The taxi, a Hyundai i40 which was equipped with a dashboard camera broke its front ^{number} plate upon impact and suffered scratches to its front bumper.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

21/02/2018

@160ams

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name: NURANAH OSMAN

NRIC/FIN No.:

Certificate of Insurance**MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)**

Cert No./Policy No. : D17MTPV01009804
Insured : AZHARIE BIN MOHAMED MUDAKIR
Motor Car (Registration No.) : SLP3374A
Cover : Comprehensive - ExcelDrive PRESTIGE
Policy Commencement Date : 24 JUNE 2017 00:00
Policy Expiry Date : 23 JUNE 2018 23:59
Maximum Liability (Section I) : Market value at time of loss
Excess* : \$400 - Section I
(Waived up to S\$1,000 if accident repair is done at ExcelDrive Workshops for the first claim per policy year)
Voluntary Excess* : Buy Up : \$500 - Section I
Windscreen Excess* : S\$100.00 - Waived if Repair at ExcelDrive Workshop
Loss of Use : Per Policy Schedule
* Subject to GST wherever applicable

Persons or Classes of Persons entitled to drive*

1. The Insured.
2. Any other person who is driving on the Insured's order or with his permission.
3. In the event of the death of the insured,
 - a. any member of the insured's family, or a paid driver who has been driving the Motor Car during the life of the insured and permission to drive had not been withdrawn prior to the death of the insured; and
 - b. any other person who has been given permission to drive the Motor Car prior to the death and such permission had not been withdrawn by the Insured.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Car or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Car. And provided further that the Motor Car is registered under the Road Traffic Act (Chapter 276) and its registration under the Road Traffic Act (Chapter 276) has not been cancelled at the time of the accident, loss or damage.

Limitations As To Use

Use only for social, domestic and pleasure purpose and for the Insured's business. The Policy does not cover use for hire or reward, racing, pace-making, speed testing, reliability trial, the carriage of goods other than samples in connection with any trade or business or use for any purposes in connection with the Motor Trade.


ExcelDrive Workshops and Accident Reporting

It is a condition precedent to liability that the Insured shall call at the Company's Accident Reporting Center with the Motor Car within 24 hours of the accident or by the next working day thereof.

All accident repairs to the Motor Car must be carried out at ExcelDrive Workshops, otherwise the claim is not payable under the Policy. For ExcelDrive Prestige Plan, accident repairs to the Motor Car can be carried out at any workshop other than ExcelDrive Workshops.

For the list of Accident Reporting Centres and ExcelDrive Workshops, please visit our website at www.sompo.com.sg or call our Emergency Hotline: (65) 6226 3323.

I/We HEREBY CERTIFY that the policy to which this Certificate relates is issued in accordance with (1) the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia); and (2) the Policy terms, conditions and exceptions of the Private Car Policy ref MTP 27

Sompo Insurance Singapore Pte. Ltd.**Authorised Signatory**

Date/Time of Issue : 23 JUNE 2017 18:10

IMPORTANT NOTICE

- o Keep the Certificate in your Motor Car;
- o Under the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189), it shall be unlawful for any person to use or cause to permit any other person to use a motor vehicle without a valid policy of insurance under the Act;
- o On the sale of the Motor Car or if for any reason the Insurance is terminated during its currency, the Insured must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a statutory declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189);
- o This Policy will cease to be valid once the Motor Car has been sold to another person. The Policy is not transferable to the new owner of the Motor Car.

REPUBLIC OF SINGAPORE DRIVING LICENCE


Licence Number: **S7436663E**

Name: **AZHARIE BIN MOHAMED MUDAKIR**

Birth Date: **09 Nov 1974**

Issue Date: **27 Dec 2002**

1000067321F



REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S7436663E



Name: **AZHARIE BIN MOHAMED MUDAKIR**

Race: **INDONESIAN**

Date of birth: **09-11-1974**

Sex: **M**

Country of birth: **SINGAPORE**





YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class	Description	PASS DATE
Class 2B	Motorcycles not exceeding 200 cc	01 Mar 1995
Class 2A	Motorcycles between 201 cc and 400 cc	22 Nov 1996
Class 3	Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	06 Dec 1994

Licence No: **S7436663E**

NP 429A



3759477

NRIC No. **S7436663E**

Date of issue: **22-08-2005**

APT BLK 139B LORONG 1A TOA PAYOH #04-52

SINGAPORE 812139

S7436663E

02/12/2013




TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/LAW/0081/2018
DATE : 23-FEB-2018

MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
S(068877)
TEL : 65073848
FAX :
ATTN:MOTOR CLAIM DEPT

OWNER'S NAME : AZHARIE BIN MOHAMED MUDAKIR
ADDRESS : BLK 139B LORONG 1 TOA PAYOH
#04-52
S(312139)
TELEPHONE NO : 96901190

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : TP-SHC754Y
VEHICLE NO : SLP3374A
MODEL CODE : FRLARBZJ11UEA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2
ENGINE NO : HRA2233358A
CHASSIS NO : SJNFEAJ11U1583267
MILEAGE : 1 KM
DATE IN : 23/02/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : LAWRENCE
ACCIDENT DATE : 20/02/2018

DIRECT SETTLEMENT

OWNER CLAIMING LOSS OF USE / RENTAL

CAR AT WORKSHOP / CAR NOT AT WORKSHOP

KINDLY REVERT TO ME ASAP

EMAIL : lawrenceteo@tanchong.com

H/P : 94568832

FAX : 64697472

LKK

Tanjin 97495749
WP

12/3/18 @ 1620

** Resurvey new parts*

sun@lkkauto.com

4 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damage - - - - - resurvey
- Parts prices are - - - - -
- Third party survey - - - - - "No Prejudice" basis
- No illegal, unethical, manipulative
- Supplementary items - - - - - and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLP3374A

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 RRMLB	TO RENEW REAR MULTI LINK BEAM	240.00	X nn.
2 RRUC	REMOVE/REPAIR WHOLE UNDERCARRIAGE MECHANICAL PARTS PER SIDE LH REAR	480.00	X nn
3 WD42	CHECK WHEEL ALIGNMENT, ADJUST WHERE NECESSARY AND TEST DRIVE VEHICLE	103.00	✓
4 ZZ/001	REPAIR AND RENEW ALL DAMAGED PARTS	1170.00	780
5 ZZ/002	RENEW LH REAR S/RIM AND CONDUCT WHEEL BALANCING	15.00	✓
6 ZZ/003	SUPPLY AND RENEW LH REAR TYRE CONTI CONTACT5 215/60R17		
TOTAL LABOUR CHARGES		2008.00	

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLP3374A

		DAMAGED PARTS & PRICES		
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST S/NETT REMARKS
1	SUNDRIES	NPN		100.00 <i>X nn</i>
2	CONTINENTAL CONTACTS 215/60R17 LH REAR	215/60R17		320.00 <i>X nn</i>
3	SEAT SPRING UPPER	55034-4EA0A		35.40 <i>X</i>
4	SEAT SPRING LOWER	55032-4EA0A		51.40 <i>X</i>
5	ABSORBER-SHOCK	E6210-4EA2A		164.00 <i>X</i>
6	HUB REAR WHEEL	43202-4EA0A		361.90 <i>X</i>
7	ORNAMENT-ROAD	40342-BR01A		32.90 <i>X</i>
8	WHEEL-ROAD AL LH REAR	D0300-4EA1A		1231.90 <i>ab</i>
9	FENDER LH REAR ARC	93829-4EA0A	483.00	<i>ab</i>
10	MOULDING LH REAR DOOR PAD	82871-4EA0A	264.80	<i>ab</i>
11	MOULDING LH FRONT DOOR PAD	80871-4EA0A	323.60	<i>ab</i>
SUB TOTAL			1071.40	0.00 2297.50
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			214.28	0.00 0.00
GRAND TOTAL			857.12	0.00 2297.50
OVERALL TOTAL			3154.62	

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLP3374A

TOTAL LABOUR CHARGES	2008.00
TOTAL SPARE PARTS CHARGES	3154.62
GRAND TOTAL	5162.62 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/LAW/0081/2018
DATE : 23-FEB-2018

MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
S(068877)
TEL : 65073848
FAX :
ATTN:MOTOR CLAIM DEPT

OWNER'S NAME : AZHARIE BIN MOHAMED MUDAKIR
ADDRESS : BLK 139B LORONG 1 TOA PAYOH
#04-52
S(312139)
TELEPHONE NO : 96901190

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : TP-SHC754Y
VEHICLE NO : SLP3374A
MODEL CODE : FRLARBEJ11UEA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2
ENGINE NO : HRA2233358A
CHASSIS NO : SJNFEAJ11U1583267
MILEAGE : 1 KM
DATE IN : 23/02/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : LAWRENCE
ACCIDENT DATE : 20/02/2018

Signature
Cheng
D/S
Remun:
#100day x 04
= \$400 + GST
= \$428/-

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLP3374A

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 RRMLB	TO RENEW REAR MULTI LINK BEAM	240.00	.00
2 RRUC	REMOVE/REFIX WHOLE UNDERCARRIAGE MECHANICAL PARTS PER SIDE LH REAR	480.00	.00
3 WD42	CHECK WHEEL ALIGNMENT, ADJUST WHERE NECESSARY AND TEST DRIVE VEHICLE	103.00	103.00
4 ZZ/001	REPAIR AND RENEW ALL DAMAGED PARTS	1170.00	780.00
5 ZZ/002	RENEW LH REAR S/RIM AND CONDUCT WHEEL BALANCING	15.00	15.00
6 ZZ/003	SUPPLY AND RENEW LH REAR TYRE CONTI CONTACT5 215/60R17		
TOTAL LABOUR CHARGES		2008.00	898.00

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/S/SHOP

SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLP3374A

		DAMAGED PARTS & PRICES		
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
1 SEAT SPRING LOWER	55032-4EA0A			51.40 X
2 SUNDRIES	NPN			100.00 X
3 CONTINENTAL CONTACT5 215/60R17 LH REAR	215/60R17			320.00 X
4 SEAT SPRING UPPER	55034-4EA0A			35.40 X
5 ABSORBER-SHOCK	E6210-4EA2A			164.00 X
6 HUB REAR WHEEL	43202-4EA0A			361.90 X
7 ORNAMENT-ROAD	40342-BR01A			32.90 X
8 WHEEL-ROAD AL LH REAR	D0300-4EA1A			1231.90 OK
9 FENDER LH REAR ARC	93829-4EA0A	483.00		OK
10 MOULDING LH REAR DOOR PAD	82871-4EA0A	264.80		OK
11 MOULDING LH FRONT DOOR PAD	80871-4EA0A	323.60		OK
SUB TOTAL		1071.40	0.00	1231.90
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		214.28	0.00	0.00
GRAND TOTAL		857.12	0.00	1231.90
OVERALL TOTAL		2089.02		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

911, BUKIT TIMAH ROAD

SINGAPORE 589623

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SLP3374A

NETT ITEM	1071.40
LESS 20.00%	-214.28
NETT AMOUNT	857.12

LIST ITEM	0.00
LESS 30.00%	0.00
LIST AMOUNT	0.00

SPECIAL NETT ITEM	1231.90
LESS .00%	0.00
SPECIAL NETT AMOUNT	1231.90

TOTAL LABOUR CHARGES	898.00
TOTAL SPARE PARTS CHARGES	2089.02

TOTAL CHARGES	2987.02
ADD 7 % GST	209.09

GRAND TOTAL	3196.11
-------------	---------




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18004389/T1rd3e2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 07-11-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 754Y	Veh. Inspected	SLP 3374A	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18001556MFSH	Excess (\$)	0.00	
Assign From	AUNG YIN MIN	Assign Date	23/02/2018	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN QASHQAI	c.c	1197	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	SJNFEAJ11U1583267	Colour	MAROON	
Odometer	55195	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R17	CONTINENTAL	6 mm	
L/H Front Tyre	215/60 R17	CONTINENTAL	6 mm	
R/H Rear Tyre	215/60 R17	CONTINENTAL	6 mm	
L/H Rear Tyre	215/60 R17	CONTINENTAL	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	20/02/2018	Inspection Date	12/03/2018	
Survey held at	TAN CHONG MOTOR SALES PTE LTD 911, BUKIT TIMAH RD, SINGAPORE 589623.			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLP 3374A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FENDER LH REAR ARC (N)	CUT	483.00	483.00
1	MOULDING LH REAR DOOR PAD (N)	CUT	264.80	264.80
1	MOULDING LH FRONT DOOR PAD (N)	CUT	323.60	323.60
	LESS 20% DISCOUNT		-214.28	-214.28
			857.12	857.12
	<u>SPECIAL NETT ITEMS</u>			
1	SUNDRIES (SN)	NOT NECESSARY	100.00	-
1	CONTINENTAL CONTACTS 215/60R17 LH REAR (SN)	NOT NECESSARY	320.00	-
1	SEAT SPRING UPPER (SN)	NOT NECESSARY	35.40	-
1	SEAT SPRING LOWER (SN)	NOT NECESSARY	51.40	-
1	ABSORBER-SHOCK (SN)	NOT NECESSARY	164.00	-
1	HUB REAR WHEEL (SN)	NOT NECESSARY	361.90	-
1	ORNAMENT-ROAD (SN)	NOT NECESSARY	32.90	-
1	WHEEL-ROAD AL LH REAR (SN)	CUT	1,231.90	1,231.90
			2,297.50	1,231.90
	<u>LABOUR</u>			
	TO RENEW REAR MULTI LINK BEAM.	NOT NECESSARY	240.00	-
	REMOVE / REFIX WHOLE UNDERCARRIAGE MECHANICAL PARTS PER SIDE LH REAR.	NOT NECESSARY	480.00	-
	CHECK WHEEL ALIGNMENT, ADJUST WHERE NECESSARY AND TEST DRIVE VEHICLE.		103.00	103.00
	REPAIR AND RENEW ALL DAMAGED PARTS.		1,170.00	780.00
	RENEW LH REAR S/RIM AND CONDUCT WHEEL BALANCING.		15.00	15.00
			-	-
			-	-
			-	-
			-	-
			-	-
			2,008.00	898.00
	GRAND TOTAL		5,162.62	2,987.02

Report Ref No. CS/FCI18004389/T1rd3e2



RECOMMENDED COST OF REPAIRS			2,987.02
-----------------------------	--	--	----------

Report Ref No. CS/FCI18004389/T1rd3e2

MOHAMAD TAUFIKH
M.MATAI, AMSAE-A
Automotive Assessor

ADRIAN LING WAI PING
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.