

12/01/2007

ASS. REC. BY:

REF CS3

MSG18004421/T10392

Special Instruction:

Surveyor:

Menthen

Taufik

ASSIGNMENT (Office)

From (Person):

Jasmine Lok

of

MSG

Date/Time: 6/3/18 @ 3:30pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV/CS

To Inspect Vehicle No:

FS 5732S

Insured:

FBK 7834H

at Workshop m/s

Racewerks Motorsports

Tel:

62732203

of

Blk 1008, Bkt Merah Lane 3 #01-26

Policy No:

MSD/VMFT/18-989325-wp

Claim No:

MSC/V/18-000338

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

25/2/2018

CA / REV / REP. / REV 24 HRS

wp

08/03/2018

H.O.D. Endorsement:

Date/Time:

10am @ 7/3/18

Person Contacted:

Ms. Chee

Vehicle IN/OUT

Date/Time	Action/Instruction (, Estimate
	FS 5732S - NBA/MSG18004421/195/Y
	FBK 7834H - NBA/MSG18004421/195/Y
09/3/18 @ 3pm	informed Jasmine Lok, we are pending estimate from repairer.
25/7/18 @ 4pm	checked with Ms Chee, they already engage their independent surveyor & lawyer.

ASSIGNMENT

WE 2020 March
2000 Sep

Date 8/3/18
Estimated Cost
OD (P) WS / TP RES / OD RES / EVA / INV / MV
To inspect Vehicle No FS 5732S
at Workshop no Racewerk Autoworks
of Blk 1006 Blk Meruh Lane 3 # 01-26
Insured
Policy No
Claims No
Sum Insured Excess
Client's Record
Make of Car



(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.

Salvage Market Value
DAG Accident Report Consistent? Yes or No
DAG PP Seen Consistent? Yes or No
Est Repairs 3 days Fee Yes or No
Lump Sum \$ 3150 Yes or No
CA / REV / REP / 24 HRS (wup)
Date Person Contacted Vehicle IN / OUT

FS 5732S
Type M/Gar M/Gar Bus/Van/Truck Taxi Private Motor
Truck Trailer
Make Honda NSR15OSP 149
Colour Black
Se Reading 18902
Eng No
Eng NS15OSP 0010517
Gen Cond Good Fair Poor Burnt
Steering In order Jammed Leaked Burnt
Brake In order Jammed Leaked Burnt
Mod STD 4 Rim
Tyre Size F 90/80R17
R 120/70R17
As DUN / EXNOVA / GY FS LIZA / MID OHTSL PR SUM
TOYO / YOKO
Front
Rear
Lsa
Rsa
DAG
DAG
Surveyed at Racewerk
Date of Damage 8/3/18
Rear NS UC Roofed

The UC / Chassis frame / Body Structure affected due to collision

Date Time Action / Instruction

Dismantle: 22/3/2018

Estimated repair range \$2,500 - \$3,300

1/8 Submit PRS report.

11/8/18

Date Time File Pass y1
Final Report

Days Of Repair 3
Resurvey No. of Trip 1

Add Fee
Site Visit
Travel
Food
Accommodation
Other

Report Form: PRS
Lump Sum





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD			Ref : CS/MSG18004421/T1qd3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 07-03-2018	
			Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	FBK 7834H	Veh. Inspected	FS 5732S	
Policy No.	MSD/VMFT/18-989325-WTT	Coverage (\$)	0.00	
Claim No.	MSC/V/18-000338	Excess (\$)	0.00	
Assign From	MERIMEN (JASMINE LOK)	Assign Date	07/03/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	25/02/2018	Inspection Date		
Survey held at	RACE WERKS MOTOR SPORTS BLK 1008 BUKIT MERAH LANE 3 #01-26 SINGAPORE 159722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Mar 2018		06 Mar 2018 15:30 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	MOHAMAD ZULKARNAI BIN WAGMAN, ID: S9137131F		
Main Claimant:	HUANG WEI JHIN, ID: S9814232J		
Vehicle Reg. No.:	FS5732S	Date of Loss:	25/02/2018 00:00 - :59
Claim Type:	TP / MSC/V/18-000338	Policy/Cover Note No.:	MSD/VMFT/18-989325-WTT (TP, Fire & Theft) Coverage: 25/01/2018 - 24/01/2019
Vehicle Reg. No. (Insured):	FBK7834H	Policy No. (Claimant):	
		Excess:	
Repairer:	Racewerks Motorsports (HQ) BLK 1008 BUKIT MERAH LANE 3 #01-26, 159722 Bukit Merah - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 07/03/2018]		
Adj Asp. Remarks:	Third Party Pre-Repair Survey		

ASSOCIATED MAIL RECEIVED View All Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAuto)

From: Do-Not-Reply <do-not-reply@merimen.com>
Sent: Friday, 9 March 2018 3:00 PM
To: do-not-reply@merimen.com
Cc: SUR
Subject: MOTORBIKE FS 5732S (YOUR REF: MSC/V/18-000338)

This mail is associated with :
***FS5732S (MSC/V/18-000338)**
[FBK7834H]
TP
HUANG WEI JHIN
Feb 25 2018 12:00AM
[MOHAMAD ZULKARNAI BIN WAGMAN]
Racewerks Motorsports

Dear Jasmine,

Please be informed that we have inspected the motorbike FS 5732S on 08/03/2018.

We are pending for estimate from repairer.

Thanks & Regards,

Shiau Chan (Ms)
LKK Auto Consultants Pte Ltd
Tel: 6256 3561
Fax: 6256 4315

[This mail is sent from a mailer account - do not reply to this email address]

Sent by : SHIAU CHAN (LKK Auto Consultants Pte Ltd)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	01/03/2018 09:15
Date Of Accident	25/02/2018 11:30
Exact Location Of Accident	PIE TOWARDS CHANGI AIRPORT BEFORE EXIT 18
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FS5732S
Insured/Policyholder	
Name Of Registered Owner	HUANG WEI JHIN
NRIC No	S9814232J
Email Address	WJHUANG15@GMAIL.COM
Mobile Phone No	(LOCAL) +65-81380598
Alternative Phone No	OTHERS-81380598

Vehicle Particulars

Manufacturer	HONDA
Model	NSR150SP-149CC (M)
Exact Purpose for which vehicle was being used at time of accident	TRAVEL TO WORK
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	MSD/TMT/17-371214-CA
Cover Note Number	

Driver

Name of Driver	HUANG WEI JHIN
NRIC No	S9814232J
Date Of Birth	01/05/1998
Occupation	INDOOR
Date Of Driving Pass	30/08/2016
Driving Experience	1 YEAR AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81380598
Fax Number	
Contact Number	OTHERS-81380598
Email Address	WJHUANG15@GMAIL.COM

Address	BLK 137 PETIR ROAD #11-434
Postcode	670137
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BUKIT PANJANG SOUTH NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 124 PENDING ROAD , POSTCODE: 670124 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-7609999 - FAX NO: 67636614
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO POLICE REPORT T/20180226/2157

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBK7834H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	HUANG WEI JHIN
Approximate Age	
Injuries Sustain	SLIGHT INJURY
Injured person in which vehicle?	FS5732S
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

Sketch Plan


SKETCH PLAN


IMPORTANT NOTICE



1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.: 

Sketch Plan #2

SKETCH PLAN

PK TOWARDS COTACHT AIRPORT BEFORE A17 18

A: FS 57325

B: PBK 7834H




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report T/20180226/2157

DECLARATION



I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:



Driver's Signature
(if driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: 
NRIC/FIN No.:

Sketch Plan #3



**SINGAPORE
POLICE FORCE**



T/20180226/2157

1 of 3

Police Station Of Origin:
Bukit Panjang South NPP
124 Pending Road #01-00 SINGAPORE
670124
Tel No: 1800-7609999

Report No. T/20180226/2157

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 26/02/2018 17:41		Vide Report No.:		Station Diary No.: 32	
Informant's Particulars					
Name of Informant: HUANG WEI JHIN			Address: APT BLK 137 PETIR ROAD #11-434 SINGAPORE 670137		
ID Type / ID No.: NRIC NO / S9814232J			Contact No.: Home/Office: Mobile: 81380598		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 19	Date of Birth: 01/05/1998	Type of Informant: Rider		
Race: Chinese			Language:		Institution / School Name: Ngee Ann Poly
Occupation: Waiter			Driving Licence Information: Class: 2B,2A,3		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 25/02/2018 11:30	Type of Location: Bend
Location: Along Road 1 PAN ISLAND EXPRESSWAY PIE towards Changi airport before exit 18				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume:	
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBK7834H	Motorcycle				Seriously Damaged	0
FS5732S	Motorcycle	HONDA	NSR150SP	Green	Seriously Damaged	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FS5732S	MSIG INSURANCE (SINGAPORE) PTE. LTD.	MSDTMT17371214	15/09/2017	14/09/2018

Sketch Plan #4



**SINGAPORE
POLICE FORCE**



T/20180226/2157

2 of 3

Police Station Of Origin:
Bukit Panjang South NPP
124 Pending Road #01-00 SINGAPORE
670124
Tel No: 1800-7609999

Report No. T/20180226/2157

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	HUANG WEI JHIN	ID No.	S9814232J
Related Vehicle	FS5732S (Motorcycle)	Contact No.	81380598
Hospital/Clinic	TAN TOCK SENG HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,2A,3 Date of Expiry: NIL
Date Treatment	25/02/2018	Date Discharge	25/02/2018
No. of Days granted Medical Leave	03	Degree of Injury	Serious

Brief Details.

On 25/02/2018 at about 1130hrs, I was riding my motorbike FS5732S along PIE towards Changi airport before exit 18 1/2km. I honked at the bike FBK7834H who was in front of me. He slowed down beside me. I gave him a hand gesture of his rear number plate was dangling. The rider acknowledged my hand gesture. After that, I moved off forward. As I was entering the bend, the bike FBK7834H who was riding behind of me collided onto my bike left rear side. We both then fell on the ground. Right after our accident, there were 2 more bikes collided onto each other beside us. There were a car SLP9140T driver namely: Ong Chee Yeow HP: 97888553 informed his in car camera might had capture the accident.

I was conveyed to Tan Tock Seng hospital and issued a 3 days MC. I suffered abrasion on my right arms, right legs, right hips, right shoulder and left ankle. I did not take down the rider of FBK7834H particulars.

Sketch Plan #5



SINGAPORE
POLICE FORCE



T/20180226/2157

3 of 3

Police Station Of Origin:
Bukit Panjang South NPP
124 Pending Road #01-00 SINGAPORE
670124
Tel No: 1800-7609999

Report No. T/20180226/2157

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

J/
Sgt 2 QUEK JUN CAI

Signature Of Informant:

Signature Of Interpreter:
Not applicable

Date/Time:
26/02/2018 17:41

Officer In Charge Of Case:
TP / GIT /
SI TAN LEE HWANG DAWN
Contact No.: 65476215

Classification Of Case:

Authentication Stamp
NP168

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4232J
Vehicle Details	
Vehicle No.:	F55732S
Vehicle to be Exported:	No
Intended De-registration Date:	09 Mar 2018
Vehicle Make:	HONDA
Vehicle Model:	NSR150SP
Primary Colour:	Green
Manufacturing Year:	2000
Engine No.:	NS150SPE0010517
Chassis No.:	NS150SP0010517
Maximum Power Output:	-
Open Market Value:	\$4,250.00
Original Registration Date:	15 Sep 2000
First Registration Date:	15 Sep 2000
Transfer Count:	12
Actual ARF Paid:	\$638.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Mar 2020
COE Category:	D - Motorcycle
COE Period(Years):	10
PQP Paid:	\$884.00
COE Rebate Amount:	\$182.00
Total Rebate Amount:	\$182.00

The information contained herein is correct as at 09 Mar 2018

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 Mar 2018		06 Mar 2018 15:30 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case




































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: MOHAMAD ZULKARNAI BIN WAGMAN , ID: S9137131F									
Main Claimant: HUANG WEI JHIN , ID: S9814232J									
Vehicle Reg. No.: FS5732S		Date of Loss: 25/02/2018 00:00 - :59 [209 Months and 10 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / MSC/V/18-000338		Policy/Cover Note No.: MSD/VMFT/18-989325-WTT (TP, Fire & Theft) Coverage: 25/01/2018 - 24/01/2019							
Vehicle Reg. No. (Insured): FBK7834H		Policy No. (Claimant):							
		Excess:							
Repairer: Racewerks Motorsports (HQ) BLK 1008 BUKIT MERAH LANE 3 #01-26, 159722 Bukit Merah - Tel:									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Imm.Advice due 07/03/2018]									
Adj Asg. Remarks: Third Party Pre-Repair Survey									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FS5732S (MSC/V/18-000338)
[FBK7834H]
TP
HUANG WEI JHIN
Feb 25 2018 12:00AM
[MOHAMAD ZULKARNAI BIN WAGMAN]
Racewerks Motorsports













Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/07/18 18:51	General View	 Load JPG	✓
2	30/07/18 18:51	General View	 Load JPG	✓
3	30/07/18 18:51	General View	 Load JPG	✓
4	30/07/18 18:51	General View	 Load JPG	✓
5	30/07/18 18:51	General View	 Load JPG	✓
6	30/07/18 18:51	General View	 Load JPG	✓
7	30/07/18 18:51	General View	 Load JPG	✓
8	30/07/18 18:51	General View	 Load JPG	✓
9	30/07/18 18:51	General View	 Load JPG	✓
10	30/07/18 18:51	General View	 Load JPG	✓
11	30/07/18 18:51	General View	 Load JPG	✓
12	30/07/18 18:51	General View	 Load JPG	✓
13	30/07/18 18:51	General View	 Load JPG	✓
14	30/07/18 18:51	General View	 Load JPG	✓
15	30/07/18 18:51	General View	 Load JPG	✓
16	30/07/18 18:51	General View	 Load JPG	✓
17	30/07/18 18:51	General View	 Load JPG	✓
18	30/07/18 18:51	General View	 Load JPG	✓
19	30/07/18 18:51	General View	 Load JPG	✓
20	30/07/18 18:51	General View	 Load JPG	✓
21	30/07/18 18:51	General View	 Load JPG	✓
22	30/07/18 18:51	General View	 Load JPG	✓
23	30/07/18 18:51	General View	 Load JPG	✓
24	30/07/18 18:51	General View	 Load JPG	✓
25	30/07/18 18:51	General View	 Load JPG	✓
26	30/07/18 18:51	General View	 Load JPG	✓
27	30/07/18 18:51	General View	 Load JPG	✓
28	30/07/18 18:51	General View	 Load JPG	✓
29	30/07/18 18:51	General View	 Load JPG	✓
30	30/07/18 18:51	General View	 Load JPG	✓
31	30/07/18 18:51	General View	 Load JPG	✓
32	30/07/18 18:51	General View	 Load JPG	✓
33	30/07/18 18:51	General View	 Load JPG	✓
34	30/07/18 18:51	General View	 Load JPG	✓
35	30/07/18 18:51	General View	 Load JPG	✓

Photos/Images					<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
36	30/07/18 18:51	General View		Load JPG	<input checked="" type="checkbox"/>
37	30/07/18 18:51	General View		Load JPG	<input checked="" type="checkbox"/>
38	30/07/18 18:51	General View		Load JPG	<input checked="" type="checkbox"/>
39	30/07/18 18:51	General View		Load JPG	<input checked="" type="checkbox"/>
40	30/07/18 18:51	General View		Load JPG	<input checked="" type="checkbox"/>
41	30/07/18 18:51	General View		Load JPG	<input checked="" type="checkbox"/>
42	30/07/18 18:51	General View		Load JPG	<input checked="" type="checkbox"/>
43	30/07/18 18:51	General View		Load JPG	<input checked="" type="checkbox"/>
44	30/07/18 18:51	General View		Load JPG	<input checked="" type="checkbox"/>
45	30/07/18 18:51	General View		Load JPG	<input checked="" type="checkbox"/>
46	30/07/18 18:51	General View		Load JPG	<input checked="" type="checkbox"/>
47	30/07/18 18:51	General View		Load JPG	<input checked="" type="checkbox"/>
48	30/07/18 18:51	General View		Load JPG	<input checked="" type="checkbox"/>
49	30/07/18 18:51	General View		Load JPG	<input checked="" type="checkbox"/>
50	30/07/18 18:51	General View		Load JPG	<input checked="" type="checkbox"/>
51	30/07/18 18:51	General View		Load JPG	<input checked="" type="checkbox"/>
52	30/07/18 18:51	General View		Load JPG	<input checked="" type="checkbox"/>
53	30/07/18 18:51	General View		Load JPG	<input checked="" type="checkbox"/>
54	30/07/18 18:51	General View		Load JPG	<input checked="" type="checkbox"/>
55	30/07/18 18:51	General View		Load JPG	<input checked="" type="checkbox"/>
56	30/07/18 18:51	General View		Load JPG	<input checked="" type="checkbox"/>
57	30/07/18 18:51	General View		Load JPG	<input checked="" type="checkbox"/>
58	30/07/18 18:51	General View		Load JPG	<input checked="" type="checkbox"/>
59	30/07/18 18:51	General View		Load JPG	<input checked="" type="checkbox"/>
60	30/07/18 18:51	General View		Load JPG	<input checked="" type="checkbox"/>
61	30/07/18 18:51	General View		Load JPG	<input checked="" type="checkbox"/>
62	30/07/18 18:51	General View		Load JPG	<input checked="" type="checkbox"/>
63	30/07/18 18:51	General View		Load JPG	<input checked="" type="checkbox"/>
64	30/07/18 18:51	General View		Load JPG	<input checked="" type="checkbox"/>
65	01/08/18 10:58	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
66	01/08/18 10:58	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
67	01/08/18 10:58	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
68	01/08/18 10:58	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
69	01/08/18 10:58	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
70	01/08/18 10:58	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
71	01/08/18 10:58	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
72	01/08/18 10:58	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
73	01/08/18 10:58	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
74	01/08/18 10:58	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
75	01/08/18 10:58	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
76	01/08/18 10:58	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
77	01/08/18 10:58	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
78	01/08/18 10:58	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
79	01/08/18 10:58	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
80	01/08/18 10:58	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
81	01/08/18 10:58	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
82	01/08/18 10:58	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
83	01/08/18 10:58	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>

Photos/Images					
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
84	01/08/18 10:58	Photographs of Damaged Parts		Load JPG	
85	01/08/18 10:58	Photographs of Damaged Parts		Load JPG	
86	01/08/18 10:58	Photographs of Damaged Parts		Load JPG	
87	01/08/18 10:58	Photographs of Damaged Parts		Load JPG	
88	01/08/18 10:58	Photographs of Damaged Parts		Load JPG	
89	01/08/18 10:58	Photographs of Damaged Parts		Load JPG	
90	01/08/18 10:58	Photographs of Damaged Parts		Load JPG	
91	01/08/18 10:58	Photographs of Damaged Parts		Load JPG	
92	01/08/18 10:58	Photographs of Damaged Parts		Load JPG	
93	01/08/18 10:58	Photographs of Damaged Parts		Load JPG	
94	01/08/18 10:58	Photographs of Damaged Parts		Load JPG	
95	01/08/18 10:58	Photographs of Damaged Parts		Load JPG	
96	01/08/18 10:58	Photographs of Damaged Parts		Load JPG	
97	01/08/18 10:58	Photographs of Damaged Parts		Load JPG	
98	01/08/18 10:58	Photographs of Damaged Parts		Load JPG	
99	01/08/18 10:58	Photographs of Damaged Parts		Load JPG	
100	01/08/18 10:58	Photographs of Damaged Parts		Load JPG	
101	01/08/18 10:58	Photographs of Damaged Parts		Load JPG	
102	01/08/18 10:58	Photographs of Damaged Parts		Load JPG	
103	01/08/18 10:58	Photographs of Damaged Parts		Load JPG	
104	01/08/18 10:58	Photographs of Damaged Parts		Load JPG	
105	01/08/18 10:58	Photographs of Damaged Parts		Load JPG	
106	01/08/18 10:58	Photographs of Damaged Parts		Load JPG	
107	01/08/18 10:58	Photographs of Damaged Parts		Load JPG	
108	01/08/18 10:58	Photographs of Damaged Parts		Load JPG	
109	01/08/18 10:58	Photographs of Damaged Parts		Load JPG	
110	01/08/18 10:58	Photographs of Damaged Parts		Load JPG	
111	01/08/18 10:58	Photographs of Damaged Parts		Load JPG	
112	01/08/18 10:58	Photographs of Damaged Parts		Load JPG	
113	01/08/18 10:58	Photographs of Damaged Parts		Load JPG	
114	01/08/18 10:58	Photographs of Damaged Parts		Load JPG	
115	01/08/18 10:58	Photographs of Damaged Parts		Load JPG	
116	01/08/18 10:58	Photographs of Damaged Parts		Load JPG	
117	01/08/18 10:58	Photographs of Damaged Parts		Load JPG	
118	01/08/18 10:58	Photographs of Damaged Parts		Load JPG	
119	01/08/18 10:58	Photographs of Damaged Parts		Load JPG	
120	01/08/18 10:58	Photographs of Damaged Parts		Load JPG	
121	01/08/18 10:58	Photographs of Damaged Parts		Load JPG	
122	01/08/18 10:58	Photographs of Damaged Parts		Load JPG	
123	01/08/18 10:58	Photographs of Damaged Parts		Load JPG	
124	01/08/18 10:58	Photographs of Damaged Parts		Load JPG	
125	01/08/18 10:58	Photographs of Damaged Parts		Load JPG	
126	01/08/18 10:58	Photographs of Damaged Parts		Load JPG	
127	01/08/18 10:58	Photographs of Damaged Parts		Load JPG	
128	01/08/18 10:58	Photographs of Damaged Parts		Load JPG	
129	01/08/18 10:58	Photographs of Damaged Parts		Load JPG	
130	01/08/18 10:58	Photographs of Damaged Parts		Load JPG	
131	01/08/18 10:58	Photographs of Damaged Parts		Load JPG	

Photos/Images				<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
132	01/08/18 10:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
133	01/08/18 10:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
134	01/08/18 10:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
135	01/08/18 10:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
136	01/08/18 10:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
137	01/08/18 10:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
138	01/08/18 10:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
139	01/08/18 10:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
140	01/08/18 10:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
141	01/08/18 10:58	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	06/03/18 14:11	TP PRI & ACCDT REPORT	 Load PDF	
2	06/03/18 15:27	TP REPLY & WE REJECT THEIR LIST OF SJE & NOMINATED OUR LKK TO BE OUR SJE	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/MSG18004421/T1D3S2**Date:** 02/08/2018REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMFT/18-989325-WTT
Claimant Vehicle No :	FS5732S	Insured Vehicle No :	FBK7834H
Date of Loss:	25/02/2018	Nature of Claim:	TP
			Claim No: MSC/V/18-000338

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FS5732S	Engine No:	NS150SPE0010517
Make & Model:	HONDA NSR, 150cc 150 (M)	Chassis No:	NS150SP0010517
Reg. Date:	15/09/2000 (Man. Year: 2000)	Odometer:	18902 km
Colour:	Black		
Engine Capacity:	149 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	90/80R17	Rear Tyre Size:	120/70R17
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	06/03/2018		Racewerks Motorsports (HQ)
Date Inspected:	08/03/2018	Inspected At:	BLK 1008 BUKIT MERAH LANE 3 #01-26
Estimated Period of Repair:	0.0 days		Singapore 159722

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

8/2/2018

Adjuster Report

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,500.00 - \$3,300.00

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 02 Aug 2018)	
Parts:	N/A	HONDA NSR 150cc 150 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FS5732S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >