

ASS. REC. BY:

REF: CS3/MSG18004425/Mid 31

Special Instruction:

Surveyor
Maiman

ASSIGNMENT (Office)

From (Person): Jasmine Lok

of MSIG

Date/Time: 7/3/18 @ 1:38pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBE 2311P

Insured:

YN 9234M

at Workshop m/s

Guan Auto Service

Tel:

9388 4210

of

Blk 7 - Sin Ming Ind. Est. Sec. C # 01-80

Policy No:

28616793MKC

Claim No:

551526

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

06/03/2018

CA / REV / REP. / REV 24 HRS

8/3/2018

H.O.D. Endorsement:

Date/Time:

3:38pm @ 7/3/18

Person Contacted:

Jueky

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	GBE 2311P-X
	YN 9234M-X

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: GBE231P Yr Regn: OCT 2015

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: NIS NAVARA cc 2298Colour: BROWN A/C: Insured / Std / NI / NASp. Reading: 47464 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WNTCB4-D2376000057Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: W / S/Rim / STD A/Rim orTyre Size: F: 225/70/R16

R: _____

BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 06/03/2018

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

3000 k - 4000 k

RECEIVED 26 APR 2018

Date/Time: File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time: File Return to?

2)

Report Format: PRS

Lump Sum / I.B./I: (\$)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee: _____

Transportation: _____

1) \$ - RS \$

2) Photos

3) Others

TOTAL

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Mar 2018		07 Mar 2018 13:38 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	TAI HUA FOOD INDUSTRIES PTE LTD, Co. Reg. No.: NA		
Main Claimant:	CSK LANDSCAPE SERVICES PTE LTD		
Vehicle Reg. No.:	GBE2311P	Date of Loss:	06/03/2018 00:00 - :59
Claim Type:	TP / 551526	Policy/Cover Note No.:	28616793MKC (Comprehensive) Coverage: 18/09/2017 - 17/09/2018
Vehicle Reg. No. (Insured):	YN9234M	Policy No. (Claimant):	
		Excess:	
Repairer:	Guan Auto Service (SING MING) Blk 7 Sin Ming Industrial Estate Sector C, #01-80, #01-82, 575642 Sin Ming - Tel: 93884210		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 08/03/2018]		
Driver/Custodian (Insured):	NG KIM HENG (), NRIC: S1132205J		
Adj Asg. Remarks:	Third Party Pre-Repair Survey		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/03/2018 15:50
Date Of Accident	06/03/2018 10:25
Exact Location Of Accident	BLK 39 TANGLIN HALT RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBE2311P
Insured/Policyholder	
Name Of Registered Owner	CSK LANDSCAPE SERVICES (S) PTE LTD
Co Reg No	- 2944P 58530R
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90085515
Alternative Phone No	OFFICE-90085515

Vehicle Particulars

Manufacturer	NISSAN
Model	-
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCVSN1661901701
Cover Note Number	

Driver

Name of Driver	GOH MIA CHUN
NRIC No	S7807651H
Date Of Birth	21/03/1978
Occupation	INDOOR
Date Of Driving Pass	27/12/1996
Driving Experience	21 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90085515
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address -
 Postcode -
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 0

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER ATTACHED REPORT.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number YN9234M
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver NG KIM HENG
 NRIC/Passport Number S1132205J
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

6/3/12

12:20pm




Driver's Signature
(If driver is not the policyholder)

Date & Time: 6/3/12

12:20pm

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 6/3/2018 @ about 1025am, my vehicle 6BE2311P was parked stationary along carpark number QX051. Vehicle B (YN9234M) Drive pass my vehicle and the rear door of the vehicle B swung and hit the back of my vehicle. The driver of vehicle B came down and admitted that he did not secure the rear loading door.

CSK LANDSCAPE SERVICES (S) PTE. LTD.

DECLARATION

I declare the foregoing particulars are true and correct to the best of my knowledge and belief.

CSK LANDSCAPE SERVICES (S) PTE. LTD.

Policyholder's Signature

Date & Time: 6/3/18

1220pm

Driver's Signature

(If driver is not the policyholder)

Date & Time:

6/3/18
1220pm

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5300R
Vehicle Details	
Vehicle No.:	GBE2311P
Vehicle to be Exported:	No
Intended De-registration Date:	26 Apr 2018
Vehicle Make:	NISSAN
Vehicle Model:	NP300 NAVARA D/CAB 7AT
Primary Colour:	Brown
Manufacturing Year:	2015
Engine No.:	YS23311970A
Chassis No.:	MNTCB4D23Z0000051
Maximum Power Output:	-
Open Market Value:	\$28,674.00
Original Registration Date:	05 Oct 2015
First Registration Date:	05 Oct 2015
Transfer Count:	0
Actual ARF Paid:	\$32,144.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	04 Oct 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$47,457.00
COE Rebate Amount:	\$35,301.00
Total Rebate Amount:	\$35,301.00

The information contained herein is correct as at 26 Apr 2018

OK

Sketch Plan #3 Pg. 1

REPUBLIC OF SINGAPORE

IDENTITY CARD NO S7807651H



GOH MIAO CHUN
(WU MINGJUN)

吳明駿

CHINESE

Date of birth 21-03-1978

Sex M

Place of birth SINGAPORE



S7807651H

21 MAR 78

21 MAR 78

GOH MIAO CHUN
(WU MINGJUN)

S7807651H

5416719

7807651H

28-08-2015

APT BLK 330 CLEMENTI AVENUE 3
#05-162
SINGAPORE 120330

5416719

7807651H

28-08-2015

APT BLK 330 CLEMENTI AVENUE 3
#05-162
SINGAPORE 120330

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	06 Mar 2018		07 Mar 2018 13:38 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	TAI HUA FOOD INDUSTRIES PTE LTD, Co. Reg. No.: NA			
Main Claimant:	CSK LANDSCAPE SERVICES PTE LTD			
Vehicle Reg. No.:	GBE2311P	Date of Loss:	06/03/2018 00:00 - :59 [29 Months and 1 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / 551526	Policy/Cover Note No.:	28616793MKC (Comprehensive) Coverage: 18/09/2017 - 17/09/2018	
Vehicle Reg. No. (Insured):	YN9234M	Policy No. (Claimant):		
		Excess:		
Repairer:	Guan Auto Service (SING MING) Blk 7 Sin Ming Industrial Estate Sector C, #01-80, #01-82, 575642 Sin Ming - Tel: 93884210			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MA CHIN FOOK] ... [Imm.Advice due 08/03/2018]			
Driver/Custodian (Insured):	NG KIM HENG (), NRIC: S1132205J			
Adj Asg. Remarks:	Third Party Pre-Repair Survey			

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBE2311P (551526)

[YN9234M]

TP

CSK LANDSCAPE SERVICES PTE LTD

Mar 6 2018 12:00AM

[TAI HUA FOOD INDUSTRIES PTE LTD]













Guan Auto Service

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Photos/Images

3 per page ▼

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/04/18 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
2	26/04/18 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
3	26/04/18 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
4	26/04/18 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
5	26/04/18 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
6	26/04/18 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
7	26/04/18 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
8	26/04/18 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
9	26/04/18 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
10	26/04/18 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
11	26/04/18 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
12	26/04/18 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>

Documentation

1 per page ▼

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	07/03/18 13:16	TP PRI	 Load PDF	
2	07/03/18 13:24	TP ACCDT DOCS, SKETCH PLAN	 Load PDF	
3	07/03/18 13:28	TP LIST OF SJE & OUR REJECTION FREPLY & NOMINATED LKK TO BE SJE	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18004425/M1D3S2
Date: 27/04/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 28616793MKC
Claimant Vehicle No: GBE2311P Insured Vehicle No: YN9234M
Date of Loss: 06/03/2018 Nature of Claim: TP Claim No: 551526

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBE2311P Engine No: YS23311970A
Make & Model: NISSAN NP300 NAVARA, 2.3 D (M) Chassis No: MNTCB4D23Z0000051
Reg. Date: 05/10/2015 (Man. Year: 2015) Odometer: 47464 km
Colour: Brown
Engine Capacity: 2298 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/70R16 Rear Tyre Size: 225/70R16
Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 07/03/2018
Date Inspected: 08/03/2018 Inspected At: Guan Auto Service (SING MING)
Estimated Period of Repair: 0.0 days Blk 7 Sin Ming Industrial Estate Sector C, #01-80, #01-82
Singapore 575642

Adjuster: MA CHIN FOOK

Manager: Nivitha Govindasamy

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

4/27/2018

Adjuster Report

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 - \$4,000.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 27 Apr 2018)

Parts: N/A NISSAN NP300 NAVARA 2.3 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBE2311P)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >