From (Person): Trent Tan of Msh Date/Time: D7032018 22 Estimated Cost: Bill to: OD / PD / WS / TP RES / OD RES / EVA / INV / MV / CS To Inspect Vehicle No: FB h 3373 k Insured: SLD 8362 P at Workshop m/s Speddway Myth Tel: of St Toh Duan Rd Fast #0 -32 Policy No: MSD / VPCP / 17-00 233-00 Claim No: MSC / V/18-000 86 Sum Insured: Excess: Make of Veh: D.O.A. 28012018 CA / REV / REP. / REV 24 HRS WP Date/Time: Person Contacted: Vehicle IN / OUT Date/Time Action/Instruction (X) Estimate LV X 18 Swam Us \$64750, 5 days Mad \$1950, 2072.	Surveyor -			ASSIGN	MENT (Offic	e)	/				
Bill to: OD /FF / WS / TP RES / OD RES / EVA / INV / MV / CS	From (Person):	Irene	Tan						Date	Time:	07032018	227pn
To Inspect Vehicle No:	Estimated Cost:											
Speedway Motor Tel:	OD /TI WS/TP	RES/O			V / CS							
Speedway Motor Tel:	To Inspect Vehicle	No:	FB	G 3393K				Insured	:	SLD	83628	
Policy No: MSD / VPCP / 17-00 233-00 Claim No: MSC / V/18-000 86 Sum Insured: Excess: Make of Veh: D.O.A. 28012018 CA / REV / REP. / REV 24 HRS WP Date/Time: Person Contacted: Vehicle IN / OUT Date/Time Action/Instruction (X) Estimate	at Workshop m/s		Sp	eedway m	notur							
Policy No:			36	Joh Guan	Rd E	Fast	#0	-32				
Sum Insured: Make of Veh: (Client's Record) CA / REV / REP. / REV 24 HRS WP Date/Time: Person Contacted: Vehicle IN / OUT Date/Time Action/Instruction (X) Estimate	Policy No: MS	D/VPC	10-FI/ 9) 233-00	Cl	aim No	0:	ms	C/V/	18-0	18100	
Make of Veh: (Client's Record) CA / REV / REP. / REV 24 HRS WP Date/Time: Person Contacted: Vehicle IN / OUT Date/Time Action/Instruction (X) Estimate												
Date/Time: Person Contacted: Vehicle IN/OUT Date/Time Action/Instruction (X) Estimate									D.O.	A. 26	3012018	
Date/Time Person Contacted: Vehicle IN/OUT Date/Time Action/Instruction (X) Estimate	CA / REV / REI	. / REV	24 HRS									
CSUMMY.					ted:							
1/7/18 Submit is \$6750, 5 days (Red \$ 1950, 20%)	Date/Time Acti	on/Instru	ction (X) Estin	ute.							
	1/7/18 5	ubni	Ly.	\$ 6750,	5 day	3 (Ru	ol 8	195	v, 7	77.)	
Enting pps + ps.	fr	lling	PPS of	PS.								

amount.	
	ASSIGNMENT
From: Date:	Veh No. FBG 3393K Yr Regn. 2012 / Jun 13
Estimated Cost:	Type: M.Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or XL 1200X Forty - Taigh
To Inspect Vehicle No:	Make: Harley Davidron Spurtater a.c 1202
at Workshop m/s	Colour Black . A/C: Insured / Std / NI / NA
of	Sp.Reading T/Radio: Insured / Std / NI / NA
Insured	Eng/No:
Policy No.	C/NO: 5HD 1LC3C5CC 400228 -
Claims No.	Gen. Cond: \$600 / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorfer) Jammed / Leaked / Burnt or
	Brake: Inofder/ Jammed / Leaked / Burnt or
(Client's Record) Make of Veh:	Modi: (Ni)/S/Rim / STD A/Rim or
Make of ven.	
(Dallar Condition)	Tyre Size: F: 110 70 R17 R: 120 70 R17
(Policy Condition) Remark: The veh had commenced its N/S	O/S BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO or
Bal. or Market Value: IDAC Accident Roort: Consistent? : Yes or No	R/Bal. 5 mm R/Bal. 5 mm
DAO AGGIOTE PORT	L/Bal. mm L/Bal. mm
5 7 1	D.O.A. D.O.I. 14 3 18
2 V I V N-	Survey held at Speedway mdw
Lum Sum: % 3 Val.: Yes or No	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
CA / REV / REP. / 24 HRS	IN / OUT
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
	12/7/2018.
Date/Time, File Pass to? : Preli. Report	Days Of Repair:
1) : Final Report Date/Time, File Return to?	Resurvey No. of Trip: Survey Fee:
	\dd Fee: : Site Insp (\$)s+Rssi
2)	Interview (\$) Photos
Report Format :	Tech Invs (\$) Others
Lump Sum / I.B.I: (\$	Weekend (\$
Lump sum / Lo. (4	VVegrend iv

...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status	
Main	29 Jan 2018		07 Mar 2018 14:27 Edit Adj Rpt			The Addition		Survey Report
	Main	R	eference	Clain	Details	Docume	ents	Show All
	UBFOLDER DET				TO ALL THE REAL PROPERTY.	[Cre	ated by insur	er]
Insured: Main Clain	nant:	TAN Y	HI CAPITAL ASIA EW TECK, ID: S1	PACIFIC PTE L	TD, Co. Reg. No.:	199400399N		
Vehicle Re	g. No.:		393К		of Loss:	[67 1	1/2018 13:00 - Months and 13 Date (Man Yr)]	:59 Days From LTA
Claim Type	e:	TP / N	/ISC/V/18-00018	6 Policy	//Cover Note No.:	(Com	/VPCP/17-0012 prehensive) rage: 01/06/20 5/2018	
Vehicle Re	g. No. (Insured):	SLD83	62P	Policy	No. (Claimant):	31/0:	5/2018	
		Encode		Exces				
Repairer:		East - 1	el: 63161611	(Toh Guan) No	. 36 Toh Guan Road	East #01-32 Ente	erprise Hub, 608	3580 Jurong
Handling I	nsurer:	MSIG 1 6594 2	insurance (Singap 541]	ore) Pte. Ltd. (HQ) - Tel: +65 682	7 7888 [Handle	d by Irene Tar	n Gek Ing -
Adjuster:		LKK Au	ito Consultants Pt 3/03/2018]	e Ltd (HQ) - Te	: 6256-3561 [Ha	ndled by MA CHIM	N FOOK] [II	mm.Advice
Driver/Cus	todian (Insured)		NG HUA (/ Male),	NRIC: S801244	14I			
ASSOCIA	TED MAIL REC	EIVED				\r •		
There are r	no mail for this ca	ase.				View A	Compo	se Case Mail

∃ ALL ASSO	CIATED TASK	S			View All Searce	th Tasks Cre	eate New Task	Complete
Due Dat	e Priority	Type Task G	roup Subject	Handler	Assigned By	Completed On	Created	

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

ACCIDENT STATEMENT

Date Of Report

29/01/2018 16:50

Date Of Accident

28/01/2018 13:30

Exact Location Of Accident

QUEENSWAY TOWARDS COMMONWEALTH AVE

Country/State of Loss

SINGAPORE

《李文明》 第5年第二十五年	DETAILS OF OWN VEHICLE
Vahiala Danist III	

Vehicle Registration Number

FBG3393K

Insured/Policyholder

Name Of Registered Owner

TAN YEW TECK

NRIC No

S1774435F

Email Address

DERRICKAEDANTAN@GMAIL.COM

Mobile Phone No.

(LOCAL) +65-97944944

Alternative Phone No

OTHERS-97944944

Vehicle Particulars

Manufacturer

HARLEY-DAVIDSON

Model

SPORTSTER 1200CC

Exact Purpose for which vehicle was being used at

time of accident

PRIVATE USE

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

MOTORCYCLE

Insurance Company

Name of Insurance Company

NTUC INCOME INSURANCE CO-OPERATIVE LTD

Type Of Coverage

THIRD PARTY FIRE AND/OR THEFT

Fleet Policy

NO

Policy Number

5077373351-02

Cover Note Number

Driver

Name of Driver DERRICK TAN PING

NRIC No Date Of Birth

S9301401D

11/01/1993 Occupation

Date Of Driving Pass

OUTDOOR

15/02/2017 **Driving Experience** 0 YEAR AND 11 MONTH

Gender

MALE

Mobile Number (LOCAL) +65-97944944

Fax Number

Contact Number

EMail Address

DERRICKAEDANTAN@GMAIL.COM

Address

663A JURONG WEST ST 65

#15-277

Postcode

641663

Was driver an employee of the Insured's Company

any NO

If No, Relationship of the Driver with the Insured

CHILDREN

Vehicle Registration Number of Driver's Own

Vehicle

-

Insurance Company of Driver's Own Vehicle

.

-

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

2

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

Police Station Name

NANYANG N.P.C

Police Station Address

ROAD: 2 JURONG WEST AVE 5 , POSTCODE: 649482 , COUNTRY:

SINGAPORE

Police Station Contact

TEL NO: 1800-7929999 - FAX NO:

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER ATTACHED.

Attachment(s)

YES

Are accident photos available for attachment?

ILC

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SLD8362P

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category Name of Driver PRIVATE CAR YEO JIONG HUA

NRIC/Passport Number

Contact Number

96573722

Address

Postcode

Insurance Company Name

Nature Of Damage

Page 2 of 26

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me:
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time:


Driver's \$\square \text{Qnature} \text{
(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Page 4 of 26

Sketch Plan #2 Pg. 1



Policyholder's Signature

Reporting Centre Personnel's Signature

Annex D



NOTICE OF COMPLIANCE

This is to confirm that <u>DERRICK TAN PING</u>, S9301401D, 663A JURONG WEST ST 65,S'PORE 641663 HP: 97944944 riding vehicle FBG3393K, has reported to the police a non-injury traffic accident which occurred along <u>COMMONWEALTH AVENUE</u> on <u>28/01/2018</u> at about <u>1330hrs</u> involving a <u>VEHICLE</u>, <u>SLD8362P</u>, <u>YEO JIONG HUA</u>, S8012444I, HP:96573722, However, no one is injured and no government property involved.

2 He / She has therefore complied with Sec 84(2) of the Road Traffic Act, Cap 276.

Date: <u>28/01/2018</u> S/D Ref; 60

Name of Issuing Officer: <u>Sgt Muhd Jameer</u> Police Post/Unit: <u>Jurong Division / Nanyang NPC</u>

> NANYANG NPC 2 JURONG WEST AVE 5 SINGAPORE 649482 TEL: 1800-7929999

This form was generated from Nanyang NPC

LHTEO Appraisal Services

3 Gambas Crescent, #07-14 Nordcom 1, Singapore 757088 Tel. 63966319 Fax: 63966320 Email: lhtas@singnet.com.sg

Loss Adjuster, Consulting Automotive Engineer, Accident Reconstruction & Analyst.

VEHICLE APPRAISAL REPORT

Mr

Tan Yew Teck

Blk 663A Jurong West St 65

15-277

Singapore - 641663

Our Ref

: TP/1803/FBG3393/IM

Date

: 17 April 2018

REFERENCE PARTICULARS

Your Reference No

: Not Advised

Date of Assignment

: 13 Mar 2018

Date of Accident

: 28 Jan 2018

Date of Inspection

: 13 Mar 2018

Date of Re-inspn.

: N/A

PARTICULARS OF VEHICLE

Regn. No

: FBG 3393K

Odometer

: 31439km

Make

: HARLEY DAVIDSON

Color

: Black

Model

: SPORTSTER XL1200X

Chassis No.

: 5HD1LC3C5CC400228

Year

: 2012 (COE.Exp : Jun 2022)

Engine No

: LC3C400228

TYRE / CONDITION

Location

Make

Size

Thread Balance

Front Rear

Bridgestone Bridgestone 110 / 70 - 17 130 / 70 - 17

5 mm 5 mm

DAMAGE PROFILE

The motor cycle sustained damage on Rear and right side.

Please refer to photographs and assessment of repairs for details.

ASSESSMENT SUMMARY

Repair cost to the vehicle is assessed as \$ 8,700.00 lump sum.

Survey conducted at: I- Motoring

Enclosed (28) photographs depicting damage to the vehicle.

Estimated time required for repairs: (6) days.

The survey was conducted on a WITHOUT PREJUDICE BASIS.

ASSESSMENT FOR REPAIR: FBG 3393K

Qty	Description		Repairer's	Our
1 pc		Condition	Estimate	Assessment
	Brake lever	Cut	113.00	113.00
1 pc		Broken	194.00	194.00
1 pc		Cut	67.00	67.00
1 pc	Brake pedal	Grazed	184.00	184.00
1 pc	Footrest RH	Grazed	156.00	156.00
1 pc	Footrest bracket RH	Grazed	304.00	304.00
1 pc	Rear mudguard	Grazed	1,143.00	1,143.00 XR
2	Rear signal light & bracket complete @			LH-brov, RH-Xnn
pcs	\$691/-	Broken/grazed	1,382.00	1,382.00 69/
l pc	Rear license plate lamp	Cut	156.00	156.00
l pc	Exhaust muffler upper	Cut	3,412.00	3,412.00
1 pc	Exhaust muffler gasket upper	Necessary	28.00	14.00
1 pc	Exhaust muffler lower	Cut	2,746.00	2,746.00 /
1 pc	Exhaust muffler gasket lower	Necessary	28.00	14.00
			9,913.00	9,885.00
			991.3	988.5
			8,921.70	8,896.50
			-,	7245.90
	Special nett Items			
1 pc	Rear number plate	Cracked	30.00	20.00
		-	30.00	20.00
			50.00	20.00
	Labour Charges			
1	Realign front fork		350.00	200.00 120
2	Remove and realign rear swing arm		500.00	400.00 200
3	Spray painting fuel tank (Special colour)		1,000.00	
4	Check electrical		40.00	800.00 400
5	Workmanship		700.00	20.00 -
		_	2,590.00	550.00 450
			2,390.00	1,970.00
				- 40
	Total Parts & Labour Concluded		11 541 70	8455,90
			11,541.70	10,886.50
	Lump Sum Adjusted Repair			8,700.00
				10.886.50 8.700.00 2/5\$ 6750 5days.

Our Ref.: TP/1803/FBG3393/IM

ADJUSTMENT/RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle. We have listed the breakdown of our findings and our recommendation as per assessment above.

Inspected by

Bok Jee Tan

Faithfully Yours

L H TEO Appraisal Services

Teo Liak Hoo

Advance Automotive Engineer (UK)
Dip. Mech. Engr. M Prof BTM(Dip.BTM)

MIIE, MIMI, AMSIM an

...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj S	Submitted	Ins Auth'ed	Status		
Main	29 Jan 2018		07 Mar 2018 14:27 Edit Adj Rpt	S\$6,750.00 Edit Estimates		,750.00 ew Rpt		Pending for Report Cancel Case		
	Main	R	eference	Claim De	tails		Documents		Show All	
CLAIM S	JBFOLDER DE	TAILS				[Created	by insurer]			
Insured:	HITACHI	CAPITAL ASIA P	ACIFIC PTE LTD,	Co. Reg. No.: 199	1003991	N				
Main Claimant:	TAN YEW	TECK, ID: S17	74435F							
Vehicle Re No.:	g. FBG339	зк		Date o	Loss:	[67 Months	3 13:00 - :59 s and 13 Days From		(Man Yr)]	
Claim Type: TP / MSC/V/18-000186				Policy/ Note N		MSD/VPCP/17-001233-00 (Comprehensi Coverage: 01/06/2017 - 31/05/2018			sive)	
Vehicle Re No. (Insured):	SLD8362	P		Policy (Claim						
				Excess						
Repairer:	Speedwa	y Motor Pte Ltd	(Toh Guan) No. 36	Toh Guan Road Ea	st #01-:	32 Enterpris	e Hub, 608580 Juror	ig East - Tel: 6	3161611	
Handling Insurer:							Irene Tan Gek Ing			
Adjuster:	08/03/20		Ltd (HQ) - Tel: 62	56-3561 [Handle	ed by M	OHD TAUF	IKH BIN HAMID]	. [Imm.Adv	ice due	
Driver/Cus dian (Insured):	YEO JIONO	G HUA (/ Male),	NRIC: S8012444I							
ASSOCIA	TED MAIL RE	CEIVED					View A	All Compos	e Case Mai	
There are	no mail for this	case.								
ALL ASS	OCIATED TAS	SKS⊡			V	/iew All S	Search Tasks Crea	te New Task	Complet	
Due Da	te Priority	Type Task	Group Subjec	t Handler	Assign	ed By	Completed On	Created On	Done	

Claim Documents

*FBG3393K (MSC/V/18-000186) [SLD8362P] TP TAN YEW TECK Jan 28 2018 1:00PM [HITACHI CAPITAL ASIA PACIFIC PTE LTD] Speedway Motor Pte Ltd

Asc	essment Report	s		1 per page	V V
No	Finalized On		ance (Singapore) Pte. Ltd. (HQ)		nail Prin
		Accident S		■ Load HT	
1	07/03/18 14:27	From:SC - Reg	No: SLD8362P, Claimant: HITACHI CAPITAL ASIA PACIFIC PTE LTD	3 2000 111	
Pho	tos/Images			3 per page	▽
No	Relabel/Reorde	er LKK Auto (onsultants Pte Ltd (HQ)	Thumbr	nail Prin
1	12/07/18 12:19	General Vi		1 Load JF	G 🗸
2	12/07/18 12:19	General Vi	w	1 Load JF	G 🗹
3	12/07/18 12:19	General Vi	w	1 Load JF	G 🗹
4	12/07/18 12:19	General Vi	w	1 Load JF	og √
5	12/07/18 12:19	General Vi	w	1 Load JF	G 🗹
6	12/07/18 12:19	General Vi	w	1 Load JF	G 🗹
7	12/07/18 12:19	General Vi	w	1 Load JF	G 🗹
8	12/07/18 12:19	General Vi	w	1 Load JF	G 🔽
9	12/07/18 12:19	General Vi	w	1 Load JF	G 🗹
10	12/07/18 12:19	General Vi	w	1 Load JF	G 🔽
11	12/07/18 12:19	General Vi	w	1 Load JF	G 🔽
12	12/07/18 12:19	General Vi	w	1 Load JF	G 🔽
13	12/07/18 12:19	General Vi	w	1 Load JF	G 🗸
14	12/07/18 12:19	General Vi	w	1 Load JF	G 🗹
15	12/07/18 12:19	General Vi	w	1 Load JF	G 🗸
16	12/07/18 12:19	General Vi	w	1 Load JF	G 🔽
17	12/07/18 12:19	General Vi	·w	1 Load JF	G 🗹
18	12/07/18 12:19	General Vi	w	Load JF	G 🔽
19	12/07/18 12:19	General Vi	w	1 Load JF	G 🔽
20	12/07/18 12:19	General Vi	w	1 Load JF	G 🗹
21	12/07/18 12:19	General Vi	w	1 Load JF	G 🔽
22	12/07/18 12:19	General Vi	w	1 Load JF	G 🔽
23	12/07/18 12:19	General Vi	w	1 Load JF	G 🗹
24	12/07/18 12:19	General Vi	w	1 Load JF	G 🗹
25	12/07/18 12:19	General Vi	w	1 Load JF	G 🗸
26	12/07/18 12:19	General Vi	w	1 Load JF	G 🗹
27	12/07/18 12:19	General Vi	w	1 Load JF	G 🗸
28	12/07/18 12:19	General Vi	w	1 Load JF	G 🔽
29	12/07/18 12:19	General Vi	w	1 Load JF	G 🗹
30	12/07/18 12:19	General Vi	w	1 Load JF	G 🗹
31	12/07/18 12:19	General Vi	ew	1 Load JF	PG ☑
32	12/07/18 12:19	General Vi		1 Load JF	og 🔽
33	12/07/18 12:19	General Vi	NW .	Load JF	G 🗹

Page 2 of 2

Ass	essment Reports		1 per p	oage 🔻	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
34	12/07/18 12:19	General View	Ø	Load JPG	✓
35	12/07/18 12:19	General View	0	Load JPG	✓
36	12/07/18 12:19	General View	0	Load JPG	✓
37	12/07/18 12:19	General View	0	Load JPG	✓
38	12/07/18 12:19	General View	0	Load JPG	V
39	12/07/18 12:19	General View	0	Load JPG	~
40	12/07/18 12:19	General View	Ð	Load JPG	✓
41	12/07/18 12:19	General View	0	Load JPG	V
42	12/07/18 12:19	General View	0	Load JPG	✓
43	12/07/18 12:19	General View	0	Load JPG	V
44	12/07/18 12:19	General View	0	Load JPG	~
45	12/07/18 12:19	General View	0	Load JPG	V
46	12/07/18 12:19	General View	0	Load JPG	~
47	12/07/18 12:19	General View	0	Load JPG	V
48	12/07/18 12:19	General View	0	Load JPG	V
49	12/07/18 12:19	General View	0	Load JPG	V
50	12/07/18 12:19	General View	0	Load JPG	V
51	12/07/18 12:19	General View	0	Load JPG	✓
52	12/07/18 12:19	General View	0	Load JPG	V
53	12/07/18 12:19	General View	0	Load JPG	V
Doc	cumentation		1 per	page V	V
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	1 pc, 1	Thumbnail	-
1	07/03/18 14:30	PRI	0	Load PDF	
2	07/03/18 14:30	TP GIA REPORT	ō	Load PDF	
3	07/03/18 14:36	Email to TP reject thier SJE	0	Load PDF	
4	16/05/18 10:24	LOD - FBG3393K.pdf	0	Load PDF	
5	16/05/18 10:24	REPAIR BILLING - FBG3393K.pdf	0	Load PDF	
6	16/05/18 10:24	L H TEO APPASIAL SERVICES TAX INVOICE - FBG3393K.pdf	O	Load PDF	
7	16/05/18 10:24	L H TEO APPASIAL SERVICES REPORT - FBG3393K.pdf	0	Load PDF	
8	16/05/18 10:24	TP SURVYOR PHOTO 1 - FBG3393K.pdf	Ō	Load PDF	
9	16/05/18 10:24	TP SURVYOR PHOTO 2 - FBG3393K.pdf	0	Load PDF	
10	23/05/18 17:28	instruction to LKK to upload final survey report	0	Load PDF	

Documents Checklist

	^
	~

LKK Auto Consultants Pte Ltd (Co.Reg. No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS3/MSG18004426/T1QD3E2

Date:

12/07/2018

REFERENCE

Handling Insurer:

MSIG Insurance (Singapore) Pte. Policy No:

MSD/VPCP/17-001233-

Claimant Vehicle

Insured Vehicle

Nature of Claim:

FBG3393K

Date of Loss:

28/01/2018

No:

SLD8362P

TP

Claim No:

MSC/V/18-000186

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

FBG3393K

Make & Model:

HARLEY-DAVIDSON SPORTSTER, 1.2 XR1200X

Engine No:

LC3C400228

0 km

Reg. Date:

15/06/2012 (Man. Year: 2011)

Chassis No: Odometer:

5HD1LC3C5CC400228

Colour: Engine Capacity:

1202 cc

Market Value/New Car Price: N/A Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

Pre-accident Condition: No

CONDITION OF TYRES

Front Tyre Size:

110/70 R17

Rear Tyre Size:

130/70 R17

Front Left Side:

Bridgestone 5 mm

Rear Left Side:

Bridgestone 5 mm

Front Right Side:

0 mm

Rear Right Side:

0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,951.70	7,265.90	1,685.80	18.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,590.00	1,190.00	1,400.00	54.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,541.70	8,455.90	3,085.80	26.74
Approved Total (Overridden) (S\$)		6,750.00		
(S\$)	11,541.70	6,750.00	4,791.70	41.52
+ GST 7.00/7.00% (S\$)	807.92	472.50	335.42	41.52
Nett Amount (S\$)	12,349.62	7,222.50	5,127.12	41.52

INSPECTION

Date of Assignment:

07/03/2018

Date Inspected:

14/03/2018 Inspected At:

Speedway Motor Pte Ltd (Toh Guan) No. 36 Toh Guan Road East #01-32

Enterprise Hub

Singapore 608580

Estimated Period of Repair:

5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Referen	ce			
Part Source:		(Last Synchronised: 12 Jul 2018)		
Parts:	N/A	HARLEY-DAVIDSON SPORTSTER 1.2 XR1200X (Model not available in database)		
Labour:	Repairer's	(Price-denominated Standard List)		
Print Code:	rint Code: (Unsubmitted, no print-code for FBG3393K)			
Validity:	These estimated numbers with	ates are valid only if they contain the print code (above) on all estimate pages, running page in the END OF ESTIMATES marker on the last estimate page		
Further Info	: Items/values	not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HANDLE GRIP	Cut	113.00 FL	*113.00 FL
2	1		*BRAKE LEVER	Broken	194.00 FL	*194.00 FL
3	1		*MIRROR RH	Cut	67.00 FL	*67.00 FL
4	1		*BRAKE PEDAL	Grazed	184.00 FL	*184.00 FL
5	1		*FOOTREST RH	Grazed	156.00 FL	*156.00 FL
6	1		*FOOTREST BRACKET RH	Grazed	304.00 FL	*304.00 FL
7	1		*REAR MUDGUARD	Repair	1,143.00 FL	*- FL
8	1		*REAR SIGNAL LIGHT & BRACKET COMPLETE	N/s Broken/O/s Not Necessary	1,382.00 FL	*691.00 FL
9	1		*REAR LICENSE PLATE LAMP	Cut	156.00 FL	*156.00 FL
10	1		*EXHAUST MUFFLER UPPER	Cut	3,412.00 FL	*3,412.00 FL
11	1		*EXHAUST MUFFLER GASKET UPPER	Necessary	28.00 FL	*14.00 FL
12	1		*EXHAUST MUFFLER LOWER	Cut	2,746.00 FL	*2,746.00 FL
13	1		*EXHAUST MUFFLER GASKET LOWER	Necessary	28.00 FL	*14.00 FL
14	1		*REAR NUMBER PLATE	Cracked	30.00 FS	*20.00 FS
F=Fra	nchise	part. S=S	SpcNett. L=ListItemDisc.			SIL SECON SEC
				Sub Total (S\$)	9,943.00	8,071.00
	- List Item Discount on L Items 10.00/10.00% (S\$)				991.30	805.10
				Total Parts (S\$)	8,951.70	7,265.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	REALIGN FRONT FORK	New	350.00	120.00
2	REMOVE AND REALIGN REAR SWING ARM	New	500.00	200.00
3	SPRAY PAINTING FUEL TANK (SPECIAL COLOUR)	New	1,000.00	400.00
4	CHECK ELECTRICAL	New	40.00	20.00
5	WORKMANSHIP	New	700.00	450.00
	Gross L	abour Cost (S\$)	500.00 1,000.00 40.00	1,190.00
	Report was unsubmitted d			

< END OF ESTIMATES >