

ASS. REC. BY:

REF: CS/CTI18004129/Uqd3e

Special Instruction:

Survivor:
Meinen

Marcus

ASSIGNMENT (Office)

From (Person):

Thane Tay

of

CTI

Date/Time:

7/3/18 2:49pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJV 1256Y

Insured:

at Workshop m/s

Car City Auto

Tel:

67810300

of

Blk 9006 # 01-98 Tampines sf-93

Policy No:

DMPCS N1689821701

Claim No:

SNM18D01146C01

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

02/03/2018

CA / REV

/ REP.

/ REV 24 HRS

Date/Time:

3:40pm 7/3/18

Person Contacted:

Mr. Ho

H.O.D. Endorsement:

Vehicle:

INT UT

Date/Time	Action/Instruction (✓) Estimate
	SJV 1256Y - X
13/3/18 @	4:59pm revert to Thane Tay via Meinen.
19/3/18 @	5:41pm Alfred informed C/A at 7041.79, via Meinen. (\$ ex: waived)
20/3/18 @	11:43am informed Mr HO C/A & ex: waived by email.
19/5/18 @	2:59pm confirmed with Mr HO final fig \$1765.81, 4 days by email.
	Cled \$ (1930.47, 57%)

(08/11/13) wef

CS/CTI18004429/49d3

REF:

ASS. REC. BY: MERCUS

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: 534/12561at Workshop m/s Car city

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: NIL

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 62

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 4 days

Res.: Yes or No

Lum Sum: 1-B-1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: 534/12561Yr Regn: 12 16Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAMake: HondaVezel / VRC c.c. 1496Colour: wh-bl

A/C: Insured / Std / NI / NA

Sp. Reading: 1193

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: RU11205257Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / STD A/Rim or

Tyre Size: F: 225/45R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 7 mmR/Bal. 7 mmL/Bal. 7 mmL/Bal. 7 mmD.O.A. 2/3/18D.O.I. 12/3/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

27A 37442Det 6800Summit 1/9P-874

RECEIVED 21 MAY 2018

Date/Time, File Pass to?

☐ : Preli. Report

1) 21/5 2018

☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 4Resurvey No. of Trip: 1

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)Survey Fee: 220

Transportation: _____

S + RS, SI

Photos

Others

TOTAL

Report Format: MER-ODLump Sum / I.B.I. (\$) 1765.81

220
220



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18004429/Uqd3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 07-03-2018



Code : CTI

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SJY 1256Y
Policy No.	DMPCSN1689821701	Coverage (\$)	0.00
Claim No.	SNM18D01146C01	Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAY)	Assign Date	07/03/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	02/03/2018	Inspection Date	
Survey held at	CAR CITY AUTO CENTRE PTE LTD BLK 9006 TAMPINES ST 93 #01-198 SINGAPORE 528840		

5a. Remarks

- A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Mar 2018 Sendback Est	06 Mar 2018 18:05 S\$3,696.28	07 Mar 2018 14:49 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	TAN HAN WEI AARON, ID: S8425472Z, Tel: +6598734768, Email: NOEMAIL		
Vehicle Reg. No.:	SJY1256Y	Date of Loss:	02/03/2018 19:00 - :59
Claim Type:	OD / SNM18D01146C01	Policy/Cover Note No.:	DMPCSN1689821701 (Comprehensive)
		Excess:	S\$0.00
Repairer:	Car City Auto Centre Pte Ltd (HQ) Blk 9006 #01-198, Tampines Street 93, 528840 Tampines - Tel: 6781 0300		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 16/03/2018]		
Driver/Custodian:	TAN HAN WEI AARON (33 / Male), NRIC: S8425472Z, Tel: +6598734768		
Adj Asg. Remarks:	PLEASE SURVEY AND REVERTO		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAuto)

From: CAR CITY AUTO CENTRE PTE LTD <ccacpl@singnet.com.sg>
Sent: Saturday, 19 May 2018 2:59 PM
To: Shiau Chan (LKKAuto)
Subject: Re: RE: VEHICLE SJY 1256Y (DOA: 02/03/2018)

Ok thank you.

Ho

-----Original Message-----

From : siewsc@lkkauto.com
Date : 18/05/2018 - 17:47 GMT+8
To : ccacpl@singnet.com.sg
Cc : sur@lkkauto.com
Subject : RE: VEHICLE SJY 1256Y (DOA: 02/03/2018)

Dear Mr Ho,

Offer final fig \$1,765.81 before GST and 4 repair days.

Kindly confirm.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAuto)
Sent: Tuesday, 20 March 2018 11:43 AM
To: ccacpl@singnet.com.sg
Cc: SUR <sur@lkkauto.com>
Subject: VEHICLE SJY 1256Y (DOA: 02/03/2018)

Dear Mr Ho,

As instructed by our client China Taiping Insurance, please proceed to repair the insured vehicle **SJY 1256Y (excess WAIVED)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Tuesday, 20 March 2018 11:43 AM
To: ccacpl@singnet.com.sg
Cc: SUR
Subject: VEHICLE SJY 1256Y (DOA: 02/03/2018)
Attachments: SJY1256Y INS REVISED AUDATEX.pdf

Dear Mr Ho,

As instructed by our client China Taiping Insurance, please proceed to repair the insured vehicle **SJY 1256Y (excess WAIVED)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	06 Mar 2018 18:03	Clim Veh Model Changed	(204586) HONDA VEZEL 1.5 X CVT (A).	[R] Ho Too Boon
2	06 Mar 2018 18:03	Clim Created	Reg No: SJY1256Y. Policy No: DMPCSN1689821701. Acct Date: 2018/03/02. Claim Type: OD. Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ). Workshop: Car City Auto Centre Pte Ltd (HQ). Created from SAS:MCCA18030258	[R] Ho Too Boon
3	06 Mar 2018 18:05	Clim Submitted	3696.28.	[R] Ho Too Boon
4	07 Mar 2018 14:49	Clim Registration Modified	Excess: -> 0.00.	[I] Irene Tay Hui Ping
5	07 Mar 2018 14:49	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):PLEASE SURVEY AND REVERTO	[I] Irene Tay Hui Ping
6	07 Mar 2018 14:49	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/03/16	[I] Irene Tay Hui Ping
7	07 Mar 2018 14:49	Adj Mandate Set	Approved:0.00.	[I] Irene Tay Hui Ping
8	07 Mar 2018 15:40	Assignment 1st Accessed		[A] Nivitha Govindasamy
9	07 Mar 2018 17:27	Adj Adjuster Assigned	[None] -> MARCUS CHUA	[A] Nivitha Govindasamy
10	13 Mar 2018 09:57	Adj Rpt Initiated		[A] SHIAU CHAN
11	13 Mar 2018 09:59	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/03/16	[A] SHIAU CHAN
12	13 Mar 2018 09:59	Adj Mandate Request	Cur.Reg:2986.88:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
13	19 Mar 2018 17:41	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/03/16. Mandate Remarks: PLEASE PROCEED TO AUTHORIZE REPAIRS AT \$2,041.79. EXCESS IS WAIVED.	[I] Alfred Toh
14	19 Mar 2018 17:41	Adj Mandate Set	Approved:2041.79:PLEASE PROCEED TO AUTHORIZE REPAIRS AT \$2,041.79. EXCESS IS WAIVED.Reinsp:Adj decides.	[I] Alfred Toh

ACTIVITY

[07/03/2018 15:42] Nivitha Govindasamy:
Vehicle not in workshop, repairer will arrange.

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1741107	06/03/2018 18:03	Motor	Car City Auto Centre Pte Ltd (HQ)	Car City Auto Centre Pte Ltd (HQ)	SJY1256Y		xx.xx
1746420	13/03/2018 09:57	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SJY1256Y		10.70

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tay Hui Ping

Date: 13 Mar 2018

Preliminary Advice

Vehicle No	: SJY1256Y	Accident Date	: 02/03/2018
Make	: HONDA VEZEL	Policy No.	: DMPCSN1689821701
Assignment Date	: 07/03/2018	Excess	: S\$0.00
Date of Inspection	: 12/03/2018	Est. Duration of Repair	: 4.00
Inspection At	: CAR CITY AUTO CENTRE PTE LTD (HQ) BLK 9006 #01-198, TAMPINES STREET 93 SINGAPORE 528840		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,696.28
Revised Amount	:S\$	1,722.88
Check Items (Estimated)	:S\$	1,264.00
Total	:S\$	2,986.88

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	62,000.00
COE / PARF Rebate	:S\$	37,442.00
Salvage Value	:S\$	
Margin for Repair	:S\$	24,558.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : WE HAVE NOT AUTHORISE REPAIR.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5472Z
Vehicle Details	
Vehicle No.:	SJY1256Y
Vehicle to be Exported:	No
Intended De-registration Date:	12 Mar 2018
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	L15B4405250
Chassis No.:	RU11205251
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$22,548.00
Original Registration Date:	30 Dec 2016
First Registration Date:	30 Dec 2016
Transfer Count:	0
Actual ARF Paid:	\$13,568.00 6784
OPC Cash Rebate Details	
OPC Cash Rebate Eligibility:	No
OPC Cash Rebate Eligibility Expiry Date:	-
OPC Cash Rebate Amount:	-
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Dec 2026
PARF Rebate Amount:	\$10,176.00
Intended COE Rebate Details	
COE Expiry Date:	29 Dec 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$31,000.00
COE Rebate Amount:	\$27,266.00
Total Rebate Amount:	\$37,442.00

The information contained herein is correct as at 12 Mar 2018

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 5472Z

Vehicle Details

Vehicle No.: SJY1256Y

Vehicle to be Exported: Yes

Intended De-registration Date: 10 Mar 2018

Vehicle Make: HONDA

Vehicle Model: VEZEL 1.5X CVT

Primary Colour: White

Manufacturing Year: 2016

Engine No.: L15B4405250

Chassis No.: RU11205251

Maximum Power Output: 96.0 kW (128 bhp)

Open Market Value: \$22,548.00

Original Registration Date: 30 Dec 2016

First Registration Date: 30 Dec 2016

Transfer Count: 0

Actual ARF Paid: \$13,568.00

OPC Cash Rebate Details

OPC Cash Rebate Eligibility: No

OPC Cash Rebate Eligibility Expiry Date: -

OPC Cash Rebate Amount: -

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 29 Dec 2026

PARF Rebate Amount: \$10,176.00

Intended COE Rebate Details

COE Expiry Date: 29 Dec 2026

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$31,000.00

COE Rebate Amount: \$24,800.00

Total Rebate Amount: \$34,976.00

The information contained herein is correct as at 03 Mar 2018

OK

SGCARMART.COM

Login

Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

FREE VALUATION

Let us tell you how much your car can sell for!

No obligations and it's FREE!

How much is my car worth?

1

2

3

4

5

6

How much is my car worth?

1

2

3

4

5

6

Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New Mercedes Benz GLC250 4MATIC AMG Line

Immediate COE Registration, 1 Day Delivery! While Stocks Last! 3 Years Warranty. Apex Trading Pte Ltd StarAd

HIN LUNG AUTO

HoBee (Sole Agent)

30 years of car sale

One Stop Car Hub

Finance, Insurance, Workshop

New and Used Cars

Browse by Category

« Back (1 2 3 4 5 6) Next »

Sort by Date Posted

20 results/page

108 vehicles		Honda Vezel		Advanced Search		Submit			
	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Honda Vezel		Any	Any	2016	Any	Any	Any	Available
<div><div></div></div>	Honda Vezel	1.5A X	\$77,888	\$8,920 /yr	10-May-2016	1,496 cc	-	SUV	Available
Most Reliable Car In The Market. New Paint Work. Excellent Condition Interior & Exterior. Buying With A Peace Of Mind, 6 Months In House Warranty For Engine And Gear Box. Flexible Loans Package Availa...									
Posted: 12-Mar-2018 Tags: 2016 Honda Vezel, Honda Vezel, Honda, Vezel, Used Honda									
<div><div></div></div>	Honda Vezel	1.5A X	\$80,000	\$9,560 /yr	29-Jan-2016	1,496 cc	25,400 km	SUV	Available
Elegant White SUV, Low Maintenance Cost, Very Well Maintained By Meticulous Owner. Car In Tip Top Condition. Up To 80% Financing Possible! Trade In Welcome! Why Wait? Call/Sms To Arrange A Viewing Tod...									
Posted: 12-Mar-2018 Tags: 2016 Honda Vezel, Honda Vezel, Honda, Vezel, Used Honda									
<div><div></div></div>	Honda Vezel	1.5A X	\$79,800	\$9,110 /yr	18-May-2016	1,496 cc	12,000 km	SUV	Available
New Arrival! Cheapest In The Market! \$3000 Drive Away! Look Like New Car Seldom Use! High Trade In Welcome! Call Me Now To View The Car Before It's Sold!									
Posted: 12-Mar-2018 Tags: 2016 Honda Vezel, Honda Vezel, Honda, Vezel, Used Honda									
<div><div></div></div>	Honda Vezel	1.5A X	\$79,800	\$9,140 /yr	16-May-2016	1,496 cc	13,210 km	SUV	Available
Well Groomed And Taken Care Off By Careful Owner, Trade In Welcomed, In House/Bank Loan Available With Flexible Interest Rates, Kindly Contact Our Sales Advisor For An Appointment Or Test Drive. Buy/S...									
Benefit Auto Enterprise Pte Ltd									
Posted: 12-Mar-2018 Tags: 2016 Honda Vezel, Honda Vezel, Honda, Vezel, Used Honda									
Car Buying									
Car Selling									
Car Aftermarket									
Car Ownership									
On The Move									
Lifestyle									
Buy Tyres Online!									
Latest Special Offers from Tyrepac!									
<div><div></div></div>	Honda Vezel	1.5A X	\$81,666	\$9,300 /yr	25-May-2016	1,496 cc	25,000 km	SUV	Available
Top The Subcompact SUV With It's Spacious Cabin, Quality Interior, Smooth Ride, And Excellent Generous 453 Litre Boot Cargo Space. Reliability Is Absolute Without Doubt And Offers High Level Of Practi...									
Creative Auto									
Posted: 12-Mar-2018 Tags: 2016 Honda Vezel, Honda Vezel, Honda, Vezel, Used Honda									
<div><div></div></div>	Honda Vezel	1.5A X	\$81,800	\$9,450 /yr	05-May-2016	1,496 cc	17,000 km	SUV	Available
\$9K Down Payment. Latest 2016 Silver Honda Vezel Model, Low Mileage, Extremely Well Maintained! Buy With A Peace Of Mind, Low Depreciation And Good Fuel Economy, Trade In Welcome, Flexible Bank/In Hou...									
Posted: 12-Mar-2018 Tags: 2016 Honda Vezel, Honda Vezel, Honda, Vezel, Used Honda									
Honda Vezel 1.5A X									
\$79,800									
\$9,110 /yr									
18-May-2016									
1,496 cc									
13,202 km									
SUV									
Available									
Very Low Mileage Done, Well Groomed And Taken Care Off By Careful Owner, Trade In Welcomed, In House/Bank Loan Available With Flexible Interest Rates, Kindly Contact Our Sales Advisor For An Appointme...									
Compare									

http://www.sgcarmart.com/used_cars/listing.php?MOD=Honda+Vezel&AVL=2&RPG=20&AVL=2&...

12-Mar-18

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/03/2018 09:35
Date Of Accident	02/03/2018 19:55
Exact Location Of Accident	ALONG CTE TOWARDS CITY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJY1256Y
Insured/Policyholder	
Name Of Registered Owner	TAN HAN WEI AARON
NRIC No	S8425472Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98734768
Alternative Phone No	OTHERS-98734768

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL-1.5 X CVT (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN1689821701
Cover Note Number	

Driver

Name of Driver	TAN HAN WEI AARON
NRIC No	S8425472Z
Date Of Birth	24/08/1984
Occupation	INDOOR
Date Of Driving Pass	10/12/2003
Driving Experience	14 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98734768
Fax Number	
Contact Number	OTHERS-98734768
Email Address	NOEMAIL

Address	BLK 130A TOA PAYOH LOR 1 #24-500
Postcode	311130
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	5
Passenger 1	NAME: : LIM QUA LIM GENDER: : FEMALE
Passenger 2	NAME: : AH MA GENDER: : FEMALE
Passenger 3	NAME: : ISTI GENDER: : FEMALE
Passenger 4	NAME: : LING JUN YING GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AS PER ATTACHED SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLT2145E
Vehicle Make/Model/Colour	MERCEDES BENZ WHITE COLOUR
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	YEO KAY HIONG

NRIC/Passport Number	S7021745G
Contact Number	97543995
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	REAR
No. Of Passenger (Including Driver)	1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

A - SJY1256Y

B - SLT2145E

[Signature]



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 02/03/18, while driving along CTE, traffic was heavy but smooth. As I was driving towards Orchard, the vehicle in front of about 2 cars ahead suddenly jam brake. Everyone had to make an e-brake to stop their vehicle. As the road was slippery & wet, my vehicle could not stop in time and it bump into the car in front despite making e-brake. After exchange contact with the front car owner, everyone went ahead with each other road.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

**CAR CITY AUTO CENTRE
PTE LTD
BLK 9006 TAMPINES
STREE 93**

**#01-198
SINGAPORE 528840**

**Claim Reference: CCA00356
Assessment Number: CCA00356
Version: CAR CITY/1
Date Calculated: 06/03/2018 08:59**

**Full Report - V1
Registration: SJY1256Y
Printed: 06/03/2018 16:59**

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	HO TOO BOON	Date of Incident:	02/03/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:	CCA00356	Estimated Repair Time:	
Policy Number:	DMPCSN1689821701	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

*Not Authorised
Main
Tulip before
painting.
4 days.
Excess Nil
12/3/18*

Vehicle Details

Vehicle

Manufacturer:	HONDA
Model:	Vezel
Sub Model:	EX
Model Sheet Number:	HVE 06
Registration:	SJY1256Y
Registration Month:	December
Registration Year:	2016
VIN Number:	RU11205251
Manufacture Year:	2016
Odometer:	Not Known
Colour:	White
Engine Number:	L15B4405250
Fuel Level:	%

Model Specs

FROM MODEL 2016	2 ZONE AUTO AIR CON
TINT GLASS (PRIVACY)	RR WDW REG W/PULSE G
TENS-/START SYS LINE	MIRROR WITH TIP FUNC
LANE CHANGING ASSIST	NAVIGATION SYSTEM
DISPLAY LCD 7.0	FOG LAMPS
SIDE FLASHER	LED HEADLAMP
REAR COMBI LIGHT	AUTO HEADLAMP LEVEL
AUTO HEADLAMP LEVEL	RAIN-/DR/LIGHT SENS
CHROME DOOR HANDLES	AUTO DIPPING MIRROR
COLLISION WARN SYS	REARVIEW CAMERA
ANTI-THEFT ALARM	REAR PARKING SYSTEM
1.5 LTR 88KW	GEARBOX CVT
STRG COLUMN ADJUST	EMERG BRAKE ASSIST
CRUISE CONTROL	TYRES 215/55 VR 17
WHEELS 7J X 17 ALLOY	STABILITY PROGRAM
PANORAMA SUNROOF	PAINTING OFF VEHICLE
PAINTED MOULDINGS	TWO COAT PEARL/MICA

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Good
Steering:	Satisfactory
Brakes Pedal Travel:	Satisfactory
Place of Inspection:	
Pre-Accident Damage:	
Tyres Condition:	Good

<p>Severity of Impact: Heavy Panel</p> <p>Vehicle Status on Inspection: Roadworthy</p> <p>Date of Inspection: 04/03/2018</p> <p>• Parts prices are subject to confirmation</p> <p>• Third party survey is on a "Without Prejudice" basis</p> <p>• No illegal modification(s) is allowed</p> <p>• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</p> <p>Acknowledged by Repairer</p> <p>Signature:</p> <p>Date:</p>	<p>Severely damaged parts during resurvey</p> <p>Parts prices are subject to confirmation</p> <p>Third party survey is on a "Without Prejudice" basis</p> <p>No illegal modification(s) is allowed</p> <p>Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</p>
--	--

CAR CITY AUTO CENTRE PTE LTD

Claim Reference: CCA00356

Assessment Number: CCA00356

Version: CAR CITY/1

Date Calculated: 06/03/2018 08:59

Full Report - V1

Registration: SJY1256Y

Printed: 06/03/2018 16:59

Tread Depth LHF:




Tread Depth LHR:

Tread Depth RHF:

Tread Depth RHR:

Direction of Impact:

Damage Areas:



Addresses

Cost Summary

Total Labour	\$924.00
Total Paint/Material	\$189.28
Total Parts	\$2,486.00
Total of Additional Costs	\$97.00
Excess:	TBA
Grand Total Exc GST:	\$3,696.28
7 % GST:	\$258.74
Grand Total Inc GST:	\$3,955.02

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$42.00/HR
Price/Dent = \$42.00/HR

Repair /

Guide Number Repair Details

		WU	Cost Price (\$)
NO NUMBER	RENEW FRONT PANEL	32.0	134.40
8101A2 ZAX	RENEW FRONT BUMPER	17.0	71.40
813110)	RENEW RADIATOR GRILLE	3.0	12.60
NO NUMBER	R + R BOTH FRONT WINGS (BUMPER REMOVED)	17.0	71.40

INCLUDES: R + R FRONT HEADLAMPS,
SILL COVER AND REQUIRED
ATTACHED PARTS.

NN	REGISTRATION FEE R&R / NEW PARTS	10	19.0*	79.80	42
NN	FRT GRILLE CHROME R&R / NEW PARTS		2.0*	8.40	x
0471	REPAIR BONNET		13.0*	54.60	x
0741	REPAIR L/F WING	5	13.0*	54.60	✓
0562	CHECK R/F HEADLAMP CPL				
0637	CHECK L/F FOG LAMP				
9646	CHECK LOW TONE HORN				
9647	CHECK HIGH TONE HORN				

LABOUR COST

Total Work Units	116.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	11.6HRS	\$487.20
Paint Labour	10.4HRS	\$436.80
Total Labour	22.0HRS	\$924.00

CAR CITY AUTO CENTRE PTE LTD

Claim Reference: CCA00356

Assessment Number: CCA00356

Version: CAR CITY/1

Date Calculated: 06/03/2018 08:59

Full Report - V1

Registration: SJY1256Y

Printed: 06/03/2018 16:59

PAINT WORK

Guide Number Description Time Basis 10 WU = 1 HR. Price = \$42.00/HR
WU Cost Price (\$)

- PAINTING OFF VEHICLE
- PAINTED MOULDINGS
- TWO COAT PEARL/MICA

340	FRT BUMPER SUPPORT NEW PART PAINTING	8.0
1009	FRONT PANEL CPL SURFACE PAINT	6.0
282	FRONT LOWER BUMPER NEW PART PAINT K1R	5.0
283	FRONT BUMPER NEW PART PAINT K1R	10.0
300	FRT TOWING EYE COVER NEW PART PAINT K1R	3.0
424	RAD GRILLE COVER NEW PART PAINT K1R	5.0
787	L/WING MOULDING NEW PART PAINT K1R	4.0
471	BONNET REPAIR PAINTING >50%	32.0
741	L/F WING REPAIR PAINTING >50%	15.0

LABOUR COST - PAINT

TIME(PAINT)

- Preparation Main Work Metal
- Preparation Comp. Work Plastic
- Preparation Work Multi Layer Paint
- Total Work Units (10WU/HR)
- Total Paintwork Labour

88.0	
11.0	
5.0	
0.0	
104.0	
10.4HRS	\$436.80

MATERIAL COST - PAINT

- New Part Painting
- New Part Painting - Plastic K1R
- Surface-/Blend Paint
- Repair Painting
- Material-Const Main Work Metal
- Material-Const Comp. Work Plastic
- Total Excluding Pearlescent Uplift
- Pearlescent Uplift @ 0.0%
- Total Paint Material Cost

	Cost Price
	\$10.32
	\$78.23
	\$11.21
	\$62.42
	\$18.10
	\$9.00
	\$189.28
	\$0.00
	\$189.28

PARTS

Guide No.	Qty	Description	Part Number	Supplier	Price Valid: 01/06/2015	Bet.	Price (\$)
282	1	FRONT LOWER BUMPER	71102T8NT00ZZ		0%	120.00*	✓
283	1	FRONT BUMPER	71101T8NT00ZZ		0%	200.00*	✓
319	1	L/F UPP BUMPER BRKT	71198T7A000		0%	12.00*	✓
320	1	R/F UPP BUMPER BRKT	71193T7A000		0%	12.00*	✓
340	1	FRT BUMPER SUPPORT	71130T8NT00ZZ		0%	180.00*	✓
343	1	L/BUMPER CORNER BRKT	71190T7A000		0%	20.00*	✓
344	1	R/BUMPER CORNER BRKT	71140T7A000		0%	20.00*	✓
345	1	L/F AIR DUCT	71116T8NT50		0%	20.00*	✓
346	1	R/F AIR DUCT	71111T8NT50		0%	20.00*	✓
347	1	L/F MOULDING	71166T8NT00		0%	12.00*	✓
348	1	R/F MOULDING	71161T8NT00		0%	12.00*	✓
351	1	LOWER FRONT GRILLE	71103T7JH00		0%	50.00*	✓
410	1	GRILLE	71121T8NQ50		0%	180.00*	✓
413	1	RAD GRILLE BRACKET	71150T7JH00		0%	20.00*	✓
415	1	L/RAD-GRILLE BRACKET	71152T7A000		0%	10.00*	✓
416	1	R/RAD-GRILLE BRACKET	71151T7JH00		0%	10.00*	✓
424	1	RAD GRILLE COVER	71122T8NT50		0%	140.00*	✓

CAR CITY AUTO CENTRE PTE LTD

Claim Reference: CCA00356

Assessment Number: CCA00356

Version: CAR CITY/1

Date Calculated: 06/03/2018 08:59

Full Report - V1

Registration: SJY1256Y

Printed: 06/03/2018 16:59

431	1	GRILLE BADGE	75700TA0A00	0%	15.00*
561	1	L/F HEADLAMP CPL	33150T7SE11	0%	790.00*
641	1	L/FOG LAMP BRACKET	33966T7AJ00	0%	10.00*
649	1	L/FOG LAMP COVER	71106T7JH00	0%	18.00*
787	1	L/WING MOULDING	74157T7YK50ZA	0%	50.00*
841	1	L/F WHEELHOUSE COVER	74150T8NT10	0%	70.00*
1009	1	FRONT PANEL CPL	60400T8NT00ZZ	0%	350.00*
2705	1	REGISTRATION FEE	NO NUMBER	0%	0.00
1000	1	FRT GRILLE CHROME	Renew	0%	45.00*
f: OEM Parts		Sub Total			\$2,386.00
g: Original		Mark Up From Cost (0 %)			\$0.00
h: Secondhand		Sundry Parts (Fixed)			\$100.00
p: Parallel		Total Parts			\$2,486.00
x: Exchange					

THIS ASSESSMENT CONTAINS UNPRICED PARTS
NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
AUDATEX	0%	\$42.00
NUM PLATE & HOLDER	SPECIALIST	\$55.00
	SPECIALIST	
Total Extras		\$97.00

Final Calculation

Total Parts	\$2,486.00
Labour	
Total Panel/Mechanical	\$487.20
Total Paintwork	\$436.80
Total Labour	\$924.00
Additional Costs	
Corr Prot Materials External	\$0.00
Corr Prot Materials Internal	\$0.00
Cost of Specialist	\$97.00
Total of Additional Costs	\$97.00
Total Paint/Material Costs	\$189.28
Grand Total Excludes GST	\$3,696.28
GST @ 7 %	\$258.74
Grand Total Includes GST	\$3,955.02

Assessment Notes

P-874

Car City Auto Centre Pte Ltd (Co.Reg.No:200719980C)

Blk 9006 #01-198, Tampines Street 93

Singapore 528840

Tel: 6781 0300 Fax: 6782 0300 Email: ccacpl@singnet.com.sg;carcity@singnet.com.sg

INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMPCSN1689821701	Date of Loss:	02/03/2018
Vehicle Reg. No.:	SJY1256Y	Driveable?	
Driver Age/Info:	33 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	TAN HAN WEI AARON	Contact No:	+6598734768
Driver:	TAN HAN WEI AARON		

Make/Model:	HONDA VEZEL, 1.5 X CVT (A)	Vehicle Reg. Date:	30/12/2016
Vehicle Colour:	WHITE		
Engine No:	L15B4405250	Chassis No:	RU11205251
Odometer:	9999 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	7

Description of Accident/Loss	AS PER ATTACHED SKETCH PLAN
Present Location:	CAR CITY AUTO CENTRE PTE LTD (HQ)

COST OF CLAIMS

	Amount
Parts	2,386.00
Miscellaneous Items	197.00
Labour	1,113.28
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	3,696.28
+ GST 7.00% (S\$)	258.74
Nett Amount (S\$)	3,955.02

This claim is handled by: HO TOO BOON

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG **Version:** 1.0 (Last Synchronised: 06 Mar 2018)**Parts:** M1-SUV **HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)****Labour:** Repairer's **(Price-denominated Standard List)****Print Code:** Car City Auto Centre Pte Ltd/SJY1256Y/06/03/2018 18:05**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	NA	*FRONT BUMPER	0.00	0.00	DO *200.00 F
2	1	NA	*FRONT LOWER BUMPER	0.00	0.00	*120.00 F x R
3	1	NA	*FRONT PANEL CPL	0.00	0.00	*350.00 F x R
4	1	NA	*FRT BUMPER SUPPORT	0.00	0.00	BA *180.00 F
5	1	NA	*FRT GRILLE CHROME	0.00	0.00	ACC *45.00 F
6	1	NA	*GRILLE	0.00	0.00	CRA *180.00 F
7	1	NA	*GRILLE BADGE	0.00	0.00	ACC *15.00 F
8	1	NA	*L/BUMPER CORNER BRKT	0.00	0.00	ACC *20.00 F
9	1	NA	*L/F AIR DUCT	0.00	0.00	*20.00 F x m
10	1	NA	*L/F HEADLAMP CPL	0.00	0.00	*790.00 F x m
11	1	NA	*L/F MOULDING	0.00	0.00	*12.00 F x m
12	1	NA	*L/F UPP BUMPER BRKT	0.00	0.00	BT *12.00 F
13	1	NA	*L/F WHEELHOUSE COVER	0.00	0.00	*70.00 F x m
14	1	NA	*L/FOG LAMP BRACKET	0.00	0.00	*10.00 F x m
15	1	NA	*L/FOG LAMP COVER	0.00	0.00	*18.00 F x m
16	1	NA	*L/RAD-GRILLE BRACKET	0.00	0.00	*10.00 F x m
17	1	NA	*L/WING MOULDING	0.00	0.00	*50.00 F x m
18	1	NA	*LOWER FRONT GRILLE	0.00	0.00	TWI *50.00 F
19	1	NA	*R/BUMPER CORNER BRKT	0.00	0.00	ACC *20.00 F
20	1	NA	*R/F AIR DUCT	0.00	0.00	*20.00 F x m
21	1	NA	*R/F MOULDING	0.00	0.00	*12.00 F x m
22	1	NA	*R/F UPP BUMPER BRKT	0.00	0.00	BT *12.00 F
23	1	NA	*R/RAD-GRILLE BRACKET	0.00	0.00	*10.00 F x m
24	1	NA	*RAD GRILLE BRACKET	0.00	0.00	nn *20.00 F x
25	1	NA	*RAD GRILLE COVER	0.00	0.00	CRA *140.00 F
26	1	NA	*REGISTRATION FEE	0.00	0.00	*-F x m

F=Franchise part.

Total Parts (S\$)**2,386.00**

Car City Auto Centre Pte Ltd/SJY1256Y/06/03/2018 18:05. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	AUDATEX FEES	42.00 ^{HA 35}
2	1	NUM PLATE & HOLDER	55.00 ^{rec}
3	1	SUNDRY PARTS	100.00 ✓
Sub Total (S\$)			197.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	Total Paint Labour	New	467.40 436.80
2	Total Paint Materials	New	181.41 189.28
3	Total Panel/Mechanical Labour	New	168 487.20
Gross Labour Cost (S\$)			1,113.28

Car City Auto Centre Pte Ltd/SJY1256Y/06/03/2018 18:05. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

51 Ubi Avenue 1, #01-25
Paya Ubi Industrial Park
Singapore
408933

Claim Reference: 6 SNM18D01146C01
Assessment Number: CCA00356
Version: CHINATAI/3
Date Calculated: 17/05/2018 08:11

Full Report - V1
Registration: SJY1256Y
Printed: 17/05/2018 15:11

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	LKK AUTO	Date of Incident:	02/03/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:	6 SNM18D01146C01	Estimated Repair Time:	4 day(s)
Policy Number:	DMPCSN1689821701	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	HONDA
Model:	Vezel
Sub Model:	EX
Model Sheet Number:	HVE 06
Registration:	SJY1256Y
Registration Month:	December
Registration Year:	2016
VIN Number:	RU11205251
Manufacture Year:	2016
Odometer:	Not Known
Colour:	White
Engine Number:	L15B4405250
Fuel Level:	%

Model Specs

FROM MODEL 2016	2 ZONE AUTO AIR CON
TINT GLASS (PRIVACY)	RR WDW REG W/PULSE G
TENS-/START SYS LINE	MIRROR WITH TIP FUNC
LANE CHANGING ASSIST	NAVIGATION SYSTEM
DISPLAY LCD 7.0	FOG LAMPS
SIDE FLASHER	LED HEADLAMP
REAR COMBI LIGHT	AUTO HEADLAMP LEVEL
AUTO HEADLAMP LEVEL	RAIN-/DR/LIGHT SENS
CHROME DOOR HANDLES	AUTO DIPPING MIRROR
COLLISION WARN SYS	REARVIEW CAMERA
ANTI-THEFT ALARM	REAR PARKING SYSTEM
1.5 LTR 88KW	GEARBOX CVT
STRG COLUMN ADJUST	EMERG BRAKE ASSIST
CRUISE CONTROL	TYRES 215/55 VR 17
WHEELS 7J X 17 ALLOY	STABILITY PROGRAM
PANORAMA SUNROOF	PAINTING OFF VEHICLE
PAINTED MOULDINGS	TWO COAT PEARL/MICA

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Good	Severity of Impact:	Heavy Panel
Steering:	Satisfactory	Vehicle Status on Inspection:	Roadworthy
Brakes Pedal Travel:	Satisfactory	Date of Inspection:	04/03/2018
Place of Inspection:			
Pre-Accident Damage:			
Tyres Condition:	Good		
Tread Depth LHF:		Tread Depth RHF:	
Tread Depth LHR:		Tread Depth RHR:	
Damage Areas:		Direction of Impact:	

51 Ubi Avenue 1, #01-25 Paya Ubi Industrial Park Singapore

Claim Reference: 6 SNM18D01146C01

Full Report - V1



Assessment Number: CCA00356

Registration: SJY1256Y

Version: CHINATAI/3

Printed: 17/05/2018 15:11

Date Calculated: 17/05/2018 08:11



Addresses

Cost Summary

Total Labour	\$575.40
Total Paint/Material	\$181.41
Total Parts	\$974.00
Total of Additional Costs	\$35.00
Excess:	- \$0.00
Grand Total Exc GST:	\$1,765.81
7 % GST:	\$123.61
Grand Total Inc GST:	\$1,889.42

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$42.00/HR
Price/Dent = \$42.00/HR

Repair /

Guide Number Repair Details

		WU	Cost Price (\$)
8101A2 ZAX	RENEW FRONT BUMPER	17.0	71.40
813110)	RENEW RADIATOR GRILLE	3.0	12.60
7111A3 ZAX	R + R BOTH HORNS	1.0	4.20
8101B1)	R + R FRONT BUMPER SUPPORT	2.0	8.40
8131A6	R + R LEFT FRONT WHEELHOUSE SHELL	2.0	8.40
0741	REPAIR L/F WING	5.0*	21.00
2705	REPAIR REGISTRATION FEE	10.0*	42.00

LABOUR COST

Total Work Units	40.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	4.0HRS	\$168.00
Paint Labour	9.7HRS	\$407.40
Total Labour	13.7HRS	\$575.40

PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$42.00/HR

Guide Number	Description	WU	Cost Price (\$)
	- PAINTING OFF VEHICLE		
	- PAINTED MOULDINGS		
	- TWO COAT PEARL/MICA		
340	FRT BUMPER SUPPORT NEW PART PAINTING	8.0	
282	FRONT LOWER BUMPER NEW PART PAINT K1R	5.0	
283	FRONT BUMPER NEW PART PAINT K1R	10.0	
424	RAD GRILLE COVER NEW PART PAINT K1R	5.0	
471	BONNET REPAIR PAINTING >50%	32.0	
741	L/F WING REPAIR PAINTING >50%	15.0	
1009	FRONT PANEL CPL SURFACE PAINT	6.0	

LABOUR COST - PAINT		
TIME(PAINT)	81.0	
Preparation Main Work Metal	11.0	
Preparation Comp. Work Plastic	5.0	
Preparation Work Multi Layer Paint	0.0	
Total Work Units (10WU/HR)	97.0	
Total Paintwork Labour	9.7HRS	\$407.40
MATERIAL COST - PAINT		Cost Price
New Part Painting		\$10.32
New Part Painting - Plastic K1R		\$70.36
Surface-/Blend Paint		\$11.21
Repair Painting		\$62.42
Material-Const Main Work Metal		\$18.10
Material-Const Comp. Work Plastic		\$9.00
Total Excluding Pearlescent Uplift		\$181.41
Pearlescent Uplift @ 0.0%		\$0.00
Total Paint Material Cost		\$181.41

PARTS

				Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Bet. Price (\$)
283	1	FRONT BUMPER	71101T8NT00ZZ		0% 200.00*
319	1	L/F UPP BUMPER BRKT	71198T7A000		0% 12.00*
320	1	R/F UPP BUMPER BRKT	71193T7A000		0% 12.00*
340	1	FRT BUMPER SUPPORT	71130T8NT00ZZ		0% 180.00*
343	1	L/BUMPER CORNER BRKT	71190T7A000		0% 20.00*
344	1	R/BUMPER CORNER BRKT	71140T7A000		0% 20.00*
351	1	LOWER FRONT GRILLE	71103T7JH00		0% 50.00*
410	1	GRILLE	71121T8NQ50		0% 180.00*
424	1	RAD GRILLE COVER	71122T8NT50		0% 140.00*
431	1	GRILLE BADGE	75700TA0A00		0% 15.00*
1000	1	FRT GRILLE CHROME	Renew		0% 45.00*
f: OEM Parts				Sub Total	\$874.00
g: Original				Mark Up From Cost (0 %)	\$0.00
h: Secondhand				Sundry Parts (Fixed)	\$100.00
p: Parallel				Total Parts	\$974.00
x: Exchange					

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
AUDATEX	0%	\$0.00
NUM PLATE & HOLDER	SPECIALIST	\$35.00
	Total Extras	\$35.00

Final Calculation

Total Parts	\$974.00
Labour	
Total Panel/Mechanical	\$168.00
Total Paintwork	\$407.40
Total Labour	\$575.40
Additional Costs	
Corr Prot Materials External	\$0.00
Corr Prot Materials Internal	\$0.00

51 Ubi Avenue 1, #01-25 Paya Ubi Industrial Park Singapore
Claim Reference: 6 SNM18D01146C01
Assessment Number: CCA00356
Version: CHINATAI/3
Date Calculated: 17/05/2018 08:11

Full Report - V1
Registration: SJY1256Y
Printed: 17/05/2018 15:11

Cost of Specialist	\$35.00	
Total of Additional Costs		\$35.00
Total Paint/Material Costs		\$181.41
Grand Total Excludes GST		\$1,765.81
GST @ 7 %		\$123.61
Grand Total Includes GST		\$1,889.42

Assessment Notes



合興汽車零件私人有限公司 HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: CAR CITY AUTO CENTRE PTE LTD

BLK 9006 TAMPINES STREET 93

#01-198

SINGAPORE 528840

VEZEL

MR NG

NO: HLI9057236

PAGE: 1

DATE: 13-03-2018

A/C CODE: LDCCA010

TERMS: CR

VEH NO: SJY1256Y

Part No	Description	Location	Qty	Unit Price	Amount
				<u>SIN</u>	<u>SIN</u>
1	H71102-T7A-000 FR.BPR.CTR.SKIRT	HDS	1	120.00	120.00 X
2	H71101-T7J-H00ZZ FR.BUMPER	HU3-TOP	1	200.00	200.00 ✓
3	H71193-T7A-000 320 FR.BPR.SIDE RETAINER RH	H2K6	1	12.00	12.00 ✓
4	H71198-T7A-000 319 FR.BPR.SIDE RETAINER LH	H2K6	1	12.00	12.00 ✓
5	H71130-T7A-000ZZ 340 FR.REINFORCEMENT	HU3017-2	1	180.00	180.00 ✓
6	H71140-T7A-000 344 FR.BPR.BEAM RH	H2A18	1	20.00	20.00 ✓
7	H71190-T7A-000 343 FR.BPR.BEAM LH(T7J)	H2A18	1	20.00	20.00 ✓
8	H71111-T7A-000 FR.BPR.AIR DUCT RH	HDS	1	20.00	20.00 X
9	H71166-T7A-000 FR.BPR.AIR GARNISH LH	HDS	1	12.00	12.00 X
10	H71161-T7A-000 FR.BPR.AIR GARNISH RH	HDS	1	12.00	12.00 X
11	H71103-T7J-H00 351 FR.BPR.LO.GRILLE	HU2R21	1	50.00	50.00 ✓
12	H71150-T7A-000 FR.GRILLE GARNISH CTR	HDS	1	20.00	20.00 X
13	H71122-T7A-901 424 FR.GRILLE LENS	HU3-32	1	140.00	140.00 ✓
14	H75700-S9A-G00 431 GRILLE EMBLEM(TA0)	H1M6	1	15.00	15.00 ✓
15	H33150-T7A-J11 561 FRT.HEADLAMP LH(J12)	HDS	1	790.00	790.00 X
16	H74157-T7A-003 FR.W/H ARCH PROT.LH	HDS	1	50.00	50.00 X
17	H74150-T7A-000 FR.COWLING LH	HDS	1	50.00	50.00 X
18	H71123-T7A-901 1000 FR.GRILLE MLDG.	H1FT1	1	45.00	45.00 ✓



合興汽車零件私人有限公司 HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R


TAX INVOICE

M/S: CAR CITY AUTO CENTRE PTE LTD

NO: HLI9057236

PAGE: 2

TOTAL QUANTITY:	18	TOTAL	SIN 1,768.00
		ADD GST @ 7%	123.76
		GRAND TOTAL	<u>SIN 1,891.76</u>




Print / LSK / 13/3/2018 11:05:08 AM

SALESMAN: LSK

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE


E & O. E.

GOODS RECEIVED BY 

日美汽車私人有限公司 JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)
WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

WINDSCREEN GLASS
Dept Direct: 6417 9781 / 6745 9820



Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Exch (Made in Germany)
Spark plug: Nippon Denso, WKB (Made in Japan)

=====
Email: jaeauto@pacific.net.sg
CAR CITY AUTO CENTRE PTE LTD
BLK 9006 TAMPINES ST 93
#01-198
SINGAPORE 528840
TEL: 67810300 FAX: 67820300
ATTN: NG 96445447, ADULLA NICK

TAX INVOICE AR201803-07500
DATE: 13/03/2018
CUSTOMER ID: CAR018
VEH REG. NO: ~~SL 9895A~~
TERMS: 30 days
PO NO.:
PAGE NO.: Page 1 of 1
CURR.: S\$

SJY 1256Y

SO STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
H71121-T7A-000 RU1	FR GRILLE AU	U1 HI 1-C3	1	180.00	180.00

✓

SUB-TOTAL: 180.00
ADD GST 7.00 % 12.60

E. & O.E TOTAL AMOUNT S\$: 192.60

[P] 13/03/2018 10:35:37AM

[E] 13/03/2018 10:34:45AM

Goods Sold are not refundable for Cash.
Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.
Sales Executive: EDMUND



This is computer generated document.
No signature is required.

ORIGINAL

Goods Received in Good Order

Signature / Stamp / Date

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	06 Mar 2018 Sendback Est	06 Mar 2018 18:05 \$3,696.28	07 Mar 2018 14:49 Edit Adj Rpt	\$1,765.81 Edit Estimates	\$1,765.81 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	-----------------

CLAIM SUBFOLDER DETAILS

Insured:	TAN HAN WEI AARON, ID: S8425472Z, Tel: +6598734768, Email: NOEMAIL		
Vehicle Reg. No.:	SJY1256Y	Date of Loss:	02/03/2018 19:00 - :59 [14 Months and 2 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / SNM18D01146C01	Policy/Cover Note No.:	DMPCSN1689821701 (Comprehensive)
		Excess:	\$0.00
Repairer:	Car City Auto Centre Pte Ltd (HQ) Blk 9006 #01-198, Tampines Street 93, 528840 Tampines - Tel: 6781 0300		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 16/03/2018]		
Driver/Custodian:	TAN HAN WEI AARON (33 / Male), NRIC: S8425472Z, Tel: +6598734768		
Adj Asg. Remarks:	PLEASE SURVEY AND REVERTO		

ASSOCIATED MAIL RECEIVED

View All | Compose Case Mail

- CHINA TAIPING (19/03/2018): Alert - Adj Mandate Approved (\$2041.79) - SJY1256Y - Claim Handler: Irene Tay H...

ALL ASSOCIATED TASKS

View All | Search Tasks | Create New Task | Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SJY1256Y (SNM18D01146C01)

OD

Mar 2 2018 7:00PM

[TAN HAN WEI AARON]









Car City Auto Centre Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View <div>View in Browser</div>	
Assessment Reports							1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)		Thumbnail	Print			
1	06/03/18 18:05	Repairer Estimates	1	Load HTM				
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print			
1	13/03/18 09:59	Adjuster Immediate Advice	1	Load HTM				
Photos/Images							3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print			
1	12/03/18 19:08	General View	1	Load JPG	<input checked="" type="checkbox"/>			
2	12/03/18 19:08	General View	1	Load JPG	<input checked="" type="checkbox"/>			
3	12/03/18 19:08	General View	1	Load JPG	<input checked="" type="checkbox"/>			
4	12/03/18 19:08	General View	1	Load JPG	<input checked="" type="checkbox"/>			
5	12/03/18 19:08	General View	1	Load JPG	<input checked="" type="checkbox"/>			
6	12/03/18 19:08	General View	1	Load JPG	<input checked="" type="checkbox"/>			
7	12/03/18 19:08	General View	1	Load JPG	<input checked="" type="checkbox"/>			
8	12/03/18 19:08	General View	1	Load JPG	<input checked="" type="checkbox"/>			
9	12/03/18 19:08	General View	1	Load JPG	<input checked="" type="checkbox"/>			
10	12/03/18 19:08	General View	1	Load JPG	<input checked="" type="checkbox"/>			
11	12/03/18 19:08	General View	1	Load JPG	<input checked="" type="checkbox"/>			
12	12/03/18 19:08	General View	1	Load JPG	<input checked="" type="checkbox"/>			
13	12/03/18 19:08	General View	1	Load JPG	<input checked="" type="checkbox"/>			
14	12/03/18 19:08	General View	1	Load JPG	<input checked="" type="checkbox"/>			
15	12/03/18 19:08	General View	1	Load JPG	<input checked="" type="checkbox"/>			
16	12/03/18 19:08	General View	1	Load JPG	<input checked="" type="checkbox"/>			
17	12/03/18 19:08	General View	1	Load JPG	<input checked="" type="checkbox"/>			
18	12/03/18 19:08	General View	1	Load JPG	<input checked="" type="checkbox"/>			
19	12/03/18 19:08	General View	1	Load JPG	<input checked="" type="checkbox"/>			
20	12/03/18 19:08	General View	1	Load JPG	<input checked="" type="checkbox"/>			
21	12/03/18 19:08	General View	1	Load JPG	<input checked="" type="checkbox"/>			
22	12/03/18 19:08	General View	1	Load JPG	<input checked="" type="checkbox"/>			
23	12/03/18 19:08	General View	1	Load JPG	<input checked="" type="checkbox"/>			
24	12/03/18 19:08	General View	1	Load JPG	<input checked="" type="checkbox"/>			
25	12/03/18 19:08	General View	1	Load JPG	<input checked="" type="checkbox"/>			
26	12/03/18 19:08	General View	1	Load JPG	<input checked="" type="checkbox"/>			
27	12/03/18 19:08	General View	1	Load JPG	<input checked="" type="checkbox"/>			
28	12/03/18 19:08	Odometer Reading	1	Load JPG	<input checked="" type="checkbox"/>			
29	12/03/18 19:08	General View	1	Load JPG	<input checked="" type="checkbox"/>			
30	12/03/18 19:08	Chassis Number	1	Load JPG	<input checked="" type="checkbox"/>			
31	12/03/18 19:08	General View	1	Load JPG	<input checked="" type="checkbox"/>			
32	12/03/18 19:08	General View	1	Load JPG	<input checked="" type="checkbox"/>			
33	12/03/18 19:09	General View	1	Load JPG	<input checked="" type="checkbox"/>			
34	12/03/18 19:09	General View		Load JPG				

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	12/03/18 19:09	General View	Load JPG	<input checked="" type="checkbox"/>
36	12/03/18 19:09	General View	Load JPG	<input checked="" type="checkbox"/>
37	12/03/18 19:09	General View	Load JPG	<input checked="" type="checkbox"/>
38	12/03/18 19:09	General View	Load JPG	<input checked="" type="checkbox"/>
39	12/03/18 19:09	General View	Load JPG	<input checked="" type="checkbox"/>
40	12/03/18 19:09	General View	Load JPG	<input checked="" type="checkbox"/>
41	12/03/18 19:09	General View	Load JPG	<input checked="" type="checkbox"/>
42	12/03/18 19:09	General View	Load JPG	<input checked="" type="checkbox"/>
43	12/03/18 19:09	General View	Load JPG	<input checked="" type="checkbox"/>
44	12/03/18 19:09	General View	Load JPG	<input checked="" type="checkbox"/>
45	12/03/18 19:09	General View	Load JPG	<input checked="" type="checkbox"/>
46	12/03/18 19:09	General View	Load JPG	<input checked="" type="checkbox"/>
47	12/03/18 19:09	General View	Load JPG	<input checked="" type="checkbox"/>
48	13/03/18 20:09	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
49	13/03/18 20:09	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
50	13/03/18 20:09	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
51	13/03/18 20:09	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
52	13/03/18 20:09	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
53	13/03/18 20:09	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
54	13/03/18 20:09	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
55	13/03/18 20:09	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
56	13/03/18 20:09	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
57	13/03/18 20:09	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
58	13/03/18 20:09	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	19/03/18 15:27	Marked Estimate	Load PDF	
2	19/03/18 15:28	Revised Estimate	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/03/18 09:55	ESTIMATE	Load PDF	
2	13/03/18 09:55	REVISED AUDATEX	Load PDF	
3	25/05/18 09:51	Parts Invoice	Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)	Thumbnail	Print
1	04/03/18 09:46	Accident Statement	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)	Thumbnail	Print
1	04/03/18 09:43	SCENE PHOTO	Load JPG	<input checked="" type="checkbox"/>
2	04/03/18 09:43	SCENE PHOTO	Load JPG	<input checked="" type="checkbox"/>
3	04/03/18 09:43	SCENE PHOTO	Load JPG	<input checked="" type="checkbox"/>
4	04/03/18 09:43	SCENE PHOTO	Load JPG	<input checked="" type="checkbox"/>
5	04/03/18 09:43	INSURED CAR	Load JPG	<input checked="" type="checkbox"/>
6	04/03/18 09:43	INSURED CAR CHASSIS NUMBER	Load JPG	<input checked="" type="checkbox"/>
7	04/03/18 09:43	INSURED CAR	Load JPG	<input checked="" type="checkbox"/>
8	04/03/18 09:43	INSURED CAR	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)	Thumbnail	Print
9	04/03/18 09:43	INSURED CAR		<input checked="" type="checkbox"/>
10	04/03/18 09:43	INSURED CAR		<input checked="" type="checkbox"/>
11	04/03/18 09:43	INSURED CAR		<input checked="" type="checkbox"/>
12	04/03/18 09:43	INSURED CAR		<input checked="" type="checkbox"/>
13	04/03/18 09:43	INSURED CAR		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)	Thumbnail	Print
1	04/03/18 09:40	Sketch Plan		<input type="checkbox"/>
2	04/03/18 09:40	Sketch Plan #2		<input type="checkbox"/>
3	04/03/18 09:41	OWNER / DRIVER IC N DL		<input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>
Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CT118004429/UQD3E2

Date: 25/05/2018

REFERENCE

Insured/Claimant: TAN HAN WEI AARON Policy No: DMPCSN1689821701
Date of Loss: 02/03/2018 Nature of Claim: OD Claim No: SNM18D01146C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJY1256Y**
Make & Model: HONDA VEZEL, 1.5 X CVT (A) Engine No: L15B4405250
Reg. Date: 30/12/2016 (Man. Year: 2016) Chassis No: RU11205251
Colour: White Odometer: 8193 km
Engine Capacity: 1496 cc
Market Value/New Car Price: S\$62,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/45 R18 Rear Tyre Size: 225/45 R18
Front Left Side: Goodyear 7 mm Rear Left Side: Goodyear 7 mm
Front Right Side: Goodyear 7 mm Rear Right Side: Goodyear 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,386.00	874.00	1,512.00	63.37
Miscellaneous Items	197.00	135.00	62.00	31.47
Labour	1,113.28	756.81	356.47	32.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,696.28	1,765.81	1,930.47	52.23
+ GST 7.00/7.00% (S\$)	258.74	123.61	135.13	52.23
Nett Amount (S\$)	3,955.02	1,889.42	2,065.60	52.23

INSPECTION

Date of Assignment: 07/03/2018 Present Location: Car City Auto Centre Pte Ltd (HQ)
Date Inspected: 12/03/2018 Inspected At: Blk 9006 #01-198, Tampines Street 93
Singapore 528840
Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 25 May 2018)

Parts: M1-SUV HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJY1256Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*FRONT BUMPER	Dented	200.00 F	*200.00 F
2	1	NA	*FRONT LOWER BUMPER	Repair	120.00 F	*- F
3	1	NA	*FRONT PANEL CPL	Repair	350.00 F	*- F
4	1	NA	*FRT BUMPER SUPPORT	Bent	180.00 F	*180.00 F
5	1	NA	*FRT GRILLE CHROME	Necessary	45.00 F	*45.00 F
6	1	NA	*GRILLE	Cracked	180.00 F	*180.00 F
7	1	NA	*GRILLE BADGE	Necessary	15.00 F	*15.00 F
8	1	NA	*L/BUMPER CORNER BRKT	Necessary	20.00 F	*20.00 F
9	1	NA	*L/F AIR DUCT	Not Necessary	20.00 F	*- F
10	1	NA	*L/F HEADLAMP CPL	Not Necessary	790.00 F	*- F
11	1	NA	*L/F MOULDING	Not Necessary	12.00 F	*- F
12	1	NA	*L/F UPP BUMPER BRKT	Bent	12.00 F	*12.00 F
13	1	NA	*L/F WHEELHOUSE COVER	Not Necessary	70.00 F	*- F
14	1	NA	*L/FOG LAMP BRACKET	Not Necessary	10.00 F	*- F
15	1	NA	*L/FOG LAMP COVER	Not Necessary	18.00 F	*- F
16	1	NA	*L/RAD-GRILLE BRACKET	Not Necessary	10.00 F	*- F
17	1	NA	*L/WING MOULDING	Not Necessary	50.00 F	*- F
18	1	NA	*LOWER FRONT GRILLE	Twisted	50.00 F	*50.00 F
19	1	NA	*R/BUMPER CORNER BRKT	Necessary	20.00 F	*20.00 F
20	1	NA	*R/F AIR DUCT	Not Necessary	20.00 F	*- F
21	1	NA	*R/F MOULDING	Not Necessary	12.00 F	*- F
22	1	NA	*R/F UPP BUMPER BRKT	Bent	12.00 F	*12.00 F
23	1	NA	*R/RAD-GRILLE BRACKET	Not Necessary	10.00 F	*- F
24	1	NA	*RAD GRILLE BRACKET	Not Necessary	20.00 F	*- F
25	1	NA	*RAD GRILLE COVER	Cracked	140.00 F	*140.00 F
26	1	NA	*REGISTRATION FEE (NPA)	Not Necessary	0.00 F	*- F

F=Franchise part.

Total Parts (S\$) 2,386.00 874.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	AUDATEX FEES	42.00	0.00
2	1	NUM PLATE & HOLDER (BENT)	55.00	35.00
3	1	SUNDRY PARTS (NECESSARY)	100.00	100.00
Sub Total (\$\$)			197.00	135.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	Total Paint Labour	New	436.80	407.40
2	Total Paint Materials	New	189.28	181.41
3	Total Panel/Mechanical Labour	New	487.20	168.00
Gross Labour Cost (\$\$)			1,113.28	756.81

Report was unsubmitted during this print-out.

< END OF ESTIMATES >