

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPRJ BTTIR%	DISC QUINT%	SALV AGE%	PART PRICE(NET)
	11	1			LEFT PROTECTOR			Serviceable	0		20		0
	12	1			REAR LEFT FENDER			Serviceable	0		20		0
	13	1			LEFT REFLECTOR			Serviceable	0		20		0
	14	1			LEFT TAIL LAMP (FENDER)			Cracked	323.7	5	20		245.01

Labour

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT
	1		PERFORM VEHICLE ELECTRONIC SYSTEM DIAGNOSIS, INTERROGATION & REPROGRAM MODULE WITH CONSULT. (DISC 5%)	228	0	0	Reviewing	
	2		PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL.	0	0	0	Reviewing	
	3		REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST. (DISC 5%)	52.25	0	0	Reviewing	
	4		APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA.	0	0	0	Reviewing	
	5		CHECK & INSPECT WIRE HARNESS FOR DAMAGE & OPEN / SHORT CIRCUIT. REPAIR WHEN NECESSARY.	0	0	0	Reviewing	
	6		RENEW REAR BUMPER, LEFT TAIL LAMP, REAR UPPER PANEL, ENERGY ABSORBER, REINFORCEMENT, WEATHERSTRIP, REAR LEFT FENDER & TRIM, ETC PANELS & REPAIR. (DISC 5%)	475	0	0	Reviewing	

Detailed Assessment

Inspection Date *

03/08/2018



Total Loss

Yes No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Good

Steering (Serviceable)

Yes No

Footbrake (Serviceable)

Yes No

Handbrake (Serviceable)

Yes No

Engine Modification

Yes No

Pre-accident condition

Good

Tyre Condition

Age of Tyres

Front Tyre Size

215/60R17

Spare wheel

Rear Tyre Size

215/60R17

POST SURVEY INF...

CATEGORY Address type

FNOL INFORMATI... Personal Correspondence

POST SURVEY INF...

CATEGORY Gender

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Marital status

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Identification #

FNOL INFORMATI... S7146977H

POST SURVEY INF...

POLICY INFORMAT... TPVD NISSAN

ASSESSMENT INFO... NISSAN

CATEGORY Model
POLICY INFORMAT... QASHQAI-1.2 DIG-T (J11)(A)

ASSESSMENT INFO... QASHQAI 1.2 DIG-T CVT ABS 2WD 5D

CATEGORY Type
POLICY INFORMAT...
ASSESSMENT INFO...

CATEGORY Type of Paint
POLICY INFORMAT...
ASSESSMENT INFO...

CATEGORY Chassis No
POLICY INFORMAT...
ASSESSMENT INFO... SJNFEAJ11U1682485

CATEGORY Date of Birth
FNOL INFORMATI... December 31, 1899

POST SURVEY INF... 

CATEGORY Age
FNOL INFORMATI... 118

POST SURVEY INF...
CATEGORY Occupation
FNOL INFORMATI... Unknown

CATEGORY Education Qualification
FNOL INFORMATI... Other

CATEGORY Driving Experience

TAN Jas
6568804844
jas.tan@axa.com.sg

- Messages
- Invoices
- History

Pending verification -
Direct Settlement

Additional Instructions

Documents Assessment Metrics Notes Document Type Document SubType

▼

Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
MANDATE AND IA.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	June 25, 2018
LKK INSPECTION PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	June 25, 2018
LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	June 25, 2018
Rear Accident Footage Between SJW4142H & (online-video-cutter.mp4	Evidence	Videos	LKK AUTO CONSULTANTS PTE LTD (TP)	March 29, 2018