



SMRT Automotive Services Pte Ltd  
251 North Bridge Road Singapore 179102  
Tel: 65 63311000 Fax: 65 63340247

## Tax Invoice

GST Reg No. : MR-8500001-7  
CRN : 199004280Z  
Invoice No. : IV180300734  
Date : 28.03.2018  
Vehicle No. : SG5150E  
Your Ref No. : BUS/02/18/7047  
Our Ref No. : 24094917  
Terms : 30 Days

Customer Code: 3000066

SMRT BUSES LTD

Block Unit  
STREET 62  
6 ANG MO KIO  
SINGAPORE 569140



Description	Qty	Unit Cost	Add %	/ (Discount) Amount	Amount
<b>Parts</b>					
COOLER DOOR ASSEMBLY	1.00	\$2872.05	(10.00 )	\$ 287.20	\$ 2584.85
FLYSCREEN ASSEMBLY	1.00	\$ 900.80	(10.00 )	\$ 90.08	\$ 810.72
Sub-Total					\$ 3395.57
<b>Labour</b>					
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	1.00	\$1090.00	0.00	\$ 0.00	\$ 1090.00
<b>Others</b>					
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	1.00	\$ 300.00	0.00	\$ 0.00	\$ 300.00
GRAND TOTAL					\$ 4,785.57

Remark :

Make/Model : Volvo B9TL DD  
Accident Date : 14.02.2018

N.B. Payment by cheque should be crossed and made payable to 'SMRT Automotive Services Pte Ltd'.  
No receipt will be issued unless requested.

Authorised Signature  
for SMRT Automotive Services Pte Ltd

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	27/02/2018 16:51
Date Of Accident	14/02/2018 18:40
Exact Location Of Accident	VICTORIA ST (BS:01112- OPP BUGIS JUNCTION)
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SG5150E
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SMRT BSUES LTD
Co Reg No	198202292D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-64823888

### Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	BUS

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category BUS

### Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	D-17087563MFBP

Cover Note Number

### Driver

Name of Driver	LIU RUI GANG
NRIC No	G8491332X
Date Of Birth	20/12/1974
Occupation	OUTDOOR
Date Of Driving Pass	23/03/2009
Driving Experience	8 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address NOADDRESS

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

### General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR

Road Surface DRY

### Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance?

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 20

### Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

### Circumstances of Accident

Bus stationary at the bus stop (BS01112 - Opp Bugis Junction) of Victoria Street for passengers activity, suddenly felt an impact from the rear right portion of the bus, after checking found that a lorry YP6653X had collided onto the rear right portion of the bus. For the alleged accident nobody was injured.

### Attachment(s)

Are accident photos available for attachment? NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number YP6653X

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category COMMERCIAL VEHICLE

Name of Driver LIU CHEN

NRIC/Passport Number G2592121L

Contact Number 88664418

Address

Postcode

Insurance Company Name AXA INSURANCE PTE LTD

Nature Of Damage

No. Of Passenger (Including Driver)

**IMPORTANT NOTE:** Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

## ADDENDUM

**(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:**

Original Report No : MSR118028078 Vehicle Registration No: SG5150E

Name (as shown in NRIC) : SMRT BUSES LTD NRIC/FIN/Passport No : 198202292D

(\*Vehicle Driver / Vehicle Owner) (\*) Please delete as appropriate

Address : — Singapore ( )

Contact (Tel) : — Mobile No. : —

Email Address : —

Date of Accident : 14/02/2018 Time of Accident : 18:40

Place of Accident : VICTORIA STREET (BS:01112-OPP BUGIS JUNCTION)

Insurance Company: FIRST CAPITAL INSURANCE LTD

**(B) ADDITIONAL INFORMATION / AMENDMENTS:**

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

The Third Party's vehicle no. should correctly read as YP6653X

---

---

---

---

---

---

---

---

---

---




Policyholder / Driver's Signature  
Date:



**BALQISH**

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:  
Date:



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

pls refer to G14 report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## Enquire Transaction History

### Transaction History Details

Log Date/Time:	01 Mar 2018 / 09:36:46		
Asset Type:	Vehicle	Transaction Amount:	\$7.49
Asset ID:	YP6653X		
Transaction Type:	18.32 Insurance Enquiry (GIRO Payment)	Channel:	External Agency
User ID:	ESASBAH0 - BALQISH BINTE ABDUL HALIL	Business Transaction Reference No.:	20180301093646399474

Search Date / Time: 14 Feb 2018 18:40:00

Insurance Company: AXA INSURANCE PTE LTD




Information displayed is correct as at the log date and time.

[Enquire Related Logs](#)[Back to List](#)

BUS/02/18/7047

SG5150E





Bus was  
stationary  
at the  
moment of  
Accident  
Bus Driver's  
Hands Away  
from Steering  
Wheel.



