

ASS. REC. BY:

REF: CS/CTI18004455/MIR d30

Special Instruction:

Survivor: MA  
Mummen

ASSIGNMENT (Office)

From (Person): Jowyn Tay

of CPI

Date/Time: 8/3/18 @ 11:59am

Estimated Cost:

Bill to:

OD  TP / WS TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGT 1354J

Insured: SIH 9425M

at Workshop m/s City Auto

Tel: 6452 1235

of 160 Sin Ming Drive #05-01

Policy No: D17MTPV01003422

Claim No: SNM18D01233C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 6/3/2018

CA / REV / REP. / REV 24 HRS lwp

H.O.D. Endorsement:

Date/Time: 12:21pm @ 8/3/18

Person Contacted:

Vronica

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SGT 1354J - X

SIH 9425M - CS/CAI/11017667/44

D.O.A: 20/08/2011

Confirm \$1664.73, 4 days

Est: 81434.75, 461.



## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Mar 2018		08 Mar 2018 11:59 <a href="#">Assign</a>				<a href="#">New Assignment</a> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	ALPHA EXCELLENCE PTE LTD, Co. Reg. No.: 201127954R		
Main Claimant:	SIN LEE KENG, ID: S1687481G		
Vehicle Reg. No.:	SGT1354J	Date of Loss:	06/03/2018 13:00 - :59
Claim Type:	TP / SNM18D01233C02	Policy/Cover Note No.:	DMHCSN3063801700 (Comprehensive)
Vehicle Reg. No. (Insured):	SJH9425M	Policy No. (Claimant):	D17MTPV01003422
		Excess:	S\$0.00
Repairer:	City Auto Pte Ltd (HQ) 160 Sin Ming Drive #05-01,, Sin Ming AutoCity,, 575722 Sin Ming - Tel: 6453 1235		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]		
Claimant's Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 19/03/2018]		
Driver/Custodian (Insured):	SYED ABDUL KADER SHAIK ABDUR RAHMAN (37 / Male), NRIC: S8170889D, Tel: +6581815342		
Adj Asg. Remarks:	NO EST, CASE WITH SJE		

### ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18004455/M1rd3

3 ANSON ROAD #16-00  
SPRINGLEAF TOWERSINGAPORE 079909

Date : 08-03-2018



Code : CTI

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJH 9425M	Veh. Inspected	SGT 1354J
Policy No.	DMHCSN3063801700	Coverage (\$)	0.00
Claim No.	SNM18D01233C02	Excess (\$)	0.00
Assign From	MERIMEN (JOWYN TAY)	Assign Date	08/03/2018

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	06/03/2018	Inspection Date	08/03/2018
Survey held at	160 SIN MING DRIVE #05-01		
Repairer	CITY AUTO PTE LTD		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---

### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### ACCIDENT STATEMENT

Date Of Report	07/03/2018 09:48
Date Of Accident	06/03/2018 13:45
Exact Location Of Accident	JUNCTION OF SERANGOON ROAD
Country/State of Loss	SINGAPORE

#### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGT1354J
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SIN LEE KENG
NRIC No	S1687481G
Email Address	JSIN174@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98200355
Alternative Phone No	OFFICE-98200355
<b>Vehicle Particulars</b>	
Manufacturer	TOYOTA
Model	YARRIS
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
<b>Insurance Company</b>	
Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D17MTPV01003422
Cover Note Number	
<b>Driver</b>	
Name of Driver	SIN LEE KENG
NRIC No	S1687481G
Date Of Birth	17/04/1965
Occupation	INDOOR
Date Of Driving Pass	19/12/1994
Driving Experience	23 YEARS AND 2 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-98200355
Fax Number	
Contact Number	OFFICE-98200355
EMail Address	JSIN174@GMAIL.COM





# CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643  
TEL: 6453 1235, 6452 0850 FAX: 6453 7944  
24hrs Towing Services Tel: 9823 9898  
Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

Estimate : QUOT201803-000186(00)

CHINA TAIPING INSURANCE (S) PTE LTD

3  
ANSON RD  
#16-00 SPRINGLEAF TOWER  
SINGAPORE 079909

Attention: Sin Lee Keng

Contact : 98200355

Fax No. : 62247175

Date : 07/03/2018

Vehicle No. : SGT1354J

Make/Model : TOYOTA YARIS E AUTO

Mileage (km) : 0

Chassis No. : MR054HY9104005634

Accident Date : 06/03/2018 00:00:00

Claim No. : SJH9425M

Reference : SGT1354J

Policy No. : D17MTPV01003422

S/No	Particular	Quantity	Unit Price	Amount S\$
<b>LIST ITEMS :</b>				
1	Rear bumper	1.0	485.30	485.30
2	Rear bumper retainer	2.0	58.00	116.00
3	Rear end panel	1.0	575.00	575.00
4	Rear boot rubber	1.0	85.00	85.00
5	Taillamp	1.0	298.00	298.00
List Total :				1,559.30
25% Discount S\$				389.82
				1,169.48
<b>SPECIAL NET :</b>				
1	Rear bumper lower spoiler	1.0	450.00	450.00
2	Reverse sensor	1.0	250.00	250.00
SPECIAL NET Total S\$:				700.00
<b>LABOUR :</b>				
	*To seal water leakage	1.0	80.00	80.00
	*To knock jackout damaged parts,panel beating,welding,align,refix and to renew accident parts	1.0	500.00	500.00
	*Spray painting on affected and replace parts	1.0	650.00	650.00
				1,230.00

Not Authorised  
HS Repair  
Affix panel  
Hole Auto (M/S)

4w days 8/3/2018

20/3/18

E. & O.E.

Total S\$: 3,099.48

GST 7% S\$: 216.96

Amount Due S\$: 3,316.44

for CITY AUTO PTE LTD



# CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643  
TEL: 6453 1235, 6452 0850 FAX: 6453 7944  
24hrs Towing Services Tel: 9823 9898  
Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

2

CHINA TAIPING INSURANCE (S) PTE LTD

3  
ANSON RD  
#16-00 SPRINGLEAF TOWER  
SINGAPORE 079909  
Attention: Sin Lee Keng  
Contact : 98200355

Fax No. : 62247175

Estimate : QUOT201803-000186(00)

Date : 07/03/2018  
Vehicle No. : SGT1354J  
Make/Model : TOYOTA YARIS E AUTO

Mileage (km) : 0  
Chassis No. : MR054HY9104005634  
Accident Date : 06/03/2018 00:00:00  
Claim No. : SJH9425M  
Reference : SGT1354J  
Policy No. : D17MTPV01003422

S/No	Particular	Quantity	Unit Price	Amount S\$
------	------------	----------	------------	------------

**LIST ITEMS :**

1	Rear bumper	1.0	485.30	485.30 ✓
2	Rear bumper retainer	2.0	58.00	116.00 ✓
3	Rear end panel	1.0	575.00	575.00 ✓
4	Rear boot rubber	1.0	85.00	85.00 ✓
5	Faillamp	1.0	298.00	298.00 ✓

List Total :

25% Discount S\$

636.30 1,559.30  
389.82  
1,169.48

**SPECIAL NET :**

1	Rear bumper lower spoiler	1.0	450.00	450.00 ✓
2	Reverse sensor	1.0	250.00	250.00 ✓

SPECIAL NET Total S\$:

700.00

**LABOUR :**

*To seal water leakage	1.0	80.00	80.00
*To knock jackout damaged parts,panel beating,welding,align,refix and to renew accident parts	1.0	500.00	500.00
*Spray painting on affected and replace parts	1.0	650.00	650.00

130 1,230.00

Not Authorized  
HS Repair  
Affiliate Panel Auto  
Hole Auto (M2)

4 wdays 8/3/2018

E. & O.E.

Total S\$: 3,099.48

P- \$ 636.30

GST 7% S\$: 216.96

- 25.10

Amount Due S\$: 3,316.44

\$ 514.73

D/P- \$ 1,664.73

MA

for CITY AUTO PTE LTD

SN- \$ 220.00

conf. 21/3/2018

L- \$ 1930.00

Page 1 of 1

\$ 1,664.73

**...CLAIM SUBFOLDER...(Pending for Survey Report)**

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Mar 2018		08 Mar 2018 11:59 <a href="#">Edit Adj Rpt</a>	<b>S\$1,664.72</b> <a href="#">Edit Estimates</a>	<b>S\$1,664.72</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by Insurer]	
Insured:	ALPHA EXCELLENCE PTE LTD, Co. Reg. No.: 201127954R		
Main Claimant:	SIN LEE KENG, ID: S1687481G		
Vehicle Reg. No.:	SGT1354J	Date of Loss:	06/03/2018 13:00 - :59
Claim Type:	TP / SNM18D01233C02	Policy/Cover Note No.:	DMHCSN3063801700 (Comprehensive)
Vehicle Reg. No. (Insured):	SJH9425M	Policy No. (Claimant):	D17MTPV01003422
		Excess:	S\$0.00
Repairer:	City Auto Pte Ltd (HQ) 160 Sin Ming Drive #05-01,, Sin Ming AutoCity,, 575722 Sin Ming - Tel: 6453 1235		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]		
Claimant's Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MA CHIN FOOK] ... [Final Rpt due 19/03/2018]		
Driver/Custodian (Insured):	SYED ABDUL KADER SHAIK ABDUR RAHMAN (37 / Male), NRIC: S8170889D, Tel: +6581815342		
Adj Asg. Remarks:	NO EST, CASE WITH SJE		
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
There are no mail for this case.			
<b>ALL ASSOCIATED TASKS</b> <input type="checkbox"/>		<a href="#">View All</a>	<a href="#">Search Tasks</a>
		<a href="#">Create New Task</a>	<a href="#">Complete</a>
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>
			<b>Subject</b>
			<b>Handler</b>
			<b>Assigned By</b>
			<b>Completed On</b>
			<b>Created On</b>
			<b>Done?</b>
No results.			

## Claim Documents

\*SGT1354J (SNM18D01233C02)  
 [SJH9425M]  
 TP  
 SIN LEE KENG  
 Mar 6 2018 1:00PM  
 [ALPHA EXCELLENCE PTE LTD]  
 City Auto Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View <input type="button" value="View in Browser"/>	
Photos/Images						3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print	
1	21/03/18 13:09	General View			 Load JPG	<input checked="" type="checkbox"/>	
2	21/03/18 13:09	General View			 Load JPG	<input checked="" type="checkbox"/>	
3	21/03/18 13:09	General View			 Load JPG	<input checked="" type="checkbox"/>	
4	21/03/18 13:09	General View			 Load JPG	<input checked="" type="checkbox"/>	
5	21/03/18 13:09	General View			 Load JPG	<input checked="" type="checkbox"/>	
6	21/03/18 13:09	General View			 Load JPG	<input checked="" type="checkbox"/>	
7	21/03/18 13:09	General View			 Load JPG	<input checked="" type="checkbox"/>	
8	21/03/18 13:09	General View			 Load JPG	<input checked="" type="checkbox"/>	
9	21/03/18 13:09	General View			 Load JPG	<input checked="" type="checkbox"/>	
10	21/03/18 13:09	General View			 Load JPG	<input checked="" type="checkbox"/>	
11	21/03/18 13:09	General View			 Load JPG	<input checked="" type="checkbox"/>	
12	21/03/18 13:09	General View			 Load JPG	<input checked="" type="checkbox"/>	
13	21/03/18 13:09	General View			 Load JPG	<input checked="" type="checkbox"/>	
14	21/03/18 13:09	General View			 Load JPG	<input checked="" type="checkbox"/>	
15	21/03/18 13:09	General View			 Load JPG	<input checked="" type="checkbox"/>	
16	21/03/18 13:10	Reinspection Photo			 Load JPG	<input checked="" type="checkbox"/>	
17	21/03/18 13:10	Reinspection Photo			 Load JPG	<input checked="" type="checkbox"/>	

## Linked Accident Report Documents

Assessment Reports						1 per page	<input checked="" type="checkbox"/>
No	Finalized On	City Auto Pte Ltd (HQ)			Thumbnail	Print	
1	07/03/18 09:53	Accident Statement			 Load HTM		
Photos/Images						3 per page	<input checked="" type="checkbox"/>
No	Finalized On	City Auto Pte Ltd (HQ)			Thumbnail	Print	
1	07/03/18 09:52	Accident Photo			 Load JPG	<input checked="" type="checkbox"/>	
2	07/03/18 09:52	Accident Photo			 Load JPG	<input checked="" type="checkbox"/>	
3	07/03/18 09:52	Accident Photo			 Load JPG	<input checked="" type="checkbox"/>	
4	07/03/18 09:52	Accident Photo			 Load JPG	<input checked="" type="checkbox"/>	
5	07/03/18 09:52	Accident Photo			 Load JPG	<input checked="" type="checkbox"/>	
6	07/03/18 09:52	Accident Photo			 Load JPG	<input checked="" type="checkbox"/>	
7	07/03/18 09:52	Accident Photo			 Load JPG	<input checked="" type="checkbox"/>	
8	07/03/18 09:52	Accident Photo			 Load JPG	<input checked="" type="checkbox"/>	
9	07/03/18 09:52	Accident Photo			 Load JPG	<input checked="" type="checkbox"/>	

			<b>1</b>		<input checked="" type="checkbox"/>
10	07/03/18 09:52	<b>Accident Photo</b>	<b>1</b>	Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>			1 per page	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
No	Finalized On	City Auto Pte Ltd (HQ)		<b>Thumbnail</b>	<b>Print</b>
1	07/03/18 09:52	<b>Accident Sketch Plan</b>	<b>1</b>	Load JPG	<input checked="" type="checkbox"/>
2	07/03/18 09:52	<b>Accident Sketch Plan</b>	<b>1</b>	Load JPG	<input checked="" type="checkbox"/>
3	07/03/18 09:52	<b>CI</b>	<b>1</b>	Load JPG	<input checked="" type="checkbox"/>
4	07/03/18 09:52	<b>NRIC &amp; Driving license</b>	<b>1</b>	Load JPG	<input checked="" type="checkbox"/>

### Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	Reset	Save	Print
There are no document checklists configured.			

<p><b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b></p> <div style="border: 1px solid black; height: 40px; width: 100%;"></div> <p><b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer</p> <p><small>Note: Remarks are private unless you show it to other parties.</small></p>
---

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118004455/M1RD3E2

Date: 29/03/2018

#### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMHCSN3063801700	
Claimant Vehicle No: SGT1354J	Insured Vehicle No: SJH9425M	
Date of Loss: 06/03/2018	Nature of Claim: TP	Claim No: SNM18D01233C02

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGT1354J		
Make & Model:	TOYOTA YARIS, 1.3 (A)	Engine No:	1NZX395843
Reg. Date:	02/04/2007 (Man. Year: 2006)	Chassis No:	MR054HY9104005634
Colour:	Silver	Odometer:	76983 km
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Yokohama 7 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Yokohama 7 mm	Rear Right Side:	Yokohama 7 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,869.47	734.72	1,134.75	60.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,230.00	930.00	300.00	24.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>3,099.47</b>	<b>1,664.72</b>	<b>1,434.75</b>	<b>46.29</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>216.96</b>	<b>116.53</b>	<b>100.43</b>	<b>46.29</b>
<b>Nett Amount (S\$)</b>	<b>3,316.43</b>	<b>1,781.25</b>	<b>1,535.18</b>	<b>46.29</b>

#### INSPECTION

Date of Assignment:	08/03/2018	
Date Inspected:	08/03/2018 Inspected At:	City Auto Pte Ltd (HQ) 160 Sin Ming Drive #05-01,, Sin Ming AutoCity, Singapore 575722
Estimated Period of Repair:	4.0 days	

**Adjuster:** MA CHIN FOOK

**Manager:** Janice Lee Si Hua

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

Different 1 cents -Finalise confirm amount: \$1664.73

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG                      Version: 1.0 (Last Synchronised: 29 Mar 2018)  
**Parts:** 144                                      TOYOTA YARIS 1.3 (A) (Catalogue:Merimen Singapore 1.0)  
**Labour:** Repairer's                      (Price-denominated Standard List)  
**Print Code:** (Unsubmitted, no print-code for SGT1354J)  
**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	485.30 FL	*485.30 FL
2	2		*REAR BUMPER RETAINER	Distorted	116.00 FL	*116.00 FL
3	1		*REAR END PANEL	Repair	575.00 FL	*- FL
4	1		*REAR BOOT RUBBER	Distorted	85.00 FL	*85.00 FL
5	1		*TAILLAMP	Serviceable	298.00 FL	*- FL
6	1		*REAR BUMPER LOWER SPOILER	Serviceable	450.00 FS	*- FS
7	1		*REVERSE SENSOR	Shorted	250.00 FS	*220.00 FS
<b>Sub Total (\$\$)</b>					<b>2,259.30</b>	<b>906.30</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>					<b>389.83</b>	<b>171.58</b>
<b>Total Parts (\$\$)</b>					<b>1,869.47</b>	<b>734.72</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO SEAL WATER LEAKAGE	New	80.00	30.00
2	TO KNOCK JACK OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW ACCIDENT PARTS	New	500.00	400.00
3	SPRAY PAINTING ON AFFECTED AND REPLACE PARTS	New	650.00	500.00
<b>Gross Labour Cost (S\$)</b>			<b>1,230.00</b>	<b>930.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >