

22/05/2002

ASS. REC. BY:

REF: CG/MSH18004462 / Rlvbn2 Special Instruction:

SUNAJOR:

Rusul

ASSIGNMENT (Office)

Date/Time: 07/03/2018 4:50pm

From (Person):

Eliza Ho

of MSH

Bill to:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

Insured:

To Inspect Vehicle No:

SLV 5059R

Tel:

9221 3150

at Workshop m/s

Borneo Motor

of

2 Pandan Crescent

Policy No:

B28990449MXY

Claim No:

551592

Excess:

\$1500.00

Sum Insured:

D.O.A. 15/02/2018

Make of Veh:

(Client's Record)

08/03/2018 @ after lunch.

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

Date/Time:

07/03/2018 5:50pm

Person Contacted:

Raymond.

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLV 5059R - X
9/3/18	Revert by merimen
9/3/18	Recd approved from Ming Shao by merimen
9/3/18	Informed Raymond C/A ex \$1500 by email
16/3/18	Final fig \$3346.59 confirmed by email (Red 3981.60, 5490)

00862

Signature: Rasul

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLV 5059R

at Workshop m/s BORUKO MOTOR

of _____

Insured: MSLH

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: 1500

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 113K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Soon: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Date / Time | Action / Instruction

Veh No: SLV 5059R Yr Regn: 2017 / BKL

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA C-HR 1.2 C.C. 1196

Colour: GREY A/C: Insured / Std / NI / NA

Sp. Reading: 3395 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTNKY3BX301006149

Gen. Cond: Good / Fail / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R17

R: _____

BS: ☒ DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 15/02/18

Survey held at BORUKO MOTOR

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

0/3 Frt

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 19 MAR 2018

Date/Time, File Pass to?

☐ : Prel. Report

☐ : Final Report

1) Date/Time, File Return to?

2) 16/3 - typist

Report Format:

Lump Sum / I.B.I. (\$

merimen

3346.59

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Survey Fee: 200

Transportation: 10

S + RS: SI

Phone: _____

Cigars: _____

TOTAL

200
10
210

Survey Department Check List (Case Handler)

Reference No.: CS/MSG/8004462/Rlvb
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are ACCURATE.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From	✓			
C	Assign Date	✓			
C	Veh No (Inspected)				
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)	✓			
C	Report Type	✓			
C	Weekend Charges	✓			
N	Survey held at/Repairer	✓			
C	Excess	✓			

Surveyor (

): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp. Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des. of Damages				

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases	✓			
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By:

VERON

16/3/18

Case Handler

Date

*C: Critical *N: Non-Critical

21/05/20




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18004462/R1vb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 08-03-2018	
		Code : MSG	
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.		Veh. Inspected	SLV 5059R
Policy No.	B28990449MCY	Coverage (\$)	0.00
Claim No.	551592	Excess (\$)	1,500.00
Assign From	MERIMEN (ELIZA HO)	Assign Date	07/03/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	15/02/2018	Inspection Date	08/03/2018
Survey held at	BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462		
5a. Remarks			
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Eliza Ho Teng Boon	Date: 09 Mar 2018

Preliminary Advice

Vehicle No	: SLV5059R	Accident Date	: 15/02/2018
Make	: TOYOTA C-HR	Policy No.	: B28990449MCY
Assignment Date	: 07/03/2018	Excess	: S\$1,500.00
Date of Inspection	: 08/03/2018	Est. Duration of Repair	: 4.00
Inspection At	: BORNEO MOTORS (S) PTE LTD (PANDAN) 2 PANDAN CRESCENT SINGAPORE 128462		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,328.19
Revised Amount	:S\$	3,346.59
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,346.59

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	113,000.00
COE / PARF Rebate	:S\$	66,374.00
Salvage Value	:S\$	
Margin for Repair	:S\$	46,626.00

Remarks☒ (X) The vehicle is economical for repair.☐ () The above survey was conducted on a 'without prejudice' basis.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 16 March 2018 4:44 PM
To: 'Raymond Seah PTCBC'; Rasul (LKKAUTO)
Cc: SUR
Subject: RE: FINALISE FOR SLV5059R

Dear Raymond,

Confirmed finalize \$3,346.59 before excess \$1500 and GST

No of days: 4 days.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Raymond Seah PTCBC [mailto:Raymond.Seah@borneomotors.com.sg]
Sent: Friday, 16 March 2018 4:22 PM
To: Rasul (LKKAUTO) <Rasul@lkkauto.com>
Cc: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Subject: FINALISE FOR SLV5059R

Dear Rasul,

Attach are photos & estimate of SLV5059R to finalize.

Thanks

Raymond Seah

9221 3150

From: Raymond.Seah@borneomotors.com.sg <Raymond.Seah@borneomotors.com.sg>
Sent: Friday, March 16, 2018 4:20 PM
To: Raymond Seah PTCBC
Subject: Scan Data from FX-ODBC96

Sent by: B051779 [Raymond.Seah@borneomotors.com.sg]

Number of Images: 3
Attachment File Type: PDF

Device Name: ApeosPort-V C2276
Device Location:

This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited. Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, delayed or incomplete, or could contain viruses. We therefore do not accept liability for any errors or omissions in the contents of this e-mail which arise as a result of e-mail transmission, and you are advised to carry out your own virus checks and confirm the accuracy of the contents of this e-mail before relying on it for any purpose.

This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited. Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, delayed or incomplete, or could contain viruses. We therefore do not accept liability for any errors or omissions in the contents of this e-mail which arise as a result of e-mail transmission, and you are advised to carry out your own virus checks and confirm the accuracy of the contents of this e-mail before relying on it for any purpose.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							Status
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	
Main	06 Mar 2018		07 Mar 2018 16:50 Assign				New Assignment Cancel Case

Main		Reference		Claim Details		Documents		Show All
------	--	-----------	--	---------------	--	-----------	--	----------

CLAIM SUBFOLDER DETAILS

Insured:

BORNEO MOTORS (S) PTE LTD, Co. Reg. No.: 196700086Z

Vehicle Reg. No.:

SLV5059R

Claim Type:

OD / 551592

Repairer:

Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent, 128462 West Coast - Tel: 66311857

Handling Insurer:

MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Eliza Ho Teng Boon - 6594 2554]

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 08/03/2018]

Driver/Custodian:

CHAN YEON KEONG (39 / Male), NRIC: S7817160Z, Tel: +6581381386

Adj Asg. Remarks:

REVERT - SURVEY @08/03/2018 ANYTIME AFTER LUNCH

[Created by insurer]

15/02/2018 18:00 - :59

Policy/Cover Note No.:

B28990449MCY (Comprehensive)
Coverage: 01/07/2017 - 30/06/2018

Excess:

S\$1,500.00

View All

Compose Case Mail

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 9 March 2018 2:56 PM
To: Raymond Seah; SUR
Subject: SLV 5059R-DOA: 15/2/2018 (MSIG OD)

Dear Raymond,

As instructed by our client MSIG , please proceed to repair the insured vehicle **SLV 5059R (Excess \$1500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***SLV5059R (551592)**
OD
Feb 15 2018 6:00PM
[BORNEO MOTORS (S) PTE LTD]
Borneo Motors (S) Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on **09/03/2018 14:40 PM.**
To LKK_HQ
Subject Alert - Adj Mandate Approved (\$3346.59) - SLV5059R - Claim Handler: Eliza Ho Teng Boon

Approved: 3346.59.

DOCUMENTS SUMMARY

There are no documents.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0086Z
Vehicle Details	
Vehicle No.:	SLV5059R
Vehicle to be Exported:	No
Intended De-registration Date:	09 Mar 2018
Vehicle Make:	TOYOTA
Vehicle Model:	C-HR 1.2 TURBO LUXURY (AUTO)
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	8NRU168429
Chassis No.:	JTNKY3BX301006149
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$29,396.00
Original Registration Date:	30 Dec 2017
First Registration Date:	30 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$33,155.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Dec 2027
PARF Rebate Amount:	\$24,866.00
Intended COE Rebate Details	

COE Expiry Date:	29 Dec 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$42,339.00
COE Rebate Amount:	\$41,508.00
Total Rebate Amount:	\$66,374.00

The information contained herein is correct as at 09 Mar 2018

OK



MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, # 21-01, SGX Centre 2, Singapore 068807
Tel: +65 6827 7888, Fax: +65 6827 7800
Co. Reg. No. 200412212G GST Reg. No. 20-0412212G

Willis Towers Watson Limited
Willis Towers Watson Brokers (Singapore) Pte Ltd
5 Battery Road #06-01/02 Singapore 049909
Tel: (65) 6591 8000 Fax: (65) 6224 0398
Co. Reg. No. 196001606H

Certificate of Insurance

ROAD TRANSPORT ACT 1987 (MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1969 (FEDERATION OF MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
(REPUBLIC OF SINGAPORE)
THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M.V.4
Company Ownership

MOTORMAX PLUS-COMMERCIAL
Comprehensive

Certificate No. B 28590449 MCY

Excess: SGD1,500
Windscreen Excess: SGD100

1. Index Mark and Registration Number of Vehicle
SLV5059R

2. Name of Policyholder
Borneo Motors (S) Pte Ltd

3. Effective Date of the Commencement of Insurance for the purposes of the Act
30/12/2017

4. Date of Expiry of Insurance
30/06/2018

5. Persons or Classes of Persons entitled to drive*

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use*

Use only for social domestic and pleasure purposes and for the Policyholder's business.
The Policy does not cover use for hire or reward racing pace-making reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

PLEASE NOTE ALL CLAIMS RELATED REPAIR CAN BE CARRIED OUT AT ANY WORKSHOP OF YOUR CHOICE OR AT ANY MSIG AUTHORISED WORKSHOP LISTED IN THE ATTACHED.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the Insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte. Ltd.
Approved Insurers

for Chief Executive Officer

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: **S7817160Z**

Name: **CHAN YEON KEONG (ZENG YONGQIANG)**

Birth Date: **22 Jun 1978**

Issue Date: **29 May 2004**

001228669J



REPUBLIC OF SINGAPORE

IDENTITY CARD NO. **S7817160Z**

Name: **CHAN YEON KEONG (ZENG YONGQIANG)**

曾永强

Race: **CHINESE**

Date of birth: **22-06-1978** Sex: **M**

Country of birth: **SINGAPORE**




YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 2B Motorcycles not exceeding 200 cc
 Class 3 Motor Cars of unladen weight not exceeding 3000 kg with not more than 7 passengers, exclusive of the driver; and Motor Tractors and other Motor Vehicles of unladen weight not exceeding 2500 kg

PASS DATE

24 May 1999
 27 Aug 1999

Licence No: **S7817160Z**



NP 428A

4311349



NRIC No: **S7817160Z**



Date of issue: **24-11-2008**

Address: **APT BLK 331 CLEMENTI AVENUE 2 #07-154 SINGAPORE 120331**

06/2015

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/03/2018 13:53
Date Of Accident	15/02/2018 18:00
Exact Location Of Accident	BLK 536 JURONG WEST AVE 1 CP LOT 513
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLV5059R
Insured/Policyholder	
Name Of Registered Owner	BORNEO MOTORS (S) PTE LTD
Co Reg No	196700086Z
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-66311298
Vehicle Particulars	
Manufacturer	TOYOTA
Model	C-HR-1.8 HYBRID ICON/DYNAMIC (A)
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	B 28990449 MCY
Cover Note Number	
Driver	
Name of Driver	CHAN YEON KEONG
NRIC No	S7817160Z
Date Of Birth	22/06/1978
Occupation	INDOOR
Date Of Driving Pass	27/08/1999
Driving Experience	18 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81381386
Fax Number	
Contact Number	OFFICE-66311298
EMail Address	YEONKEONG.CHAN@INCHCAPE.COM.SG

Address BLK 331 CLEMENTI AVE 2 #07-154
 Postcode 120331
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? NO
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name JURONG WEST NEIGHBOURHOOD POLICE CENTRE
 Police Station Address ROAD: 700 CORPORATION ROAD , POSTCODE: 649818 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 1800-2689999 - FAX NO: 62672438
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

PLEASE REFER AS ATTACHED

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

TYPE OF CLAIM: ☐ OD ☒ OD/UL ☐ DS

MCA: Pay M

MOTOR ACCIDENT REPORT

Date Of Report: 15/02/2018 Time: 22:49 Date Of Accident: 15/02/2018 Time: 18:00 to 21:45
 Exact Location Of Accident: BLK 536 Jwing west Ave 1, Car park lot: 513
 Country/State of Loss: Singapore ☒ / Wilayah Persekutuan ☐ / Selangor Darul Ehsan ☐ / Negeri Sembilan ☐ / Melaka ☐ / Pahang ☐ /

OWN VEHICLE DETAILS (INSURED/POLICY HOLDER)

Vehicle Registration Number: SLV5059R Co. Reg. No (for Co. Vehicle)/NRIC/PP/FIN No: 1967000862
 Name Of Registered Owner: BORNEO MOTORS (S) PTE LTD
 Mobile Number: Alternative No: Email Address:

Vehicle Particulars

Manufacturer: Toyota ☒ Lexus ☐ Suzuki ☐ Hino ☐ Model: C-HR LUXURY
 Exact Purpose for which vehicle was being used at time of accident: Normal Usage ☒ Other ☐ (please specify):
 Are you claiming under your own insurance policy for repair to your vehicle? Yes ☒ Reporting Only ☐ Third Party ☐
 Vehicle Category: Private Car ☒ Commercial Vehicle ☐ Others ☐ To recover for 21 lot

Insurance Company

Name of Insurance Company: MSSG
 Type Of Coverage: Comprehensive ☒ Third Party ☐ Third Party Fire and/or Theft ☐
 Fleet Policy: Yes ☐ No ☒ Policy / Cover Note No: B S 899 0449 mcy

DRIVER DETAILS AT POINT OF ACCIDENT

Name of Driver: CHAN YEON KEONG NRIC/ Passport / FIN No: S7871602
 Date Of Birth: 22/06/1978 Occupation: Indoor ☒ Outdoor ☐
 Date Of Driving Pass: 27/08/1999 Gender: Male ☒ Female ☐
 Mobile Number: 87381386 Fax No: Alternative No: 66311248
 Address: BLK 331, CLEMENTI AVE 2, #07-154 Postal Code: 120331
 Email Address: yeonkeong.chan@incheap.com.sg
 Was driver an employee of the Insured's Company? Yes ☒ No ☐ State relationship of the driver with the insured:
 Vehicle Registration Number of Driver's Own Vehicle (if applicable):
 Insurance Company of Driver's Own Vehicle (if applicable):

GENERAL INFORMATION OF THE ACCIDENT

Type Of Accident: car park hit and run
 Number of Passengers in the above vehicle (Including Driver): 0 / If more than 2 Pax Please fill ANNEX B

PASSENGER 1

Name: Gender: Male ☐ Female ☐
 Weather Conditions: Clear ☒ Raining ☐ Others ☐ (If others, please state condition):
 Road Surface: Wet ☐ Dry ☒ Others ☐ (If others, please state condition):
 Was any body injured in the Accident? No ☒ Yes ☐
 Was any injured conveyed to hospital by ambulance? No ☒ Yes ☐
 Was any foreign vehicle involved in this accident? No ☒ Yes ☐ Vehicle No: Vehicle type:
 Number of vehicles involved in the accident:
 Was there any witness? No ☒ Yes ☐ If yes, please furnish witness details column below
 Witness Name: Contact No.: Email:
 Was there any other vehicle or property damaged? No ☒ Yes ☐
 Was there any video captured by Car Camera? No ☒ Yes ☐ Are accident scene photos available for attachment? No ☒ Yes ☐
 Was the accident reported to the police? No ☒ Yes ☐ (If yes, please state which Police Station): JURONG WEST NPC
 Was notice of intended Prosecution given? No ☒ Yes ☐ (If yes, please state against whom):
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. No ☒ Yes ☐

DETAILS OF OTHER VEHICLE PROPERTY 1 (Please fill Annex A if more vehicles involved)

Vehicle Registration Number: Vehicle Make/Model/Colour:
 Details Of Properties Damage in Accident:
 Vehicle Category:
 Name of Driver: Contact Number: Postal Code:
 NRIC/Passport/FIN Number:
 Address:
 Insurance Company Name:
 Nature Of Damage: No. Of Passenger (Including Driver):



SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time

Driver's Signature (if Driver is not the policyholder) / Date & Time

Chan Yee Keong
S78171602
Borneo Motors (S) Pte Ltd

Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident

Please refer to police report made, 15/02/18 22:49.

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Driver's Signature (if not the policyholder) / Date & Time

Chan Yuen Keong
S7817160Z
Borneo Motors (S) Pte Ltd

Witnessed by Reporting Centre Personnel



**SINGAPORE
POLICE FORCE**



T/20180215/2154

1 of 3

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

Report No. T/20180215/2154

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 15/02/2018 22:49	Vide Report No.:	Station Diary No.: 133
--	------------------	---------------------------

Informant's Particulars

Name of Informant: CHAN YEON KEONG			Address: APT BLK 331 CLEMENTI AVENUE 2 #07-154 SINGAPORE 120331		
ID Type / ID No.: NRIC NO / S7817160Z			Contact No.: Home/Office: Mobile: 81381386		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 39	Date of Birth: 22/06/1978	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: ASSISTANT MANAGER			Driving Licence Information: Class: 2B,3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 15/02/2018 18:00	Type of Location: Car Park
Location: Along Road 1 JURONG WEST AVENUE 1 open space car park of Blk 536 Jurong West Ave 1 lot: 513				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume:
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SLV5059R	Car				Slightly Damaged	0



**SINGAPORE
POLICE FORCE**



T/20180215/2154

2 of 3

Report No. T/20180215/2154

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

CONTINUATION OF REPORT

Brief Details.

On 15/02/2018 at about 1800hrs, I parked my vehicle V1) SLV5059R Toyota C-HR grey in colour at the open space carpark lot number: 513 located at Blk 536 Jurong West Ave 1. I secured my vehicle and everything was intact before I left the vicinity.

At about 2145hrs, I returned back to my vehicle and discovered scratches and dents on the right front side of my vehicle. Based on my observation, it is quite obvious that it must be hit and run. I then made a thorough check and everything else was fine. This is the first incident and I have no suspect in mind. There is CCTV at the Blk 536 Jurong West Ave 1. The estimated cost of repair might be S\$2000/-



SINGAPORE
POLICE FORCE



T/20180215/2154

3 of 3

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

Report No. T/20180215/2154

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J/

Staff Sgt NIRHMALA K GOVINDASAMY

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / HRT /

SI ABDUL KAREEM BIN ABDUL HAGUE

Contact No.: 65476079

Signature Of Informant:

Date/Time:

15/02/2018 22:49

Classification Of Case:

Authentication Stamp

NP168



Signature:

Singapore Police Force

SN 126



**SINGAPORE
POLICE FORCE**


Traffic Police
Singapore Police Force
10, Ubi Avenue 3
Singapore 408865
Tel : 6547 0000
Fax : 6547 6259

Date : 23 Feb 2018

Your Ref :
Our Ref : TP/IP/12609/2018

000012

CHAN YEON KEONG
APT BLK 331 CLEMENTI AVENUE 2
#07-154
SINGAPORE 120331



Dear Sir / Madam,

CASE OF TRAFFIC ACCIDENT ALONG JURONG WEST AVENUE 1 ON 15 FEB 2018 @ 6.00 PM

Please be informed that Traffic Police is investigating into the above matter and will update you the status in due course.

2 IF you have not lodged a Police Report of a Traffic Accident (NP168) in respect of the said accident which is now required for police investigation, please do so as soon as possible at the nearest police station, Neighbourhood Police Centre (NPC), Neighbourhood Police Post (NPP) or online via Singapore Police Force Electronic Police Centre (<http://www.police.gov.sg/epc>).

3 Please note that the information given by you in the Police Report of a Traffic Accident (NP168) will be carefully considered. You may not be called upon for an interview if the information in the Police Report is sufficient for our investigation. However, if you have any further information or other evidence (such as CCTV footages) which you have not stated in your report and which you think will assist in the investigation, you are advised to contact the Investigation Officer within 2 weeks of this letter to arrange for an appointment.

4 You may contact the Investigation Officer ABD KAREEM B ABD HAGUE at his / her office number: 65476079 or the supervisor CHEW SOOK YENG at 65476425 if you have any further queries.

5 Thank you.

Yours faithfully,

PUTEH BTE SHARIFF (DSP)
CHIEF INVESTIGATION OFFICER
INVESTIGATION BRANCH
TRAFFIC POLICE

This is computer generated and does not require a signature.



Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingsapore.com.sgToyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188
Customer DetailCo-Reg No : 196700086Z
GST Reg No : MR-8500000-9Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

ESTIMATE

Account Detail	Account No	M/s Borneo Motors (Singapore) Pt 2 Pandan Crescent Inchcape Centre Singapore 128462 Work: 64751288
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	SI0000004 / ICCUA1	
	Document No 0	
	Document Date 06/03/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	AHXEQ	L1	30/12/2017	SLV5059R	0	29878	9UL/SLV5059R-15021:
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	

JTNKY3BX301006149 8NRU168429 60 Raymond Seah L M --/--/---- 0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY TO RECOVER FROM TP LATER-OD/UL POLICY NO.:B28990449MCY ACC DATE:15/02/2018 NO OF REPAIR DAYS: EXCESS:\$1500.00 DATE-IN: DATE SURVEY: BY: AUTHORISED ON:				new 30.00
2	B	BP-ECU TO RESET ECU AND REPROGRAMME				✓ 462.00
3	B	BP-MECH TO CONDUCT WHEEL ALIGNMENT CHECK.				X 308.00
4	B	BP-LAB TO CHECK WIRING & LIGHTING. TO FOCUS HEADLAMP.				104.72
5	B	BP-LAB TO REPLACE FRONT RH SIDE ACCIDENT DAMAGE PARTS.STRAIGHTEN/REALIGN ALL OTHER AFFECTED AREAS.				✓ 924 2464.00
6	B	BP-RES TO SPRAY PAINT ON FRONT RH ACCIDENT AFFECTED AREAS.				✓ 1012 2024.00
7	1	T52129-10010 COVER, FR BUMPER,	1.00	499.30	15.00	R 424.40
8	2	T75392-35200 OUTSIDE RETAINER,	8.00	3.30	15.00	X 22.40
9	3	T52119-10916 COVER, FR BUMPER	1.00	385.00	15.00	X 327.25
10	4	T52535-10040 RETAINER, FR BUMPER	1.00	115.10	15.00	SVC X 97.83
11	5	T52536-10040 RETAINER, FR BUMPER	1.00	115.10	15.00	X 97.83
12	6	T53114-10030 GRILLE, RADIATOR,	1.00	97.20	15.00	X 82.62

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every
6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Materials	
		Lubrication/Fluid	Amount Due
		Others	

PLEASE TEAR ALONG PERFORATED LINE.

3621174

TO SECURITY GUARD

3621174

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE
TIME 06/03/2018
11:13

VEHICLE NO

SLV5059R

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

Borneo Motors

Co-Reg No : 196700086Z
 GST Reg No : MR-8500000-9

 Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

ESTIMATE

 Toyota Bodycare Centre
 No. 2 Pandan Crescent
 Singapore 128462
 Tel no.: 6631 1188
 Customer Detail

Account Detail		Account No	M/s Borneo Motors (Singapore) Pt 2 Pandan Crescent Inchcape Centre Singapore 128462 Work: 64751288
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 069807 Attn: Motor Claims Dept		SI000004 / ICCUA1	
		Document No 0	
		Document Date 06/03/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	AHXEQ	L1	30/12/2017	SLV5059R	0	29878	9UL/SLV5059R-15021
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	

JTNKY3BX301006149 8NRU168429 60 Raymond Seah L M --/--/---- 0.00 --/--/---- 0.00


L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
13	7	T52127-10050 COVER, FR BUMPER	1.00	81.50	15.00	Svc X 69.27
14	8	T75601-10010 MOULDING SUB-ASSY,	1.00	143.50	15.00	Svc X 121.97
15	9	T53801-10600 FENDER SUB-ASSY, FR	1.00	814.00	15.00	Svc X 691.90

Rasul
 Hp 96010068
 4 days
 08/03/18 @ 1435
 Resurf 6x paint
 EXCESS: 1500
 REVERT


12/3/18

LKK Auto Consultants is the Repaired of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: 
 Date: 8/3

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	7,328.19
		Labour 1,935.47	GST 7.00%
		Materials 5,392.72	Less
		Lubrication/Fluid 0.00	0.00
		Others 0.00	0.00
		Amount Due	7,841.16

PLEASE TEAR ALONG PERFORATED LINE

3621175

TO SECURITY GUARD

3621175

 PLEASE ALLOW THE UNDERMENTIONED
 VEHICLE TO LEAVE THE COMPANY PREMISES.

 DATE
 TIME 06/03/2018
 11:13

VEHICLE NO

SLV5059R

CUSTOMER

 SIGNATURE
 FOR BORNEO MOTORS (SINGAPORE) PTE LTD

Borneo Motors



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingsapore.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462

Tel no.: 6631 1188
Customer Detail

ESTIMATE

Account Detail		Account No	M/s Borneo Motors (Singapore) Pt 2 Pandan Crescent Inchcape Centre Singapore 128462 Work: 64751288
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept		S1000004 / ICCUA1	
		Document No 0	
		Document Date 14/03/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	AHXEQ	L1	NGX10R	30/12/2017	SIV5059R	1037	29878 :9HIL/SIV5059R-150211
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	

JTNKY3BX301006149 8NRU168429 60 Raymond Seah L M 12/03/2018 17.10 14/03/2018 18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY TO RECOVER FROM TP LATER-OD/UL POLICY NO.:B28990449MCY ACC DATE:15/02/2018 NO OF REPAIR DAYS:04 EXCESS:\$1500.00 DATE-IN:13/03/2018 DATE SURVEY:08/03/2018 BY:LKK-RASUL AUTHORIZED ON:09/03/2018				30.00/
2	B	BP-ECU TO RESET ECU AND REPROGRAMME	02			462.00/
3	B	BP-LAB TO CHECK WIRING & LIGHTING.				104.72/
4	B	BP-LAB TO FOCUS HEADLAMP.	02			924.00/
5	B	BP-LAB TO REPLACE FRONT RH SIDE ACCIDENT DAMAGE PARTS.STRAIGHTEN/REALIGN ALL OTHER AFFECTED AREAS.				1012.00/
6	V	BP-RES TO SPRAY PAINT ON FRONT RH ACCIDENT AFFECTED AREAS.				-1500.00/
7	1	EXC Excess element of insurance repair to be paidby the insured party	1.00	143.50	15.00	121.97/
8	2	T75601-10010 MOULDING SUB-ASSY, T53801-10600 FENDER ASSY,FR RH	1.00	814.00	15.00	691.90/

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	1,846.59
		Labour	129.26
		Materials	0.00
		Lubrication/Fluid	
		Others	
			GST 7.00%
			Less
			Amount Due

3623612

PLEASE TEAR ALONG PERFORATED LINE

3623612

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE
TIME 14/03/2018
17:18

VEHICLE NO

SIV5059R

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Vehicle Diagnostic Report

003646 km

JTNKY3BX301006149

TOYOTA BODY CARE

Printed By: Default User(1)

16/03/2018 9:55:27 AM

Health Check Results All Systems(1 of 1)

Enhanced

Engine	Yes	P160500	X				896631017100
LKA/LDA	Yes	U0235			X		-
Front Recognition Camera	Yes	U0235			X		8646FF406000
							8646GF401600
Combination Meter	No	U023A			X		83800F402002
	No	U1104			X		-
Main Body	No	B1244			X		8922F1002001
Entry&Start	No	U0142			X		-
	No	U0155			X		-
PA/ICS/Clearance Sonar	No	C1AE1			X		8934F0W0200
	No	C1AE2			X		-
	No	C1AE3			X		-
	No	C1AE4			X		-
Power Source Control	No	U0140			X		-
Blind Spot Monitor Slave	Yes	C1AB5			X		8816F1003002
HL AutoLeveling	Yes	U0242			X		8994F1001001
Transmission							896651015000
Cruise Control							-
ABS/VSC/TRC/EPB							F152610163
Steering Angle Sensor							8924GF4010
EMPS							8965B10011
Air Conditioner							8865F1001001
D-Door Motor							-
P-Door Motor							-
RR-Door Motor							-
RL-Door Motor							-
Master Switch							-
SRS Airbag							8917F10021
Pre-Collision 2							8821FF406000
Front Radar Sensor							8821FF406000
Starting Control							-
Blind Spot Monitor Master							8816F1003001
Central Gateway							8911F1002001

Vehicle Diagnostic Report

003646 km

JTNKY3BX301006149

TOYOTA BODY CARE

Printed By: Default User(1)

16/03/2018 9:58:24 AM

Health Check Results All Systems(1 of 1)

Enhanced

Engine							*	896831017100
Transmission							*	896651015000
Cruise Control							*	-
ABS/VSC/TRC/EPB							*	F152610163
Steering Angle Sensor							*	8924GF4010
EMPS							*	8965B10011
LKA/LDA							*	-
Front Recognition Camera							*	8546FF406000
							*	8646GF401600
Air Conditioner							*	8865F1001001
Combination Meter							*	83800F402002
Main Body							*	8922F1002001
D-Door Motor							*	-
Entry&Start							*	-
P-Door Motor							*	-
RR-Door Motor							*	-
RL-Door Motor							*	-
Master Switch							*	-
IPA/ICS/Clearance Sonar							*	8934F0W0200
SRS Airbag							*	8917F10021
Pre-Collision 2							*	8821FF406000
Front Radar Sensor							*	8821FF406000
Starting Control							*	-
Power Source Control							*	-
Blind Spot Monitor Master							*	8816F1003001
Blind Spot Monitor Slave							*	8816F1003002
HL AutoLeveling							*	8994F1001001
Central Gateway							*	8911F1002001

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/NSG18004462/R1VBN2

Date: 20/03/2018

REFERENCE

Insured/Claimant: BORNEO MOTORS (S) PTE LTD
Date of Loss: 15/02/2018

Policy No: B28990449MCY
Nature of Claim: OD

Claim No: 551592

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLV5059R
Make & Model: TOYOTA C-HR, 1.2 (A)
Reg. Date: 30/12/2017 (Man. Year: 2017)
Colour: Grey
Engine Capacity: 1196 cc
Market Value/New Car Price: S\$113,000.00
Sum Insured (S\$): Market Value/New Car Price

Engine No: 8NRU168429
Chassis No: JTNKY3BX301006149
Odometer: 3395 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/60R17
Front Left Side: Dunlop 6 mm
Front Right Side: Dunlop 6 mm
Rear Tyre Size: 215/60R17
Rear Left Side: Dunlop 6 mm
Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	1,965.47	843.87	1,121.60	57.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,362.72	2,502.72	2,860.00	53.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,328.19	3,346.59	3,981.60	54.33
- Excess (S\$)	1,500.00	1,500.00	0.00	0.00
(S\$)	5,828.19	1,846.59	3,981.60	68.32
+ GST 7.00/7.00% (S\$)	407.97	129.26	278.71	68.32
Nett Amount (S\$)	6,236.16	1,975.85	4,260.31	68.32

INSPECTION

Date of Assignment: 07/03/2018

Date Inspected: 08/03/2018 Inspected At:

Borneo Motors (S) Pte Ltd (Pandan)
2 Pandan Crescent
Singapore 128462

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Mar 2018)
Parts:	M1-SUV	TOYOTA C-HR 1.2 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLV5059R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER FR BUMPER	Repair	424.40 FS	*- FS
2	8		*OUTSIDE RETAINER	Serviceable	22.40 FS	*- FS
3	1		*COVER,FR BUMPER	Serviceable	327.25 FS	*- FS
4	1		*RETAINER,FR BUMPER	Serviceable	97.83 FS	*- FS
5	1		*RETAINER,FR BUMPER	Serviceable	97.83 FS	*- FS
6	1		*GRILLE,RADIATOR	Serviceable	82.62 FS	*- FS
7	1		*COVER,FR BUMPER	Serviceable	69.27 FS	*- FS
8	1		*MOULDING SUB-ASSY	Scratched	121.97 FS	*121.97 FS
9	1		*FENDER SUB-ASSY,FR	Bent	691.90 FS	*691.90 FS
10	1		*SUNDRY	Necessary	30.00 FS	*30.00 FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					1,965.47	843.87

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RESET ECU AND REPROGRAMME	New	462.00	462.00
2	TO CONDUCT WHEEL ALIGNMENT CHECK	New	308.00	-
3	TO CHECK WIRING & LIGHTING TO FOCUS HEADLAMP	New	104.72	104.72
4	TO REPLACE FRONT RH SIDE ACCIDENT DAMAGE PARTS.STRAIGHTEN/REALIGN ALL OTHER AFFECTED AREAS	New	2,464.00	924.00
5	TO SPRAY PAINT ON FRONT RH ACCIDENT AFFECTED AREAS	New	2,024.00	1,012.00
Gross Labour Cost (\$\$)			5,362.72	2,502.72

Report was unsubmitted during this print-out.

< END OF ESTIMATES >