

22/03/2018

ASS. REC. BY:

REF:

CS/SPF18004468/Avb⁰²

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): Abdul Rahman of SPF Date/Time: 08/03/2018

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: Gx 6429Z Insured: QX 486Dat Workshop m/s Kai Motor Tel: 6747 4006of Blk 3007 Ubi Rd I # 01-440Policy No: _____ Claim No: AEED / 105 / 009 / 2018 / 023

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 22012018
(Client's Record)

CA / REV / REP. / REV 24 HRS wpi

H.O.D. Endorsement:

Date/Time: 08/03/2018 736am Person Contacted: Wendy Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	Gx 6429Z - x
	QX 486D - CS1 / SPF18004468 / Qbed
	DOA: 03062016
11/4/18	LS \$ 2600 (Red 1954.23, 432)

ASS. REC. BY: Adrian King

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: GX6429Z Yr Regn: 2004 / AgentType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Dyna c.c. 2986Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 396898 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTFUF34Y203002601Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 185R14C BSR: 155R12C Charmhoo

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 09/03/18Survey held at Kai MotorDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP SPF.
	COE Expiry: 31/07/19.
	MV: 13K
	PV: 5.7K.
	Nett: 7.3K.
RECEIVED 11 APR 2018	

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: 5

1)

☐ : Final ReportResurvey No. of Trip: -

Date/Time, File Return to?

2) 11/4 - typistAdd Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS. \$ _____

Photos

Others

TOTAL

280Report Format: TPLump Sum / I.B.I. (\$) 26000

Survey Department Check List (Case Handler)

Reference No.: CS/SPF 1804468/Avb
 Policy Type: OD/TP/TP RES/TL/EVA

Case Handler

Typist

Admin (): Case handler to make sure all information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No				
C	Claim No	✓			
C	Insurance Authorisation (CA/REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount				
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded				
---	-------------------------	--	--	--	--

Check By: VERON 11/4/18
 Case Handler Date

*C: Critical *N: Non-Critical

21/05/201



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTOMOTIVE ENGINEERING & MGT DIVISION

Ref : CS/SPF18004468/Avb

ACCIDENT CLAIM SECTION
(SINGAPORE POLICE FORCE)

1 MOUNT PLEASANT ROAD

BLK 8 OLD POLICE ACADEMY SINGAPORE 298333

Date : 08-03-2018



Code : SPF

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	QX 486D	Veh. Inspected	GX 6429Z
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/009/2018/023	Excess (\$)	0.00
Assign From	ABDUL RAHMAN	Assign Date	08/03/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	22/01/2018	Inspection Date	
Survey held at	KAI MOTOR TRADING BLK 3007 UBI ROAD 1 #01-434 SINGAPORE 408701		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



SINGAPORE POLICE FORCE

SPF Accidents Claims Section
Automotive Engg & Mgmt Div
Police Logistics Department
No. 1 Mount Pleasant Road
Block 8 Old Police Academy
#02-12 Singapore 298333

Your Ref : GX6429Z

Our Ref : AEMD/105/009/2018/023

Date : 8 March 2018

Tel: 64784840

Fax: 64784848

M/s LKK Auto Consultants Pte Ltd
Paya Ubi Industrial Park
51 Ubi Avenue 1 #01/02-25
Singapore 408933

Via Fax only: 62564315

Dear Sir/Madam,

ACCIDENT ON 22 JANUARY 2018 INVOLVING POLICE VEHICLE QX486D AND OTHER VEHICLE GX6429Z

We refer to the above matter.

- 2 Please arrange for a Pre-Repair Inspection of vehicle no. GX6429Z at M/s Kai Motor Trading of Blk 3007 Ubi Road 1 #01-440, Singapore 408701.
- 3 For appointment, please contact Tel: 67474006.
- 4 Estimates were provided by the workshop.
- 5 Thank you.

Abdul Rahman
Accident Claims Officer
for ASST DIRECTOR

A FORCE FOR THE NATION

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1293N
Vehicle Details	
Vehicle No.:	GX6429Z
Vehicle to be Exported:	Yes
Intended De-registration Date:	09 Mar 2018
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 D
Primary Colour:	Blue
Manufacturing Year:	2004
Engine No.:	5L5447237
Chassis No.:	JTFUF34Y203002601
Maximum Power Output:	-
Open Market Value:	\$23,715.00
Original Registration Date:	02 Aug 2004
First Registration Date:	02 Aug 2004
Transfer Count:	1
Actual ARF Paid:	\$1,186.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Jul 2019
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$20,383.00
COE Rebate Amount:	\$5,676.00
Total Rebate Amount:	\$5,676.00
Message	
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.	

The information contained herein is correct as at 09 Mar 2018

**Fuel Type:** Diesel

One Owner. New 5 Years COE, Private Owner Maintained, New Paintwork, Very Good Condition, Accident Free, Full Checkered Pad, Pass Inspection, New Road Tax, Air-con Just Renewed.

Posted: 07-Mar-2018 Tags: 2003 Toyota Dyna, Toyota Dyna, Toyota, Dyna, Used Toyota

**Toyota Dyna 150 (New 5-yr COE)****\$30,800**

\$6,160 /yr

20-Jun-2003

2,986 cc

-

Truck

Available

Fuel Type: Diesel

The Japanese Workhorse For Your Company Needs. Low Maintenance And Low Fuel Consumption. Very Well Maintained! Engine And Gearbox In Excellent Condition! Call Now For Viewing Before You Miss This Vehi...

Tan Wei Auto Pte Ltd

Posted: 07-Mar-2018 Tags: 2003 Toyota Dyna, Toyota Dyna, Toyota, Dyna, Used Toyota

**Toyota Dyna 150 (COE till 09/2018)****\$14,000**

\$25,940 /yr

23-Sep-2003

2,986 cc

-

Truck

Available

Fuel Type: Diesel

Rare 7 Feet High Box. Tip Top Condition, With New 5-year COE!

PREMIUM AD

Posted: 14-Jan-2018 Tags: 2003 Toyota Dyna, Toyota Dyna, Toyota, Dyna, Used Toyota

**Toyota Dyna 150 (COE till 12/2018)****\$12,800**

\$17,300 /yr

05-Dec-2003

2,986 cc

-

Truck

Available

Fuel Type: Diesel

Engine Is Powerful And Smooth. Very Low Mileage! Aircon In Excellent Condition. New Paint, Fast Loan Approval, Price Negotiable, See To Believe!

Posted: 24-Feb-2018 Tags: 2003 Toyota Dyna, Toyota Dyna, Toyota, Dyna, Used Toyota

**Toyota Dyna 150 (COE till 02/2019)****\$16,000**

\$17,590 /yr

05-Feb-2004

2,986 cc

-

Truck

Available

Fuel Type: Diesel

Full Canopy With Checked Plate. Well Maintained And Good Condition.

DIRECT OWNER

Posted: 20-Jan-2018 Tags: 2004 Toyota Dyna, Toyota Dyna, Toyota, Dyna, Used Toyota

**Toyota Dyna 150 (COE till 03/2022)****\$30,800**

\$7,580 /yr

09-Sep-2004

2,986 cc

462,621 km

Truck

Available

Fuel Type: Diesel

The Most Highly Sought After Japanese Commercial Vehicle That Cater Your Business Need. Best Economical Buy, Fuel Efficient Diesel Engine. Call Now For A Non Obligatory Discussion.

PREMIUM AD

Posted: 05-Mar-2018 Tags: 2004 Toyota Dyna, Toyota Dyna, Toyota, Dyna, Used Toyota

**Toyota Dyna 150 (COE till 03/2024)****\$37,800**

\$6,230 /yr

30-Sep-2004

2,986 cc

-

Truck

Available

Fuel Type: Diesel

7 More Years To Drive. Free 6 Months New Road Tax. Probably The Most Worth It Unit In The Market. Comes With Existing Hood, Checker Plate And Wooden Railing Or We Can Convert Back To The Normal Metal ...

ABWIN (1994) Pte Ltd

Posted: 09-Mar-2018 Tags: 2004 Toyota Dyna, Toyota Dyna, Toyota, Dyna, Used Toyota

**Toyota Dyna 150 (COE till 04/2020)****\$22,800**

\$10,860 /yr

14-Apr-2005

2,986 cc

-

Truck

Available

Fuel Type: Diesel

This Vehicle Is Eligible For Early Turnover Scheme. Buy With Assurance! Well Maintained & Taken Care Of Under 1 Owner Previously! Finance Up To 100%!

PREMIUM AD

Car (S) Pte Ltd

Posted: 28-Feb-2018 Tags: 2005 Toyota Dyna, Toyota Dyna, Toyota, Dyna, Used Toyota

**Toyota Dyna 150 (COE till 03/2020)****\$18,800**

\$9,110 /yr

04-May-2005

2,986 cc

-

Truck

Available

Fuel Type: Diesel

Previous Owner Retired, Super Good Original Condition, No Need Repair, Cheapest In Town, Price Negotiable, High Loan With Lowest Interest Rate Available, High Trade In, Call Now!

PREMIUM AD

ABWIN Bus Pte Ltd

Posted: 25-Feb-2018 Tags: 2005 Toyota Dyna, Toyota Dyna, Toyota, Dyna, Used Toyota

**Toyota Dyna 150 (COE till 04/2020)****\$16,800**

\$7,830 /yr

12-May-2005

2,986 cc

-

Truck

Available

Fuel Type: Diesel

Posted: 02-Mar-2018 Tags: 2005 Toyota Dyna, Toyota Dyna, Toyota, Dyna, Used Toyota

Toyota Dyna 150 (COE till 07/2020)**\$21,800**

\$9,350 /yr

08-Jul-2005

2,986 cc

-

Truck

Available

Fuel Type: Diesel

Cheapest In Town! Tip Top Condition, Well Maintained, New Road Tax, High Loan Available, Trade In Welcome, Price Negotiable And Call Us For

PREMIUM AD

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 01/03/2018 19:00
Date Of Accident 22/01/2018 06:50
Exact Location Of Accident 17 LENG KEE ROAD
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number GX6429Z
Insured/Policyholder
Name Of Registered Owner S & P SYSTEM SERVICES PTE LTD
Co Reg No 2007711293N
Email Address KAIMOTOR@GMAIL.COM
Mobile Phone No (LOCAL) +65-83575245
Alternative Phone No OFFICE-83575245

Vehicle Particulars

Manufacturer TOYOTA
Model DYNA

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company GREAT EASTERN GENERAL INSURANCE LIMITED
Type Of Coverage THIRD PARTY FIRE AND/OR THEFT
Fleet Policy NO
Policy Number 2018-V0086648-VCV-R006
Cover Note Number

Driver

Name of Driver RAMASAMY ELAYARAJA
Passport No/FIN G8333100W
Date Of Birth 02/06/1987
Occupation OUTDOOR
Date Of Driving Pass 14/12/2009
Driving Experience 8 YEARS AND 1 MONTH
Gender MALE
Mobile Number (LOCAL) +65-83575245
Fax Number
Contact Number
EMail Address NOEMAIL

tel: 6747 2441 / Hp: 9238 2759

Address

BLK 33 KAKI BUKIT AVE 3 #06-01

Postcode

415917

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle

-
-
-
-

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - ROUNDABOUT

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 0

Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

Police Station Name

WOODLANDS EAST N.P.C

Police Station Address

ROAD: 3 WOODLANDS DRIVE 63, POSTCODE: 737890, COUNTRY: SINGAPORE

Police Station Contact

TEL NO: - FAX NO:

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

QX486D

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage


SPF Accident claims Section
AFMD Pld Logistics

T: 647 84 840 - Abbul

F: 6478 4848

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report T/20180128/2643

DECLARATION

I/We declare that the foregoing particulars are true in every respect.

X



Policyholder's Signature
Date & Time:

[Signature]

Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Signature]

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

[Signature]

1/3/18

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

B. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20180125/2143

1 of 3

Police Station Of Origin:
Woodlands East N.P.C.
3 Woodlands Drive 63 SINGAPORE 737890
Tel No: 1800-7679999

Report No. T/20180125/2143

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 25/01/2018 17:46		Vide Report No.: G/20180122/0039		Station Diary No.: 207	
Name of Informant: RAMASAMY ELAYARAJA			Address: APT BLK 33 KAKI BUKIT AVENUE 3 #06-01 HOMESTAY LODGE SINGAPORE 415917		
ID Type / ID No.: FIN NO / G8333100W			Contact No.: Home/Office: Mobile: 83575245		
Nationality: INDIAN			Email:		
Sex: Male	Age: 30	Date of Birth: 02/06/1987	Type of Informant: Driver		
Race: Indian			Language:	Institution / School Name:	
Occupation: SITE SUPERVISOR			Driving Licence Information: Class: 3 Date of Expiry:		

Type of Accident:	Non-Injury Government Vehicle	Drink Drive: No	Date/Time of Accident: 22/01/2018 06:50	Type of Location: Car Park
Location: Along Road 1 KAKI BUKIT AVENUE 3 17 Leng Kee Road Aik Chuan Building Singapore 159092 Open Carpark				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume:	
Type of Collision: Moving Vehicle Against - Parked Vehicle			Anyone conveyed by ambulance: No	

GX6429Z	Lorry				Slightly Damaged	0
QX486D	Car					0

Any Pedestrian Involved: No		Use of Pedestrian Crossing: NA	
No. of Pedestrians Injured: NIL			

**SINGAPORE
POLICE FORCE**

T/20180125/2143

2 of 3

Police Station Of Origin:
Woodlands East N.P.C.
3 Woodlands Drive 63 SINGAPORE 737890
Tel No: 1800-7679999

Report No. T/20180125/2143

CONTINUATION OF REPORT

Name	RAMASAMY ELAYARAJA		ID No.	G8333100W
Related Vehicle	GX6429Z (Lorry)		Contact No.	83575245
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL	
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL	

Brief Details.

On 21/01/2018 at about 2030hrs, I parked my vehicle GX6429Z at 17 Leng Kee Road Aik Chuan Building Singapore 159092 open carpark lot number 5.

On 22/01/2018 at about 0650hrs, I went to retrieve my vehicle and discovered that there were police along my vehicles. Thereafter, the Police IO Dylan (DID: 85476251) informed that a traffic accident involving my vehicle and police vehicle had happened and requested for me to lodge a traffic accident report at any police station. I am unsure of the details of the accident. However, my vehicle front bumper suffered a dent.

**SINGAPORE
POLICE FORCE**

T/20180125/2143

Police Station Of Origin:
Woodlands East N.P.C.
3 Woodlands Drive 63 SINGAPORE 737890
Tel No: 1800-7679999

3 of 3

Report No. T/20180125/2143

CONTINUATION OF REPORT**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J /

Sgt 2 NG KOK WEI JOHN

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

25/01/2018 17:46

Officer In Charge Of Case:

TP / GIA /

Staff Sgt TANG SIEW PING

Contact No.: 65476430

SN 130

Classification Of Case:

Authentication Stamp
NP168

Signature :

Singapore Police Force



凱摩哆服務

KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.
TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com.
BUS. REG. NO: 44223100L GST NO: M90371531Y

專業服務：汽車意外保險賠償，拖車，汽車修理及維修服務，打嗎呷，噴漆。

Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.

Date : 07/03/2018

Attn: The Motor Claims Department / ABBul

Your Insured veh no : QX 486 D

SPF Accident Claims Section

AEMD PLD Logistice

Tel : 6478 4840

Fax : 6478 4848

Dear Sir / Madam

Estimate Cost repair Bill To Toyota Dyna GX 6429 Z & QX 486 D on 22/01/2018

To Supply :-

1pc	Front body panel <i>Dented</i>	\$ 1,100.40	✓
1pc	Front Windscreen glass rubber <i>m</i>	\$ 310.10	✓
1pc	front body panel logo <i>m</i>	\$ 98.10	✓
1pc	Front grille <i>at</i>	\$ 535.40	✓
1pc	Front head lamp <i>Not m</i>	\$ 736.30	✗
1pc	Front bumper <i>Bea Dented</i>	\$ 496.30	✓
1pc	Front bumper bracket <i>Bea</i>	\$ 98.60	✓
1pc	Front panel garnish <i>when</i>	\$ 297.10	✗
		\$ 3,672.30	
less		25% \$ 918.08	
		\$ 2,754.23	

1pc	Front windscreen seal <i>3m</i>	\$ 55.00	s/nett 30
1pc	Front windscreen sealert <i>3m</i>	\$ 55.00	s/nett 30

To dismantl & replace damage parts, panel beat where necessary.

To putty, apply primer & spray paint on the affected portion.
labour charge to remove & refix windscreen

To check wiring functions.

\$ 750.00 *600*

\$ 700.00 *500*

\$ 120.00 *100*

\$ 120.00 *30*

\$ 4,554.23

Adrian King
L/S 09/03/18
05 Days.

total 3269.18
L/S: 2-6K

LKIK

LKIK Auto Consultant's hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

WITHOUT PREJUDICE

(By Email Only)

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTOMOTIVE ENGINEERING & MGT DIVISION

Ref : CS/SPF18004468/Avbn2

ACCIDENT CLAIM SECTION
(SINGAPORE POLICE FORCE)

1 MOUNT PLEASANT ROAD

BLK 8 OLD POLICE ACADEMY SINGAPORE 298333

Date : 12-04-2018



Code : SPF

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	QX 486D	Veh. Inspected	GX 6429Z
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/009/2018/023	Excess (\$)	0.00
Assign From	ABDUL RAHMAN	Assign Date	08/03/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA DYNA	c.c	2986
Engine No.	HIDDEN	Year of Reg.	2004
Chassis No.	JTFUF34Y203002601	Colour	SILVER
Odometer	396898	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185 R14C	BRIDGESTONE	6 mm
L/H Front Tyre	185 R14C	BRIDGESTONE	6 mm
R/H Rear Tyre	155 R12C	CHARMHOO	6 mm
L/H Rear Tyre	155 R12C	CHARMHOO	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	22/01/2018	Inspection Date	09/03/2018
Survey held at	KAI MOTOR TRADING BLK 3007 UBI ROAD 1 #01-434 SINGAPORE 408701		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GX 6429Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BODY PANEL	DENTED	1,100.40	1,100.40
1	FRONT WINDSCREEN GLASS RUBBER	NECESSARY	310.10	310.10
1	FRONT BODY PANEL LOGO	NECESSARY	98.10	98.10
1	FRONT GRILLE	CUT	535.40	535.40
1	FRONT HEAD LAMP	NOT NECESSARY	736.30	-
1	FRONT BUMPER	DENTED	496.30	496.30
1	FRONT BUMPER BRACKET	BENT	98.60	98.60
1	FRONT PANEL GARNISH	NOT NECESSARY	297.10	-
	LESS 25% DISCOUNT		-918.07	-659.72
			2,754.23	1,979.18
<u>SPECIAL NETT ITEMS</u>				
1	FRONT WINDSCREEN SEAL (SN)	NECESSARY	55.00	30.00
1	FRONT WINDSCREEN SEALERT (SN)	NECESSARY	55.00	30.00
			110.00	60.00
<u>LABOUR</u>				
	TO DISMANTLE & REPLACE DAMAGE PARTS,PANEL BEAT WHERE NECESSARY.		750.00	600.00
	TO PUTTY,APPLY PRIMER & SPRAY PAINT ON THE AFFECTED PORTION.		700.00	500.00
	LABOUR CHARGE TO REMOVE & REFIX WINDSCREEN.		120.00	100.00
	TO CHECK WIRING FUNCTIONS.		120.00	30.00
			1,690.00	1,230.00
GRAND TOTAL			4,554.23	3,269.18
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,600.00

Report Ref No. CS/SPF18004468/Avbn2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.