Surveyor	GQ	ASSIGNMENT	
From (Perso	rene tay	of <u>C71</u>	Date/Time: 7/3/180 4.31pr
Estimated C			1 to:
		/EVA/INV/MV7CS	
To Inspect ' at Worksho	A STATE OF S	SGI 9566P	Tel: 6555 5556
of	60 W	oodlands Ind Pr	KE4
	OMPCSN 70	142621710	Claim No: SNM18001176001
Sum Insure			Excess: \$ -
Make of Vo (Client's Rec			D.O.A. 5 3 2018
) REP. / REV 24 HB	RS	H.O.D. Endorsement:
CA / RE	P AND THE PARTY AND THE		· 11
_ Date/Time	9.08umg	Person Contacted:	Ster Vehicle (IN DOUT
	현기 :		Vehicle (IN DOUT
_ Date/Time	g.osumg	(-) Estimate P-05/07/18004	1467 Mrd3 D.OA: S/3/18
_ Date/Time	g.osumg	P-colot118004	1467/Mlrd3 D.O.A: S/3/18 Tay un Meinen.
Date/Time	Action/Instruction (SCI 9566 94-374 VEW 248M Affred	P-colot118004	1467/Mlrd3 D.OA: S/3/18 Tay Ma Meinun.

...CLAIM SUBFOLDER...(New Assignment)

Case Noti	OPT - I			A ship Direct	Adi Submitted	Ins Auth'ed	Status
	ified	Est Submitted	Adj Assigned	With Why	Find to work the control		The second secon
07 N	Mar 2018 endback Est	07 Mar 2018 15:44	07 Mar 2018 16:31				Cancel Case

Main	Reference	Claim Details	Documents	Show All		
CLAIM SUBFOLDER DET	TAILS					
Insured:	ANG BIN KEONG, LAWRENCE,	ID: S1401021A	05/03/2018 07:0	0 59		
Vehicle Reg. No.:	SGJ9566P	Date of Loss:	The second secon			
Claim Type:	OD / SNM18D01178C01	Policy/Cover Note No.:	(Comprehensive) Coverage: 25/07			
		Excess:	S\$0.00	5\$0.00		
Repairer:	SMRT Automotive Services Pte					
	at the Tananana (Sings	anore) Pte. Ltd. (HO) - Tel: 6:	389 6111 [Handled b	y Irene Tay Hui		
Handling Insurer:	China Taiping Insurance (Singa					
Handling Insurer: Adjuster:	China Taiping Insurance (Singa Ping - 638986192)	(HQ) - Tel: 6256-3561 [Fin:				
Adjuster:	China Taiping Insurance (Singa Ping - 638986192] LKK Auto Consultants Pte Ltd (ANG BIN KEONG, LAWRENCE (/ M	(HQ) - Tel: 6256-3561 [Fin:				
Adjuster: Driver/Custodian:	China Taiping Insurance (Singa Ping - 638986192)	(HQ) - Tel: 6256-3561 [Fin:	al Rpt due 16/03/2	018]		
Adjuster: Driver/Custodian: Adj Asg, Remarks:	China Taiping Insurance (Singa Ping - 638986192] LKK Auto Consultants Pte Ltd (ANG BIN KEONG, LAWRENCE (/ M PLEASE SURVEY AND REVERT	(HQ) - Tel: 6256-3561 [Fin:	al Rpt due 16/03/2	018]		
Adjuster: Driver/Custodian:	China Taiping Insurance (Singa Ping - 638986192) LKK Auto Consultants Pte Ltd (ANG BIN KEONG, LAWRENCE (/ M PLEASE SURVEY AND REVERT	(HQ) - Tel: 6256-3561 [Fin:	al Rpt due 16/03/2	018]		
Adjuster: Driver/Custodian: Adj Asg. Remarks: ASSOCIATED MAIL RE	China Taiping Insurance (Singa Ping - 638986192] LKK Auto Consultants Pte Ltd (ANG BIN KEONG, LAWRENCE (/ M PLEASE SURVEY AND REVERT CEIVED case.	(HQ) - Tel: 6256-3561 [Fin : Male), NRIC: S1401021A	View All Search Tasks Create			



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	计算数据证	Affiliated to Federation Intern	nationale Des Experts En Autor	mobile	
СН	NA TAIPING INSU	JRANCE (S) PTE LTD	Ref : CS/CTI180044	471/Gqd3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Date: 08-03-2018 Code: CTI		
		Policy Partic	culars :- OWN DAMAGE		
	Insured Veh.	7	Veh. Inspected	SGJ 9566P	
	Policy No.	DMPCSN7042621710	Coverage (\$)	0.00	
	Claim No.	SNM18D01178C01	Excess (\$)	0.00	
	Assign From	MERIMEN (IRENE TAY)	Assign Date	08/03/2018	
		Vehicle Pa	rticulars & Condition		
	Make & Model		c.c	0	
	Engine No.	HIDDEN	Year of Reg.		
	Chassis No.		Colour		
	Odometer	•	Steering		
	Brakes		Modification		
	General				
	M. S. C.	Cond	ditions of Tyres		
		Size	Make	Balance	
	R/H Front Tyre			mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre			mm	
	L/H Rear Tyre			mm	
		Descrip	otion of Damages	in Call Line	
140			7305-		
	Assident Det		ral Information		
_	Accident Date	05/03/2018	Inspection Date	08/03/2018	
	Survey held at	SMRT AUTOMOTIVE SERVI			
a.		60 WOODLANDS INDUSTRIA		57705	
1.	ANTILE MARKET	ALUE IO CO	Remarks		
	B)IN ACCORDANG	ALUE IS S\$(EST. AVE CE TO YOUR INSTRUCTIONS,	ERAGE)	EDAIDS	

Shiau Chan (LKKAuto)

From:

Esther Tey Chor Keng (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR)

<TeyChorKeng@smrt.com.sg> Tuesday, 15 May 2018 3:30 PM

Sent: To:

Shiau Chan (LKKAuto)

Cc:

SUR; Guo Qiang (LKKAuto); Koo Yew Chung (Auto Svcs/Ext Biz Svs/AR & SC); Peh

Eng Hock (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)

Subject:

RE: SGJ9566P - CTP OD - Finalisation

Dear Shiau Chan,

We have confirm the finalise amount at Lump Sum \$5,500.00 before GST and 5 repair days.

Thank you. Regards, Esther

From: Shiau Chan (LKKAuto) [mailto:siewsc@lkkauto.com]

Sent: 02 May 2018 17:40

To: Esther Tey Chor Keng (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR)

Cc: SUR; Guo Qiang (LKKAuto)

Subject: RE: SGJ9566P - CTP OD - Finalisation

Dear Esther,

Offer Lump Sum \$5,500.00 before GST and 5 repair days.

Kindly confirm.

Best Regards,

Shiau Chan (Ms) | Case Handler LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>siewsc@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Guo Qiang (LKKAuto)

Sent: Tuesday, 24 April 2018 10:12 AM

To: Shiau Chan (LKKAuto) < siewsc@lkkauto.com > Subject: FW: SGJ9566P - CTP OD - Finalisation

From: Esther Tey Chor Keng (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR) [mailto:TeyChorKeng@smrt.com.sg]

Sent: Monday, 16 April, 2018 3:20 PM

To: Guo Qiang (LKKAuto)

Subject: RE: SGJ9566P - CTP OD - Finalisation

Hi Guo Qiang,

Kindly finalise ASAP, thanks.

Regards,

Shiau Chan (LKKAuto)

From:

Shiau Chan (LKKAuto)

Sent:

Friday, 16 March 2018 11:46 AM

To:

Esther Tey Chor Keng (Auto Svcs/Ext Biz Svs/AR & SC/ARC/AR)

Cc:

SUR

Subject:

VEHICLE SGJ 9566P (DOA: 05/03/2018)

Dear Esther,

As instructed by our client EQ Insurance, please proceed to repair the insured vehicle SGJ 9566P. (Excess \$0/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>siewsc@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Claim Audit

1	AUDIT TRAIL			By
o.	On	Audit	Remarks	[R] Tey Chor
1	07 Mar 2018 15:19	Clm Veh Model Changed	(204672) HONDA ODYSSEY 2.4 (A).	Keng
2	07 Mar 2018 15:19	Clm Created	Reg No: SGJ9566P. Policy No: DMPCSN7042621710. Acct Date: 2018/03/05. Cl aim Type: OD. Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ), Workshop: SMRT Automotive Services Pte Ltd (Woodlands)	[R] Tey Chor Keng
2	07 Mar 2018	Clm Submitted	13241.31.	[R] Tey Chor Keng
4	15:44 07 Mar 2018	Clm Registration	Excess: -> 0.00.	[I] Irene Tay Hui Ping
4	16:31	Modified	The state of the s	[I] Irene Tay
5	07 Mar 2018 16:31	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):PLEASE SURVEY AND REVERT	Hul Ping [I] Irene Tay
6	07 Mar 2018 16:31	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/03/16	Hui Ping
7	07 Mar 2018	Adj Mandate Set	Approved:0.00.	[I] Irene Tay Hui Ping
8	10:31 07 Mar 2018	Assignment 1st Accessed		[A] CATHERINE CHONG KAI LING
9	08 Mar 2018 14:00	Adj Adjuster Assigned	[None] -> XING GUO QIANG	[A] Nivitha Govindasam [A] SHIAU
10	09 Mar 2018 15:59	Adj Rpt Initiated		CHAN [A] SHIAU
1	00 Mar 2018	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/03/16	CHAN
1.			Cur.Req:8328.23:DAMAGES CONSISTENT, REPAIR COST ECONOMICAL, WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
1	15.03	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/03/16. Mandate Remarks: Please proceed to authorize repairs UP TO \$8,328.23. Re-Inspection of vehicle required.	
1	4 15 Mar 2018 14:48	Adj Mandate Set	Approved:8328.23:Please proceed to authorize repairs UP TO \$8,328.23. Re-In spection of vehicle required.Reinsp:Adj decides.	[I] Alfred To

ACTIVITY

No record

terimen Billin	g for this case -	Transaction	History				
Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1742088	07/03/2018 15:19	Motor	SMRT Automotive Services Pte Ltd (Woodlands)	SMRT Automotive Services Pte Ltd (Woodlands)	SGJ9566P		xx.xx
1744425	09/03/2018 15:59	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SGJ9566P		10.70

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road

#16-00 Springleaf Tower Singapore 079909

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn:

Irene Tay Hui Ping

Date:

09 Mar 2018

Preliminary Advice

Vehicle No

: SGJ9566P

Accident Date

: 05/03/2018

Make

: HONDA ODYSSEY

Policy No.

: DMPCSN7042621710

Assignment Date

: 07/03/2018

Excess

: \$\$0.00

Date of Inspection : 08/03/2018

Est. Duration of Repair

: 5.00

Inspection At

: SMRT AUTOMOTIVE SERVICES PTE LTD (WOODLANDS)

60 WOODLANDS INDUSTRIAL PARK E4

SINGAPORE 757705

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,241.31
Revised Amount	:S\$	5,963.42
Check Items (Estimated)	:S\$	2,364.81
Total	:S\$	8,328.23

Lump Sum Repair

:S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	35,000.00
COE / PARF Rebate	:S\$	14,854.00
Salvage Value	:S\$	
Margin for Repair	:S\$	20,146.00

Remarks

(X)	The vehicle is repairable at our a let us have your authorisation.	justed amount. W	e have also	confirmed	excess	and policy	coverage.	Kindly
-------	--------------------------------------------------------------------	------------------	-------------	-----------	--------	------------	-----------	--------

)	The vehicle is uneconomical to	be repaired,	you are advised to invite tend	er for the	wreck.
--	---	--------------------------------	--------------	--------------------------------	------------	--------

Other comments:

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	1021A
Vehicle Details	
Vehicle No.;	\$GJ9566P
Vehicle to be Exported:	No
intended De-registration Date:	09 Mar 2018
/ehicle Make:	HONDA
Vehicle Model:	ODYSSEY 2.4 A
Primary Colour:	Black
Manufacturing Year:	2006
Engine No.:	K24A64000278
Chassis No.:	JHMRB18507C200278
Maximum Power Output:	118.0 kW (158 bhp)
Open Market Value:	\$29,632.00
Original Registration Date:	25 Jul 2006
irst Registration Date:	25 Jul 2006
ransfer Count:	0
ctual ARF Paid:	\$32,596.00
ntended PARF Rebate Details	
ARF Eligibility:	Forfeited
ARF Eligibility Expiry Date:	
ARF Rebate Amount:	\$0.00
ntended COE Rebate Details	
OE Expiry Date:	31 May 2021
OE Category:	B - Car (1601cc & above)
OE Period(Years):	5
QP Paid:	\$23,024.00
OE Rebate Amount:	\$14,854.00
otal Rebate Amount:	\$14,854.00
1essage	

The information contained herein is correct as at 09 Mar 2018

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

By the lodgement of this report to the insurers, you hereby conseaforesaid.	ant to the archiving of this report at the centre and to copies of the report being made distinction
	ACCIDENT STATEMENT
Date Of Report	05/03/2018 13:46
Date Of Accident	05/03/2018 07:15
Exact Location Of Accident	BUKIT PANJANG RING ROAD
Country/State of Loss	SINGAPORE
D	ETAILS OF OWN VEHICLE
Vehicle Registration Number	SGJ9566P
Insured/Policyholder	
Name Of Registered Owner	ANG BIN KEONG, LAWRENCE
NRIC No	S1401021A
Email Address	LAWRENCEANG@ICLOUD.COM
Mobile Phone No	(LOCAL) +65-97572244
Alternative Phone No	OTHERS-97572244
Vehicle Particulars	
Manufacturer	HONDA
Model	ODYSSEY-2.4 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN7042621710
Cover Note Number	
Driver	
Name of Driver	ANG BIN KEONG, LAWRENCE
NRIC No.	S1401021A

S1401021A NRIC No 19/06/1960 Date Of Birth INDOOR Occupation 28/05/1984 Date Of Driving Pass

33 YEARS AND 9 MONTHS **Driving Experience**

Gender

(LOCAL) +65-97572244 Mobile Number


Fax Number

OTHERS-97572244 Contact Number

LAWRENCEANG@ICLOUD.COM EMail Address

Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

7	I was driving along Bukit Panjano Rug Road during morning to 7.15 am, just outside Beacon Prunary School. I was driving Short as the road was jam during that time. I was one the 12f4 land (inner left lane) as I went up the hump. I saw a taxi town and breakbraice just after the hump as he hat a carl in front. As he stop abaupty I consider to brake in this as I just went up the hump.
a	+ 7.15 am just outside Beacon Princy School. I was driving
9	Justy as the road was jam during that time. I was in the 1244
	land (inner left (ane) as I went up the hung. I saw a taxi
-	samian breakbraice just after the hump as he hat a can
1	in front. To be stop abupty I contain to brace on how as I
_	just went up the himp.
_	7
_	
_	
-	
_	
_	
-	

Annua	_	_	_	-	-
DECL	Λ	DA	T	0	ħ

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature Date & Time: 5 3 2018

Driver's Signature

1.5 om if driver is not the policyholder)
Date & Time:

al 5/3/2018

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:





SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 757705

For surveyor Marking

SGD

TBA

05/03/2018

Claim Reference: WL/MAR2018/003 Assessment Number: CTI10133

Version: SMRTAUTO/2

Date Calculated: 07/03/2018 07:34

Full Report - V1 Registration: SGJ9566P Printed: 07/03/2018 15:34

Summary Information

Claim

Location:

Printed by: Authorisation Status:

Work Provider:

Claim Reference: Policy Number:

Other Reference: Third Party: Insured Amount: Under Warranty: Warranty Expired: Singapore (SG)

MR Raymond Interim

China Taiping Insurance

HONDA

HAB 01 SGJ9566P

July

2006

2006 Not Known

WL/MAR2018/003

Odyssey (Reference

BASE MODEL

DMPCSN7042621710

Estimated Repair Time: Ouote Due Date: Actual Repair Days:

Repairs Authorised:

Date of Incident:

Able to Authorise Repairs: TBA

Currency:

Parts Ordered Date: Hire Car Start: Hire Car End: Vehicle Collected:

Vehicle Details

Vehicle

Manufacturer:

Model: Sub Model:

Model Sheet Number:

Registration:

Registration Month:

Registration Year:

VIN Number:

Manufacture Year: Odometer:

Colour:

Engine Number:

Fuel Level:

%

Model Specs

2.3 LTR 110KW

TWO COAT PEARL/MICA

Vehicle Condition

Vehicle Status

Pre-Accident Condition:

Steering:

Brakes Pedal Travel: Place of Inspection: Pre-Accident Damage:

Tyres Condition:

Tread Depth LHF: Tread Depth LHR:

Damage Areas:

Severity of Impact:

Vehicle Status on Inspection:

Date of Inspection:

05/03/2018

Tread Depth RHF:

Tread Depth RHR: Direction of Impact: