

227-001

ASS. REC. BY:

REF: CS/ASM18004473/Uqd367

Special Instruction:

Surveyor:

Marcus

ASSIGNMENT (Office)

From (Person):

Winnie Ho

of

ASM

Date/Time: 8/3/2018

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLG 63P

Insured:

at Workshop m/s

SME Motor

Tel:

67476106

of

J kaki Bkt Ave 6 # 02-15 Autobay

Policy No:

Claim No:

88M009YW

Sum Insured:

Excess:

\$100.00

D.O.A. 5/3/18

Make of Veh:

(Client's Record)

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

Date/Time: 2:03pm 8/3/18

Person Contacted:

Jenny

Vehicle IN OUT

Date/Time

Action/Instruction

(✓)

Estimate

Pls Ensure Consistence? Be stringent

on COR

SLG 63P - CC4/ASM18004169/Upb3

D.O.A: 5/3/18

09/3/18 @

3:13pm revised to Winnie Ho via Smart Claim.

(08/11/13) waf

ASS. REC. BY: Marcus

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLG 63P

at Workshop m/s Sme

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: 900

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 103k.

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: 0

Consistent? : Yes or No

Est. Repairs: 6 days

Res.: Yes or No

Lum Sum: 131 %

3 Val.: Yes or No

CA / REV

REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLG 63P

Yr Regn: 2, 11

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or A7

Make: mer

Berz 5350L.c.c 3498

Colour: 3100k

A/C: Insured / Std / NI / NA

Sp. Reading: 6000

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: W 00221562A 348130

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 255/45 R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 5/3/18

D.O.I. 8/3/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

LTA 82800

2/11/18

Dep 18 Act 20200

Bothy 2/1/18

inform Repairer has CIA not more than 20K.

13/6/18

confirmed find by \$1800/ with AH 9/18

(Red 65963, 25/1/18)
no lump sum.

RECEIVED 20 JUN 2018

Date/Time, File Pass to?

☐

: Preli. Report

1) 20/6/18

☐

: Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 6

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee: 300

Transportation: _____

S + RS, Si

Photos

Others

TOTAL

Report Format: SMART claim

Lump Sum / I.B.I. (\$ 18001)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CS/ASM18004473/Uqd3

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811

Date : 08-03-2018



Code : ASM

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SLG 63P
Policy No.	Coverage (\$)	0.00
Claim No. S8M009YW	Excess (\$)	900.00
Assign From SMARTCLAIM (WINNIE HO)	Assign Date	08/03/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	05/03/2018	Inspection Date	08/03/2018
Survey held at	SME MOTOR PTE LTD 1 KAKI BUKIT AVE 6 #02-15 (AUTOBAY @ KAKI BUKIT) SINGAPORE 417883		

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.



Service Request Details

Claim

S8M009YW

Reference

None 

Loss Date

March 5, 2018

Request Date

March 8, 2018

Due Date

March 15, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated survey and authorize

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SLG63P

Make

MERCEDES

Service Address

1 Kaki Bukit Ave 6 #02-15, , 417883

Primary Contact/Insured

LAU YONG KWEE

BLK 351 YISHUN AVENUE 11, #08-199, 760351, Singapore

eilim@huihua.sg

Claim Handler

HO Winnie

6568804833

winnie.ho@axa.com.sg

Additional Instructions

1) PLS ENSURE CONSISTENCE & BE STRINGENT ON COR 2) est-\$21,694 3) XS-\$900

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)

New Message



SUPPLEMENTARY LIST OF VEHICLE SLG 63P UPLOADED

Type

🔗 Question

Message

Hi, pls proceed. Tks

Reply

photo.

power steering tank cracked - P 3210040
P 3210042

Engine oil ~~Dip~~ Dipstick cracked P-3210070

front Bonnet Top Air vent During survey already cracked and missing
Due to Bonnet Body Buckled
P-3080383

Radiator top hose LH Pin - P 3210059

front nozzle pump LH Dope/- P 3210043
Jammed - P 3210044

front Bonnet top lock side twisted - P 3080435

front Bonnet lock cable Jammed - During survey Bonnet
spring lever is Jammed
P-3210077

Radiator top bush & pin is necessary item. & Dope.
photo P-3080401
P-3080402

front Bonnet logo necessary/missing is paste on Bonnet P 3080356

headlight signal control unit Dope/cracked - P 3210069
- P 3210071 black bracket
cracked & missing

Power Steering oil necessary item.
When replaced power steering tank refer (1) P-3210073 black bracket
headlight panel bracket - Bad P-3210027 - P 3210028 - P 3210030
cracked
burner lamp Pin - P-3210034 - P 3210021



Sent:

Thursday, 14 June 2018 5:33 PM

Dear Winnie,

Refer to the message dated 13/06/2018 via Smart Claim.

Please be informed that the supplementary photos already uploaded in Smart Claim.




Power steering tank – cracked



Engine oil dipstick – cracked



Front bonnet top air vent – during survey already cracked and missing due to bonnet body buckled



Radiator top hose LH – torn





Front nozzle pump LH – damaged / jammed



Front bonnet top lock side – twisted



Front bonnet lock cable – jammed - during survey bonnet spring lever is jammed.




Radiator top brush & pin are necessary items and damaged






Front bonnet logo – necessary/missing is paste on bonnet





Headlamp signal control unit – damaged / cracked -block bracket cracked & missing





Headlamp panel bracket - bent



Bypass hose - torn

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



SUPPLEMENTARY LIST OF VEHICLE SLG 63P UPLOADED

Type

🔗 Question

Message

pls provide supplementary photos and advise which photo is the items. Tks

Reply



SUPPLEMENTARY LIST OF VEHICLE SLG 63P UPLOADED

Type

🔗 Question

Message

Dear Winnie, we have received supplementary of \$2,270.00 from repairer. Our surveyor had since checked and verified the supplementary parts and is of the view that the supplementary parts are consistent to the nature of the accident and is economical to repair. - Shiau Chan

Reply



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: S8M009YW

Date: 09th March 2018

Our Ref: CS/ASM18004473/Uqd3

The Motor Claims Department
AXA Insurance Singapore Pte L td

Attn: Winnie

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. SLG 63P


We thank you for the instruction on 08/03/2018.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 08/03/2018 (2.21pm) at the premises of M/s SME MOTOR and have the following to report:-

Workshop Estimate Amount	: S\$ <u>21,694.00</u>
Revised Estimate Amount	: S\$ <u>14,531.00</u>
"Check" Items Amount	: S\$ <u>4,967.00</u>
Total	: S\$ <u>19,498.00</u>
Market Value	: S\$ <u>103,000.00</u>
LTA Reimbursement Value	: S\$ <u>82,800.00</u>
Nett Value	: S\$ <u>20,200.00</u>

Description of Damage:

The vehicle sustained damages at the front portion.



Comments/ Present Status:

Damages consistent.

Repair cost economical.

Recommmed repair days: 6 days

We have authorised the repairs.

Yours faithfully

MARCUS CHUA
Licensed Appraiser

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1105J
Vehicle Details	
Vehicle No.:	SLG63P
Vehicle to be Exported:	No
Intended De-registration Date:	08 Mar 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	S350L
Primary Colour:	Black
Manufacturing Year:	2010
Engine No.:	27296531594841
Chassis No.:	WDD2211562A348130
Maximum Power Output:	200.0 kW (268 bhp)
Open Market Value:	\$102,322.00
Original Registration Date:	28 Feb 2011
First Registration Date:	28 Feb 2011
Transfer Count:	3
Actual ARF Paid:	\$102,322.00 <i>57161</i>
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Feb 2021
PARF Rebate Amount:	\$61,393.00
Intended COE Rebate Details	
COE Expiry Date:	27 Feb 2021
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$76,102.00
COE Rebate Amount:	\$21,407.00
Total Rebate Amount:	\$82,800.00

The information contained herein is correct as at 08 Mar 2018

OK

SGCARMART.COM

Login Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

FREE VALUATION

Let us tell you how much your car can sell for!

No obligations and it's FREE!

How much is my car worth?



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

3/2014 Jaguar Xj 2.0a Premium Luxury @ \$163800



Low Mileage Done, car In Show
Room Condition, Enjoy
Promotion Rate @ 1.99%
Bellamy Trading StarAd



Browse by Category

Sort by Date Posted 20 results/page

15 vehicles

Mercedes-Benz s350

Advanced Search Submit

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Mercedes-Benz s350	Any	Any	2011	Any	Any	Any	Available



**Mercedes-Benz CLS-Class
CLS350 Sunroof**

\$116,800

\$21,470 /yr

20-Oct-2011

3,498 cc

125,800 km

Luxury

Available

Price Reduced! Consignment Unit. Well Maintained By Current Owner, Beautiful Pearl White Unit With Black Interior, Tip Top Condition On Both Exterior And Interior, Attractive And Flexible Financing. H...

DreamCarz Pte Ltd

Posted: 08-Mar-2018 Tags: 2011 Mercedes-Benz CLS350, Mercedes-Benz CLS350, Mercedes-Benz, CLS350, Used Mercedes-Benz



**Mercedes-Benz CLS-Class
CLS350 Sunroof**

\$110,800

\$18,550 /yr

01-Nov-2011

3,498 cc

-

Luxury

Available

C&C Unit! 1 Owner, Maintained By Agent(C&C) With Records. Own This Powerful And The Most Reliable Luxury Family Sedan In The Market For Your Daily Drive! Immaculate Condition! Very Reliable And Fuel E...

TS Wheeler Capital Pte Ltd

Posted: 07-Mar-2018 Tags: 2011 Mercedes-Benz CLS350, Mercedes-Benz CLS350, Mercedes-Benz, CLS350, Used Mercedes-Benz



**Mercedes-Benz S-Class S350L
AMG**

\$112,800

\$20,530 /yr

09-Mar-2011

3,498 cc

115,012 km

Luxury

Available

C&C Unit And Maintained! Rare Brown On Beige Unit, Car In Meticulous Condition, Flagship Model From Mercedes Benz, Second To None. First Class Commuting Experience, Unparalleled Status And Comfort. Of...

TS Wheeler Capital Pte Ltd

Posted: 07-Mar-2018 Tags: 2011 Mercedes-Benz S350L, Mercedes-Benz S350L, Mercedes-Benz, S350L, Used Mercedes-Benz



**Mercedes-Benz CLS-Class
CLS350 Sunroof**

\$112,800

\$20,900 /yr

22-Sep-2011

3,498 cc

68,500 km

Luxury

Available

Excellent Car Maintained In Pristine Condition. Owner Has Full Service Records For The Car And Selling The Car With Nice Number Plate. Owner Just Changed New Brake Pads & Rotors. Ultimate Luxury Sedan...

AutoInc Eurosports

Posted: 07-Mar-2018 Tags: 2011 Mercedes-Benz CLS350, Mercedes-Benz CLS350, Mercedes-Benz, CLS350, Used Mercedes-Benz

Car Buying

Car Selling

Car Aftermarket

Car Ownership

On The Move

Lifestyle

► Buy Tyres Online!
► Latest Special Offers from Tyrepack!



**Mercedes-Benz S-Class S350L
AMG**

\$119,800

\$18,680 /yr

19-Dec-2011

3,498 cc

78,000 km

Luxury

Available

1 Owner Full AMG Body-Kit. C&C Maintained! Low Mileage! Beautiful Jet Black-On-Black Combination. Nice Bidded Number Plate '3232' One Of A Kind! Indulge In A Remarkably Quiet And Supple Ride Quality...

Posted: 06-Mar-2018 Tags: 2011 Mercedes-Benz S350L, Mercedes-Benz S350L, Mercedes-Benz, S350L, Used Mercedes-Benz



**Mercedes-Benz S-Class S350L
CGI**

\$108,800

\$18,110 /yr

24-Jun-2011

3,498 cc

121,000 km

Luxury

Available

Powerful Car W/ 301bhp, Well Maintained, Original Condition Interior & Exterior, Call Us Now! Test Drive Today.

Posted: 06-Mar-2018 Tags: 2011 Mercedes-Benz S350L, Mercedes-Benz S350L, Mercedes-Benz, S350L, Used Mercedes-Benz



**Mercedes-Benz S-Class S350L
AMG**

\$110,800

\$18,680 /yr

28-Jun-2011

3,498 cc

81,000 km

Luxury

Available

At Atlantis All Our Cars Have Fully Diagnosed, Repair N Replace Before Put On Sales And Come With 6 Mth Warranty. C&C Maintained! Low Mileage! Indulge In A Remarkably Quiet And Supple Ride Quality, AL...

Atlantic Automobile Pte Ltd

Posted: 06-Mar-2018 Tags: 2011 Mercedes-Benz S350L, Mercedes-Benz S350L, Mercedes-Benz, S350L, Used Mercedes-Benz

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GiA Records Management Centre established by the General Insurance Association of Singapore (GiA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/03/2018 16:14
Date Of Accident	05/03/2018 09:00
Exact Location Of Accident	TPE EXIT 7
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLG63P
Insured/Policyholder	
Name Of Registered Owner	LAU YONG KWEE
NRIC No	S1591105J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-94749498
Alternative Phone No	OFFICE-94749498

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	S350L-3.5 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA194691
Cover Note Number	

Driver

Name of Driver	LAU YONG KWEE
NRIC No	S1591105J
Date Of Birth	05/11/1963
Occupation	INDOOR
Date Of Driving Pass	23/02/1981
Driving Experience	37 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94749498
Fax Number	
Contact Number	OFFICE-94749498
E Mail Address	NOEMAIL

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



redefining insurance

Date: 06/03/2018

To: Owner of Vehicle Number: SLG63P

The following has been advised to you via your workshop, SME MOTORPTE LTD through their staff, _____

Please tick the applicable box if you had been advice on the content as seen below:

☒ You had been advised by the workshop that in the case that you wish to claim against your own policy, there is a Fourteen (14) days clause whereby the claim must be made within the stipulated timeframe from the day of occurrence.

☐ You had been advised by the workshop on the liability and merits of the case accordingly.

☒ You had been advised by the workshop on the claims procedure for the type of claim that you will be making due to this accident.

☐ There will be delay to your vehicle repair due to the unavailability of spare parts locally and there is no other option except to indent it from overseas.

☒ There will be no cancellation/withdrawal of the Own Damage claim once the order of the spare parts have been placed. If you wish to cancel/withdraw the claim, you shall bear all costs, expenses &/or related charges incurred directly &/or indirectly to the procurement of the spare parts.

☐ The estimated waiting time for the spare parts to arrive is _____. The estimated arrival time does not include the repair period.

☐ You will be driving the vehicle out despite being advised by the workshop mechanic/personnel that the vehicle may not be road worthy.

☒ For vehicles below Three (3) years old, your Insurance Company will use only genuine original parts to repair your vehicle.

For vehicles above Three (3) years old, your Insurance Company will be carrying out repairs using any combination of genuine original parts and/or original equipment manufacturer (OEM) parts.

☒ You had been advised by the workshop of the Twelve (12) months warranty for Own Damage repairs on workmanship related to the accident.

☐ For vehicles that are under warranty with a local distributor, you have been advised by the workshop to check with your local distributor on any effect to your warranty prior to making this Own Damage claim.

☐ Others _____

Signed and acknowledge by:

X

Name and signature of policyholder/authorised driver

Name and signature of workshop personnel including company stamp

VEHICLE NO.: SLG63P
 MAKE: MERCEDES
 MODEL: S350L
 YEAR OF MAKE: 2010
 CHASSIS NO.: WDD2211562A348130
 SUPPLIERS : SURPASS

Not Authorized
26/11
To be ph. before
painting
8/3/18
6 day
excess \$900

S/N	Parts Description	QTY	Amount
	PARTS		
1	FRT BONNET <i>Buc</i>	1	\$1,800.00
2	FRT BONNET HINGE <i>Buff/Pan</i>	2	\$300.00
3	FRT BONNET LOCK -CENTER (TOP) <i>TW</i>	1	\$165.00
4	FRT BONNET INSULATOR <i>D.S</i>	1	\$270.00
5	FRT BONNET INSULATOR CLIP <i>all</i>	8	\$28.00
6	FRT BONNET STOPPER <i>290/1</i>	2	\$40.00
7	FRT BONNET LOCK -BOTTOM <i>twi</i>	2	\$130.00
8	FRT GRILLE ASSY <i>320</i>	1	\$530.00
9	FRT BUMPER <i>D.S</i>	1	\$1,050.00
10	FRT BUMPER SIDE RETAINER <i>320</i>	2	\$130.00
11	FRT BUMPER CLIP <i>all</i>	10	\$30.00
12	FRT NUMBER PLATE GARNISH <i>all</i>	1	\$70.00
13	FRT BUMPER REINFORCEMENT <i>Top</i>	1	\$850.00
14	FRT BUMPER INNER SPONGE -CENTER <i>Buff/Pan</i>	1	\$50.00
15	FRT BUMPER INNER SPONGE -SIDE <i>1A</i>	2	\$90.00
16	FRT BUMPER CHROME MOULDING -CENTER <i>all</i>	1	\$80.00
17	FRT BUMPER CHROME MOULDING -SIDE <i>all</i>	2	\$150.00
18	FRT BUMPER INNER GARNISH <i>Top</i>	1	\$55.00
19	FRT BUMPER LOWER GRILLE <i>320</i>	1	\$125.00
20	FRT NOZZLE <i>all</i>	2	\$290.00
21	HEADLAMP <i>320</i>	2	\$4,100.00
22	HEADLAMP PANEL <i>Buc</i>	2	\$150.00
23	HEADLAMP SUPPORT PANEL (LOWER) <i>1A</i>	1	\$65.00
24	HEADLAMP SUPPORT TOP RUBBER <i>twi</i>	1	\$48.00
25	CENTER TOP PANEL <i>Buc</i>	1	\$230.00
26	AIRCON CONDENSER <i>Buff/Pan</i>	1	\$1,050.00
27	RADIATOR <i>Buff/Pan</i>	1	\$850.00
28	AIR BUFFER TOP <i>all</i>	1	\$150.00
29	AIR HOSE <i>Top</i>	2	\$150.00
30	RADIATOR FAN MOTOR ASSY <i>one/320</i>	1	\$850.00
31	RADIATOR TOP HOSE <i>1A</i>	1	\$70.00
32	RADIATOR SPARE TANK <i>one</i>	1	\$130.00
33	WASHER TANK <i>1A</i>	1	\$95.00
34	ABS PUMP <i>1A</i>	1	\$2,500.00
35	ENGINE TOP COVER <i>1A</i>	1	\$150.00
36	ENGINE UNDER COVER <i>1A</i>	1	\$350.00
37	ENGINE UNDER COVER CLIP <i>1A</i>	12	\$36.00
38	FRT FENDER RH <i>1A</i>	1	\$820.00
39	FRT FENDER CHROME RH <i>all</i>	1	\$25.00
40	FRT FENDER INNER COWLING CLIP <i>1A</i>	10	\$30.00
41	FRT FENDER INNER TOP GARNISH <i>1A</i>	2	\$52.00
42	FAN BELT <i>1A</i>	1	\$85.00
43	FRT PARKING SENSOR <i>shut</i>	6	\$1,080.00
44			
45			
TOTAL PARTS			\$19,304.00

145 12C
310
360 2pos.
14251

S/N		
1 FRT NUMBER PLATE	110	\$35.00
2 RADIATOR COOLANT	25	\$25.00
TOTAL S/N		\$60.00
LABOUR :		
1 WIRE CHECKING		\$20.00
2 REMOVE & REFIX AIRCON AND GAS		\$100.00
3 REMOVE & REFIX ABS PUMP	11	\$180.00
4 RESET ABS SYSTEM	11	\$180.00
5 LABOUR CHARGE		\$900.00
6 SPRAY PAINTING		\$950.00
TOTAL LABOUR		\$2,330.00
TOTAL		\$21,694.00
GST 7%		\$1,518.58
		\$23,212.58

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-16321

S.N- 60

1620
18001

VEHICLE NO.: SLG63P
 MAKE: MERCEDES
 MODEL: S350L
 YEAR OF MAKE: 2010
 CHASSIS NO.: SUPPLEMENTARY
 SUPPLIERS : SURPASS

S/N	Parts Description	QTY	Unit price	Amount
PARTS				
1	POWER STEERING TANK <i>one</i>	1	\$95.00	\$95.00
2	ENGINE OIL DIPSTICK <i>one</i>	1	\$75.00	\$75.00
3	FRT BONNET TOP AIR VENT <i>one / mes</i>	2	\$225.00	\$450.00
4	RADIATOR TOP HOSE LH <i>Top</i>	1	\$75.00	\$75.00
5	FRT NOZZLE PUMP LH <i>Page / 4M</i>	1	\$65.00	\$65.00
6	FRT BONNET TOP LOCK SIDE <i>one</i>	2	\$60.00	\$120.00
7	FRT BONNET LOCK CABLE <i>1M</i>	1	\$75.00	\$75.00
8	RADIATOR TOP BUSH <i>one</i>	2	\$18.50	\$37.00
9	RADIATOR TOP PIN <i>one</i>	2	\$7.50	\$15.00
10	FRT BONNET LOGO <i>one</i>	1	\$68.00	\$68.00
11	HEADLAMP SIGNAL CONTROL UNIT <i>one / one</i>	2	\$380.00	\$760.00
12	POWER STEERING OIL <i>one</i>	2	\$35.00	\$70.00
13	HEADLAMP PANEL BRACKET <i>one</i>	2	\$55.00	\$110.00
14	RADIATOR SPARE TANK BYPASS HOSE <i>one</i>	1	\$55.00	\$55.00
TOTAL PARTS				\$2,070.00
LABOUR :				
1	REPROGRAMME PARKING SENSOR			\$200.00
TOTAL LABOUR				\$200.00
TOTAL			\$2,270.00	
GST 7%			\$158.90	
			\$2,428.90	

parts 16,321

SURPASS AUTO PARTS SUPPLIES PTE LTD

29/03/2018 17:57:31

10 KAKI BUKIT ROAD 1 #01-33 KB INDUSTRIAL BUILDING SINGAPORE 416175

Tel: 67476016 Fax: 67449644 Email: surpasslim@gmail.com

Co & Gst Reg No: 199904808E

SME MOTOR PTE LTD

1 KAKI BUKIT AVE 6

#02-15 /16 /17 /18 AUTOBAY

SINGAPORE 417883

TAX INVOICE

Inv No. : 18030113

Date : 12/03/2018

Page : 1 of 4

S/N	Item No.	Description	Qty	U/ Price	Amount
1		slg63 02/16			
2	A2218800157	BONNET	1	1,800.00	1,800.00 ✓
3	A2218800328	HINGE	1	150.00	150.00 ✓
4	A2218800428	HINGE	1	150.00	150.00 ✓
5	A2218800464	SAFETY HOOK	1	165.00	165.00 ✓
6	A2216820026	BONNET SPONGE	1	270.00	270.00 ✓
7	A2218800327	SPRING	2	20.00	40.00 ✓
8	A22188004839040	GRILLE	1	530.00	530.00 ✓
9	A22188507819051	LICENSE PLATE MOULDING 2218805940	1	70.00	70.00 ✓
10	A2216203186	SUPPORT,FRONT BUMPER,METL	1	850.00	850.00 ✓
11	A2218850021	FRT BUMPER MOULDING CTE	1	80.00	80.00 ✓
12	A2218850121	FRT BUMPER MOULDING LH	1	75.00	75.00 ✓
13	A2218850221	FRT BUMPER MOULDING RH	1	75.00	75.00 ✓
14	A2218201159B	1307023058 HEADLAMP UNIT	1	2,050.00	2,050.00 ✓

SURPASS AUTO PARTS SUPPLIES PTE LTD

29/03/2018 17:57:31

10 KAKI BUKIT ROAD 1 #01-33 KB INDUSTRIAL BUILDING SINGAPORE 416175

Tel: 67476016 Fax: 67449644 Email: surpasslim@gmail.com

Co & Gst Reg No: 199904808E

SME MOTOR PTE LTD

1 KAKI BUKIT AVE 6

#02-15 /16 /17 /18 AUTOBAY

SINGAPORE 417883

TAX INVOICE

Inv No. : 18030113

Date : 12/03/2018

Page : 2 of 4

S/N	Item No.	Description	Qty	U/ Price	Amount
15	A2218201259B	1307023059 HEADLAMP UNIT	1	2,050.00	2,050.00 ✓
16	A2216200172	TOP STIFFENING >>>>>	1	230.00	230.00 ✓
17	A2215000754	CONDENSER 2215001354	1	1,050.00	1,050.00 ✓
18	A2215003103VL	735298 RADIATOR	1	850.00	850.00 ✓
19	A2215000816	TOP AIR BUFF >>>>>	1	150.00	150.00 ✓
20	A2215001193HL	8EW376791-681 A2219066500 FAN	1	850.00	850.00 ✓
21	A22188059409999	TRIM BUMPER	1	1,050.00	1,050.00 ✓
22	A2218800060	LOWER LOCK SIDE	2	65.00	130.00 ✓
23	A2218855637	CTE FRT IMPACT ABSORBER	1	50.00	50.00 ✓
24	A2218850136	BUMPER IN P	1	55.00	55.00 ✓
25	A2218852322	LOWER GRILLE CTE 2218805940	1	125.00	125.00 ✓
26	A2218601347	DOUBLE NOZZLE	1	145.00	145.00 ✓
27	A2216200191	HEADLAMP FRAME TOP	1	155.00	155.00 ✓
28	A2216200291	HEADLAMP FRAME TOP	1	155.00	155.00 ✓

SURPASS AUTO PARTS SUPPLIES PTE LTD

29/03/2018 17:57:31

10 KAKI BUKIT ROAD 1 #01-33 KB INDUSTRIAL BUILDING SINGAPORE 416175

Tel: 67476016 Fax: 67449644 Email: surpasslim@gmail.com

Co & Gst Reg No: 199904808E

SME MOTOR PTE LTD

1 KAKI BUKIT AVE 6

#02-15 /16 /17 /18 AUTOBAY

SINGAPORE 417883

TAX INVOICE

Inv No. : 18030113

Date : 12/03/2018

Page : 3 of 4

S/N	Item No.	Description	Qty	U/ Price	Amount
29	A2215000649	TANK 2215013584 /0725	1	130.00	130.00 ✓
30	A2214660302	OIL TANK	1	95.00	95.00 ✓
31	A2720101172	OIL DIPSTICK	1	75.00	75.00 ✓
32	A2720903382	2720900982 AIR HOSE	1	75.00	75.00 ✓
33	A2720903482	2720900882 SCOOP RH	1	75.00	75.00 ✓
34	A22188002059999	SCREEN	1	225.00	225.00 ✓
35	A22188003059999	SCREEN	1	225.00	225.00 ✓
36	A2215013584	HOSE TOP	1	75.00	75.00 ✓
37	A2218800260	LOCK	2	60.00	120.00 ✓
38	A0009912595	PIN RADIATOR S221	2	7.50	15.00 ✓
39	A1695040114	BEARING	2	18.50	37.00 ✓
40	A2218800086	2228101200 MERCEDES STAR	1	68.00	68.00 ✓
41	A2108691121 MY	PUMP	1	65.00 ✓	65.00 ✓
42	A2218800159	CABLE BONNET 1	1	75.00	75.00 ✓

SURPASS AUTO PARTS SUPPLIES PTE LTD

29/03/2018 17:57:31

10 KAKI BUKIT ROAD 1 #01-33 KB INDUSTRIAL BUILDING SINGAPORE 416175

Tel: 67476016 Fax: 67449644 Email: surpasslim@gmail.com

Co & Gst Reg No: 199904808E

SME MOTOR PTE LTD

1 KAKI BUKIT AVE 6

#02-15 /16 /17 /18 AUTOBAY

SINGAPORE 417883

TAX INVOICE

Inv No. : 18030113

Date : 12/03/2018

Page : 4 of 4

S/N	Item No.	Description	Qty	U/ Price	Amount
43	A2219008001	CONTROL UNIT	2	380.00	760.00 ✓
44	A0019892403FB	21647 ST OIL	2	35.00	70.00 ✓
45	A2215011725	TANK HOSE	1	55.00	55.00 ✓
46	A2216200183	BRACKET HEADLAMP	1	55.00	55.00 ✓
47	A2216200283	BRACKET HEADLAMP	1	55.00	55.00 ✓
48	A0019880325FB	34572 BONNET S/P CLIP	8	3.50	28.00 ✓
49	A1249900492	39067 RIVET	10	3.00	30.00 ✓
50	A2216280598	SEAL	1	48.00	48.00 ✓
51	A2216904080	FRT FENDER M/D	1	25.00	25.00 ✓
52	A21254200189999	SENDER U	2	180.00	360.00 ✓

Sub Total 16,191.00 ✓

GST 7% 1,133.37

Total 17,324.37

Customer's Signature

P-16321

SURPASS AUTO PARTS SUPPLIES PTE LTD

07/05/2018 10:34:11

10 KAKI BUKIT ROAD 1 #01-33 KB INDUSTRIAL BUILDING SINGAPORE 416175

Tel: 67476016 Fax: 67449644 Email: surpasslim@gmail.com

Co & Gst Reg No: 199904808E

SME MOTOR PTE LTD

1 KAKI BUKIT AVE 6

#02-15 /16 /17 /18 AUTOBAY

SINGAPORE 417883

TAX INVOICE

Inv No. : 18050039

Date : 12/03/2018

Page : 1 of 1

S/N	Item No.	Description	Qty	U/ Price	Amount
1	A2218850714	BRACKET FRT BUMPER TOP SIDE	1	65.00	65.00
2	A2218850814	BRACKET sig96p	1	65.00	65.00

Sub Total	130.00
GST 7%	9.10
Total	139.10

Customer's Signature

SERVICE REQUESTS MESSAGES CLAIMS

<< Service Request Details

Claim	S8M009YW	Vehicle Information	
Reference		Incident Vehicle	SLG63P
None 	Loss Date	Registration #	MERCEDES 1
March 5, 2018	Request Date	Make	S350L
March 8, 2018	Due Date	Kaki Bukit Ave 6 #02-15, , 417883	
June 8, 2018	Vendor Name	Primary Contact/Insured	
LKK AUTO CONSULTANTS PTE LTD (OD)	Type of Loss	LAU YONG KWEE BLK 351 YISHUN AVENUE 11, #08-199, 760351, Singapore	
Own Damage	Services	eilim@huihua.sg	

Actions

Next Step

PAST DUE: Report that your block modify the Expected Completion Date.

Complete Work More

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
SLG63P IA.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (OD)	March 9, 2018
SLG63P ESTIMATE.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (OD)	March 9, 2018
SLG63P ESTIMATE.pdf	Reports & Statement	GIA Report	SME MOTOR PTE LTD	March 8, 2018
SLG63P.pdf	Reports & Statement	GIA Report	SME MOTOR PTE LTD	March 8, 2018
SLR4098E - TP GIA REPORT.PDF	Reports & Statement	GIA Report	HO Winnie	March 8, 2018

SERVICE REQUESTS

MESSAGES

CLAIMS

Service Request Details

Claim	S8M009YW	Reference	Vehicle Information
None 	Loss Date		Incident Vehicle SLG63P
March 5, 2018	Request Date		Registration # Make Service Address
March 8, 2018	Due Date		Model S350L
June 8, 2018	Vendor Name		Kaki Bukit Ave 6 #02-15, , , 417883
LKK AUTO CONSULTANTS PTE LOSS LTD (OD)	Type of		Primary Contact/Insured
Own Damage	Services		LAU YONG KWEE BLK 351 YISHUN AVENUE 11, #08-199, 760351, Singapore elim@huihua.sg



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#
SLG63P

Purchase Date
mm/dd/yyyy

Registration State
SINGAPORE

Registration Date *
02/28/2011

Mileage
0

Age of Vehicle
7

Driver Details

CATEGORY
Manufacturing Year

POLICY INFORMAT... 2010

CATEGORY
Driver Name

ASSESSMENT INFO... 2010

FNOL INFORMATI...

POST SURVEY INF...

ASSESSMENT INFO... WDD2211562A348130

FNOL INFORMATI...
POST SURVEY INF...

CATEGORY Engine No
POLICY INFORMAT... 27296531594841
ASSESSMENT INFO... 27296531594841

CATEGORY License Type
FNOL INFORMATI...
POST SURVEY INF...

CATEGORY Engine Capacity
POLICY INFORMAT...
ASSESSMENT INFO... 3498 cc

CATEGORY License Issue Date
FNOL INFORMATI...
POST SURVEY INF... mm/dd/yyyy

CATEGORY Sum Insured
POLICY INFORMAT... 0
ASSESSMENT INFO... 0

CATEGORY License Expiration Date
FNOL INFORMATI...
POST SURVEY INF... mm/dd/yyyy

CATEGORY Market Value
POLICY INFORMAT... 0
ASSESSMENT INFO... 103000

CATEGORY Address
FNOL INFORMATI...
POST SURVEY INF...

Address type

CATEGORY

FNOL INFORMATI

-  SERVICE REQUESTS
- MESSAGES
- CLAIMS

<<

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Front left side

MICHELIN 6mm

Front right side

MICHELIN 6mm

Rear left side

MICHELIN 6mm

Rear right side

MICHELIN 6mm

SERVICE REQUESTSMESSAGESCLAIMS

Assessment Details

General & Workshop Details			Vehicle & Driver Details		Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary	Parts					
Add Agree Disagree		EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPRJ 811%	DISC OUNT%	SALV AGE%	PART PRICE(NET)
			1	1			FRT BONNET			Buckled	1800		0		1800
			2	2			FRT BONNET HINGE			Bent	150		0		300
			3	1			FRT BONNET LOCK CENTER (TOP)			Twisted	165		0		165
			4	1			FRT BONNET INSULATOR			Damaged	270		0		270
			5	8			FRT BONNET INSULATOR CLIP			Necessary	3.5		0		28
			6	2			FRT BONNET STOPPER			Necessary	20		0		40
			7	2			FRT BONNET LOCK -BOTTOM			Twisted	65		0		130
			8	1			FRT GRILLE ASSY			Broken	530		0		530
			9	1			FRT BUMPER			Damaged	1050		0		1050
			10	2			FRT BUMPER SIDE RETAINER			Bent	65		0		130

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTRY%	DISC OUNT%	SALV AGE%	PART PRICE(NET)
☐	 24	1			HEADLAMP SUPPORT TOP RUBBER			Twisted	48		0		48
☐	 25	1			CENTER TOP PANEL			Buckled	230		0		230
☐	 26	1			AIRCON CONDENSER			Bent	1050		0		1050
☐	 27	1			RADIATOR			Bent	850		0		850
☐	 28	1			AIR BUFFER TOP			Cracked	150		0		150
☐	 29	2			AIR HOSE			Damaged	75		0		150
☐	 30	1			RADIATOR FAN MOTOR ASSY			Cracked	850		0		850
☐	 31	1			RADIATOR TOP HOSE			Serviceable	0		0		0
☐	 32	1			RADIATOR SPARE TANK			Cracked	130		0		130
☐	 33	1			WASHER TANK			Serviceable	0		0		0
☐	 34	1			ABS PUMP			Serviceable	0		0		0
☐	 35	1			ENGINE TOP COVER			Serviceable	0		0		0
☐	 36	1			ENGINE UNDER COVER			Serviceable	0		0		0
☐	 37	12			ENGINE UNDER COVER CLIP			Serviceable	0		0		0
☐	 38	1			FRT FENDER RH			Repair	0		0		0

SERVICE REQUESTS MESSAGES CLAIMS

<< Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
☐		1	FRT NUMBER PLATE	Reviewing	35	BROKEN	
☐		2	RADIATOR COOLANT	Reviewing	25	NECESSARY	
☐		3	FRT BONNET TOP AIR VENT	Reviewing	450	SUPPLEMENTARY ADDED 04/07/2018 (CRACKED / MISSING)	
☐		4	RADIATOR TOP HOSE LH	Reviewing	75	SUPPLEMENTARY ADDED 04/07/2018 (TORN)	

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
☐	 11	HEADLAMP SIGNAL CONTROL UNIT	Reviewing	760	SUPPLEMENTARY ADDED 04/07/2018 (DAMAGED / CRACKED)	
☐	 12	POWER STEERING OIL	Reviewing	70	SUPPLEMENTARY ADDED 04/07/2018 (NECESSARY)	
☐	 13	HEADLAMP PANEL BRACKET	Reviewing	110	SUPPLEMENTARY ADDED 04/07/2018 (BENT)	
☐	 14	RADIATOR SPARE TANK BYPASS HOSE	Reviewing	55	SUPPLEMENTARY ADDED 04/07/2018 (TORN)	
☐	 15	DAYS OF REPAIR	Reviewing	6		
☐	 16	POWER STEERING TANK	Reviewing	95	SUPPLEMENTARY ADDED 04/07/2018 (CRACKED)	
☐	 17	ENGINE OIL DIPSTICK	Reviewing	75	SUPPLEMENTARY ADDED 04/07/2018 (CRACKED)	

SERVICE REQUESTS MESSAGES CLAIMS

<< **Assessment Details**

General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous
Summary	Claim Amount	\$17,101.00	Claim Amount	\$17,101.00	

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$2,330.00	\$1,620.00
Miscellaneous	\$60.00	\$2,130.00
Excess	-\$900.00	-\$900.00