

ASS. REC. BY:

REF: CS/FCI18004508/Gcd3² Special Instruction:

Surveyor:

Sebastian

ASSIGNMENT (Office)

From (Person):

Serene Ter

of

FCI

Date/Time: 8/3/18 @ 2:43pm

Estimated Cost:

Bill to:

OD: TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

FBG 1944J

Insured:

SHC 8739P

at Workshop m/s

Mitra Auto

Tel:

9234 1367

of

873/875 Upper Bkt Timah Rd

Policy No:

Claim No:

D18001476 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

16/02/2018

CA / REV / REP. / REV 24 HRS

lwp,

9/3/18

H.O.D. Endorsement:

Date/Time:

3:14pm @ 8/3/18

Person Contacted:

Ms. Chong

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

FBG 1944J - NS/INC18003671/K/vbn2

D.O.A. 16/2/18

SHC 8739P - NS/INC18003671/K/vbn2

D.O.A. 16/2/18

2/13

Claimant change workshop to Mitra Auto.

Signature: Xhl REF: FCI PRS

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s _____
ol _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)
Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
IDAC Accident Report: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 4 days Res.: Yes or No
Lum Sum: 20 % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____
Vehicle: IN / OUT

Veh No: FBG 1944J Yr Regn: 26/4/2012
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Honda GLH125 C.C. 125
Colour: Black A/C: Insured / Std / NI / NA
Sp. Reading: 13163 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: LALJA 1148C 3615733
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modl: NI / S/Rim / STD A/Rim or
Tyre Size: F: 2.75-18 max 2eler
R: 80/90-18 IRC
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front 6 mm Rear 6 mm
R/Bal. 6 mm L/Bal. 6 mm
D.O.A. 16/2/18 D.O.I. 29/3/18
Survey held at Lee Hing 5:30pm
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
The U/C / Chassis frame / Body Structure affected due to collision

Date / Time | Action / Instruction
9/3/18 | No GIA / Estimator
limited \$1750 with 1dris (red. 1258, 4120)

RECEIVED 20 FEB 2019

Date/Time, File Pass to? ☐ : Preli. Report
☐ : Final Report

Days Of Repair: 4
Resurvey No. of Trip: 2

1) _____
Date/Time, File Return to? _____
2) _____

Report Format: TP
Lump Sum / I.B.I. (\$) 1750

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Insp (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee: _____
Transportation: _____
S + RS, SI _____
Phone _____
Others _____

TOTAL

130
50
50 + 50
102
382

MOTOR SURVEY ASSIGNMENT

Date	20-02-2018	Our Ref No. D18001476MFSH
Accident Date	16-02-2018	Claim Type. Third Party
Insured Vehicle	SHC8739P	Third Party Vehicle. FBG1944J
Survey Location	2 KAKI BUKIT AUTO HUB #02-07	
Contact Person.	MR IDRIS	
Contact No.	92341367/ 92341367	Fax No. 0
Survey Type	WITHOUT PREJUDICE: NO EST. *	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	MITRA AUTO TRADING	Attention. NIL
Cc : TP Solicitor	A C SYED & PARTNERS	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

MOTOR SURVEY ASSIGNMENT

Date	20-02-2018	Our Ref No. D18001476MFSH
Accident Date	16-02-2018	Claim Type. Third Party
Insured Vehicle	SHC8739P	Third Party Vehicle. FBG1944J
Survey Location	873/875 UPPER BUKIT TIMAH ROAD	
Contact Person.	JEFFREY	
Contact No.	67691717/ 0	Fax No. 0
Survey Type	WITHOUT PREJUDICE: NO EST. *	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	LEE HUAT COMPANY	Attention. NIL
Cc : TP Solicitor	A C SYED & PARTNERS	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/235152)



PRI Documents



Close



PRI Header Details

Claim No	D18001476MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & AC SYED
Workshop Name	MITRA AUTO TRADING (Contact Person : MR IDRIS)	Survey Location & Contact Details	2 KAKI BUKIT AUTO HUB #02-07 Mobile: 92341367 , Phone: 92341367 , Fax: 0 EmailId: ACSYED@SINGNET.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: NO EST. *		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHC8739P	TP Vehicle No	FBG1944J
PRI Recieved Date	27-03-2018 04:33:37 PM	Surveyor Appointed Date	27-03-2018 02:23:23 PM	Surveyor Accept Date	08-03-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	27-03-2018	Upload Survey Report *:	Choose File
------------------------------------	--	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents

File Name

Action

Surveyor Job Remarks

Remarks

Job Sheet (/ClaimWS/Surveyor/JobSheet/235152)



PRI Documents



Close



PRI Header Details

Claim No	D18001476MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & AC SYED COMPANY [OV OTHMAN]
Workshop Name	LEE HUAT COMPANY (Contact Person : JEFFREY)	Survey Location & Contact Details	873/875 UPPER BUKIT TIMAH ROAD Mobile: 0 , Phone: 67691717 , Fax: 0 EmailId: ACSYED@SINGNET.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: NO EST. *		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHC8739P	TP Vehicle No	FBG1944J
PRI Recieved Date	06-03-2018 08:57:41 PM	Surveyor Appointed Date	08-03-2018 02:41:59 PM	Surveyor Accept Date	08-03-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	08-03-2018	Upload Survey Report *:	Choose File
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Remarks		Save
---------	----------------------	-------------------------------------

Nivitha (LKK Auto)

From: Teo Swee Keong <TeoSweeKeong@msfirstcapital.com.sg>
Sent: Tuesday, 27 March 2018 12:38 PM
To: 'assignments@lkkauto.com'
Cc: Serene Ler
Subject: OUR REF: D18/1476 - CHANGE OF WS
Attachments: 27032018120422-0001.pdf

Dear Sirs

Please assist & refer as per attached.

Thanks and Regards,

SK Teo
Motor Claims Dept

MS First Capital Insurance Ltd | 36 Robinson Road #16-01 City House Singapore 068877 | DID : 6507 3848 | Fax No. : 6507 3849 |

Personal Data Protection Act 2012 ("PDPA"):
Under the PDPA, there are various requirements that regulate the processing of your personal data.
Please refer to www.msfirstcapital.com.sg for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.
If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.
If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

-----Original Message-----

From: Nandu Kumar
Sent: Tuesday, March 27, 2018 12:09 PM
To: Teo Swee Keong <TeoSweeKeong@msfirstcapital.com.sg>
Subject: FW: Fax data from cwsmotorclaims@msfirstcapital.com.sg

FYA

-----Original Message-----

From: CWS Motor Claims
Sent: Tuesday, 27 March, 2018 12:04 PM
To: CLFax <CLFax@msfirstcapital.com.sg>
Subject: Fax data from cwsmotorclaims@msfirstcapital.com.sg

A C SYED & PARTNERS

Advocates & Solicitors
Commissioner for Oaths
101A Upper Cross Street
#13-23 People's Park Centre
Singapore 058358

Tel : 6538 7411 Fax : 6534 1011 (Not for service of Court Documents)

Your Ref : D18001476MFSH (Your insured vehicle no. SHC 8739P)
Our Ref : ACS.10959.18.INJ.GN.ts
Date : 27 March 2018

M/s. First Capital Insurance Ltd
36 Robinson Road
#16-01 City House
Singapore 068877

URGENT

BY FAX 6507 3849 & POST

Dear Sir

PRE-REPAIR INSPECTION

ACCIDENT INVOLVING FBG 1944J & SHC 8739P ON 16.2.18 ALONG WOODLANDS DRIVE 50

We are instructed by our client **ABDUL KAHAR BIN OTHMAN** to notify you of a road traffic accident on **16.2.2018** at about **1430 hours** along **Woodlands Drive 50** involving our client's motorcycle registration no. **FBG 1944J** and vehicle registration no. **SHC 8739P** driven by your insured at the material time. A copy of our client's GIA/police report is enclosed.

As a result of the accident our client motorcycle has been damaged. Before our client proceed to repair to the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would you like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference you.

In this regard, our clients' motor vehicle is available for pre-repair inspection at the following workshop:-

M/s. Mitra Auto Trading
2 Kaki Bukit Auto HUB
#02-07 Singapore 417921
HP: 9234 1367
Person In-Charge : Mr Idris

Yours faithfully



Encl.

cc. Comfort Transportation Pte Ltd
383 Sin Ming Drive
GAS Building, Singapore 575717

BY CERTIFICATE OF POSTING

cc. client



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18001476MFSH

Date: 13 April 2018

Our Ref: CS/FCI18004508/Grd3

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. FBG 1944J.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 09/03/2018 at the premises of M/s Mitra Auto Trading and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 3,008.00 .</u>
Revised Estimate Amount	: <u>S\$ 2,200.20 .</u>
"Check" Items Amount	: <u>S\$ - .</u>
Market Value	: <u>S\$ - .</u>
LTA Reimbursement Value	: <u>S\$ - .</u>
Nett Value	: <u>S\$ - .</u>

Description of Damage:
The vehicle sustained damages
at the front, o/s, n/s portion.



Repair days: 4 Days

Comments/ Present Status:
Damages Consistent.

Yours faithfully,
Xing Guo Qiang
Automotive Assessor

idris's

Tel / Fax : 6747 5658 Hp : 92341367

Name	ABDUL KAHAR BIN Othman	Vehicle Reg No	FBG 19445
Address	Panekider Zuhairi	Mode	Honda CG 125cc
IC	Bin A. KAHAR	Mileage	
Tel	90605001	Date	10/4/18

ITEMS	DESCRIPTION OF REPAIRS	AMOUNT	
106	Front Fender	78	00
12et	Front Right & Left Signal/SS&R	70	00
12et	Side mirror (Left Right)	58	00
1net	Front Head light cover 249	120	00
1ms	Handle Bar	110	00
1ms	Triple clamp Assy (under bracket) BT	178	00
	Fork core & Bearing	78	00
12et	Front Fork Assy (left right) 860	550	00
per	Front Wheel (whole alloy) 330	280	00
1m	gear pedal	38	00
	left Foot rest	48	00
1ps	Front Brake Disk	185	00
1m	Right starter switch	125	00
1ms	Rear Box carrier	140	00
	spray paint & touch up	350	00
Labor	Dismantled & replacement repaired damage parts, Body alignment welding check, Brake, Engine services	600	00
			20%
		Total L/S : \$	
	Lump sum repair.		
	After repair photos.		
	Guo Qiang - 82880282		
	(UKK) 67418434		
	11/4/18		
	4 days.		
	cc/7	Total: S\$	3,008 00

~~Cut~~
~~Cut~~
~~Cut~~
~~CRA~~
~~BT~~
~~NBC~~
~~BT~~
~~Report X~~
~~BT~~
~~BT~~
~~BT~~
~~BR~~
~~Cut~~
 300
 300
 2199.3
 1750
 1777
 10% = 159

Wang Sun Report

After repair photos.

Guo Qiang - 82880282
(UKK) 6741 8434

11/4/18

4 days.

25/3

Total: S\$	3.008	00
------------	-------	----

Lk Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary work done after resurveyed area is subject to final approval from Insurance Company

Signature: _____

Date:

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18004508/Gcd3s2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 21-02-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 8739P	Veh. Inspected	FBG 1944J
Policy No.	D-18088936MFSH	Coverage (\$)	0.00
Claim No.	D18001476MFSH	Excess (\$)	0.00
Assign From	SERENE LER	Assign Date	08/03/2018
2. Vehicle Particulars & Condition			
Make & Model	HONDA GLH125	c.c	125
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	LALJA11U8C3015733	Colour	BLACK
Odometer	73163	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	2.75-18	METZELER	6 mm
L/H Front Tyre			mm
R/H Rear Tyre	80/90-18	RC	6 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION, O/S AND N/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	16/02/2018	Inspection Date	29/03/2018
Survey held at	873/875 UPPER BKT TIMAH RD		
Repairer	MITRA AUTO TRADING		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBG 1944J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT FENDER	CUT	78.00	78.00
1	SET FRONT RIGHT & LEFT SIGNAL	CUT	70.00	70.00
1	SET SIDE MIRROR (LEFT & RIGHT)	CUT	58.00	58.00
1	SET FRONT HEAD LIGHT COVER	CRACKED	120.00	120.00
1	HANDLE BAR	BENT	110.00	110.00
1	TRIPLE CLAMP ASSY (UNDER BRACKET)	BENT	178.00	178.00
1	FORK CONE & BEARING	NECESSARY	78.00	78.00
1	SET FRONT FORK ASSY (LEFT & RIGHT)	BENT	550.00	550.00
1	FRONT RIM (WHEEL ALLOY)	TO REPAIR SEE LABOUR	280.00	-
1	GEAR PEDAL	BENT	38.00	38.00
1	LEFT FOOT REST	BENT	48.00	48.00
1	FRONT BRAKE DISK	BENT	185.00	185.00
1	RIGHT STARTER SWITCH	BROKEN	125.00	125.00
1	REAR BOX CARRIER	CUT	140.00	140.00
	LESS 10% DISCOUNT		-	-177.80
			2,058.00	1,600.20
LABOUR				
	SPRAY PAINT & TOUCH UP.		350.00	300.00
	LABOUR: DISMANTLED & REPLACEMENT REPAIRED DAMAGE PARTS, BODY ALIGN RESET WIRING CHECK, BRAKE & ENGINE SERVICES. INCLUSIVE OF THE REPAIR OF FRONT RIM (WHEEL ALLOY).		600.00	300.00
			950.00	600.00
GRAND TOTAL			3,008.00	2,200.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,750.00

Report Ref No. CS/FCI18004508/Gcd3s2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.