

ASS. REC. BY:

REF: CS/CTI18004540/Kvd3ⁿ²

Special Instruction:

Surveyor: Kenneth ASSIGNMENT (Office)

From (Person): Irene Tay of CTI Date/Time: 8/3/18 @ 4:39pm

Estimated Cost: _____ Bill to: _____

OD-TP-WS/TP RES / OD RES / EVA / INV / MV ? CS

To Inspect Vehicle No: SFX 4848Y Insured: SLC 2438A

at Workshop m/s Motor Image Tel: 67038104

of 19 towing & Tod Payoh

Policy No: DMHCSN1734931700 Claim No: SNM18D01221C02

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 5/3/2018
(Client's Record)

CA / REV / REP. / REV 24 HRS wp H.O.D. Endorsement: _____

Date/Time: 9:19am @ 9/3/18 Person Contacted: 8ayed Vehicle IN/OUT IN

Date/Time	Action/Instruction (✓) Estimate
	SFX 4848Y-X
	SLC 2438A-X
<u>15/5/18</u>	<u>Final fig \$ 1498 (Rec 1972.32, 567)</u>

REF: CTR

REF: CTR

ASSIGNMENT

From: _____ Date: **02042018**

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: **SFX 4848Y**

at Workshop m/s: **Motor Image**

of: **19 Lorong 8 Tea Payoh**

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

Veh No: **SFX 4848Y** Yr Regn: **08 17**

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or _____

Make: **Subaru Wagon 1998**

Colour: **M. Grey** A/C: Insured / Std / NI / NA

Sp. Reading: **8072** T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: **JF1S JGK 854G-093 432**

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or _____

Brake: In order / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: _____ R: **225/55R18**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or _____

Front	Rear
R/Bal. 9 mm	R/Bal. 9 mm
L/Bal. 9 mm	L/Bal. 9 mm
D.O.A. 5/3/18	D.O.I. 2/4/18

Survey held at: _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

After 10am



Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: **02** days Res.: Yes or No

Lum Sum: **1-B.1** % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time	Action / Instruction
3/4	File pass to Catherine

RECEIVED 15 MAY 2018

Date/Time, File Pass to? : Preli. Report

1) : Final Report

Date/Time, File Return to? _____

Days Of Repair: **2**

Resurvey No. of Trip: **1**

2) **15/5 - typist**

Report Format: **Merimen**

Lump Sum / I.B.I: (\$) **1498/2**

Add Fee: : Site Insp (\$)

: Interview (\$)

: Tech. Invs (\$)

: Weekend (\$)

Survey Fee: _____

Transportation: _____

\$ + R5. _____

Photos _____

Other _____

TOTAL **220**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18004540/Kvd3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 09-03-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLC 2438A	Veh. Inspected	SFX 4848Y
Policy No.	DMHCSN1734931700	Coverage (\$)	0.00
Claim No.	SNM18D01221C02	Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAY)	Assign Date	09/03/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	05/03/2018	Inspection Date	
Survey held at	MOTOR IMAGE ENTERPRISES PTE LTD 19 TOA PAYOH LORONG 8 SINGAPORE 319255		

5a. Remarks

	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--	---

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Mar 2018		08 Mar 2018 16:39 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS				[Created by insurer]					
Insured:	DUBER , Co. Reg. No.: 53312796C								
Main Claimant:	CHANG YEN LENG KATHERINE , ID: S1414683J								
Vehicle Reg. No.:	SFX4848Y	Date of Loss:	05/03/2018 17:00 - :59						
Claim Type:	TP / SNM18D01221C02	Policy/Cover Note No.:	DMHCSN1734931700 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLC2438A	Policy No. (Claimant):	1700042786						
		Excess:	S\$0.00						
Repairer:	Motor Image Enterprises Pte Ltd (Toa Payoh) 19 Lorong 8 Toa Payoh, 319255 Toa Payoh - Tel: 67038104								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]								
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 19/03/2018]								
Driver/Custodian (Insured):	TAN WEI HIANG JACKY (CHEN WEIXIANG) (40 / Male), NRIC: S7713089F, Tel: +6583686649								
Adj Asg. Remarks:	NO EST, CASE WITH SJE								
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS <input type="checkbox"/>				View All Search Tasks Create New Task Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Lucas Lee

From: Lucas Lee
Sent: Thursday, 8 March, 2018 4:35 PM
To: 'Sayedinah Bin Ali'
Cc: Irene Tay
Subject: RE: PRS FOR SFX4848Y (CTI REF: SNM18D01221C02)
Attachments: leeSZ_SNM18D01221-BOX-16-TP-LTR_CLCR66.883.pdf

Dear Sirs,

Kindly refer to the above attachment.

Case Handler: Irene Tay

Regards,

Lucas Lee
Claims Department (Motor)
China Taiping Insurance (Singapore) Pte. Ltd.
3, Anson Road, #16-00
Springleaf Tower,
Singapore 079909
Co. Reg. No. 200208384E
DID: 6389 6181
Fax: 6224 7175
Email: claimsdept@sg.cntaiping.com
Email: lucas.lee@sg.cntaiping.com
Website: www.sg.cntaiping.com

From: Sayedinah Bin Ali [<mailto:sayedinah@motorimage.net>]
Sent: Thursday, 8 March, 2018 11:48 AM
To: Lucas Lee
Cc: Irene Tay; Kuan Wei Loong; Daniel Lim
Subject: RE: PRS FOR SFX4848Y (CTI REF: SNM18D01221C02)
Importance: High

Hi Lucas,
Kenneth Kong LKK will be our choice.

Regards
Sayedinah Ali
Service Executive
Motor Image Enterprises Pte Ltd
19 Lorong 8 Toa Payoh Singapore 319255
HP:92992693 DID:67038109 FAX:+65-62535535
Email:sayedinah@motorimage.net
Website:www.tanchong.com :: www.motorimage.net

From: Lucas Lee [<mailto:lucas.lee@sg.cntaiping.com>]
Sent: Thursday, 8 March 2018 11:36 AM
To: Sayedinah Bin Ali <sayedinah@motorimage.net>

Cc: Irene Tay <irene.tay@sg.cntaiping.com>
Subject: PRS FOR SFX4848Y (CTI REF: SNM18D01221C02)

Without Prejudice

Dear Sirs

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

TAY BENG HEE
DERECK OH SIONG WEE
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Case Handler: Irene Tay

Regards,

Lucas Lee
Claims Department (Motor)
China Taiping Insurance (Singapore) Pte. Ltd.
3, Anson Road, #16-00
Springleaf Tower,
Singapore 079909
Co. Reg. No. 200208384E
DID: 6389 6181
Fax: 6224 7175
Email: claimsdept@sg.cntaiping.com
Email: lucas.lee@sg.cntaiping.com
Website: www.sg.cntaiping.com

From: Sayedinah Bin Ali [<mailto:sayedinah@motorimage.net>]
Sent: Tuesday, 6 March, 2018 10:08 PM
To: Claims Dept of CTI
Cc: Daniel Lim; Kuan Wei Loong
Subject: SFX4848Y-AIG-3RD PARTY CLAIM-TP(SLC2438A)CHINA TAIPING DOA:05.03.2018

Hi Claims Team,

Kindly advise liability status of above mention vehicle.

Regards

Sayedinah Ali

Service Executive


Motor Image Enterprises Pte Ltd

19 Lorong 8 Toa Payoh Singapore 319255

HP:92992693 DID:67038109 FAX:+65-62535535

Email:sayedinah@motorimage.net

Website:www.tanchong.com :: www.motorimage.net



Disclaimer: This e-mail is confidential. It may also be legally privileged. If you are not the addressee you may not copy, forward, disclose or use any part of this message. If you have received this message in error, please delete it and all copies from your system and notify the sender immediately by return e-mail. Internet communications cannot be guaranteed to be timely, secure, error-free or virus-free. The sender does not accept liability for any errors or omissions.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/03/2018 09:47
Date Of Accident	05/03/2018 17:45
Exact Location Of Accident	NON UPP CHANGI ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFX4848Y
Insured/Policyholder	
Name Of Registered Owner	CHANG YEN LENG KATHERINE
NRIC No	S1414683J
Email Address	DTKCYL@GMAIL.COM
Mobile Phone No	(LOCAL) +65-91864858
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	SUBARU
Model	FORESTER-2.0 XT (A)
Exact Purpose for which vehicle was being used at time of accident	LEISURE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	1700042786
Cover Note Number	

Driver

Name of Driver	DAVID TAN KIM CHUI
NRIC No	S1852761H
Date Of Birth	02/01/1959
Occupation	INDOOR
Date Of Driving Pass	06/01/2003
Driving Experience	15 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-91864858
Fax Number	
Contact Number	
Email Address	DTKCYL@GMAIL.COM

Address	1
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : 1 GENDER: : MALE
Passenger 2	NAME: : 2 GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident


KINDLY ATTACHED TO STATEMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

WHILE DRIVING ALONG NEW UPPER CHANGI ROAD TOWARDS
CITY FROM CHANGI, AFTER EXPI. CAR A AHEAD OF MINE
BRAKED SUDDENLY, I BRAKED TO A STOP AND THE CAR
BEHIND HIT MINE.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

C:\NMC\SketchPlan\04_15


Driver's Signature
(if driver is not the policyholder)
Date & Time: 6.3.18
9.42 am



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is **not** an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 6.3.18
8.40am


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0682/2018
DATE : 05-MAR-2018

CHINA TAIPING INSURANCE (SINGAPORE)PTE LTD
3 ANSON ROAD
#15-00 SPRINGLEAF TOWER
SINGAPORE S(079909)
TEL : 6389 6111
FAX : 6222 1033

OWNER'S NAME : CHANG YEN LENG KATHERINE
ADDRESS : 137 TANAH MERAH KECHIL ROAD SOUTH
#01-02
S(466671)
TELEPHONE NO : 91864858

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1700042786
VEHICLE NO : SPX4848Y
MODEL CODE : SJGGKK8
MODEL/YEAR : FORESTER 2.0XT AWD CVT
ENGINE NO : FA20CA72791
CHASSIS NO : JF1SJK85HG093432
MILEAGE : 1 KM
DATE IN : 05/03/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SAYEDINAH ALI**
ACCIDENT DATE : 05/03/2018

Print Date : 08/03/2018
Print Time : 17:22:35

MOTORIMAGE ENTERPRISES PTE. LTD.

19 LORONG 8, TOA PAYOH

SINGAPORE 319255

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SFX4848Y

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM)		
2	ZZ/001	CONDUCT TP CLAIM CHINA TAIPING LOCATION:NON UPP CCHANGI RD DATE:05/03/2018 TIME:1745HRS		
3	ZZ/002	REPAIR/REPLACE RR BUMPER AND RR PANEL	1120.00	280 ✓
4	ZZ/003	RESPRAY RR BUMPER AND RR PANEL	840.00	420 ✓
5	ZZ/004	TO CONDUCT RR LIGHTING TEST	50.00	20 ✓
6	ZZ/005	TO SUPPLY/INSTALL REVERSE SENSOR-2 EYES	300.00	? × SVC
7	ZZ/006	SUNDRIES	100.00	? × NN
		TOTAL LABOUR CHARGES	2410.00	

MOTORIAGE ENTERPRISES PTE. LTD.
 19 LORONG 9, TOA PAYOH
 SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SPX4848Y

		DAMAGED PARTS & PRICES				
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST REMARKS
1	BUMPER FACE REAR FORESTER IL	57704SG012	540.00	✓		
2	BRKT CORNER R RH	57707SG060	18.00	✗		
3	BRKT CORNER R LH	57707SG070	18.00	✗		
4	BRKT SD R RH	57707SG080	14.40	✗		
5	BRKT SD R LH	57707SG090	14.50	✗		
6	BEAM COMPL R EU	57711SG0219P	288.00	✗		
7	COVER HOOK R	57731SG010NN	12.50	✓		
8	CARGO STEP PANEL (RESIN)FORESTER	E775E8G000	420.00	✓		
SUB TOTAL			1325.40	0.00	0.00	0.00
LESS DISCOUNT (NETT-20 %)			265.08	0.00	0.00	0.00
GRAND TOTAL			1060.32	0.00	0.00	0.00
OVERALL TOTAL			1060.32			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
19-LORONG 8, TOA PAYOH
SINGAPORE 319255

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SFX4848Y

TOTAL LABOUR CHARGES	2410.00
TOTAL SPARE PARTS CHARGES	1060.32
GRAND TOTAL	3470.32 *

* All charges do not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

*Not Authorized
Permy B4 paint
2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Kv

MTORIMAGS ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0682/2018
DATE : 05-MAR-2018

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
3 ANSON ROAD
#15-00 SPRINGLEAF TOWER
SINGAPORE S(079909)
TEL : 6389 6111
FAX : 6222 1033

OWNER'S NAME : CHANG YEN LENG KATHERINE
ADDRESS : 137 TANAH MERAH KECHIL ROAD SOUTH
#01-02
S(466671)
TELEPHONE NO : 91864858

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1700042786
VEHICLE NO : SPX4848Y
MODEL CODE : SJGKKS
MODEL/YEAR : FORESTER 2.0XT AWD CVT
ENGINE NO : FA20CA72791
CHASSIS NO : JF1SJGK85BG093432
MILEAGE : 1 KM
DATE IN : 05/03/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SAYEDINAH ALI**
ACCIDENT DATE : 05/03/2018

Print Date : 10/05/2018
Print Time : 10:09:42

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SFX4848Y

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM)		
2	ZZ/001	CONDUCT TP CLAIM CHINA TAIPIING LOCATION:NON UPF CCHANGI RD DATE:05/03/2018 TIME:1745HRS		
3	ZZ/002	REPAIR/REPLACE RR BUMPER AND RR PANEL	1120.00	280.00
4	ZZ/003	RESPRAY RR BUMPER AND RR PANEL	840.00	420.00
5	ZZ/004	TO CONDUCT RR LIGHTING TEST	50.00	20.00
6	ZZ/005	TO SUPPLY/INSTALL REVERSE SENSOR-2 EYES	300.00	.00
7	ZZ/006	SUNDRIES	100.00	.00
		TOTAL LABOUR CHARGES	2410.00	720.00

MDTURIMAGE ENTERPRISES PTE. LTD.
 19 LORONG 8, TOA PAYOH
 SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SFX4848Y

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
		NETT	LIST	S/NETT	
1 BUMPER FACE REAR FORESTER LL	57704SG012	540.00			OK
2 BRKT CORNER R RH	57707SG060	18.00			X
3 BRKT CORNER R LH	57707SG070	18.00			X
4 BRKT SD R RH	57707SG080	14.40			X
5 BRKT SD R LH	57707SG090	14.50			X
6 BEAM COMPL R EU	57711SG0219P	288.00			X
7 COVER HOOK R	57731SG010NN	12.50			OK
8 CARGO STEP PANEL (RESIN)FORESTER	E775ESG000	420.00			OK
SUB TOTAL		972.50	0.00	0.00	0.00
LESS DISCOUNT (NETT-20 %)		194.50	0.00	0.00	0.00
GRAND TOTAL		778.00	0.00	0.00	0.00
OVERALL TOTAL		778.00			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SFX4848Y

NETT ITEM	972.50
LESS 20 %	-194.50
NETT AMOUNT	778.00
LIST ITEM	0.00
LESS 50 %	0.00
LIST AMOUNT	0.00
SPECIAL NETT AMOUNT	0.00
S/LIST ITEM	0.00
LESS 30 %	0.00
S/LIST AMOUNT	0.00
TOTAL LABOUR CHARGES	720.00
TOTAL SPARE PARTS CHARGES	778.00
TOTAL CHARGES	1498.00
ADD 7 % GST	104.86
GRAND TOTAL	1602.86

✓ ok

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0682/2018
DATE : 05-MAR-2018

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
3 ANSON ROAD
#15-00 SPRINGLEAF TOWER
SINGAPORE S(079909)
TEL : 6389 6111
FAX : 6222 1033

OWNER'S NAME : CHANG YEN LENG KATHERINE
ADDRESS : 137 TANAH MERAH KECHIL ROAD SOUTH
#01-02
S(466671)
TELEPHONE NO : 91864858

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1700042786
VEHICLE NO : SPX4848Y
MODEL CODE : SJGGKK8
MODEL/YEAR : FORESTER 2.0XT AWD CVT
ENGINE NO : FA20CA72791
CHASSIS NO : JF18JGK85HG093432
MILEAGE : 1 KM
DATE IN : 05/03/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SAYEDINAH ALI**
ACCIDENT DATE : 05/03/2018

Print Date : 08/03/2018
Print Time : 17:22:35

MOTORIMAGE ENTERPRISES PTE. LTD.
 19 LORONG 8, TOA PAYOH
 SINGAPORE 319255

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SPX4848Y

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM)		
2	22/001	CONDUCT TP CLAIM CHINA TAIPING LOCATION:NON UPP CCHANGI RD DATE:05/03/2018 TIME:1745HRS		
3	22/002	REPAIR/REPLACE RR BUMPER AND RR PANEL <i>plastic part</i>	1120.00	2801 + 560 <i>←</i>
4	22/003	RESPRAY RR BUMPER AND RR PANEL <i>plastic part</i>	840.00	4201 + 420 <i>←</i>
5	22/004	TO CONDUCT RR LIGHTING TEST	50.00	201
6	22/005	TO SUPPLY/INSTALL REVERSE SENSOR-2 EYES	<i>su</i> 300.00	X
7	22/006	SUNDRIES	<i>na</i> 100.00	X
TOTAL LABOUR CHARGES			2410.00	

MOTORIAGE ENTERPRISES PTE. LTD.

19 LORONG 8, TOA PAYOH

SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SFX4848Y

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
		NETT	LIST	S/NETT	
1 BUMPER FACE REAR FORESTER IL	57704SG012	<i>R</i> 540.00	<i>✓</i>		
2 BRKT CORNER R RH	57707SG060	<i>Sm</i> 18.00	<i>X</i>		
3 BRKT CORNER R LH	57707SG070	<i>Sm</i> 18.00	<i>X</i>		
4 BRKT SD R RH	57707SG080	<i>Sm</i> 14.40	<i>X</i>		
5 BRKT SD R LH	57707SG090	<i>Sm</i> 14.50	<i>X</i>		
6 BEAM COMPL R EU	57711SG0219P	<i>R</i> 288.00	<i>X</i>		
7 COVER HOOK R	57731SG010NN	<i>Od</i> 12.50	<i>✓</i>		
8 CARGO STEP PANEL (RESIN)FORESTER	E775ESG000	<i>Mc</i> 420.00	<i>✓</i>		
SUB TOTAL		1325.40	0.00	0.00	0.00
LESS DISCOUNT (NETT-20 %)		265.08	0.00	0.00	0.00
GRAND TOTAL		1060.32	0.00	0.00	0.00
OVERALL TOTAL		1060.32			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTOREMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SFX4848Y

TOTAL LABOUR CHARGES 2410.00
TOTAL SPARE PARTS CHARGES 1060.32

GRAND TOTAL 3470.32 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME :
SURVEYED DATE :
AUTHORIZED DATE :
EXCESS CLAUSE : 0.00
LIABILITY : 0.00
REMARKS :

*Not Withheld
Permy B4 paint
2 days*

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118004540/KVD3N2

Date: 17/05/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSN1734931700
Claimant Vehicle No :	SFX4848Y	Insured Vehicle No :	SLC2438A
Date of Loss:	05/03/2018	Nature of Claim:	TP
		Claim No:	SNM18D01221C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFX4848Y	Engine No:	FA20CA72791
Make & Model:	SUBARU FORESTER, 2.0 XT (A)	Chassis No:	JF1SJGK85HG093432
Reg. Date:	21/08/2017 (Man. Year: 2017)	Odometer:	8072 km
Colour:	Metallic Grey		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55R18	Rear Tyre Size:	225/55R18
Front Left Side:	Bridgestone 9 mm	Rear Left Side:	Bridgestone 9 mm
Front Right Side:	Bridgestone 9 mm	Rear Right Side:	Bridgestone 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,460.32	778.00	682.32	46.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,010.00	720.00	1,290.00	64.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,470.32	1,498.00	1,972.32	56.83
+ GST 7.00/7.00% (S\$)	242.92	104.86	138.06	56.83
Nett Amount (S\$)	3,713.24	1,602.86	2,110.38	56.83

INSPECTION

Date of Assignment:	08/03/2018		
Date Inspected:	02/04/2018	Inspected At:	Motor Image Enterprises Pte Ltd (Toa Payoh) 19 Lorong 8 Toa Payoh Singapore 319255
Estimated Period of Repair:	2.0 days		

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 17 May 2018)	
Parts: M1-SUV	SUBARU FORESTER 2.0 XT (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SFX4848Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER FACE REAR FORESTER IL	Bent	540.00 FN	*540.00 FN
2	1		*BRKT CORNER R RH	Serviceable	18.00 FN	*- FN
3	1		*BRKT CORNER R LH	Serviceable	18.00 FN	*- FN
4	1		*BRKT SD R RH	Serviceable	14.40 FN	*- FN
5	1		*BRKT SD R LH	Serviceable	14.50 FN	*- FN
6	1		*BEAM COMPL R EU	Serviceable	288.00 FN	*- FN
7	1		*COVER HOOK R	Dented	12.50 FN	*12.50 FN
8	1		*CARGO STEP PANEL (RESIN) FORESTER	Necessary	420.00 FN	*420.00 FN
9	1		*SUNDRIES	Not Necessary	100.00 FS	*- FS
10	1		*REVERSE SENSOR-2 EYES	Serviceable	300.00 FS	*- FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (S\$)	1,725.40	972.50
- Nett Item Discount on N Items 20.00/20.00% (S\$)	265.08	194.50
Total Parts (S\$)	1,460.32	778.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPAIR/REPLACE RR BUMPER AND RR PANEL	New	1,120.00	280.00
2	RESPRAY RR BUMPER AND RR PANEL	New	840.00	420.00
3	TO CONDUCT RR LIGHTING TEST	New	50.00	20.00
Gross Labour Cost (\$\$)			2,010.00	720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >