



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

1 2010 MAZDA 2 1.5 (SVJ9719S)

Date of Loss

7 March 2018

Time of Loss

15.05

Loss Description

SVJ9719S (INSD) HIT SKJ7728E WHILE REVERSING INTO PARKING LOT

Comment

Workshop Details

Total Rebate Amount

12949

Nett Loss Amount

\$15,051.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *

09/05/2018



Days of work completion *

61



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#
SJV9719S

Registration State

SINGAPORE

Mileage

117968

CATEGORY

Manufacturing Year

POLICY INFORMAT... 2010

ASSESSMENT INFO...

2010

Purchase Date

dd/mm/yyyy



Registration Date *

25/02/2010



Age of Vehicle

8

Driver Details

CATEGORY

Driver Name

FNOL INFORMATI...

WEE HOW TOH

POST SURVEY INF...

CATEGORY Make

POLICY INFORMAT... MAZDA

ASSESSMENT INFO... MAZDA

CATEGORY Model

POLICY INFORMAT... 2 1.5

ASSESSMENT INFO... MAZDA2 SDN AT V GRADE

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT... MM6DE10Y1A0106296

CATEGORY Date of Birth

FNOL INFORMATI... 9 April 1971

POST SURVEY INF... dd/mm/yyyy

CATEGORY Age

FNOL INFORMATI... 47

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Education Qualification

FNOL INFORMATI... Other

POST SURVEY INF...

CATEGORY Driving Experience

ASSESSMENT INFO... MM6DE10Y1A0106296

CATEGORY Engine No

POLICY INFORMAT... ZY598904

ASSESSMENT INFO... ZY598904

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO... 1498

CATEGORY Sum Insured

POLICY INFORMAT... 0

ASSESSMENT INFO... 0

CATEGORY Market Value

POLICY INFORMAT... 0

ASSESSMENT INFO... 28000

FNOL INFORMATI... 18

POST SURVEY INF...

CATEGORY Driver License #

FNOL INFORMATI... S7111624G

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI... 3

POST SURVEY INF...

CATEGORY License Issue Date

FNOL INFORMATI... 15 October 1999

POST SURVEY INF... dd/mm/yyyy

CATEGORY License Expiration Date

FNOL INFORMATI... 15 October 1999

POST SURVEY INF... dd/mm/yyyy

CATEGORY Address

FNOL INFORMATI... Singapore

POST SURVEY INF...

CATEGORY Address type

FNOL INFORMATI... Personal Correspondence

POST SURVEY INF...

CATEGORY Gender

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Marital status

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Identification #

FNOL INFORMATI... S7111624G

POST SURVEY INF...



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

13/03/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

400

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

205/45R16

Condition of Vehicle at time of survey

General condition

Fair



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Fair



Tyre Condition

Spare wheel

Rear Tyre Size

205/45R16

Front left side

FALKEN6mm

Front right side

FALKEN6mm

Rear left side

FALKEN6mm

Rear right side

FALKEN6mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes

No

Save

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary **Parts**

Add Approve Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
		1	1			BOOT LID			Repair	0	0	0	0	0	Deny
		2	1			BOOT LID EMBLEM - MAZDA			Necessary	16				16	Reviewing
		3	1			BOOTLID EMBLEM - 2			Necessary	12				12	Reviewing
		4	1			BOOT LID LOGO			Necessary	24				24	Reviewing
		5	1			BOOT LID LOCK			Serviceable	0	0	0	0	0	Deny
		6	1			REAR BUMPER			Deformed	570				570	Reviewing
		7	1			REAR BUMPER RETAINER			Necessary	28				28	Reviewing
		8	1			REAR BUMPER REFLECTOR LH			Serviceable	0	0	0	0	0	Deny
		9	10			REAR BUMPER CLIPS			Necessary	3.5				35	Reviewing
		10	1			REAR NUMBER PLATE LAMP GARNISH			Serviceable	0	0	0	0	0	Deny
		11	1			REAR END PANEL			Repair	0	0	0	0	0	Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
		12	1			REAR END PANEL TOP COVER			Serviceable	0	0	0	0	0	Deny
		13	1			REAR FENDER LH			Repair	0	0	0	0	0	Deny
		14	1			TAILLAMP ASSY LH			Cracked	350				350	Reviewing

Labour

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
		1		TO KNOCK AND STRAIGHTEN BOOT LID, REAR END PANEL, REAR FENDER LH, REMOVE AND REPLACE ACCIDENT DAMAGED PARTS, REALIGN ALL CONNECTION.	450	0	0	Reviewing		
		2		SPRAY PAINT BOOT LID, REAR END PANEL, REAR BUMPER, REAR FENDER LH	600	0	0	Reviewing		
		3		REMOVE & REPLACE LUGGAGE COMPARTMENT INNER TRIM, GARNISH, COVERING	40	0	0	Reviewing		
		4		REMOVE & REPLACE REVERSE SENSOR AND CHECK FUNCTION	40	0	0	Reviewing		

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Add

Approve

Deny

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
☐		1	DAYS OF REPAIR : 4 DAYS	Reviewing			
☐		2	REVERSE SENSOR	Reviewing	200	NOT WORKING	
☐		3	REAR NUMBER PLATE	Reviewing	35	SCRATCHED	

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Claim Amount \$2,000.00

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$1,130.00	\$1,130.00
Spare Parts	\$1,035.00	\$1,035.00
Miscellaneous	\$235.00	\$235.00
Excess	-\$400.00	-\$400.00

Submit for Review