

(08/11/13) - wef

ASS. REC. BY: *MORIS*

REF:

*MS16/ CC3/MSG18004576/Uqbm*

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *1P69065*at Workshop m/s *BF.*

of \_\_\_\_\_

Insured: *GBF 6523M*Policy No. *29004183MKE*Claims No. *549801*

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

DAC Accident Report: \_\_\_\_\_

Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_

Consistent? : Yes or No

Est. Repairs: *3* days

Res.: Yes or No

Lum Sum: *20* %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT *35296*

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: *1P69065*Yr Regn: *8, 17*

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or *Lim*Make: *1 Suzuki*c.c. *5-193*Colour: *white*

A/C: Insured / Std / NI / NA

Sp. Reading: *17192*

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: *YAANIR75LH 7100245*

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: *215/75R17.5*R: *215/75R17.5*

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front *6*Rear *6/6*

R/Bal. \_\_\_\_\_ mm

R/Bal. *6/6* mmL/Bal. *6* mmL/Bal. *6/6* mmD.O.A. *13/2/18*D.O.I. *9/3/18*

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

*12/3/18 @ 3.13pm Email GIA report to Katherine & Nabilah**20/3/18 confirmed v/s \$2100 with Alan. (Car # 5348.35, 73%)**21/3/18 @ 2.41pm revised to Katherine Wong via messenger.*

RECEIVED 22 MAR 2018

21/3/2018

Date/Time, File Pass to?

☐ : Preli. Report*11/3/18 MMR*☐ : Final Report

Date/Time, File Return to?

2)

Report Format: *MR-TF*Lump Sum / I.B.I. (\$) *2100*Days Of Repair: *3*

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

200

10

210



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CC3/MSG18004576/Uqb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 09-03-2018	
		Code : MSG	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	GBF 6523M	Veh. Inspected	YP 6906S
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	09/03/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	12/02/2018	Inspection Date	09/03/2018
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Note: This document has not been finalised.

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Katherine Wong Chew Shong

Date: 21 Mar 2018

**Preliminary Advice**

Insured Vehicle No	: GBF6523M	Accident Date	: 13/02/2018
TP Vehicle No	: YP6906S	Assignment Date	: 15/03/2018
Make	: ISUZU NQR75UL5A	Est. Duration of Repair	: 3.00
Date of Inspection	: 09/03/2018		
Inspection At	: FASTECH AUTO PTE LTD (HQ) 1 KAKI BUKIT AVE 6, #01-46/48/50 AUTOBAY SINGAPORE 417883		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,648.35
Revised Amount	:S\$	2,627.64
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,627.64
Lump Sum Repair	:S\$	2,100.00

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is economical/not economical for repair.
- ( X ) The above survey was conducted on a 'without prejudice' basis.

## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Monday, 12 March 2018 3:13 PM  
**To:** 'Katherine Wong'; 'Nabilah Rasol'  
**Cc:** Christopher Chionh; KKLau; SUR; Accounts (LKKAuto)  
**Subject:** DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD, DOA: 13/02/2018, YP 6906S (TP VEHICLE), GBF 6523M (OI VEHICLE)  
**Attachments:** YP6906 GIA.pdf

Dear Katherine and Nabilah,

Please be informed that we had inspected the vehicle YP 6906S at M/s: FASTECH AUTO PTE LTD, 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883 on 09/03/2018.

Enclosed herewith a copy of TP's GIA report. The estimated cost of repair will forward to you shortly.

Meanwhile, kindly provide us the claim reference number for our necessary action.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

# Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	3529E
Vehicle Details	
Vehicle No.:	YP6906S
Vehicle to be Exported:	No
Intended De-registration Date:	09 Mar 2018
Vehicle Make:	ISUZU
Vehicle Model:	NQR75UL5A
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	4HK1577293
Chassis No.:	JAAN1R75LH7100245
Maximum Power Output:	-
Open Market Value:	\$37,063.00
Original Registration Date:	02 Aug 2017
First Registration Date:	02 Aug 2017
Transfer Count:	0
Actual ARF Paid:	\$1,854.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	01 Aug 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$18,958.00
COE Rebate Amount:	\$17,811.00
<b>Total Rebate Amount:</b>	<b>\$17,811.00</b>

The information contained herein is correct as at 09 Mar 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	13/02/2018 09:54
Date Of Accident	13/02/2018 09:00
Exact Location Of Accident	CENTREPOINT (LOADING/UNLOADING)
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	YP6906S
<b>Insured/Policyholder</b>	
Name Of Registered Owner	KIM LONG TRADING
Co Reg No	53093529E
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-96265237

### Vehicle Particulars

Manufacturer	ISUZU
Model	NQR75UL5A
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5092934083 (PREF W/SHOP)
Cover Note Number	

### Driver

Name of Driver	DENNIS YAP TECK LEONG
NRIC No	S1673926Z
Date Of Birth	28/09/1964
Occupation	OUTDOOR
Date Of Driving Pass	04/03/1983
Driving Experience	34 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96265237
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 899 TAMPINES ST 81 #08-736
Postcode	520899
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

#### General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

MY LORRY WAS PARKED AT THE LOADIN/UNLOADING BAY. WHEN I CAME BACK TO MY LORRY, I DISCOVERED THE LEFT SIDE MIRROR OF MY LORRY WAS ALREADY DROPPED ON THE FLOOR. THE DRIVER OF THE LORRY(GBF6523M) WHO HIT ONTO MY LORRY WAS THERE BUT HAD ALREADY PARKED OTHER SIDE. I DO NOT KNOW HOW THE ACCIDENT HAPPENED.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBF6523M
Vehicle Make/Model/Colour	MITSUBISHI CANTER FEA01BR2SDEB (CBU)
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	RAZIMAN BIN MOHAMAD
NRIC/Passport Number	G7140103R
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	



## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer [collectively the "Personal Information"] and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature:  
Date & Time:


Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 13 FEB 2018

IDAC KAKI BUKIT (VAC)  
23 Kaki Bukit Ave 4  
Singapore 415933  
Tel: 67416697 Fax: 67492305  
Email: [accid@singnet.com.sg](mailto:accid@singnet.com.sg)  
Name:  
NRIC/FIN No:



Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer

L-File

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 13 FEB 2018

IDAC KAKI BUKIT (VAC)  
23 Kaki Bukit Ave 4  
Singapore 415933  
Tel: 67416697 Fax: 67492305  
Email: [yackb@singnet.com.sg](mailto:yackb@singnet.com.sg)

Reporting Centre Personnel's Signature  
Name:  
NRIC/TIN No.:

# FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No:67452063/67467158 Fax No:67458520

*Not Authorised*  
*date*  
*1/5 # 2100*  
*3 day.*  
*9/3/18*

VEH: YP 6906S

QTY	PARTICULAR	AMOUNT
1PCS	FRONT DOOR VIEW MIRROR BRACKET N/S 745.00	CN \$892.15 ✓
1PCS	FRONT DOOR SQUARE VIEW MIRROR N/S 165.00	SW \$320.50 ✓
1PCS	FRONT DOOR ROUND VIEW MIRROR N/S 102.00	SW \$166.00 ✓
1PCS	FRONT CORNER PANEL GARNISH N/S 385.15	CN \$485.35 ✓
1PCS	SINGAL LAMP N/S 141.60	CN \$280.20 ✓
1PCS	HEADLAMP N/S	17 \$520.15 X
1PCS	FRONT WINDSCREEN RUBBER 282.	CN \$309.00 ✓
1PCS	FRONT GRILLE	11 \$485.00 X
1PCS	FRONT WINDSCREEN	SW \$1,500.00 X
1PCS	FRONT BUMPER	~ \$880.00 X
		\$5,838.35

TO CHECK WIRING	\$50.00 20
TO DISMENTLE & REFIX FRONT WINDSCREEN	\$150.00 80
TO SPRAY RUST PROOFING	11 \$50.00 X
LABOUR FOR PANEL BEATING & REPLACING PARTING	\$680.00 380
TO PUTTY & SPRAY PAINTING	\$880.00 600
<b>TOTAL</b>	<b>\$7,648.35</b>

*1820.75*  
*1547.63*  
*2627.63*

Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- To do body survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplier's liability must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG18004576/UQBN2

Date: 23/03/2018

## REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29004183MKF
Claimant Vehicle No :	YP6906S	Insured Vehicle No :	GBF6523M
Date of Loss:	13/02/2018	Nature of Claim:	TP
		Claim No:	549801

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	YP6906S	Engine No:	4HK1577293
Make & Model:	ISUZU NQR75UL5A, 5.2 D (M)	Chassis No:	JAAN1R75LH7100245
Reg. Date:	02/08/2017 (Man. Year: 2017)	Odometer:	17192 km
Colour:	White		
Engine Capacity:	5193 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	215/75 R17.5	Rear Tyre Size:	215/75 R17.5 (D)
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6/6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6/6 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	5,838.35	1,547.64	4,290.71	73.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,810.00	1,080.00	730.00	40.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,648.35</b>	<b>2,627.64</b>	<b>5,020.71</b>	<b>65.64</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,100.00</b>		
(S\$)	7,648.35	2,100.00	5,548.35	72.54
+ GST 7.00/7.00% (S\$)	535.38	147.00	388.38	72.54
<b>Nett Amount (S\$)</b>	<b>8,183.73</b>	<b>2,247.00</b>	<b>5,936.73</b>	<b>72.54</b>

## INSPECTION

Date of Assignment: 15/03/2018

Date Inspected: 09/03/2018 Inspected At:

Fastech Auto Pte Ltd (HQ)  
1 Kaki Bukit Ave 6, #01-46/48/50  
Autobay  
Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

## Reference

Part Source:	(Last Synchronised: 23 Mar 2018)	
Parts:	N/A	ISUZU NQR75UL5A 5.2 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YP6906S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR VIEW MIRROR BRACKET N/S	Cracked	892.15 F	*745.00 FL
2	1		*FRONT DOOR SQUARE VIEW MIRROR N/S	Broken	320.50 F	*165.00 FL
3	1		*FRONT DOOR ROUND VIEW MIRROR N/S	Broken	166.00 F	*102.00 FL
4	1		*FRONT CORNER PANEL GARNISH N/S	Cracked	485.35 F	*385.15 FL
5	1		*SIGNAL LAMP N/S	Cracked	280.20 F	*141.60 FL
6	1		*HEADLAMP N/S	Not Necessary	520.15 F	*- FL
7	1		*FRONT WINDSCREEN RUBBER	Cut	309.00 F	*282.00 FL
8	1		*FRONT GRILLE	Not Necessary	485.00 F	*- FL
9	1		*FRONT WINDSCREEN	Serviceable	1,500.00 F	*- FL
10	1		*FRONT BUMPER	Repair	880.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	5,838.35	1,820.75
- List Item Discount on L Items 0.00/15.00% (\$\$)	0.00	273.11
Total Parts (\$\$)	5,838.35	1,547.64

Report was unsubmitted during this print-out.

**Recommended Miscellaneous Items**

There are no new miscellaneous items selected.

**Recommended Labour**

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMENTLE & REFIX FRONT WINDSCREEN	New	150.00	80.00
3	TO SPRAY RUST PROOFING	New	50.00	-
4	LABOUR FOR PANEL BEATING & REPLACING PARTING	New	680.00	380.00
5	TO PUTTY & SPRAY PAINTING	New	880.00	600.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,810.00</b>	<b>1,080.00</b>

Report was unsubmitted during this print-out.

&lt; END OF ESTIMATES &gt;