

7/03/2018

ASS. REC. BY:

REF: C8/MSG18004580/UTD31

Special Instruction:

Surveyor:

Mennen

Marcus

ASSIGNMENT (Office)

From (Person):

Eline Ngu

of

MSG

Date/Time:

9/3/18 @ 3:51pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBK 4190B

Insured:

SLU 4700J

at Workshop m/s

Erofia Motor

Tel:

G7527740 / 90696165

of

1 kaki Bkt Ave 6 # 02-62

Policy No:

MSD/vpcp/18-000001

Claim No:

551562

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

27/02/2018

CA / REV / REP. / REV 24 HRS

lwp

12/03/2018 @ after 10am

H.O.D. Endorsement:

Date/Time:

4:22pm @ 9/3/18

Person Contacted:

Lily

Vehicle

IN/OUT

Date/Time

Action/Instruction

(✓)

Estimate

FBK 4190B - X

SLU 4700J - X

13/3-

Revert preli

Submit unrecronomical total loss.

MS19

## ASSIGNMENT

Form Date 12/3/18

Estimated Cost

QD TP WS TR RES OD RES EVA INV MV

Torced Vehicle No: FBK 4190B  
 at Workrooms: Erofia Motor  
 of 1kaki Bkt Ave 6 #02-62

Insured

Policy No

Claims No

Sum Insured

Excess

Client's Record

Make of Van

After 10 am

Policy Condition

Remark: The van had commenced its  
 repair at the time of inspection.



Salvage/Market Value

\$197.18/c.

DAD Accident Report

Consistent? Yes or No

DAD PR Seen

Consistent? Yes or No

Est. Repair

days

Res: Yes or No

Lum Sum

%

3 Val: Yes or No

CA / REV / REP / 24 HRS 'wp'

Date

Person Contacted

Vehicle IN / OUT

Date Time Action / Instruction

TOTAL 1055 + LTA 4600  
 after mv 17

chassis frame crack

25/4/18 owner agree mv 18/c.

Summit TOTAL 1055

MV: 18,000/- LTA 4600/- NV: 13,400/-

RECEIVED 27 APR 2018

Date Time Dis Pass of

26/4 Typist



Prelim. Report

Final Report

Date Time Dis Pass of

Report Form

TP-TL

Date Time Dis Pass of

F3/c 4190B

8 15'

Time Motor

Type of Van

Make

KAWASAKI VER SYS 1043

Color

white

Se-Reading

Eng No

Gatty 86

Chassis

JKAL2T00BBA0035-73

Gen. Cond. Good

Car Body Burnt

Steering

In order / Jammed / Leaked / Burnt

Brake

In order / Jammed / Leaked / Burnt

Mod

NI 65 STD A.R.M.

Tire Size

R 120/70 R17  
 R 180/55 R17

BS/DUN EXVOLA SH PS LIA MO CHTEL PR SLM

TOYO/YOKO

metre/c

Front

7

Rear

7

Rise

L.Sal

D.O.A

27/2/18

D.O

12/3/18

Surveyed at

Des. of Damage Fr Rear DS NS UC Roofing

0/5 Lft, 0/5 Rght 1153.5

The UC Chassis frame Body Structure affected due to collision

Add. Fee

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

29

30

31

32

33

34

35

36

37

38

39

40

41

42

43

44

45

46

47

48

49

50

51

52

53

54

55

56

57

58

59

60

61

62

63

64

65

66

67

68

69

70

71

72

73

74

75

76

77

78

79

80

81

82

83

84

85

86

87

88

89

90

91

92

93

94

95

96

97

98

99

100

101

102

103

104

105

106

107

108

109

110

111

112

113

114

115

116

117

118

119

120

121

122

123

124

125

126

127

128

129

130

131

132

133

134

135

136

137

138

139

140

141

142

143

144

145

146

147

148

149

150

151

152

153

154

155

156

157

158

159

160

161

162

163

164

165

166

167

168

169

170

171

172

173

174

175

176

177

178

179

180

181

182

183

184

185

186

187

188

189

190

191

192

193

194

195

196

197

198

199

200

201

202

203

204

205

206

207

208

209

210

211

212

213

214

215

216

217

218

219

220

221

222

223

224

225

226

227

228

229

230

231

232

233

234

235

236

237

238

239

240

241

242

243

244

245

246

247

248

249

250

251

252

253

254

255

256

257

258

259

260

261

262

263

264

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Mar 2018		09 Mar 2018 15:51 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	BLUECAR EAST ASIA PTE LTD, Co. Reg. No.: 201617259H		
Main Claimant:	MOHAMAD OTHMAN BIN SUPARI, ID: S1241462E		
Vehicle Reg. No.:	FBK4190B	Date of Loss:	27/02/2018 06:00 - :59
Claim Type:	TP / 551562	Policy/Cover Note No.:	MSD/VPCP/18-000001 (Comprehensive) Coverage: 01/01/2018 - 31/12/2018
Vehicle Reg. No. (Insured):	SLU4700J	Policy No. (Claimant):	
		Excess:	S\$2,000.00
Repairer:	Erofia Motor Trading Pte Ltd - (Kaki Bukit) (HQ) 1 Kaki Bukit Avenue 6, #02-62 AutoBay @ Kaki Bukit, 417883 Kaki Bukit - Tel: 67527740 / 90696165		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 10/03/2018]		
Driver/Custodian (Insured):	MUHAMMAD AL HAFIZ BIN AZAMI (), NRIC: S9336319A, Tel: +6587291792		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18004580/Utd3

16 RAFFLES QUAY  
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 09-03-2018



Code : MSG

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLU 4700J	Veh. Inspected	FBK 4190B
Policy No.	MSD/VPCP/18-000001	Coverage (\$)	0.00
Claim No.	551562	Excess (\$)	0.00
Assign From	MERIMEN (ELAINE NGU)	Assign Date	09/03/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	27/02/2018	Inspection Date
Survey held at	EROFIA MOTOR TRADING PTE LTD 1 KAKI BUKIT AVENUE 6 #02-62 SINGAPORE 417883	

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Elaine Ngu Siau Mei

Date: 13 Mar 2018

**Preliminary Advice**

Insured Vehicle : SLU4700J

No

TP Vehicle No : FBK4190B

Make : KAWASAKI VERSYS

Date of :

Inspection

Inspection At :

Accident Date : 27/02/2018

Assignment Date : 09/03/2018

Est. Duration of :

Repair :

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages o/s front, o/s body and n/s body portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	32,458.10
Revised Amount	:S\$	22,280.50
Check Items (Estimated)	:S\$	0.00
Total	:S\$	22,280.50

Lump Sum Repair	:S\$	
-----------------	------	--


**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

( ) The vehicle is economical/not economical for repair.

( x ) The above survey was conducted on a 'without prejudice' basis.



# ISLAND TOWING SERVICES

Blk 3026, Ubi Road 1 #04-146 Singapore 408719  
Telephone: 6747 7400 Email: islandrecovery@gmail.com  
Facsimile: 6844 7233 Web: www.islandrecovery.com.sg  
Co. Reg. 53269210A

Cash Sales/ Work Order

NO. 26363

Date: 27/2/18

M/S: Cash

Vehicle No: FBK4190B Model : Kawasaki

From: Corporation Rd Time Start: 09:05Am

To: Kaki Bukit Parkway #02-62 Time End: 09:50Am

Remarks:

☐ Change Tyres / Jump Start

☐ Accident

☐ Use Car Carrier

☐ Basement / Multi Carpark

☐ Crane Up / Winch Out

☐ Open Door

☐ Using King Dolly

☐ Dismantle Shaft / Brake

☐ Loaded

AMOUNT S\$ 80

*[Signature]*

Received By

Island Recovery Services

Vehicle is transported at owner's risk. The company accepts no responsibility for damaged or other misdemeanour to your vehicle whilst being transported.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	28/02/2018 18:27
Date Of Accident	27/02/2018 06:30
Exact Location Of Accident	JUNCT OF INTERNATIONAL RD AND CORPORATION RD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBK4190B
<b>Insured/Policyholder</b>	
Name Of Registered Owner	MOHAMAD OTHMAN BIN SUPARI
NRIC No	S1241462E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97534574
Alternative Phone No	OFFICE-97534574

### Vehicle Particulars

Manufacturer	KAWASAKI
Model	VERSYS 1000 MANUAL
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	MOTORCYCLE

### Insurance Company

Name of Insurance Company	DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MC00403434
Cover Note Number	

### Driver

Name of Driver	MOHAMAD OTHMAN BIN SUPARI
NRIC No	S1241462E
Date Of Birth	02/06/1957
Occupation	INDOOR
Date Of Driving Pass	25/02/1985
Driving Experience	33 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97534574
Fax Number	
Contact Number	OFFICE-97534574
EMail Address	NOEMAIL

Address	NIL
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	JURONG NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 158 YUNG LOH ROAD , POSTCODE: 610158 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2659999 - FAX NO: 62664987
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

Refer to Police Report number T20180227/2062 : On 27.02.2018 at about 0630hrs. I was riding my motorcycle: FBK4190B along International road travelling on the third lane. As I approached the X-junction of International Rd and Corporation road, the traffic light was still green and in my way. Thus I proceeded to go straight towards Yung Kuang road. However in the middle of the junction, an oncoming vehicle. SLU4700J from Yung Kuang road had turn right into Corporation Rd and collided onto the front right side of my motorcycle. The next, I knew I was already on the ground facing up onto the sky. I did not lost consciousness. The ambulance and traffic police came down to the scene. At that point of time I did not feel any pain in my body. However on the same day I went to NTFGH and was granted 8 days medical leave. The doctor informed that I have a suspected fractured on the left side of my ribs. I have to proceed to follow up on the medical appointment. My motorcycle was towed away to my respective insurance workshop.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLU4700J
Vehicle Make/Model/Colour	BLUECAR
Details Of Properties	NA
Vehicle Category	PRIVATE CAR
Name of Driver	MOHD ALHAFIZ
NRIC/Passport Number	S9336319A

Contact Number	87291792
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### DETAILS OF INJURED PERSON 1

Name	MOHAMAD OTHMAN BIN SUPARI
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	FBK4190B
Were seat belts worn?	NO
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

# Sketch Plan

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
  2. This Form must be completed by the Policyholder and/or the Authorized Driver.
  3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
  4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
  5. Any false reporting may be referred to the Police for investigation.
  6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
  7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
  8. Consent under the Personal Data Protection Act (PDPA)
- I understand, acknowledge, agree and consent that:
- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
    - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
    - (ii) investigating the accident and/or my claims;
    - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
    - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
    - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
  - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
  - (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

1515 28/2/18


Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

VERIFIED BY AJAX MARS  
REPORTING OFFICER  
EUGENE KOH

Witnessed by Reporting Centre  
Personnel

Sketch Plan



JUNCT OF INTERNATIONAL RD &  
CORPORATION RD.

A) FBK 4190 B

B) SLU 4700 J



# SINGAPORE POLICE FORCE



T/20180227/2062

Police Station Of Origin:  
Jurong NPP  
158 Yung Loh Road #01-58 SINGAPORE  
610158  
Tel No: 1800-2659999

1 of 3

Report No. T/20180227/2062

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 27/02/2018 12:51	Vide Report No.:	Station Diary No.: 14
--	------------------	--------------------------

## Informant's Particulars

Name of Informant: MOHAMAD OTHMAN BIN SUPARI			Address: APT BLK 160 YUNG PING ROAD #02-43 SINGAPORE 610160		
ID Type / ID No.: NRIC NO / S1241462E			Contact No.: Home/Office: Mobile: 97534574		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 60	Date of Birth: 02/06/1957	Type of Informant: Rider		
Race: Malay			Language:		Institution / School Name:
Occupation: Process Technician			Driving Licence Information: Class: 2B,2A,2,3,4 Date of Expiry:		

Police Station

## General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 27/02/2018 06:30	Type of Location: X-Junction
Location: Junction of Road 1 and Road 2 INTERNATIONAL ROAD CORPORATION ROAD X-junction of Corporation Rd and International Rd/Yung Kuang Rd				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Dual Carriage Way		Traffic Control: Traffic Light - Working		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

## Details of Vehicle Involved

Vehicle	Type	Make	Model	Color	Condition	No. of Passenger
FBK4190B	Motorcycle	KAWASAKI	VERSYS 1000 MANUAL	White	Totally Damaged	0
SLU4700J	Car			White	Seriously Damaged	0

## Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
-------------	-------------------	---------------	-----------	-------------



**SINGAPORE  
POLICE FORCE**



T/20180227/2062

2 of 3

Police Station Of Origin:

Jurong NPP

158 Yung Loh Road #01-58 SINGAPORE

610158

Tel No: 1800-2659999

Report No. T/20180227/2062

## CONTINUATION OF REPORT

nei Road  
oration Rd, the  
Kuang Rd

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
FBK4190B	DIRECT ASIA INSURANCE (SINGAPORE) PTE. LTD.	MC/00403434	14/08/2017	13/08/2018

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	MOHAMAD OTHMAN BIN SUPARI	ID No.	S1241462E
Related Vehicle	FBK4190B (Motorcycle)	Contact No.	97534574
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3,4 Date of Expiry: NIL
Date Treatment	27/02/2018	Date Discharge	27/02/2018
No. of Days granted Medical Leave	08	Degree of Injury	Serious

**Brief Details.**

On 27.02.2018 at about 0630hrs, I was riding my motorcycle; FBK4190B along International Road travelling on the third lane. As I approached the X-junction of International Rd and Corporation Rd, the traffic light was still green and in my way. Thus I proceeded to go straight towards Yung Kuang Rd. However in the middle of the junction, an oncoming vehicle; SLU4700J from Yung Kuang Rd had turned right into Corporation Rd and collided onto the front right side of my motorcycle. The next thing I knew I was already on the ground facing up onto the sky. I did not lost consciousness.

The ambulance and traffic police came down to the scene. At that point of time I did not feel any pain in my body. However on the same day I went to NTFGH and was granted 8 days medical leave. The doctor informed that I have a suspected fractured on the left side of my ribs. I have to proceed to follow up on the medical appointment. I motorcycle was towed away to my respective insurance workshop.

**SINGAPORE  
POLICE FORCE**

T/20180227/2062

Police Station Of Origin:

Jurong NPP

158 Yung Loh Road #01-58 SINGAPORE

6 10158

Tel No: 1800-2659999

3 of 3

Report No. T/20180227/2062

## CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J /

Staff Sgt MOHAMMED AMIRULHAFIZ BIN  
RAMLAN

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

27/02/2018 12:51

Officer In Charge Of Case:

TP / GIT /

Staff Sgt MA JUNXIANG

Contact No.: 65476251

SN 124

Classification Of Case:

Authentication Stamp

NP168

Signature:

Singapore Police Force

**REPUBLIC OF SINGAPORE DRIVING LICENCE**

Licence Number: **S1241462E**

Name: **MOHAMAD OTHMAN BIN SUPARI**

Birth Date: **02 Jun 1957**

Issue Date: **17 Sep 2003**

0008315988

**REPUBLIC OF SINGAPORE**

IDENTITY CARD NO. **S1241462E**

Name: **MOHAMAD OTHMAN BIN SUPARI**

محمد عثمان بن سقري

Race: **MALAY**

Date of Birth: **02-06-1957** Sex: **M**

Country of Birth: **SINGAPORE**

**YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)**

Class	Description	PASS DATE
Class 2B	Motorcycles not exceeding 200 cc	25 Feb 1985
Class 2A	Motorcycles between 201 cc and 400 cc	25 Feb 1985
Class 2	Motorcycles exceeding 400 cc	25 Feb 1985
Class 3	Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	08 Nov 1978
Class 4	Heavy Motor Cars and Motor Tractors the weight of which unladen exceeds 2500 kilograms	30 Sep 1997

Licence No: S1241462E

NP 425A

2229144

2229144

NRIC No: **S1241462E**

MIB

Co-Pay \$5.00

Blood Group: **A+** Date of issue: **31-07-1994**

Address: **APT BLK 160 YONG PING ROAD #02-43 SINGAPORE 610180**

NRIC No: **S1241462E** Date: **24-11-1999** No: **1552215**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1462E
Vehicle Details	
Vehicle No.:	FBK4190B
Vehicle to be Exported:	No
Intended De-registration Date:	12 Mar 2018
Vehicle Make:	KAWASAKI
Vehicle Model:	VERSYS 1000 MANUAL
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	ZRT00DE083465
Chassis No.:	JKALZT00BBA003573
Maximum Power Output:	-
Open Market Value:	\$15,726.00
Original Registration Date:	14 Aug 2015
First Registration Date:	14 Aug 2015
Transfer Count:	0
Actual ARF Paid:	\$2,359.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	13 Aug 2025
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$6,201.00
COE Rebate Amount:	\$4,600.00
Total Rebate Amount:	\$4,600.00

The information contained herein is correct as at 12 Mar 2018

OK



(/)



Bike model

KAWASAKI VERSYS 1000

Type

Any

Price From

Any

Price To

Any

Class

Any

MORE SEARCH OPTIONS ▾

Q SEARCH

VIEW ALL (/LISTING/USEDBIKES/LISTING/)

Kawasaki Versys 1000 (/listing/usedbike/kawasaki-kawasaki-versys-1000/6429/)



(/listing/usedbike/kawasaki-kawasaki-versys-1000/6429/)

==\$14800

Reg : 05/02/2013

Type: Sport Tourers

1043cc

-

Well taken care of Kawasaki Versys 1000 best price in the market. Bike available to view at Speedway Motor Pte Ltd location at No 36 Toh Guan road East #01-32 enterprise hub Singapore 608580.

Posted on : 06/03/2018

★ PAID AD ★ DEALER AD

DETAILS &gt; (/LISTING/USEDBIKE/KAWASAKI-KAWASAKI-VERSYS-1000/6429/)

Kawasaki Versys 1000 (/listing/usedbike/kawasaki-kawasaki-versys-1000/2409/)



(/listing/usedbike/kawasaki-kawasaki-versys-1000/2409/)

-

Reg : 18/10/2012

Type: Sport Tourers

1043cc

49700km

# EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

*ring 1G*

Name : Mohamad Othman Bin Supari

Accident Date : 27-Feb-18

Vehicle No : FBK 4190 B

Vehicle Model : Kawasaki  
Versys

## Estimated Repair Costs

Qty	Description List Items	Amount S(\$)
1	Front fender	S CR 380.00 ✓
1	Front fairing inner bracket	S VS 509.00 X
1	Fork tube assy -L/H	S Tu/ 1,732.00 ✓
1	Fork tube assy -R/H	S Tu/ 1,732.00 ✓
1	Fork upper bracket	S CR 600.00 ✓
1	Fork under bracket	S CR 609.00 ✓
1	Front rim shaft	S CR 75.00 ✓
2	Front brake discs	S CR 1,218.00 ✓
1	Front sport rim	S CR 1,950.00 ✓
1	Windshield	S CR 450.00 ✓
1	Windshield bracket	S CR 1,800.00 X
1	Windshield outer cover	S CR 250.00 X
1	Headlamp	S CR 1,350.00 ✓
2	Side mirrors	S CR 700.00 ✓
1	Handle bar	S CR 285.00 ✓
2	Handle bar ends	S CR 120.00 ✓
1	Hand grip (1 set)	S CR 120.00 X
1	Clutch lever	S CR 155.00 ✓
1	Brake lever	S CR 155.00 ✓
2	Front signals	S CR 440.00 ✓
1	Front fairing	S CR 800.00 ✓
2	Front side covers -inner	S CR 320.00 ✓
2	Front fairing lower inner covers	S CR 360.00 ✓
2	Air intake tubes	S CR 360.00 ✓
2	Side outer fairings	S CR 1,100.00 ✓
2	Side inner fairings	S CR 1,476.00 ✓
2	Side lower fairings	S CR 910.00 ✓
1	Meter assy	S CR 1,478.00 X
1	Meter panel	S CR 247.00 X
1	Radiator	S CR 1,848.00 ✓
1	Engine cover -R/H	S CR 280.00 ✓
2	Front footrests	S CR 220.00 ✓
2	Front footrest brackets	S CR 330.00 X
1	Gear pedal	S CR 185.00 ✓
1	Brake pedal	S CR 175.00 ✓
		S 24,719.00

# EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

Name : Mohamad Othman Bin Supari

Accident Date : 27-Feb-18

Vehicle No : FBK 4190 B

Vehicle Model : Kawasaki  
Versys

## Estimated Repair Costs

	c/f:	S	24,719.00
2	Rear footrests	S 117	170.00 ✓
2	Rear footrest brackets	S 11	560.00 ✓
1	Fuel tank	S 12	1,820.00 ✓
1	Exhaust pipe	S 12	1,550.00 ✓
1	Exhaust pipe cover	S 12.5	120.00 ✓
2	Side panels	S 12	220.00 ✓
1	Key switch assy	S 11	580.00 ✓
2	Front brake pumps - lower	S 11	1,100.00 ✓
1	Magnet coil cover	S 117	450.00 ✓
1	Magnet coil cover gasket	S 11	50.00 ✓
1	Radiator fan	S 11	350.00 ✓
1	Front inner fairing	S 11	350.00 ✓
1	Engine cover gasket	S 11	80.00 ✓
		S	32,119.00
	Less 10%	S	3,211.90
		S	28,907.10

## Special Nett Items

1	Number plate (1 set)	S 11	28.00 ✓
1	Fork oil	S 11	20.00 ✓
1	Fork oil seal	S 11	38.00 ✓
1	Coolant	S 11	35.00 ✓
1	Steering cone (1 set)	S 11	180.00 ✓
1	Front tyre	S 11	200.00 ✓
3	Engine oil	S 11	60.00 ✓
1	Rear box	S 11	500.00 ✓
1	Rear box bracket	S 11	400.00 ✓
		S	1,461.00

LKA Auto Consultants hence notify the Repairer of the following:

- To resurvey and/or after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No actual modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

PAGE 2 OF 3

Signature:

Date:

# EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

Name : Mohamad Othman Bin Supari

Accident Date : 27-Feb-18

Vehicle No : FBK 4190 B

Vehicle Model : Kawasaki  
Versys

## Estimated Repair Costs

<u>S/No.</u>	<u>Labour</u>			
1	To provide towing service.	\$	80.00	35
2	To check wiring and reset headlamp focusing.	\$	11 80.00	2
3	To provide labour.	\$	480.00	380
4	To respray painting.	\$	1,000.00	500
5	To check , repair and straighten body frame.	\$	450.00	300
		\$	2,090.00	

Grand Total \$ 32,458.10

Dollars: Thirty-Two Thousand Four Hundred Fifty-Eight And Ten Cents Only.



EROFIA MOTOR TRADING PTE LTD

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Mar 2018		09 Mar 2018 15:51 <a href="#">Edit Adj Rpt</a>	<b>S\$22,277.00</b> <a href="#">Edit Estimates</a>	<b>S\$22,277.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	<b>BLUECAR EAST ASIA PTE LTD</b> , Co. Reg. No.: 201617259H								
Main Claimant:	<b>MOHAMAD OTHMAN BIN SUPARI</b> , ID: S1241462E								
Vehicle Reg. No.:	<b>FBK4190B</b>	Date of Loss:	27/02/2018 06:00 - 159 [30 Months and 13 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 551562</b>	Policy/Cover Note No.:	MSD/VPCP/18-000001 (Comprehensive) Coverage: 01/01/2018 - 31/12/2018						
Vehicle Reg. No. (Insured):	<b>SLU47003</b>	Policy No. (Claimant):							
		Excess:	S\$2,000.00						
Repairer:	<b>Erofia Motor Trading Pte Ltd - (Kaki Bukit) (HQ)</b> 1 Kaki Bukit Avenue 6, #02-62 AutoBay @ Kaki Bukit, 417883 Kaki Bukit - Tel: 67527740 / 90696165								
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Elaine Ngu Siau Mei</b> - 6594 2540]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MARCUS CHUA</b> ] ... [Final Rpt due 08/04/2018]								
Driver/Custodian (Insured):	<b>MUHAMMAD AL HAFIZ BIN AZAMI</b> (), NRIC: S9336319A, Tel: +6587291792								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*FBK4190B (551562)

[SLU47003]

TP

MOHAMAD OTHMAN BIN SUPARI

Feb 27 2018 6:00AM

[BLUECAR EAST ASIA PTE LTD]

Erofia Motor Trading Pte Ltd - (kaki Bukit)

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Assessment Reports















































1 per page



















































No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	09/03/18 15:50	<b>Accident Statement</b> <small>From: DD - Reg. No: SLU47003, Claimant: BLUECAR EAST ASIA PTE LTD</small>		<div>1</div> <div>Load HTM</div>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	13/03/18 16:35	<b>Adjuster Immediate Advice</b>		<div>1</div> <div>Load HTM</div>	













































Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	12/03/18 19:58	<b>General View</b>		<div>1</div> <div>Load JPG</div>	<input checked="" type="checkbox"/>
2	12/03/18 19:58	<b>General View</b>		<div>1</div> <div>Load JPG</div>	<input checked="" type="checkbox"/>
3	12/03/18 19:58	<b>General View</b>		<div>1</div> <div>Load JPG</div>	<input checked="" type="checkbox"/>
4	12/03/18 19:58	<b>General View</b>		<div>1</div> <div>Load JPG</div>	<input checked="" type="checkbox"/>
5	12/03/18 19:58	<b>General View</b>		<div>1</div> <div>Load JPG</div>	<input checked="" type="checkbox"/>
6	12/03/18 19:58	<b>General View</b>		<div>1</div> <div>Load JPG</div>	<input checked="" type="checkbox"/>
7	12/03/18 19:59	<b>General View</b>		<div>1</div> <div>Load JPG</div>	<input checked="" type="checkbox"/>
8	12/03/18 19:59	<b>General View</b>		<div>1</div> <div>Load JPG</div>	<input checked="" type="checkbox"/>
9	12/03/18 19:59	<b>General View</b>		<div>1</div> <div>Load JPG</div>	<input checked="" type="checkbox"/>
10	12/03/18 19:59	<b>General View</b>		<div>1</div> <div>Load JPG</div>	<input checked="" type="checkbox"/>
11	12/03/18 19:59	<b>General View</b>		<div>1</div> <div>Load JPG</div>	<input checked="" type="checkbox"/>
12	12/03/18 19:59	<b>General View</b>		<div>1</div> <div>Load JPG</div>	<input checked="" type="checkbox"/>
13	12/03/18 19:59	<b>General View</b>		<div>1</div> <div>Load JPG</div>	<input checked="" type="checkbox"/>
14	12/03/18 19:59	<b>General View</b>		<div>1</div> <div>Load JPG</div>	<input checked="" type="checkbox"/>
15	12/03/18 19:59	<b>General View</b>		<div>1</div> <div>Load JPG</div>	<input checked="" type="checkbox"/>
16	12/03/18 19:59	<b>General View</b>		<div>1</div> <div>Load JPG</div>	<input checked="" type="checkbox"/>
17	12/03/18 19:59	<b>General View</b>		<div>1</div> <div>Load JPG</div>	<input checked="" type="checkbox"/>
18	12/03/18 19:59	<b>General View</b>		<div>1</div> <div>Load JPG</div>	<input checked="" type="checkbox"/>
19	12/03/18 19:59	<b>General View</b>		<div>1</div> <div>Load JPG</div>	<input checked="" type="checkbox"/>
20	12/03/18 19:59	<b>General View</b>		<div>1</div> <div>Load JPG</div>	<input checked="" type="checkbox"/>
21	12/03/18 19:59	<b>General View</b>		<div>1</div> <div>Load JPG</div>	<input checked="" type="checkbox"/>
22	12/03/18 19:59	<b>General View</b>		<div>1</div> <div>Load JPG</div>	<input checked="" type="checkbox"/>
23	12/03/18 19:59	<b>General View</b>		<div>1</div> <div>Load JPG</div>	<input checked="" type="checkbox"/>
24	12/03/18 19:59	<b>General View</b>		<div>1</div> <div>Load JPG</div>	<input checked="" type="checkbox"/>
25	12/03/18 19:59	<b>General View</b>		<div>1</div> <div>Load JPG</div>	<input checked="" type="checkbox"/>
26	12/03/18 19:59	<b>General View</b>		<div>1</div> <div>Load JPG</div>	<input checked="" type="checkbox"/>
27	12/03/18 19:59	<b>General View</b>		<div>1</div> <div>Load JPG</div>	<input checked="" type="checkbox"/>
28	12/03/18 19:59	<b>General View</b>		<div>1</div> <div>Load JPG</div>	<input checked="" type="checkbox"/>
29	12/03/18 19:59	<b>General View</b>		<div>1</div> <div>Load JPG</div>	<input checked="" type="checkbox"/>
30	12/03/18 19:59	<b>General View</b>		<div>1</div> <div>Load JPG</div>	<input checked="" type="checkbox"/>
31	12/03/18 19:59	<b>General View</b>		<div>1</div> <div>Load JPG</div>	<input checked="" type="checkbox"/>
32	12/03/18 19:59	<b>General View</b>		<div>1</div> <div>Load JPG</div>	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail Print
				<input checked="" type="checkbox"/>
33	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
34	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
35	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
36	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
37	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
38	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
39	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
40	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
41	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
42	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
43	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
44	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
45	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
46	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
47	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
48	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
49	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
50	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
51	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
52	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
53	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
54	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
55	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
56	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
57	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
58	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
59	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
60	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
61	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
62	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
63	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
64	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
65	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
66	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
67	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
68	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
69	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
70	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
71	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
72	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
73	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
74	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
75	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
76	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
77	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
78	12/03/18 19:59	General View	Load JPG	<input checked="" type="checkbox"/>
79	12/03/18 19:59	General View	Load JPG	<input checked="" type="checkbox"/>
80	12/03/18 19:59	General View	Load JPG	<input checked="" type="checkbox"/>
81	12/03/18 19:59	General View	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
82	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
83	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
84	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
85	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
86	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
87	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
88	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
89	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
90	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
91	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
92	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
93	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
94	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
95	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
96	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
97	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
98	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
99	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
100	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
101	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
102	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
103	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
104	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
105	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
106	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
107	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
108	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
109	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
110	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
111	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
112	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
113	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
114	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
115	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
116	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
117	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
118	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
119	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
120	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
121	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
122	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
123	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
124	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
125	12/03/18 19:59	General View	 Load JPG	<input checked="" type="checkbox"/>
126	12/03/18 20:00	General View	 Load JPG	<input checked="" type="checkbox"/>
127	12/03/18 20:00	General View	 Load JPG	<input checked="" type="checkbox"/>
128	12/03/18 20:00	General View	 Load JPG	<input checked="" type="checkbox"/>
129	12/03/18 20:00	General View	 Load JPG	<input checked="" type="checkbox"/>
130	12/03/18 20:00	General View	 Load JPG	<input checked="" type="checkbox"/>
131	12/03/18 20:00	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
132	12/03/18 20:00	General View	 Load JPG	<input checked="" type="checkbox"/>
133	12/03/18 20:00	General View	 Load JPG	<input checked="" type="checkbox"/>
134	12/03/18 20:00	General View	 Load JPG	<input checked="" type="checkbox"/>
135	12/03/18 20:00	General View	 Load JPG	<input checked="" type="checkbox"/>
136	12/03/18 20:00	General View	 Load JPG	<input checked="" type="checkbox"/>
137	12/03/18 20:00	General View	 Load JPG	<input checked="" type="checkbox"/>
138	12/03/18 20:00	General View	 Load JPG	<input checked="" type="checkbox"/>
139	13/03/18 20:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
140	13/03/18 20:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
141	13/03/18 20:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
142	13/03/18 20:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
143	13/03/18 20:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
144	13/03/18 20:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
145	13/03/18 20:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
146	13/03/18 20:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
147	13/03/18 20:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
148	13/03/18 20:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
149	13/03/18 20:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
150	13/03/18 20:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
151	13/03/18 20:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
152	13/03/18 20:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
153	13/03/18 20:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
154	13/03/18 20:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
155	13/03/18 20:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
156	13/03/18 20:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
157	13/03/18 20:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
158	13/03/18 20:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
159	13/03/18 20:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
160	13/03/18 20:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
161	13/03/18 20:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
162	13/03/18 20:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
163	13/03/18 20:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
164	13/03/18 20:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
165	13/03/18 20:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
166	13/03/18 20:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
167	13/03/18 20:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
168	13/03/18 20:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
169	13/03/18 20:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
170	13/03/18 20:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
171	13/03/18 20:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
172	13/03/18 20:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
173	13/03/18 20:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
174	13/03/18 20:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	09/03/18 15:49	TP FBK41908 GIA REPORT	 Load PDF	

### Documents Checklist

**DOCUMENTS CHECKLIST**

Reset

Save

Print

There are no document checklists configured.

**Our Checklist Remarks - LXX Auto Consultants Pte Ltd (HQ)****Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18004580/TD3Q2

Date: 27/04/2018

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: MSD/VPCP/18-000001  
**Claimant Vehicle No :** FBK4190B **Insured Vehicle No :** SLU4700J  
**Date of Loss:** 27/02/2018 **Nature of Claim:** TP **Claim No:** 551562

### DESCRIPTION & IDENTIFICATION OF VEHICLE

**Reg No:** FBK4190B  
**Make & Model:** KAWASAKI VERSYS, 649cc 650 M **Engine No:** ZRT00DE083465  
**Reg. Date:** 14/08/2015 (Man. Year: 2015) **Chassis No:** JKALZT00BBA003573  
**Colour:** White **Odometer:** 0 km  
**Engine Capacity:** 1043 cc  
**Market Value/New Car Price:** N/A  
**Sum Insured (\$\$):** Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

**General Condition:** Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes  
**Handbrake (Serviceable):** Yes **Engine Modification:** No **Pre-accident Condition:** Yes

### CONDITION OF TYRES

**Front Tyre Size:** 120/70 R17 **Rear Tyre Size:** 180/55 R17  
**Front Left Side:** Metzeler 7 mm **Rear Left Side:** Metzeler 7 mm  
**Front Right Side:** 0 mm **Rear Right Side:** 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	30,368.10	21,062.00	9,306.10	30.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,090.00	1,215.00	875.00	41.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>32,458.10</b>	<b>22,277.00</b>	<b>10,181.10</b>	<b>31.37</b>

### INSPECTION

**Date of Assignment:** 09/03/2018  
**Date Inspected:** 12/03/2018 **Inspected At:** Erofia Motor Trading Pte Ltd - (kaki Bukit) (HQ)  
1 Kaki Bukit Avenue 6, #02-62 AutoBay @ Kaki Bukit  
Singapore 417883  
**Estimated Period of Repair:** 0.0 days

**Adjuster:** MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



Market Value : \$18,000.00

LTA Reimbursement Value(RV) : \$4,600.00

Nett Value : \$13,400.00

IN VIEW OF THE ABOVE, THE VEHICLE IS UNECONOMICAL TO BE REPAIRED.

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	(Last Synchronised: 27 Apr 2018)	
<b>Parts:</b>	N/A	KAWASAKI VERSYS 649cc 650 M (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for FBK4190B)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Cracked	380.00 FL	*380.00 FL
2	1		*FRONT FENDER INNER BRACKET	No such part	509.00 FL	*- FL
3	1		*FORK TUBE ASSY -L/H	Bent Twisted	1,732.00 FL	*1,732.00 FL
4	1		*FORK TUBE ASSY -R/H	Bent / Twisted	1,732.00 FL	*1,732.00 FL
5	1		*FORK UPPER BRACKET	Cracked	600.00 FL	*600.00 FL
6	1		*FORK UNDER BRACKET	Bent	609.00 FL	*609.00 FL
7	1		*FRONT RIM SHAFT	Bent	75.00 FL	*75.00 FL
8	2		*FRONT BRAKE DISCS	Bent	1,218.00 FL	*1,218.00 FL
9	1		*FRONT SPORT RIM	Broken	1,950.00 FL	*1,950.00 FL
10	1		*WINDSHIELD	Grazed	450.00 FL	*450.00 FL
11	1		*WINDSHIELD BRACKET	Repair	1,800.00 FL	*- FL
12	1		*WINDSHIELD OUTER COVER	Not Necessary	250.00 FL	*- FL
13	1		*HEADLAMP	Broken	1,350.00 FL	*1,350.00 FL
14	2		*SIDE MIRRORS	Grazed	700.00 FL	*700.00 FL
15	1		*HANDLE BAR	Bent	285.00 FL	*285.00 FL
16	2		*HANDLE BAR ENDS	Scratched	120.00 FL	*120.00 FL
17	1		*SET HAND GRIP	Not Necessary	120.00 FL	*- FL
18	1		*CLUTCH LEVER	Cracked	155.00 FL	*155.00 FL
19	1		*BRAKE LEVER	Cracked	155.00 FL	*155.00 FL
20	2		*FRONT SIGNALS	Bracket torn	440.00 FL	*440.00 FL
21	1		*FRONT FAIRING	Broken	800.00 FL	*800.00 FL
22	2		*FRONT SIDE COVERS -INNER	Cracked	320.00 FL	*320.00 FL
23	2		*FRONT FAIRING LOWER INNER COVERS	Cracked	360.00 FL	*360.00 FL
24	1		*AIR INTAKE TUBES	O/S Cracked	360.00 FL	*180.00 FL
25	2		*SIDE OUTER FAIRINGS	Cracked	1,100.00 FL	*1,100.00 FL
26	2		*SIDE INNER FAIRINGS	Cracked	1,476.00 FL	*1,476.00 FL
27	1		*SIDE LOWER FAIRINGS	N/S Not Necessary / O/S Cracked	910.00 FL	*455.00 FL
28	1		*METER ASSY	Not Necessary	1,478.00 FL	*- FL
29	1		*METER PEDAL	Not Necessary	247.00 FL	*- FL
30	1		*RADIATOR	Dented	1,848.00 FL	*1,848.00 FL
31	1		*ENGINE COVER-R/H	Cut	280.00 FL	*280.00 FL
32	1		*FRONT FOOTRESTS	N/S Cut	220.00 FL	*110.00 FL
33	2		*FRONT FOOTREST BRACKETS	Not Necessary	330.00 FL	*- FL
34	1		*GEAR PEDAL	Bent	185.00 FL	*185.00 FL
35	1		*BRAKE PEDAL	Bent	175.00 FL	*175.00 FL
36	2		*REAR FOOTREST	Cut	170.00 FL	*170.00 FL
37	2		*REAR FOOTREST BRACKETS	Not Necessary	560.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
38	1		*FUEL TANK	Repair	1,820.00 FL	*- FL
39	1		*EXHAUST PIPE	Dented	1,550.00 FL	*1,550.00 FL
40	1		*EXHAUST PIPE COVER	Distorted	120.00 FL	*120.00 FL
41	2		*SIDE PANELS	Repair	220.00 FL	*- FL
42	1		*KEY SWITCH ASSY	Not Necessary	580.00 FL	*- FL
43	2		*FRONT BRAKE PUMPS -LOWER	Not Necessary	1,100.00 FL	*- FL
44	1		*MAGNET COIL COVER	Cut	450.00 FL	*450.00 FL
45	1		*MAGNET COIL COVER GASKET	Necessary	50.00 FL	*50.00 FL
46	1		*RADIATOR FAN	Cracked / Jammed	350.00 FL	*350.00 FL
47	1		*FRONT INNER FAIRING	No such part	350.00 FL	*- FL
48	1		*ENGINE COVER GASKET	Necessary	80.00 FL	*80.00 FL
49	1		*SET NUMBER PLATE	Necessary	28.00 FS	*10.00 FS
50	1		*FORK OIL	Necessary	20.00 FS	*20.00 FS
51	1		*FORK OIL SEAL	Necessary	38.00 FS	*38.00 FS
52	1		*COOLANT	Necessary	35.00 FS	*35.00 FS
53	1		*SET STEERING CONE	Necessary	180.00 FS	*180.00 FS
54	1		*FRONT TYRE (70%)	Punctured	200.00 FS	*140.00 FS
55	1		*ENGINE OIL (50%)	Necessary	60.00 FS	*30.00 FS
56	1		*REAR BOX	Cracked	500.00 FS	*400.00 FS
57	1		*REAR BOX BRACKET	Cracked	400.00 FS	*400.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (S\$) **33,580.00**    **23,263.00**  
 - List Item Discount on L Items 10.00/10.00% (S\$)    3,211.90    2,201.00

Total Parts (S\$) **30,368.10**    **21,062.00**

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO PROVIDE TOWING SERVICE	New	80.00	35.00
2	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
3	TO PROVIDE LABOUR	New	480.00	380.00
4	TO RESPRAY PAINTING	New	1,000.00	500.00
5	TO CHECK ,REPAIR AND STRAIGHTEN BODY FRAME	New	450.00	300.00
Gross Labour Cost (S\$)			<b>2,090.00</b>	<b>1,215.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >