

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/03/2018 19:43
Date Of Accident	09/03/2018 14:50
Exact Location Of Accident	ALONG BEACH ROAD BEFORE GOLDENMILE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLV7500U
Insured/Policyholder	
Name Of Registered Owner	TAN BENG CHUA
NRIC No	S1289599B
Email Address	TANBC@SRC.COM.SG
Mobile Phone No	(LOCAL) +65-93822358
Alternative Phone No	OFFICE-93822358

Vehicle Particulars

Manufacturer	BMW
Model	520I 2.0L AT D/AB 2WD 4DR GAS/D NAV
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPPHQ18-001067
Cover Note Number	

Driver

Name of Driver	TAN BENG CHUA
NRIC No	S1289599B
Date Of Birth	10/11/1958
Occupation	INDOOR
Date Of Driving Pass	17/01/1981
Driving Experience	37 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-93822358
Fax Number	
Contact Number	OFFICE-93822358
EEmail Address	TANBC@SRC.COM.SG

Address	APT BLK 855 TAMPINES STREET 83 #11-258 SINGAPORE 820855
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : JESSIE TAN
	GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS TRAVELLING ON BEACH ROAD TOWARDS GOLDEN MILE SHOPPING CENTRE. I WAS DRIVING BEHIND VEHICLE SLU7932L ON THE CENTRE LANE AND AFTER WE HAVE PASSED THE BEACH ROAD AND OPHIR ROAD TRAFFIC JUNCTION AND AS BOTH OF OUR VEHICLE WAS GRADUALLY PICKING UP SPEED (BEFORE ARAB STREET) , SUDDENLY THE FRONT VEHICLE SLU 7932L CAME TO COMPLETE STOP, UPON SEEING THIS I IMMEDIATELY PUT ON MY EMERGENCY BRAKES. UNFORTUNATELY MY IMMEDIATE REACTION WAS NOT ABLE TO PREVENT A SLIGHT CONTACT WITH THE FRONT CAR SLU7932L REAR BUMPER. DAMAGE ACCESS ON SITE: SLU 7932L: SLIGHT DENT ON THE REAR BUMPER SLV 7500U : 1) LEFT SIDE FRONT NUMBER PLATE DISLODGE (SCREW CAME OFF) 2) RIGHT SIDE FRONT GRILL PANEL SLIGHT CRACK SLU 7932L DRIVER PARTICULARS: MS KWA LAY SAN JOANNE (GRAB DRIVER) I/C S7528050E

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLU7932L
Vehicle Make/Model/Colour	TOYOTA/ C-HR HYBRID 1.8S CVT/BLACK
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	KWA LAY SAN JOANNE
NRIC/Passport Number	S7528050E
Contact Number	

Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Sketch Plan

2. This Form must be completed by the driver of the vehicle involved in the accident.
3. Information provided on this Form is for the use of the insurance companies and is not an admission of policy liability on the part of insurance companies.
4. The issue and acceptance of this Form by the insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting on this Form is a criminal offence under the Police for investigation.
6. The report will be forwarded to the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


VERIFIED BY AJAX MARS
REPORTING OFFICER
MOHAMMAD SULHANDI BIN
MOHD AFFANDI

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre
Personnel

Sketch Plan



Common Statement

Mr Tan Beng Chua Desmond

IC : S1289599B

Vehicle No : SLV 7500 U

Date : 09/03/2018

Time : 1450hrs

Accident Report :

I was travelling on Beach road towards Golden mile shopping centre.

I was driving behind vehicle SLU 7932 L on the centre lane and after we have passed the Beach road and Ophir road traffic junction and as both of our vehicle was gradually picking up speed (before ARAB street) , suddenly the front vehicle SLU 7932L came to a **complete stop** , upon seeing this I immediately put on my emergency brakes. Unfortunately my immediate reaction was not able to prevent a slight contact with the front car SLU 7932 L rear bumper.

Damage access on site :

SLU 7932 L : Slight dent on the rear bumper

SLV 7500 U : 1) Left side Front number plate dislodge (screw came off)

2) Right side Front grill panel slight crack

SLU 7932 L Driver Particulars :

Ms KWA LAY SAN JOANNE (GRAB Driver)

I/C S7528050E

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Identification Card

REPUBLIC OF SINGAPORE **DRIVING LICENCE**



Licence Number: **S1289599B**
Name: **TAN BENG CHUA**

Birth Date: **10 Nov 1958**
Issue Date: **28 Dec 2002**



000070375C

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1289599B



Name: **TAN BENG CHUA**

陈 炳 全

Race: **CHINESE**

Date of birth: **10-11-1958** Sex: **M**

Country of birth: **SINGAPORE**



Identification Card

