

22/03/2002

ASS. REC. BY:

REF: CS/TMI18004620/K1/d3

Special Instruction:

Surveyor:
Mehmet

Kelvin

ASSIGNMENT (Office)

From (Person):

Zheng Han yong

of

TMI

Date/Time:

12/3/18 @ 11:07am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SH 9101R

Insured:

SDA 779J

at Workshop m/s

Comfort Delgro

Tel:

6214 8300

of

Sg Layang Drive

Policy No:

MX006408

Claim No:

M1801320

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

09/03/2018

CA / REV / REP. / REV 24 HRS

wp?

H.O.D. Endorsement:

Date/Time:

11:37am @ 12/3/18

Person Contacted:

Vehicle

IN/OUT

Date/Time

Action/Instruction

() Estimate

SH 9101R - CC3/ICS17012404/Gra3q2

D.O.A: 23/6/17

SDA 779J - CC3/TMI15020006/Kvbnd

D.O.A: 19/11/2015

Surve: Kalvin

ASSIGNMENT

From: _____ Date: _____

Estimate Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Insp Vehicle No: _____

at Work Shop m/s _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SH 9101R Yr Regn: 29 Oct / 2015

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai 240 c.c. 1685

Colour: Blue A/C: Insured Std / NI / NA

Sp. Reading: 378455 T/Radio: Insured Std / NI / NA

Eng/No: _____

C/No: KMHLB414M64079830

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Insured / Jammed / Leaked / Burnt or

Brake: Insured / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size: F: 205/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Ward/Le - Rear

Front HeonKok - Front.

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 9/3/18 D.O.I. 12/3/18

Survey held at CDGE (Loyang)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>14/3/18</u>	<u>Confirmed P/P \$1296.18 / 2 Hrs.</u>
	<u>(Red: 144.60 / 52%)</u>
	<u>To Kio</u>
	<u>P/P</u>

Date/Time, File Pass to?

1) 15B Typist

Date/Time, File Return to?

2) _____

☐ : Preli. Report
☒ : Final Report

Days Of Repair: 2

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Test (In/Out) (\$ _____)

Survey Fee: 250

Transportation: _____

S + RS, SI

Photos

Other

<u>250</u>
<u>10</u>

TP

0

1296.18

260

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Mar 2018 Sendback Est	10 Mar 2018 11:10 S\$4,446.00	12 Mar 2018 11:07 Assign				New Assignment Cancel Case
Supp #1	10 Mar 2018 11:37 Sendback Est	10 Mar 2018 11:42 S\$2,710.78	12 Mar 2018 11:07 Assign			Combine Suppl.	New Assignment Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

Insured:	YEUNG KOON SANG, ID: S2196747E		
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R		
Vehicle Reg. No.:	SH9101R	Date of Loss:	09/03/2018 15:00 - :59
Claim Type:	TP / M1801320	Policy/Cover Note No.:	MX006408 (Comprehensive) Coverage: 10/09/2017 - 09/09/2018
Vehicle Reg. No. (Insured):	SDA779J	Policy No. (Claimant):	MCOM0015
		Excess:	S\$2,000.00
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300		
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Zheng Hanyang - 65926416]		
Claimant's Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 21/03/2018]		
Driver/Custodian (Insured):	YEUNG KOON SANG (68 / Male), NRIC: S2196747E		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
TOKIO MARINE INSURANCE SINGAPORE LTD		Ref : CS/TMI18004620/K1td3		
20 MCCALLUM STREET #09-01 TOKIO MARINE CENTRESINGAPORE 069046		Date : 12-03-2018		
		Code : TMI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SDA 779J	Veh. Inspected	SH 9101R	
Policy No.	MX006408	Coverage (\$)	0.00	
Claim No.	M1801320	Excess (\$)	0.00	
Assign From	MERIMEN (ZHENG HAN YANG)	Assign Date	12/03/2018	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	09/03/2018	Inspection Date	12/03/2018	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

T/MARINE/LKK

(SUPPLEMENTARY)

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)

COMFORT TRANSPORTATION PTE LTD

Singapore

*Front tyre - Han/kuk
Rear tyre - West/oke.*

Claimant Insurer: India International Insurance Pte Ltd

PARTICULARS OF CLAIM

Claim Type: THIRD PARTY

Policy No:

Vehicle Reg. No.: SH9101R

Party At Fault: UNKNOWN

Driver (TP): CHEONG KIN WENG

Ref. No:

Date of Loss: 09/03/2018

Driveable? NO

Make/Model: HYUNDAI I40, 1.7 D CRDI (A)

Vehicle Reg. Date: 25/07/2013

Vehicle Colour: WHITE

Gen Condition: FAIR

Engine No: 65192431502427

Chassis No: WDD2120022A757386

Odometer: 200000 KM

Paint Type:

List Item 20.00 %

Discount:

Total Loss? NO

Est. Duration of 6

Repair (day)

Description of Accident/Loss REFER ATTACHED

Remarks: CANCEL 1ST, ESTIMATE WRONG AMOUNT

Present Location: COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)

COST OF CLAIMS

	Amount
Parts	1,750.78
Miscellaneous Items	0.00
Labour	960.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	2,710.78
+ GST 7.00% (S\$)	189.75
Nett Amount (S\$)	2,900.53
+ Previous Estimates (S\$)	4,757.22
Claim Total (S\$)	7,657.75

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 3809660

JC NO: 305123595

TOMER COMFORT TRANSPORTATION PTE LTD MS 7010045 TOMER NO 383 SIN MING DRIVE RESS Singapore SINGAPORE 575717 65508755 (R) (O) (P)		REGN NO SH 9101R MAKE HYUNDAI MODEL T-40 YR OF MANU 29.10.2015 CHASSIS CODE KMHLE41UMGU079830	MILEAGE FUEL E.....1/2.....F DATE/TIME IN 09.03.2018 16:35 TARGET DATE COMPLETION DATE/TIME:
---	--	---	---

Accident Date: 09.03.2018
ATURE: 3P 09.03.18/B-

JOB DESCRIPTION

/NO LABOR CODE DESCRIPTION

WORKED & PASSED OUT BY:

SERVICE ADVISOR CUSTOMER'S SIGNATURE

pledgement Slip

Exit Pass

No.: SH 9101R FZ T-MARINE

Vehicle No.: SH 9101R

f Service Advisor Signature/Date

Name of Service Advisor Date

turned to Service Reception upon collection

To be kept by Security Guard

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/03/2018 08:28
Date Of Accident	09/03/2018 15:35
Exact Location Of Accident	BRADDELL RD TWDS TOA PAYOH NEAR SLIP RD FROM CTE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SH9101R
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	

Driver

Name of Driver	CHEONG KIN WENG
NRIC No	S0053819A
Date Of Birth	19/12/1953
Occupation	OUTDOOR
Date Of Driving Pass	20/12/1974
Driving Experience	43 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 85C LORONG 4 TOA PAYOH #07-370
Postcode	313085
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SDA779J
Vehicle Make/Model/Colour	LEXUS
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	UNKNOWN
NRIC/Passport Number	
Contact Number	97409845
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	FRONT LH
No. Of Passenger (Including Driver)	

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

07/03/18
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

As per attached.

DECLARATION

I/We declare the foregoing particulars are true in every respect.
COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SIARMC SketchPlanForm_V3

Describe Circumstances of the Accident.

On 09 Mar 2018 at about 15:35 hrs I was driving straight on the left lane along Braddell Rd heading towards Comfort Delgro workshop.

As I approached the slip road from CTE I saw an unknown car drove out from the slip road hence I slowed down to give way to the car.

Suddenly a Lexus car SDA779J came from behind collided onto the Rear Portion of my taxi.

No passenger on board my taxi. No injury at the point of the accident.

Enclosed is a video footage to support my claims.

Declaration

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature/Date &
Time

Driver's Signature (If driver is not the policyholder) / Date
& Time

Witnessed by Reporting
Centre Personnel

COMFORTDELGRO ENGINEERING

Our Job Ref No : 305123595
Date : 13.03.2018

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : KALVIN

Vehicle Reg No. : SH 9101R

Date of Accident : 09.03.2018

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: TOKIO MARINE — SDA 779J
2. The finalized amount shall be:
 - (a) Spare Parts after List discount \$866.18
 - (b) Labour Charges \$430.00
 - Total for Part-By-Part Repair Cost** \$1,296.18
 - (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20% \$0.00
Final Lumpsum Repair cost \$0.00

3. Estimated normal period for repairs: 2 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.


We confirm the estimates and finalized amount

Signature : 

Name : FAUZY BIN MOKHTAR

Tel : 62148319

Fax : 65468156

Signature : 

Name : Kelvin

Date : 14/3/18

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305123595
REGN NO : SH 9101R
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 29.10.2015
DATE/TIME IN : 09.03.2018 16:35
ACCIDENT DATE : 09.03.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-0579-G	I40VC COVER ASSY-RR BUMPE	1	603.60	20.00	482.88
0002	04-01-0103-0738-G	I40VC COVER-RR BUMPER LWR	1	225.00	20.00	180.00
0003	04-01-0101-0111-A	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60
0004	09-01-9999-0068-A	HYUNDAI REVERSE SENSOR AS	1	135.70	2.00-	135.70
0005	04-01-0103-1150-A	I40VC PROTECTOR MAT	1	50.00	0.20	50.00

SUB-TOTAL : 866.18

JOB NATURE

0000 L	PANEL BEATING	220.00
0001 L	SPRAY PAINTING CHARGE	180.00
0002 L	REMOVE/REFIX REVERSE SENSOR	20.00
0003 L	MERIMEN FEE	10.00

SUB-TOTAL : 430.00

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305123595
REGN NO : SH 9101R
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 29.10.2015
DATE/TIME IN : 09.03.2018 16:35
ACCIDENT DATE : 09.03.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 1,296.18

MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO

REPAIR DETAILS**Reference**

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 10 Mar 2018)

Parts: 143 **HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)**

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SH9101R/10/03/2018 11:42

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER <i>Actual</i>	20.00	0.00	*603.60 FL
2	1		*REAR BUMPER REINFORCEMENT <i>Xsu</i>	20.00	0.00	*504.35 FL
3	1		*REAR BUMPER REINFORCEMENT BRACKET RH <i>Xsu</i>	20.00	0.00	*180.00 FL
4	1		*REAR BUMPER REINFORCEMENT BRACKET LH <i>Xsu</i>	20.00	0.00	*180.00 FL
5	1		*REAR BUMPER SPONGE <i>Xsu</i>	20.00	0.00	*143.40 FL
6	1		*REAR BUMPER UNDER COVER <i>cut</i>	20.00	0.00	*225.00 FL
7	10		*REAR BUMPER CLIPS <i>nee</i>	20.00	0.00	*22.00 FL
8	1		*REAR BUMPER SIDE BRACKET LH <i>Xsu</i>	20.00	0.00	*49.00 FL
9	1		*REAR BUMPER SIDE BRACKET RH <i>Xsu</i>	20.00	0.00	*49.00 FL
10	1		*REAR BUMPER REVERSE SENSOR <i>shorted</i>	0	0.00	*135.70 FS
11	1		*REAR BUMPER RUBBER MAT <i>nee</i>	0	0.00	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,142.05
- List Item Discount on L Items (\$\$)	391.27
Total Parts (\$\$)	1,750.78

ComfortDelGro Engineering Pte Ltd/SH9101R/10/03/2018 11:42. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			220
1	PANEL BEATING	New	400.00
2	SPRAY PAINTING CHARGE	New	400.00 180
3	WIRING CHARGE	New	30.00 X 1"
4	REMOVE / REFIX REVERSE SENSOR	New	120.00 20
5	MERIMEN FEE	New	10.00 +
Gross Labour Cost (S\$)			960.00

ComfortDelGro Engineering Pte Ltd/SH9101R/10/03/2018 11:42. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Ka Li (KK)
 12/3/18 1040 hrs.
 2 Pys
 PIP
 Before Part pLb

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 10 Mar 2018)
Parts: 143 HYUNDAI I40 1.7 D CRDI (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: ComfortDelGro Engineering Pte Ltd/SH9101R/10/03/2018 11:10
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER	20.00	0.00	*1,510.00 FL
2	1		*REAR BUMPER BRACKET LOWER LH	20.00	0.00	*135.00 FL
3	1		*REAR BUMPER BRACKET LOWER RH	20.00	0.00	*135.00 FL
4	1		*REAR BUMPER BRACKET TOP LH	20.00	0.00	*125.00 FL
5	1		*REAR BUMPER BRACKET TOP RH	20.00	0.00	*125.00 FL
6	1		*REAR BUMPER RETAINER LH	20.00	0.00	*115.00 FL
7	1		*REAR BUMPER RETAINER RH	20.00	0.00	*115.00 FL
8	1		*REAR RH RIM	0	0.00	*1,248.00 FS
9	1		*REAR RH TYRE	0	0.00	*480.00 FS

} wrong estimate.

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,988.00
- List Item Discount on L Items (\$\$)	452.00
Total Parts (\$\$)	3,536.00

ComfortDelGro Engineering Pte Ltd/SH9101R/10/03/2018 11:10. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1 1 OD/TP Case (Insurer)

10.00

3 wrong estimate

Sub Total (S\$)

10.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1 PANEL BEATING

New

400.00

2 SPRAY PAINTING CHARGE

New

400.00

3 WIRING CHARGE

New

50.00

4 REMOVE / REFIX RIM AND TYRE WITH BALACING

New

50.00

} wrong estimate

Gross Labour Cost (S\$)

900.00

ComfortDelGro Engineering Pte Ltd/SH9101R/10/03/2018 11:10. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 Mar 2018 Sendback Est	10 Mar 2018 11:10 S\$4,446.00	12 Mar 2018 11:07 Edit Adj Rpt	S\$1,296.18 Edit Estimates	S\$1,296.18 View Rpt		Pending for Survey Report Cancel Case
Supp #1	10 Mar 2018 11:37	10 Mar 2018 11:42 S\$2,710.78	12 Mar 2018 11:07			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	YEUNG KOON SANG , ID: S2196747E		
Main Claimant:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R		
Vehicle Reg. No.:	SH9101R	Date of Loss:	09/03/2018 15:00 - :59
Claim Type:	TP / M1801320	Policy/Cover Note No.:	MX006408 (Comprehensive) Coverage: 10/09/2017 - 09/09/2018
Vehicle Reg. No. (Insured):	SDA779J	Policy No. (Claimant):	MCOM0015
		Excess:	S\$2,000.00
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300		
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Zheng Hanyang - 65926416]		
Claimant's Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KALVIN ANG WEI KUN] ... [Final Rpt due 21/03/2018]		
Driver/Custodian (Insured):	YEUNG KOON SANG (68 / Male), NRIC: S2196747E		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SH9101R (M1801320)
[SDA779J]
TP
COMFORT TRANSPORTATION PTE LTD
Mar 9 2018 3:00PM
[YEUNG KOON SANG]
ComfortDelGro Engineering Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	10/03/18 11:10	Repairer Estimates	Load HTM	
2	10/03/18 11:42	Repairer Estimates Suppl. #1	Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/03/18 17:41	General View	Load JPG	<input checked="" type="checkbox"/>
2	12/03/18 17:41	General View	Load JPG	<input checked="" type="checkbox"/>
3	12/03/18 17:41	General View	Load JPG	<input checked="" type="checkbox"/>
4	12/03/18 17:41	General View	Load JPG	<input checked="" type="checkbox"/>
5	12/03/18 17:41	General View	Load JPG	<input checked="" type="checkbox"/>
6	12/03/18 17:41	General View	Load JPG	<input checked="" type="checkbox"/>
7	12/03/18 17:41	General View	Load JPG	<input checked="" type="checkbox"/>
8	12/03/18 17:41	General View	Load JPG	<input checked="" type="checkbox"/>
9	12/03/18 17:41	General View	Load JPG	<input checked="" type="checkbox"/>
10	12/03/18 17:41	General View	Load JPG	<input checked="" type="checkbox"/>
11	12/03/18 17:41	General View	Load JPG	<input checked="" type="checkbox"/>
12	12/03/18 17:41	General View	Load JPG	<input checked="" type="checkbox"/>
13	12/03/18 17:41	General View	Load JPG	<input checked="" type="checkbox"/>
14	12/03/18 17:41	General View	Load JPG	<input checked="" type="checkbox"/>
15	12/03/18 17:41	General View	Load JPG	<input checked="" type="checkbox"/>
16	12/03/18 17:41	General View	Load JPG	<input checked="" type="checkbox"/>
17	12/03/18 17:41	General View	Load JPG	<input checked="" type="checkbox"/>
18	12/03/18 17:41	General View	Load JPG	<input checked="" type="checkbox"/>
19	12/03/18 17:41	General View	Load JPG	<input checked="" type="checkbox"/>
20	13/03/18 17:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
21	13/03/18 17:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
22	13/03/18 17:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

^

v

Show Remarks To:

☐ Repairer

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI18004620/K1TD3E2

Date: 19/03/2018

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd

Policy No: MX006408

Claimant Vehicle No : SH9101R

Insured Vehicle No : SDA779J

Date of Loss: 09/03/2018

Nature of Claim: TP

Claim No: M1801320

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SH9101R

Make & Model: HYUNDAI I40, 1.7 D CRDi (A)

Engine No: D4DFU553476

Reg. Date: 29/10/2015 (Man. Year: 2015)

Chassis No: KMHLB41UMGU079830

Colour: Blue

Odometer: 378455 km

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

Average

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size: 205/60 R16

Front Left Side: Hankook 7 mm

Rear Left Side: West Lake 7 mm

Front Right Side: Hankook 7 mm

Rear Right Side: West Lake 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,286.78	866.18	4,420.60	83.62
Miscellaneous Items	10.00	10.00	0.00	0.00
Labour	1,860.00	420.00	1,440.00	77.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,156.78	1,296.18	5,860.60	81.89
+ GST 7.00/7.00% (S\$)	500.97	90.73	410.24	81.89
Nett Amount (S\$)	7,657.75	1,386.91	6,270.84	81.89

INSPECTION

Date of Assignment: 12/03/2018 Present Location:

ComfortDelGro Engineering Pte Ltd
(Loyang)

Date Inspected: 12/03/2018 Inspected At:

59 Loyang Drive
Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: KALVIN ANG WEI KUN

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 19 Mar 2018)
Parts: 143 HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SH9101R)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	No Estimate	1,510.00 FL	*- FL
2	1		*REAR BUMPER BRACKET LOWER LH	No Estimate	135.00 FL	*- FL
3	1		*REAR BUMPER BRACKET LOWER RH	No Estimate	135.00 FL	*- FL
4	1		*REAR BUMPER BRACKET TOP LH	No Estimate	125.00 FL	*- FL
5	1		*REAR BUMPER BRACKET TOP RH	No Estimate	125.00 FL	*- FL
6	1		*REAR BUMPER RETAINER LH	No Estimate	115.00 FL	*- FL
7	1		*REAR BUMPER RETAINER RH	No Estimate	115.00 FL	*- FL
8	1		*REAR RH RIM	No Estimate	1,248.00 FS	*- FS
9	1		*REAR RH TYRE	No Estimate	480.00 FS	*- FS
Supplementary #1						
10	1		*REAR BUMPER	Deformed	603.60 FL	*603.60 FL
11	1		*REAR BUMPER REINFORCEMENT	Serviceable	504.35 FL	*- FL
12	1		*REAR BUMPER REINFORCEMENT BRACKET RH	Serviceable	180.00 FL	*- FL
13	1		*REAR BUMPER REINFORCEMENT BRACKET LH	Serviceable	180.00 FL	*- FL
14	1		*REAR BUMPER SPONGE	Serviceable	143.40 FL	*- FL
15	1		*REAR BUMPER UNDER COVER	Cut	225.00 FL	*225.00 FL
16	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
17	1		*REAR BUMPER SIDE BRACKET LH	Serviceable	49.00 FL	*- FL
18	1		*REAR BUMPER SIDE BRACKET RH	Serviceable	49.00 FL	*- FL
19	1		*REAR BUMPER REVERSE SENSOR	Shorted	135.70 FS	*135.70 FS
20	1		*REAR BUMPER RUBBER MAT	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,130.05	1,036.30
- List Item Discount on L Items 20.00/20.00% (\$\$)	843.27	170.12
Total Parts (\$\$)	5,286.78	866.18

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer) (No Estimate)	10.00	10.00
Sub Total (S\$)			10.00	10.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING (No Estimate)	New	400.00	0.00
2	SPRAY PAINTING CHARGE (No Estimate)	New	400.00	0.00
3	WIRING CHARGE (No Estimate)	New	50.00	0.00
4	REMOVE / REFIX RIM AND TYRE WITH BALACING (No Estimate)	New	50.00	0.00
Supplementary #1				
Labour Items				
5	PANEL BEATING	New	400.00	220.00
6	SPRAY PAINTING CHARGE	New	400.00	180.00
7	WIRING CHARGE	New	30.00	0.00
8	REMOVE / REFIX REVERSE SENSOR	New	120.00	20.00
9	MERIMEN FEE	New	10.00	0.00
Gross Labour Cost (S\$)			1,860.00	420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >