

08/11/13 wef

ASS. REC. BY: Marcus

REF:

CS/TP 18004643/Urbn2

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SK4921PP

at Workshop m/s: Ry.

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 14800

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: 9 Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

9/11/2018  
Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SK4921PP Yr Regn: 11/08

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA

Make: Honda airwave c.c. 1496

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 138559 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: GJ11301196

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: \_\_\_\_\_

R: 185/65R14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 Rear 6

R/Bal. \_\_\_\_\_ mm R/Bal. \_\_\_\_\_ mm

L/Bal. \_\_\_\_\_ mm L/Bal. \_\_\_\_\_ mm

D.O.A. 9/3/18 D.O.I. 12/3/18

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Ry.

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>20/3/18</u>	<u>n.g L7A 6825 met 7978</u> <u>confirmed n/s @ 7800 with Alan. (Reel 8793-72, 5370)</u>

RECEIVED 22 MAR 2018

Date/Time, File Pass to?  : Preli. Report  : Final Report

1) \_\_\_\_\_

Date/Time, File Return to? 20/3- typist

2) \_\_\_\_\_

Report Format : TP

Lump Sum / I.B.I: (\$ 7800)

Days Of Repair: 6

Resurvey No. of Trip: 2

Add Fee:  : Site Insp (\$ \_\_\_\_\_)  : Interview (\$ \_\_\_\_\_)  : Tech. Invs (\$ \_\_\_\_\_)  : Weekend (\$ \_\_\_\_\_)

Survey Fee:	<u>6x15=90</u>
Transportation:	<u>170+90</u>
S + RS, SI	<u>50</u>
Photos	<u>50+50</u>
Others	<u>94</u>
	<u>80</u>
TOTAL	<u>584</u>

Ref. No :	CS/TP 18004643/UMB <sup>02</sup>	Res. Date:	1/3/18	Date Received:	
Veh. No :	SKU 9287	SP:		WKSP:	<i>[Signature]</i>
C/No :					
<b>Action/Instruction:</b>					
1. File	2. Submit Photo?	YES / NO		Message:	
3. Indicate Res. Date On Photo Page?	YES / NO				
If No, due to	a) No authorisation	b) Days of repair			
others:	<i>[Handwritten mark]</i>				
Final Re-inspection	or	Progress Photos	Inspected By: <i>[Signature]</i>		



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		Ref : CS/TP18004643/Uvb  Date : 12-03-2018  Code : TP130	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	Veh. Inspected	SKU 9218P	
Policy No.	Coverage (\$)	0.00	
Claim No.	Excess (\$)	0.00	
Assign From	Assign Date	12/03/2018	
2. Vehicle Particulars & Condition			
Make & Model	c.c	0	
Engine No. HIDDEN	Year of Reg.		
Chassis No.	Colour		
Odometer	Steering		
Brakes	Modification		
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	09/03/2018	Inspection Date	12/03/2018
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	11/03/2018 09:40
Date Of Accident	09/03/2018 17:00
Exact Location Of Accident	PASIR RIS INDUSTRIAL DRIVE 1
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKU9218P
<b>Insured/Policyholder</b>	
Name Of Registered Owner	ISA BIN AHMAD
NRIC No	S0984207A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-94560161
Alternative Phone No	OTHERS-94560161

### Vehicle Particulars

Manufacturer	HONDA
Model	AIRWAVE 1.5M A
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5076311339-01
Cover Note Number	

### Driver

Name of Driver	ISA BIN AHMAD
NRIC No	S0984207A
Date Of Birth	21/07/1954
Occupation	INDOOR
Date Of Driving Pass	03/05/1978
Driving Experience	39 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94560161
Fax Number	
Contact Number	OTHERS-94560161
EEmail Address	NOEMAIL

Address	BLK 751 #11-68 PASIR RIS STREET 71
Postcode	510751
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ
Police Station Address	<b>ROAD:</b> 10 UBI AVENUE 3 , <b>POSTCODE:</b> 408865 , <b>COUNTRY:</b> SINGAPORE
Police Station Contact	<b>TEL NO:</b> 65470000 - <b>FAX NO:</b>
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

AS PER POLICE REPORT No.T/20180310/7001

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	MID33654
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	GOVERNMENT
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name	ISA BIN AHMAD
Approximate Age	63
Injuries Sustain	WHIPLASH.HEADACHE.BACK PAIN.NUMBNESS IN RIGHT LEG
Injured person in which vehicle?	SKU9218P
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	
Address	BLK 751 #11-68 PASIR RIS STREET 71
Postcode	510751

# Accident Sketch Plan Pg. 1

## SKETCH PLAN

### IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


  
\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

  
\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

**IDAC KAKI BUKIT(VAG)**  
23 KAKI BUKIT AVE 4  
Reporting Centre  
Name:   
Tel: 67416697  
NRIC/FIN No:   
Fax: 67492305  
Email: vackb@singnet.com.sg

Accident Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

RSEA Police Report.

Driver: ISA BIN AHMAD ID Whiplash.

① Headache.

② Back Pain.

③ Numbness in front leg.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
 Policyholder's Signature  
 Date & Time:

  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

**IDAC KAKI BUKIT (VAC)**  
 23 KAKI BUKIT AVE 4  
 Reporting Centre Personnel's Signature  
 Name: Tel: 67416697  
 NRIC/FIN No.: Fax: 67492305  
 Email: vackb@singnet.com.sg



Accident Sketch Plan Pg. 1



**SINGAPORE  
POLICE FORCE**



T/20180310/7001

Police Station Of Origin:  
Traffic Police Division HQ  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

2 of 3  
Report No. T/20180310/7001

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	ISA BIN AHMAD	ID No.	S0984207A
Related Vehicle	SKU9218P (Car)	Contact No.	94560161
Hospital/Clinic	CHANGI GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	09/03/2018	Date Discharge	09/03/2018
No. of Days granted Medical Leave	03	Degree of Injury	Slight

Brief Details.

I was driving alone along Pasir Ris Dr 1. When nearing the traffic junction between Pasir Ris Dr 1 and Pasir Ris Dr 12 the traffic light was green and proceed to drive straight. A MID vehicle no 33654 was coming from the opposite direction of Pasir Ris Dr 1 moving to make a right turn into Pasir Ris Dr 12. The said vehicle failed to make a stop to allow me to go straight as i have the right of way. It caused a collision between both vehicles inside the traffic junction. The side of MID vehicle had hit the front bonnet of my car causing some damages to the front bonnet.

The MID vehicle commander do admitted that I have the right of way as the traffic light was green and the MID driver should have stop to make way before proceeeding to turn right.  
Later Traffic police officers arrived at the site to facilitate in the investigation.

Accident Sketch Plan Pg. 1



**SINGAPORE  
POLICE FORCE**



T/20180310/7001

Police Station Of Origin:  
Traffic Police Division HQ  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

3 of 3

Report No. T/20180310/7001

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report: Not applicable
Signature Of Interpreter: Not applicable
Officer In Charge Of Case:

Authentication Stamp  
NP188

Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Date/Time: 10/03/2018 11:12
Classification Of Case:

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4207A
Vehicle Details	
Vehicle No.:	SKU9218P
Vehicle to be Exported:	No
Intended De-registration Date:	12 Mar 2018
Vehicle Make:	HONDA
Vehicle Model:	AIRWAVE 1.5M A
Primary Colour:	Black
Manufacturing Year:	2008
Engine No.:	L15A5201339
Chassis No.:	GJ11301196
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$16,755.00
Original Registration Date:	10 Nov 2008
First Registration Date:	10 Nov 2008
Transfer Count:	1
Actual ARF Paid:	\$12,203.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Nov 2018
PARF Rebate Amount:	\$6,101.00
Intended COE Rebate Details	
COE Expiry Date:	09 Nov 2018
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$10,989.00
COE Rebate Amount:	\$724.00
<b>Total Rebate Amount:</b>	<b>\$6,825.00</b>

The information contained herein is correct as at 12 Mar 2018

OK



honda airwave Price Range Depreciation 2008 Vehicle Type Submit

Advanced Search

Home » Used Cars » Millenia Motor » Honda Airwave 1.5A Skyroof

Resources

- Car Buying
- Car Selling
- Car Aftermarket
- Car Ownership
- On The Move
- Lifestyle

Vehicle Number Plates

Honda Airwave 1.5A Skyroof

Overview Financial Accessories Similar Research Photos Map

Add to Shortlist Add to Compare Add a Note Report Error More Actions Share

Car Details

<b>Price</b>	<b>\$11,700</b>	?
<b>Depreciation</b>	-	?
<b>Reg Date</b>	01-Sep-2008 (5mths 19days COE left)	
<b>Manufactured</b>	2007	?
<b>Mileage</b>	135,000 km (14.2k /yr)	
<b>Transmission</b>	Auto	
<b>Engine Cap</b>	1,496 cc	
<b>Road Tax</b>	\$682 /yr	?
<b>Power</b>	81.0 kW (108 bhp) View specs of the Honda Airwave (2008-2014)	
<b>Curb Weight</b>	1,180 kg	?
<b>Features</b>	1.5L I-VTEC Engine, CVT Automatic Transmission, SRS Airbags, ABS, Digital Auto Climatic Aircon, Skyroof.	
<b>Accessories</b>	Sports Rims, Leather Seats, Retractable Side Mirrors, Reverse Sensors, Audio Player, Knockdown Rear Seats, Solar Film.	
<b>Description</b>	Spacious Interior! Large Boot Space! Ideal For Daily Usage And Family! Trade In Welcome, Bank/In House Loan Available, Call Now For Viewing And Test Drive.	
<b>COE</b>	\$5,652	?
<b>OMV</b>	\$15,538	?
<b>ARF</b>	\$13,801	?
<b>Dereg Value</b>	\$7,167 as of today (change)	?
<b>No. of Owners</b>	2	?
<b>Type of Veh</b>	Stationwagon	
<b>Category</b>	PARF Car	
<b>Availability</b>	Available	

Add to Shortlist Add to Compare Add a Note

Posted on: 09-Mar-2018 | Last Updated on: 10-Mar-2018

Tags: Honda Airwave, 2008 Honda Airwave, Honda, Airwave, Used Honda



Seller Information

<b>Company</b>	Millenia Motor » dealer's pricelist » 36 vehs sold   15 vehs available
<b>Address</b>	160 Sin Ming Drive #07-05 Search cars nearby this location
<b>Location</b>	Sin Ming AutoCity
<b>Office No</b>	63520086
<b>Contact Person(s)</b>	Ricky 98469696

Useful Services

Upfront Payment [» more Financial info](#)

<b>Transfer Fee</b>	\$25	?
<b>Down Payment</b>	\$3,510 (change)	Maximum 70% Loan ?
<b>1st Instalment</b>	\$1,658	?

- Anyone selling nice car number plates
- For Hong Kong Movies lovers
- No Idling for cars






[Advanced Search](#)
[Home](#) > [Used Cars](#) > [SG Car Consign Pte Ltd](#) > [Honda Airwave 1.5A M](#)

## Resources

- [Car Buying](#)
- [Car Selling](#)
- [Car Aftermarket](#)
- [Car Ownership](#)
- [On The Move](#)
- [Lifestyle](#)

## Car Tyres



## Honda Airwave 1.5A M

[Overview](#)
[Financial](#)
[Accessories](#)
[Similar](#)
[Research](#)
[Photos](#)
[Map](#)
[CONSIGNMENT](#)
[Add to Shortlist](#)
[Add to Compare](#)
[Add a Note](#)
[Report Error](#)
[More Actions](#)
[Share](#)

## Car Details

<b>Price</b>	<b>\$12,900</b>	<a href="#">Share</a>
<b>Depreciation</b>	-	<a href="#">Email</a>
<b>Reg Date</b>	11-Sep-2008 (5mths 29days COE left)	<a href="#">?</a>
<b>Manufactured</b>	2008	<a href="#">?</a>
<b>Mileage</b>	144,000 km (15.2k /yr)	
<b>Transmission</b>	Auto	
<b>Engine Cap</b>	1,496 cc	
<b>Road Tax</b>	\$682 /yr	<a href="#">?</a>
<b>Power</b>	81.0 kW (108 bhp) View specs of the <a href="#">Honda Airwave (2008-2014)</a>	<a href="#">?</a>
<b>Curb Weight</b>	1,160 kg	<a href="#">?</a>
<b>Features</b>	Black Color. A 4 Cylinders SOHC Engine Powering 108Bhp On A Front Wheel Drive Setup Mated To A 5 Speed Automatic Gearbox With Safety ABS/SRS Airbag.	
<b>Accessories</b>	Factory Black Leather Upholstery Audio Player, Solar Film, Knockdown Rear Seats, Retractable Side Mirror And 15" Sports Rims.	
<b>Description</b>	If You Make Some Comparisons Amongst All The 2008 Honda Airwave, You'll Find That This Is Undeniably The Most Reasonably Priced Unit In Town Yet With A Tip Top Engine Condition. Previous Owner Considering To Take Public Transport Due To Cutting Down Overheads And Not Driving A Lot Recently. Beautiful Hatchback That Is Very Fuel Economical And Low Maintenance. Selling On Behalf Of Owner, Hence Please Call Before Viewing.	
<b>COE</b>	\$9,501	<a href="#">?</a>
<b>OMV</b>	\$13,380	<a href="#">?</a>
<b>ARF</b>	\$13,380	<a href="#">?</a>
<b>Dereg Value</b>	\$7,164 as of today (change)	<a href="#">?</a>
<b>No. of Owners</b>	1	<a href="#">?</a>
<b>Type of Veh</b>	Stationwagon	
<b>Category</b>	PARF Car, Consignment Car	
<b>Availability</b>	Available	<a href="#">CONSIGNMENT</a>

[Add to Shortlist](#)
[Add to Compare](#)
[Add a Note](#)

Posted on: 10-Jan-2018 | Last Updated on: 05-Mar-2018

 Tags: [Honda Airwave](#), [2008 Honda Airwave](#), [Honda, Airwave](#), [Used Honda](#)

## Owner Consignment Car

This car is for sale by direct owner via a consignment agent. Consignment agents help to market, sell and handle all documentation on the car seller's behalf.

- » [List of owner consignment cars](#)
- » [List of consignment agents](#)



## Seller Information

<b>Company</b>	SG Car Consign Pte Ltd » dealer's pricelist » 75 vehs sold   132 vehs available
<b>Address</b>	170 Upper Bukit Timah Road #01-28 <a href="#">Search cars nearby this location</a>
<b>Location</b>	Bukit Timah Shopping Centre
<b>Office No</b>	61000200
<b>Contact Person(s)</b>	Bryan Tan 91795745 Kelvin Liew 91509055

**FASTECH AUTO PTE LTD**

1 Kaki Buki 7 Ave 6 #01-48 Autobay  
Singapore 417883

Tel No:67452063/67467158 Fax No:67458520

Tex Reg No: 20-0006262-D

*Not Authorized  
2/5 @ 7800  
6 day.  
12/3/18*

VEH: SKU 9218P

QTY	PARTICULAR	AMOUNT
1PCS	BONNET <i>845.20</i>	<i>20/3uc</i> \$945.20 ✓
1PCS	BONNET CHROME MOULDING	<i>butlere</i> \$285.60 ✓
1PCS	BONNET LOCK	<i>twi</i> \$183.00 ✓
2PCS	BONNET HINGES @ \$92.50	<i>2</i> \$185.00 ✓
1PCS	BONNET INSULATOR	<i>11</i> \$188.20 X
1SET	BONNET INSULATOR CLIPS	<i>rec</i> \$40.00 ✓
1PCS	FRONT GRILLE	<i>one</i> \$190.60 ✓
1PCS	FRONT GRILLE LOGO	<i>rec</i> \$38.80 ✓
1PCS	FRONT GRILLE BASE	<i>one</i> \$240.50 ✓
2PCS	HEADLAMPS @1050.00 <i>868.70 x 2 = 1737.40</i>	<i>one</i> \$2,100.00 ✓
1PCS	HEADLAMP LOWER BRACKET N/S	<i>one/3uc</i> \$65.50 ✓
1PCS	FRONT BUMPER <i>945</i>	<i>715</i> \$1,380.00 ✓
1PCS	FRONT BUMPER CENTRE AIR GIRLLE	<i>twi</i> \$148.50 ✓
2PCS	FRONT BUMPER SIDE GIRLLE @\$55.00	<i>11</i> \$110.00 X
2PCS	FRONT BUMPER SIDE HOLDERS @38.50	<i>but</i> \$77.00 ✓
1PCS	FRONT BUMPER REINFORCEMENT	<i>Bert</i> \$282.90 ✓
1PCS	FRONT SUPPORT PANEL <i>822.30</i>	<i>but/twi</i> \$966.02 ✓
1PCS	AIR CON CONDENSER <i>1255.60</i>	<i>but/twi</i> \$1,385.00 ✓
1PCS	RADIATOR <i>1485.30</i>	<i>but/twi</i> \$1,886.00 ✓
1PCS	RADIATOR FAN ASSY	<i>11</i> \$295.00 X
1PCS	FRONT FENDER N/S	<i>but/3uc</i> \$665.30 ✓
1PCS	FRONT FENDER INNER SHIELD N/S	<i>11</i> \$182.60 X
1SET	FRONT FENDER INNER SHIELD CLIPS	<i>rec</i> \$38.00 ✓
1PCS	FRONT DOOR N/S	<i>2</i> \$1,105.00 X
		\$12,983.72
	S.NETT	
1PCS	FRONT LICENCE PLATE W/HOLDER	<i>520</i> \$50.00 ✓
1BOL	RADIATOR COOLANT	<i>rec</i> \$50.00 ✓

*207*

*9346.5  
7477.2*

TO CHECK WIRING	\$80.00	30
TO SPRAY RUST PROOFING	\$120.00	100
TO REFILL AIR CON GAS	\$150.00	100
TO CONDUCT WHEEL ALIGNMENT	^1 \$80.00	X
TO MOUNT VEHICLE ON CAR O-LINER	^^ \$380.00	X
LABOUR FOR PANEL BEATING,CUT,WELD STRAIGHTENED & REPLACING PARTS	\$1,200.00	800
TO PUTTY & SPRAY PAINTING	\$1,500.00	1200
<b>TOTAL</b>	<b>\$16,593.72</b>	

9777.2  
7821

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

Ref : CS/TP18004643/Uvbn2

ISA BIN AHMAD  
BLK 751 #11-68  
PASIR RIS STREET 71  
SINGAPORE 510751

Date : 23-03-2018



Code : TP130

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	Veh. Inspected	SKU 9218P
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	12/03/2018

## 2. Vehicle Particulars & Condition

Make & Model	HONDA AIRWAVE (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	GJ11301196	Colour	BLACK
Odometer	138359	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/65 R14	DUNLOP	6 mm
L/H Front Tyre	185/65 R14	DUNLOP	6 mm
R/H Rear Tyre	185/65 R14	DUNLOP	6 mm
L/H Rear Tyre	185/65 R14	DUNLOP	6 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.  
DAMAGES SEE DETAILS.

## 5. General Information

Accident Date	09/03/2018	Inspection Date	12/03/2018
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKU 9218P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	BONNET	DENTED / BUCKLED	945.20	845.20
1	BONNET CHROME MOULDING	BENT / CRACKED	285.60	285.60
1	BONNET LOCK	TWISTED	183.00	183.00
2	BONNET HINGES @\$92.50	TO REPAIR SEE LABOUR	185.00	-
1	BONNET INSULATOR	NOT NECESSARY	188.20	-
1	SET BONNET INSULATOR CLIPS	NECESSARY	40.00	40.00
1	FRONT GRILLE	CRACKED	190.60	190.60
1	FRONT GRILLE LOGO	NECESSARY	38.80	38.80
1	FRONT GRILLE BASE	CRACKED	240.50	240.50
2	HEADLAMPS @\$1050.00	CRACKED	2,100.00	1,737.40
1	HEADLAMP LOWER BRACKET N/S	CRACKED / BENT	65.50	65.50
1	FRONT BUMPER	DISTORTED	1,380.00	945.00
1	FRONT BUMPER CENTRE AIR GRILLE	TWISTED	148.50	148.50
2	FRONT BUMPER SIDE GRILLE @\$55.00	NOT NECESSARY	110.00	-
2	FRONT BUMPER SIDE HOLDERS @\$38.50	BENT	77.00	77.00
1	FRONT BUMPER REINFORCEMENT	BENT	282.90	282.90
1	FRONT SUPPORT PANEL	BENT / TWISTED	966.02	822.30
1	AIR CON CONDENSER	BENT / TWISTED	1,385.00	1,255.60
1	RADIATOR	PUNCTURE / TWISTED	1,886.00	1,485.30
1	RADIATOR FAN ASSY	NOT NECESSARY	295.00	-
1	FRONT FENDER N/S	BENT / BUCKLED	665.30	665.30
1	FRONT FENDER INNER SHIELD N/S	NOT NECESSARY	182.60	-
1	SET FRONT FENDER INNER SHIELD CLIPS	NECESSARY	38.00	38.00
1	FRONT DOOR N/S	TO REPAIR SEE LABOUR	1,105.00	-
	LESS 20% DISCOUNT		-	-1,869.30
			12,983.72	7,477.20
<b><u>SPECIAL NETT ITEMS</u></b>				
1	FRONT LICENCE PLATE W/HOLDER (SN)	BROKEN	50.00	40.00
1	BOL RADIATOR COOLANT (SN)	NECESSARY	50.00	30.00
			100.00	70.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	TO CHECK WIRING.		80.00	30.00
	TO SPRAY RUST PROOFING.		120.00	100.00
	TO REFILL AIR CON GAS.		150.00	100.00
	TO CONDUCT WHEEL ALIGNMENT.	NOT NECESSARY	80.00	-
	TO MOUNT VEHICLE ON CAR O-LINER.	NOT NECESSARY	380.00	-
	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTENED & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF BONNET HINGES AND FRONT DOOR N/S.		1,200.00	800.00
	TO PUTTY & SPRAY PAINTING.		1,500.00	1,200.00
			3,510.00	2,230.00
	<b>GRAND TOTAL</b>		<b>16,593.72</b>	<b>9,777.20</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>7,800.00</b>

Report Ref No. CS/TP18004643/Uvbn2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.