

INS. CASE OWNER

Unelma | CC 6 WRF / ATG 1800 4647, Mjbn

LKK: IDAC

Surveyor: MARMS DOI: ASSIGNMENT 17/7/18 Date / Time: 12/7/18 Registered in Merimen: 12/7/18

Pre-assign / CCU / FTE



Insured Vehicle No.: SIM 7212E Claim No.: 314974660759
Name of Insured: WRF Policy No.: ANAN5090
Insured Tel No.: _____ HP: _____ Make / Model: MAZDA
Excess Sec II :SS _____ D.O.A.: 10/7/18 Place of Accident: JALAN OF BASTIER RD & MONTMELIN RD
Is driver the owner? (YES / NO) Nature of Accident: _____
If NO, Driver Name / Age: DARMAWAN BIN MUHAMMAD SMT OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO
Driver Tel No.: _____ (V/L: YES / NO) Insured Liability: _____ % Final ? Yes / No

SEE 1716E



INSRS: Kim
WSP: Chwee
Tel: _____
Liability: _____
RMKS: _____



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time	STAGE	DATE / PIC
14/7/18	Non-Reporting Itr (1st):	
	Non-Reporting Itr (2nd):	
	Non-Reporting Itr (Final):	
	Notification Itr (if non-pickup):	
	Call OI:	
	After call Itr to OI:	<u>20414-318</u>
	Documentation Check List:	Handler Typist
	Notification Itr (if non-pickup)	<input checked="" type="checkbox"/> <input type="checkbox"/>
	After call Itr to OI	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Car Rental Invoice:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Towing Invoice	<input checked="" type="checkbox"/> <input type="checkbox"/>
	LTA / CIA :	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Medical Bill:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	PIR:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	LOD	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/> <input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/> <input type="checkbox"/>
	Others:	<input type="checkbox"/> <input type="checkbox"/>

RECEIVED 14 JUL 2018

PRELIMINARY ADVICE	Date/Time:	Sent By:	
FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost:	SS _____	(_____ days) Reduction:	% _____ Email <input type="checkbox"/> Call <input type="checkbox"/>
FINAL SETTLEMENT	Date/Time: <u>2-4-18</u>	Confirm with: <u>JASON</u>	Email <input type="checkbox"/> Call <input type="checkbox"/>
Final Liability:	% <u>100</u>	(Agreed / Assessed) BOLA S/N No.: <u>2+</u>	If NO or B 28, Ass. Lia: _____
Repair Cost:	SS <u>651</u>	SS <u>5,367.89</u>	
Loss of Rental (LOR):	SS <u>200 x 21 ?</u>	days) X <u>100</u>	
Loss of Use (LOU):	SS <u>-</u>	(5 x days)	
Loss of Income (LOI):	SS <u>-</u>	(5 x days)	
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/>	<input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/> (Tick only one)		
GIA/LTA Search	SS <u>7.45</u>		
Medical:	SS _____		
Disbursement:	SS _____	(e.g. Tow/Independent)	
Legal Cost	SS _____		
Total:	SS <u>5,575.34</u>	Global Sum SS: <u>5,500.x</u>	
FINAL PAYMENT	Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>
Payee 1:	SS <u>5,500.x</u>	Name 1: <u>KIM CHWEE AUTO PTE LTD</u>	
Payee 2: (Strike if N.A.)	SS <u>X</u>	Name 2: <u>X</u>	
Payee 3: (Strike if N.A.)	SS _____	Name 3: <u>X</u>	

OI HIT TP FROM
MERRY SENT

(09/11/13) wef

ASS. REC. BY: Marcus

REF:

716/

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKE1716E

at Workshop m/s Kimchee

of _____

Insured: SLM72127

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GI / PR Seen: 0 Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

3703E

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKE1716E Yr Regn: 3, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA

Make: Honda Verel c.c. 1495

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 89778 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: RU11111 820

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 215/60R16

BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 7 mm Rear 7 mm

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 10/3/18 D.O.I. 12/3/18

Survey held at _____

Des. of Damages: Rear / Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction LTA 43827

Home G.A

Date/Time, File Pass to?

: Prell. Report

1) _____

: Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

: Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS ___ \$

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/LCR18004647/Ujb3	
78 SHENTON WAY #08-16 CHARTIS BUILDINGS SINGAPORE 079120		Date : 12-03-2018	
		Code : LCR	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLM 7212Z	Veh. Inspected	SKE 1716E
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	12/03/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	10/03/2018	Inspection Date	12/03/2018
Survey held at	KIM CHWEE AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

KIM CHWEE AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Not Allocation
 when
 P/P # 5016.72
 12/3/18
 4 day.

Qty Particular SKE 1716E

Amount SS

List Item:

- 1 PCS REAR WINDSCREEN MOULDING
- 1 PCS TAILGATE
- 1 PCS TAILGATE OUTER HANDLE GARNISH
- 1 PCS TAILGATE 'H' LOGO
- 2 PCS TAILGATE REFLECTORS @\$280
- 1 PCS TAILGATE 'VEZEL' EMBLEM
- 1 PCS TAILGATE INNER LOCK
- 1 PCS TAILGATE LOCK STRIKER
- 1 PCS TAILGATE INNER TRIM BOARD
- 1 SET TAILGATE INNER TRIM BOARD CLIPS
- 1 PCS TAILGATE WEATHERSTRIP
- 1 PCS TAILGATE KEYLESS SENSOR
- 1 PCS REAR BUMPER CENTRE
- 2 PCS REAR BUMPER SIDES @\$235.10
- 2 PCS REAR BUMPER SIDE RETAINERS @\$35.20
- 2 PCS REAR BUMPER SCREW SPACERS @\$12
- 2 PCS REAR BUMPER REFLECTORS @\$151.20
- 2 PCS TAILLAMPS @\$460.60
- 2 PCS TAILLAMP HOUSING PANELS @\$195
- 1 PCS REAR END PANEL
- 1 PCS REAR END PANEL TOP GARNISH
- 1 PCS REAR BUMPER LOWER DIFFUSER
- 1 SET REAR BUMPER LOWER DIFFUSER CLIPS
- 1 PCS REAR EXHAUST
- 2 PCS REAR EXHAUST MOUNTINGS @\$45
- 1 PCS REAR EXHAUST HEAT SHIELD
- 2 PCS REAR FENDER INNER TRIMS @\$295.30
- 1 SET REAR FENDER INNER TRIM CLIPS
- 2 PCS REAR FENDER OUTER GARNISH @\$195.80
- 1 PCS REAR FLOOR PANEL
- 1 PCS REAR FLOOR PANEL TOOLS SPONGE
- 2 PCS REAR FENDERS @\$1100

rec	\$	121.30	/
sol/d	\$	1,100.90	/
11	\$	285.30	x
11	\$	35.80	x
o/scre	\$	560.00	ipc
rec	\$	56.20	/
twi	\$	198.50	/
11	\$	25.50	x
o/scre	\$	321.70	/
rec	\$	50.00	/
twi	\$	135.70	/
11	\$	180.00	x
o/scre	\$	762.70	/
11	\$	470.20	x
11	\$	70.40	x
11	\$	24.00	x
11	\$	302.40	x
o/scre	\$	921.20	ipc
11	\$	390.00	x
11	\$	514.00	x
twi	\$	125.00	/
11	\$	348.20	x
11	\$	50.00	x
11	\$	899.20	x
11	\$	90.00	x
11	\$	98.30	x
11	\$	590.60	x
11	\$	50.00	x
o/scre	\$	391.60	ipc
11	\$	912.30	x
11	\$	685.00	x
11	\$	2,200.00	x
		\$	12,966.00

(20%)

3084
 3046.72

List Item Total:

Special Nett Item:

- 1 SET REAR BUMPER REVERSER SENSOR
- 1 PCS REAR REVERSE CAMERA
- 1 PCS REAR WINDSCREEN SEALANT
- 1 PCS REAR END PANEL SEALANT
- 1 PCS REAR FLOOR PANEL INSULATOR

shel	\$	280.00	200
11	\$	500.00	x
rec	\$	50.00	40
11	\$	50.00	x
11	\$	180.00	x
		\$	1,060.00

Special Nett Total:

Labour Charge:

TO CHECK WIRING

\$ 80.00 30

TO DISMANTLE & REPLACE REVERSE SENSOR	\$	80.00	50
TO TRANSFER TAILGATE MECHANISM	\$	100.00	60
TO DISMANTLE & REFIX REAR WINDSCREEN	\$	150.00	120
TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTERY	\$	150.00	80
TO DISMANTLE & REPLACE REAR EXHAUST	\$	100.00	60
TO SPRAY RUST PROOFING	\$	150.00	50
TO MOUNT VEHICLE ON CAR O-LINER	\$	380.00	X
TO DISMANTLE & REFIX PETROL TANK	\$	100.00	X
LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS	\$	2,000.00	600
TO PUTTY & SPRAY PAINTING	\$	2,000.00	680
Labour Charge Total:	\$	5,290.00	

ESTIMATE PARTS AND LABOUR GRAND TOTAL

\$ 19,316.00

LKK Auto Consultants hereby notify
the Repairer of the following:

- To resurvey before repair commencing
- To display damaged vehicle in a secure way
- To provide access to the vehicle for inspection
- To provide advice on a 'without prejudice' basis
- To allow inspection of the vehicle
- Supplementary damage must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
 Owner ID: 3703E

Vehicle Details

Vehicle No.: SKE1716E
 Vehicle to be Exported: No
 Intended De-registration Date: 12 Mar 2018
 Vehicle Make: HONDA
 Vehicle Model: VEZEL 1.5X A
 Primary Colour: White
 Manufacturing Year: 2015
 Engine No.: L15B4031825
 Chassis No.: RU11111820
 Maximum Power Output: 96.0 kW (128 bhp)
 Open Market Value: \$19,721.00
 Original Registration Date: 24 Mar 2016
 First Registration Date: 24 Mar 2016
 Transfer Count: 0
 Actual ARF Paid: \$9,721.00

Intended PARF Rebate Details

PARF Eligibility: Yes
 PARF Eligibility Expiry Date: 23 Mar 2026
 PARF Rebate Amount: \$7,290.00

Intended COE Rebate Details

COE Expiry Date: 23 Mar 2026
 COE Category: A - Car up to 1600cc & 97kW
 (130bhp)
 COE Period(Years): 10
 QP Paid: \$45,504.00
 COE Rebate Amount: \$36,537.00
Total Rebate Amount: \$43,827.00

The information contained herein is correct as at 12 Mar 2018

OK

KIM CHWEE AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-50 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 199802379R

Date : 20.03.2018

AIG Asia Pacific Insurance Pte Ltd

Chartis Building

78 Shenton Way #07-16

Singapore 079120

Attn: Motor Claim Department

Dear Sir/Madam,

ACCIDENT INVOLVING VEHICLES NO : SKE 1716E / SLM 7212Z ON 10.03.2018

We are the authorized repair workshop for the owner of motor vehicle no: **SKE 1716E**, which was involved in the captioned accident with your insured vehicle no: **SLM 7212Z**. The vehicle owner has requested and authorized us to assist him in presenting his/her claim against the party responsible for the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving, we are submitting these claims for your consideration on behalf of the owner/claimant.

1) Cost of Repair (inclusive of GST)	\$	5,367.89
2) Loss of Rental (2 days X S\$200)	\$	200.00
3) LTA Search Fee	\$	7.45
	<u>\$</u>	<u>5,575.34</u>

We enclosed herewith the following documents to support the claims:

- | | |
|--------------------------|------------------------------------|
| a) Final Repair Invoice | b) Car Rental Invoice / Agreement |
| c) LTA Search Result | d) Letter of Authorisation, etc... |
| e) GIA Report | f) I/C & Driving Licence |
| g) Insurance Certificate | h) Vehicle Registration Log Card |

Kindly look into the matter and let us hear from you on the settlement of our customer's claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.

Thank you,
Yours faithfully,

Jason Tang (jason@fastechauto.com.sg)
For KIM CHWEE AUTO PTE LTD



Joy Irene (LKKAuto)

From: Jason Fastech Auto <jason@fastechauto.com.sg>
Sent: Monday, 2 April 2018 4:26 PM
To: Joy Irene (LKKAuto)
Cc: Admin A; Vivian Lau (LKKAuto)
Subject: RE: SKE 1716E ON 10.03.2018 / AIG SLM 7212Z

Without Prejudice

Dear Joy,

We are pleased to accept your offer of global sum \$5,550.00 (all-in).

Thank you.

Best Regards

Jason Tang
Kim Chwee Auto Pte Ltd
1 Kaki Bukit Ave 6
#01-46/48/50 AutoBay
Singapore 417883
Tel: 67465405
Hp: 98218445
jason@fastechauto.com.sg

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.

From: Joy Irene (LKKAuto) [mailto:JoyIrene@lkkauto.com]
Sent: Monday, April 2, 2018 10:46 AM
To: jason@fastechauto.com.sg
Cc: Admin A <admin-a@lkkauto.com>; Vivian Lau (LKKAuto) <vivianlau@lkkauto.com>
Subject: SKE 1716E ON 10.03.2018 / AIG SLM 7212Z

WITHOUT PREJUDICE*

Dear Jason,

For a quick and amicable settlement on your client's claim, please accept our global sum offer of \$5,550.00 (all-in).

For your confirmation.

Thank you.

Best Regards,
Joy Irene | Case Handler

LKK Auto Consultants Pte Ltd
DID: 6749-5792 | email: joyirene@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

Joy Irene (LKKAuto)

From: Joy Irene (LKKAuto)
Sent: Wednesday, 14 March 2018 5:01 PM
To: 'Eileen, May Hwee Yap'
Cc: Vivian Lau (LKKAuto); Admin A
Subject: ACCIDENT INVOLVING LCRF SLM 7212Z AND SKE 1716E ON 10.03.2018 (11:40 HOURS) ALONG BALLESTIER ROAD & MOULMEIN RD

14 March 2018

LION CITY RENTALS PTE LTD

Policy Holder

AIG : 3149746607SG
LKK : CC6/LCR18004647/Ujb3

Dear Sir/Madam,

ACCIDENT INVOLVING LCRF SLM 7212Z AND SKE 1716E ON 10.03.2018 (11:40 HOURS) ALONG BALLESTIER ROAD & MOULMEIN RD

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

We have received a claim from SKE 1716E against your insurance policy.

Based on the information on hand, we are of the opinion that we cannot be absolved from liability. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please call us if you have further queries.

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

AUTHORIZATION TO ACT
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

I, Aloysius Michael Mok Kok Jun (莫国俊) ("the third party claimant")
of 17 Anchorvale Crescent #13-15 Singapore 54465 (address),
owner of SKE 1716E (vehicle no.) hereby authorize
Kim Chwee Auto Pte Ltd
("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. SKE 1716E that was
damaged pursuant to the accident which occurred on 10/03/2018 (date) along
Balestier Road (location)
involving vehicle no/s SLM 7212Z ("the accident").

I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment further to settlement of my claim with payment cheque/s being made in
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 12 day of 03 (month) 20 18 (year)

[Signature]
Signed by "the third party claimant"

[Signature]

Signed by "the workshop"

✓

DATE : 20/03/18

TO : AIG Asia Pacific Insurance Pte Ltd

RE : ACCIDENT INVOLVING VEHICLE NO. SKE 1716 E / 3UM 7212 Z

ALONG Balestier Road

ON 10.3.2018

I/We, Aloysius Michael Mok Kok Jun (Mo GuoJun)

of (NRIC No./ROC No.) S7923703 E

of 17 Anchorvale Crescent #13-15 Singapore 544652

owner of vehicle no. SKE 1716 E in consideration of M/s KIM CHWEE AUTO PTE LTD repairing my/our vehicle SKE 1716 E at my/our instruction and hereby authorise M/s KIM CHWEE AUTO PTE LTD to demand claim settlement whatever amount settled/payable by the Insurance Company and/or third party or to commence legal proceedings, if necessary, under my name, for the cost of repairs, car rental and/or loss of use, etc. and to their appointing solicitor to act for me/us in respect of the said accident/claim and all claimed and/or settled shall belong to them absolutely.

I/We further agree and undertake to indemnify them against the above-mentioned claim cost which may arisen therewith.

Signature of Owner : 

Name of Owner : _____

RELEASE VOUCHER
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

We/I, Kim Chwee Auto Pte Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte. Ltd. LKK AUTO CONSULTANTS PTE LTD ("name of surveyor") with respect to the amount claimed for S\$ 5,500.00 (GLOBAL SUM) (loss of use/rental) S\$ _____ (search fees) for vehicle no. SXE 1716E that was damaged pursuant to the accident which occurred on 10/03/2018 (date) along Ralestien Road (location) involving vehicle no/s SLM 7212Z.

This is pursuant to the inspection conducted on 12/03/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Aloysius Michael Mok Kok Jun (MO GUSTIN) ("third party claimant") of vehicle no. SXE 1716E to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte. Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SXE 1716E (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 03 day of 04 (month) 20 18 (year)



LKS



Signed by AIG appointed surveyor

Chopped & Signed by "the workshop"

TAX INVOICE

KIM CHWEE AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-50 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 199802379R

AIG Asia Pacific Insurance Pte Ltd
Chartis Building
78 Shenton Way #07-16
Singapore 079120

Attn : Motor Claim Department

Tax Invoice : 20189

Date : 20.03.2018
Vehicle No : SKE 1716E
Make/Model : HONDA VEZEL
Chassis/Eng# :
Accident Date : 10.03.2018
Claim No :
Reference : 0318 -20189
Policy No :

	Amount
To proceed on parts by parts repair inclusive of knocking ,spray painting labour charges and etc.	S\$ 5016.72

E. & O. E.	Total : S\$	5016.72
	GST @ 7% : S\$	351.17
	Amount Due : S\$	5367.89



for KIM CHWEE AUTO PTE LTD

All Invoices are subjected to GST

DYNAMIC CAR RENTAL

1 Kaki Bukit Ave 6 #01-46 Autobay

Singapore 417883

Tel No: 6741 7244 / 6746 5405 Fax No: 6745 8520 / 6746 5786

Co. Reg No: 52928467K

To: ALOYSIUS MICHEAL MAK KOK JUN (MO GUOJIN)

Invoice : DCR-2018-03-06

Date : 14.03.2018

Agreement No : 19992

Payment Term : LOD

DESCRIPTION

AMOUNT

Rental charges for vehicle : SFD 2468D (0318-20189) \$ 200.00

Rental Period from 12.03.2018 to 14.03.2018 .

E. & O. E.

Total \$ 200.00

LINA PANG

for Dynamic Car Rental

Dynamic Car Rental

1 KAKI BUKIT AVENUE 6, #01-46/48/50 AUTOBAY, SINGAPORE 417883.

TEL: (+65) 6741 7244, 6746 5405 FAX: (+65) 6745 8520, 6746 5786

Co. Reg. No. 52928467K

RENTAL TERMS AND CONDITIONS

No. 19992

Name: <u>Aloysius Micheal Mak Kok Jun (Mo Guan Jin)</u>			REG. No.:	MAKE MODEL:							
ADDRESS:			<u>SFD 2468D</u>	DIESEL	PETROL	E	1/4	1/2	3/4	F	
			KM IN	DATE & TIME IN: <u>14/3/18 @ 4.45pm</u>							
			KM OUT	DATE & TIME OUT: <u>12/3/18 @ 1.25pm</u>							
			KM DRIVEN	TIME USED:							
NAMED DRIVER											
DRIVING LICENCE NO.	DATE OF EXPIRY	PLACE OF ISSUE	HOURS			@SS					
<u>S7923703E</u>			<u>2</u> DAYS			@SS <u>100</u> # <u>200</u>					
PASSPORT NO	DATE OF ISSUE	PLACE OF ISSUE	WEEKS			@SS					
			MONTHS			@SS					
ADD NAMED DRIVER											
DRIVING LICENCE NO.	DATE OF EXPIRY	PLACE OF ISSUE	BY INITIALLING, RENTER AGREES TO PAY ADD FEE FOR COLLISION DAMAGES WAIVER (C.D.W.)			SUB-TOTAL		<u>\$ 200</u>			
PASSPORT NO	DATE OF ISSUE	PLACE OF ISSUE				TOTAL RENTAL					
IMPORTANT NOTES:						DELIVERY FEE					
This vehicle is licensed to carry 04 passengers only. No refund will be given for vehicle returns early. No refund will be given for period left in vehicle. Hirer is liable to pay first \$2000 under section I & II in any accident plus loss of earnings while damaged vehicle is under repair. Hirer is liable to pay all parking fee and traffic summonses.						COLLECTION FEE					
Vehicle return during office hour only. No Service on Public Holiday and Sunday.											
ADDITIONAL CONDITIONS:											
* Geographical areas: Singapore & West Malaysia.											
* Driver must be:											
a) 18 years old and above;											
b) holding a valid relevant class of driving license.											
* Additional Own Damage Excess of S\$1,000 is applicable for any named/unnamed drivers who:											
a) age 22 to 23 years old;											
b) age 66 to 70 years old;											
c) with driving experience of 1 year to less than 2 years in Singapore on the relevant classes of driving license.											
* Additional All Claims excess of S\$2,000 is applicable for any named/unnamed drivers who:											
a) is 18 years old to 21 years old and/or											
b) is 71 years old and above and/or											
c) with driving experience of less than 1 year on the relevant classes of driving license.											
* Upon returning the replacement vehicle, you must ensure that all expensive and important items to be removed away from this replacement vehicle. We'll not be responsible for any reporting of such losses.											
* Hirer is liable to pay first \$2000 under section I & II in any accident plus loss of earning while damage vehicle is under repair.											
Hirer is responsible for Additional \$2,000.00 Excess to the THIRD PARTY DAMAGE / FURTHER claims.											
I HAVE READ THE TERMS AND CONDITIONS ON BOTH SIDES OF THIS RENTAL AGREEMENT AND AGREE THEREOF.											
SIGNED BY THE PARTIES HERETO ON THE _____ DAY OF _____											
<p>X _____</p> <p>DYNAMIC CAR RENTAL</p>			<p>X _____</p> <p>RENTER'S/DRIVER'S SIGNATURE</p>								

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Mar 2018 Edit Reg		12 Mar 2018 00:00 Edit Adj Rpt	S\$5,016.72 Edit Estimates	S\$5,016.72 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	LCRF Pte Ltd, Co. Reg. No.: NA								
Main Claimant:	ALOYSIUS MICHAEL MOK KOK JUN (MO GUOJIN), ID: S7923703E								
Vehicle Reg. No.:	SKE1716E	Date of Loss:	10/03/2018 00:00 - :59 [23 Months and 14 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 3149746607SG	Policy/Cover Note No.:	0999994787						
Vehicle Reg. No. (Insured):	SLM7212Z	Policy No. (Claimant):	5078699014-01						
		Excess:							
Repairer:	Kim Chwee Auto Pte Ltd (HQ) 1 Kaki Bukit Avenue 6 #01-48, AutoBay@Kaki Bukit, 417883 Eunos - Tel: 67465405/67417244								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tee, Chee-Wah] Chee-Wah.Tee@aig.com								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 21/03/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (13/03/2018): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKE1716E (3149746607SG)
[SLM7212Z]

TP

ALOYSIUS MICHAEL MOK KOK JUN (MO GUOJIN)

Mar 10 2018 12:00AM

[LCRF Pte Ltd]

Kim Chwee Auto Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View View in Browser	
Letters/Correspondences										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	(Draft)	Third Party Express Settlement – Payment Breakdown							Edit		
Photos/Images										3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	12/03/18 19:41	Odometer Reading							Load JPG	<input checked="" type="checkbox"/>	
2	12/03/18 19:41	General View							Load JPG	<input checked="" type="checkbox"/>	
3	12/03/18 19:41	Chassis Number							Load JPG	<input checked="" type="checkbox"/>	
4	12/03/18 19:41	General View							Load JPG	<input checked="" type="checkbox"/>	
5	12/03/18 19:41	General View							Load JPG	<input checked="" type="checkbox"/>	
6	12/03/18 19:41	General View							Load JPG	<input checked="" type="checkbox"/>	
7	12/03/18 19:41	General View							Load JPG	<input checked="" type="checkbox"/>	
8	12/03/18 19:41	General View							Load JPG	<input checked="" type="checkbox"/>	
9	12/03/18 19:41	General View							Load JPG	<input checked="" type="checkbox"/>	
10	12/03/18 19:41	General View							Load JPG	<input checked="" type="checkbox"/>	
11	12/03/18 19:41	General View							Load JPG	<input checked="" type="checkbox"/>	
12	12/03/18 19:41	General View							Load JPG	<input checked="" type="checkbox"/>	
13	12/03/18 19:41	General View							Load JPG	<input checked="" type="checkbox"/>	
14	12/03/18 19:41	General View							Load JPG	<input checked="" type="checkbox"/>	
15	12/03/18 19:41	General View							Load JPG	<input checked="" type="checkbox"/>	
16	12/03/18 19:41	General View							Load JPG	<input checked="" type="checkbox"/>	
17	12/03/18 19:41	General View							Load JPG	<input checked="" type="checkbox"/>	
18	12/03/18 19:41	General View							Load JPG	<input checked="" type="checkbox"/>	
19	12/03/18 19:41	General View							Load JPG	<input checked="" type="checkbox"/>	
20	12/03/18 19:41	General View							Load JPG	<input checked="" type="checkbox"/>	
21	12/03/18 19:41	General View							Load JPG	<input checked="" type="checkbox"/>	
22	12/03/18 19:41	General View							Load JPG	<input checked="" type="checkbox"/>	
23	12/03/18 19:41	General View							Load JPG	<input checked="" type="checkbox"/>	
24	12/03/18 19:41	General View							Load JPG	<input checked="" type="checkbox"/>	
25	12/03/18 19:41	General View							Load JPG	<input checked="" type="checkbox"/>	
26	12/03/18 19:41	General View							Load JPG	<input checked="" type="checkbox"/>	
27	12/03/18 19:41	General View							Load JPG	<input checked="" type="checkbox"/>	
28	12/03/18 19:41	General View							Load JPG	<input checked="" type="checkbox"/>	
29	12/03/18 19:41	General View							Load JPG	<input checked="" type="checkbox"/>	
30	12/03/18 19:41	General View							Load JPG	<input checked="" type="checkbox"/>	
31	12/03/18 19:41	General View							Load JPG	<input checked="" type="checkbox"/>	
32	12/03/18 19:41	General View							Load JPG	<input checked="" type="checkbox"/>	
33	12/03/18 19:41	General View							Load JPG	<input checked="" type="checkbox"/>	
34	12/03/18 19:41	General View							Load JPG	<input checked="" type="checkbox"/>	

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
35	12/03/18 19:41	General View		Load JPG <input checked="" type="checkbox"/>
36	12/03/18 19:41	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
37	12/03/18 19:41	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
38	12/03/18 19:41	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
39	12/03/18 19:41	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
40	12/03/18 19:41	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
41	12/03/18 19:41	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
42	12/03/18 19:41	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
43	12/03/18 19:41	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
44	12/03/18 19:41	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
45	12/03/18 19:41	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
46	12/03/18 19:41	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
47	12/03/18 19:41	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
48	12/03/18 19:41	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
49	12/03/18 19:41	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
50	12/03/18 19:41	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
51	12/03/18 19:41	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
52	12/03/18 19:41	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
53	12/03/18 19:41	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
54	12/03/18 19:41	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
55	12/03/18 19:41	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
56	12/03/18 19:41	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
57	12/03/18 19:41	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
58	12/03/18 19:41	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
59	12/03/18 19:41	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
60	12/03/18 19:41	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
61	12/03/18 19:41	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
62	12/03/18 19:41	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
63	12/03/18 19:41	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
64	12/03/18 19:41	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
65	12/03/18 19:41	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
66	12/03/18 19:41	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
67	12/03/18 19:41	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
68	12/03/18 19:41	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
69	12/03/18 19:41	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
70	13/03/18 20:11	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
71	13/03/18 20:11	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
72	13/03/18 20:11	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
73	13/03/18 20:11	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
74	13/03/18 20:11	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	13/03/18 18:51	TP GIA REPORT		Load PDF
2	14/03/18 17:03	LETTER TO LCRF		Load PDF
3	05/04/18 11:35	WORKSHOP INVOICE		Load PDF
4	05/04/18 11:35	AUTHORISATION TO ACT FORM		Load PDF
5	05/04/18 11:35	Release Voucher		Load PDF
6	05/04/18 11:35	RENTAL RECEIPT		Load PDF
7	05/04/18 11:35	LTA SEARCH		Load PDF
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail Print

Letters/Correspondences			1 per page	<input type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/03/18 16:52	OI GIA	 Load PDF	<input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SLM7212Z (Insd veh)	Model:	HONDA VEZEL 1.5 X (A)
	SKE1716E (TP veh)		
Date of Accident:	10/03/2018		

Global Sum Settlement	: [X] Yes	[] No
Repair Estimate	: \$	20,668.12
Final Repair Cost	: \$	5,500.00
Loss of Use	: \$	_____ days at \$0.00 per day
Rental (if any)	: \$	2 days
LTA / GIA Search Fee	: \$	
Others:	: \$	
	: \$	
Final Settlement Sum (Global Sum)	: \$	5,500.00

Is Third Party Workshop GIA Registered? [] YES [X] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown		
1)	Kim Chwee Auto Pte Ltd	: \$ 5,500.00
2)		: \$
3)		: \$

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

05 Apr
2018

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/LCR18004647/UJB3Q2

Date: 05/04/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999994787
Claimant Vehicle No : SKE1716E	Insured Vehicle No :	SLM7212Z
Date of Loss: 10/03/2018	Nature of Claim:	TP Claim No: 3149746607SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKE1716E		
Make & Model:	HONDA VEZEL, 1.5 X (A)	Engine No:	L15B4031825
Reg. Date:	24/03/2018 (Man. Year: 2015)	Chassis No:	RU11111820
Colour:	White	Odometer:	89778 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 7 mm	Rear Left Side:	Dunlop 7 mm
Front Right Side:	Dunlop 7 mm	Rear Right Side:	Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,026.00	3,286.72	10,739.28	76.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,290.00	1,730.00	3,560.00	67.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	19,316.00	5,016.72	14,299.28	74.03
+ GST 7.00/7.00% (S\$)	1,352.12	351.17	1,000.95	74.03
Nett Amount (S\$)	20,668.12	5,367.89	15,300.23	74.03
+ Car Rental (2.0 x S\$100.00/day) (S\$)		200.00		
+ Doc/Search Fee (S\$)		7.45		
		Nett Liability (S\$)		5,575.34
		Global Sum Settlement (S\$)		5,500.00

INSPECTION

Date of Assignment:	12/03/2018	
Date Inspected:	12/03/2018 Inspected At:	Kim Chwee Auto Pte Ltd (HQ) 1 Kaki Bukit Avenue 6 #01-48, AutoBay@Kaki Bukit Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Necessary	121.30 F	*121.30 FL
2	1		*TAILGATE	Badly Dented	1,100.90 F	*1,100.90 FL
3	1		*TAILGATE OUTER HANDLE GARNISH	Not Necessary	285.30 F	*- FL
4	1		*TAILGATE H LOGO	Not Necessary	35.80 F	*- FL
5	1		*TAILGATE REFLECTORS	O/S Cracked	560.00 F	*280.00 FL
6	1		*TAILGATE VEZEL EMBLEM	Necessary	56.20 F	*56.20 FL
7	1		*TAILGATE INNER LOCK	Twisted	198.50 F	*198.50 FL
8	1		*TAILGATE LOCK STRIKER	Not Necessary	25.50 F	*- FL
9	1		*TAILGATE INNER TRIM BOARD	Deformed / Cracked	321.70 F	*321.70 FL
10	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 F	*50.00 FL
11	1		*TAILGATE WEATHERSTRIP	Twisted	135.70 F	*135.70 FL
12	1		*TAILGATE KEYLESS SENSOR	Not Necessary	180.00 F	*- FL
13	1		*REAR BUMPER CENTRE	Dented / Deformed	762.70 F	*762.70 FL
14	2		*REAR BUMPER SIDES	Repair	470.20 F	*- FL
15	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	70.40 F	*- FL
16	2		*REAR BUMPER SCREW SPACERS	Not Necessary	24.00 F	*- FL
17	2		*REAR BUMPER REFLECTORS	Not Necessary	302.40 F	*- FL
18	1		*TAILLAMPS	O/S Cracked	921.20 F	*460.60 FL
19	2		*TAILLAMP HOUSING PANELS	Repair	390.00 F	*- FL
20	1		*REAR END PANEL	Repair	514.00 F	*- FL
21	1		*REAR END PANEL TOP GARNISH	Twisted	125.00 F	*125.00 FL
22	1		*REAR BUMPER LOWER DIFFUSER	Not Necessary	348.20 F	*- FL
23	1		*SET REAR BUMPER LOWER DIFFUSER CLIPS	Not Necessary	50.00 F	*- FL
24	1		*REAR EXHAUST	Repair	899.20 F	*- FL
25	2		*REAR EXHAUST MOUNTINGS	Not Necessary	90.00 F	*- FL
26	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	98.30 F	*- FL
27	2		*REAR FENDER INNER TRIMS	Not Necessary	590.60 F	*- FL
28	1		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	50.00 F	*- FL
29	1		*REAR FENDER OUTER GARNISH	O/S Torn	391.60 F	*195.80 FL
30	1		*REAR FLOOR PANEL	Repair	912.30 F	*- FL
31	1		*REAR FLOOR PANEL TOOLS SPONGE	Not Necessary	685.00 F	*- FL
32	2		*REAR FENDERS	Not Necessary	2,200.00 F	*- FL
33	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
34	1		*REAR REVERSE CAMERA	Not Necessary	500.00 FS	*- FS
35	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
36	1		*REAR END PANEL SEALANT	Not Necessary	50.00 FS	*- FS
37	1		*REAR FLOOR PANEL INSULATOR	Not Necessary	180.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	14,026.00	4,048.40
- List Item Discount on L Items 0.00/20.00% (S\$)	0.00	761.68
Total Parts (S\$)	14,026.00	3,286.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	80.00	30.00
2	TO DISMANTLE & REPLACE REVERSE SENSOR	New	80.00	50.00
3	TO TRANSFER TAILGATE MECHANISM	New	100.00	60.00
4	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	120.00
5	TO DISMANTLE & REFIX SEAT ,CUSHION UPHOLSTERY	New	150.00	80.00
6	TO DISMANTLE & REPLACE REAR EXHAUST	New	100.00	60.00
7	TO SPRAY RUST PROOFING	New	150.00	50.00
8	TO MOUNT VEHICLE ON CAR O-LINER	New	380.00	0.00
9	TO DISMANTLE & REFIX PETROL TANK	New	100.00	0.00
10	LABOUR FOR PANEL BEATING ,CUT,WELD ,STRAIGHTEN & REPLACING PARTS	New	2,000.00	600.00
11	TO PUTTY & SPRAY PAINTING	New	2,000.00	680.00
Gross Labour Cost (S\$)			5,290.00	1,730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >