

ASS. REC. BY:

REF: CS/CT118004650/Gvd3/

Special Instruction:

Surveyor:  
Merimen

From (Person):

GQ  
Irene Tay

ASSIGNMENT (Office)

of CTI

Date/Time: 9/13/18 @ 4:30pm

Estimated Cost:

Bill to:

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBH1919M

Insured:

SLN 4978L

at Workshop m/s

Pan Euro Bikes

Tel:

62994929

of

21 Moonstone Lane #01-01

Policy No:

DMHCSN1733401700

Claim No:

SNM18D01271C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

02/03/18

CA / REV / REP. / REV 24 HRS

(wp)

Date/Time:

9:31am @ 12/3/18

Person Contacted:

Kin Wah

H.O.D. Endorsement:

Vehicle IN/OUT


Date/Time	Action/Instruction (✓) Estimate
	FBH1919M-X
	SLN 4978L-X
12/1/18	@ 4:39pm Kin Wah said vehicle still under repair
30/7/18	@ 5:11pm Final fig \$ 949.40 confirmed with Kin Wah
	(Ref 220, 1970)

CTI

ASSIGNMENT

From: \_\_\_\_\_ Date: 12/3/18  
 Estimated Cost: \_\_\_\_\_  
 OD (TP) WS / TP RES / OD RES / EVA / INV / MV  
 To inspect Vehicle No: FBH 1919M  
 at Workshop no: Pan Euro Bikes  
 of: 21 Moonstone Lane # 01-01  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.



Sal. or Market Value: \_\_\_\_\_  
 IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
 G/A PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 4 days Res: Yes or No  
 LHM Sum: \_\_\_\_\_ % G Val: Yes or No  
 CA / REV / REP. / 24 HRS wp  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle IN / OUT

Date Time Action Instruction

Van No: FBH 1919M Date: 12 Sep 2013  
 Type: M Car Blue Van Long Van Prime Model  
 Truck Trailer: \_\_\_\_\_  
 Make: Piaggio Vespa 278  
 Colour: white  
 Seating: 8192  
 Engine: \_\_\_\_\_  
 C/V: 2APM 45200000 62503  
 Gen Cond: Good Fair Poor Burnt  
 Steering: In order Jammed Leaked Burnt  
 Brake: In order Jammed Leaked Burnt  
 Mod: Nil S Rim STD A Rim  
 Tyre Size: F 120/70-12  
R 130/70-12  
 BS / DUN / EXNOVA / GY / FS / LIZA / MID / OHTSL / PIR / SUM  
 TOYO / YOKO  
 Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
 R.Ba: 5 --- R.Ba: 5 ---  
 L.Ba: --- L.Ba: ---  
 D.D.A: \_\_\_\_\_ D.D: 12-03-18  
 Survey recd at: w/s 1pm  
 Des of Damages: Front Rear OS UC Roofed  
and  
 The UIC / Chassis frame / Body Structure affected due to collision

RECEIVED 31 JUL 2018

Intanto  
30/7/2018

Date Time File Pass to: ☐ Preli. Report  
☐ Final Report

Days Of Repair: 4  
 Resurvey No. of Trip: 1

307-typist

Add Fee: ☐ Site Fee: \$  
☐ Night Fee: \$  
☐ Day Fee: \$  
☐ Report Fee: \$

Report Form: menmen  
 LHM Sum: P/P \$ 949.40

Surveys Fee: 220  
 Transportation: \_\_\_\_\_  
 Total: 220



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI18004650/Gvd3		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 12-03-2018		
		Code : CTI		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SLN 4978L	Veh. Inspected	FBH 1919M	
Policy No.	DMHCSN1733401700	Coverage (\$)	0.00	
Claim No.	SNM18D01271C02	Excess (\$)	0.00	
Assign From	MERIMEN (IRENE TAY)	Assign Date	12/03/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	02/03/2018	Inspection Date	12/03/2018	
Survey held at	PAN EURO BIKES PTE LTD 21 MOONSTONE LANE #01-01 POH LENG BUILDING SINGAPORE 328462.			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Mar 2018		09 Mar 2018 16:30 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

Insured:	<b>[Created by insurer]</b>		
Main Claimant:	<b>NG CHOON TENG ANDY</b>		
Vehicle Reg. No.:	<b>FBF1919M</b>	Date of Loss:	02/03/2018 00:00 - :59
Claim Type:	<b>TP / SNM18D01271C02</b>	Policy/Cover Note No.:	DMHCSN1733401700
Vehicle Reg. No. (Insured):	<b>SLN4978L</b>	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	<b>Pan Euro Bikes Pte Ltd (HQ)</b> 21 Moonstone Lane #01-01 Poh Leng Building, 328462 Serangoon - Tel: 62994929		
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Irene Tay Hui Ping</b> - 638986192]		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... <b>[Final Rpt due 20/03/2018]</b>		
Adj Asg. Remarks:	EST \$1251.26, CASE WITH SJE.		

### ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

### ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Enquire Transfer Fee

Vehicle Details																
Vehicle No. :	FBF1919M															
Vehicle Type :	P01 - Passenger Scooter															
Vehicle Attachment 1 :	No Attachment															
Vehicle Scheme :	Normal															
Vehicle Make :	PIAGGIO															
Vehicle Model :	VESPA GTS 300 SUPER															
Chassis No. :	ZAPM4520000062503															
Propellant :	Petrol															
Engine No. :	M454M1024245															
Engine Capacity :	278 cc															
Maximum Power Output :	-															
Maximum Laden Weight :	-															
Unladen Weight :	158 kg															
Year Of Manufacture :	2012															
Original Registration Date :	12 Sep 2013															
Lifespan Expiry Date :	-															
COE Category :	D - Motorcycle															
Quota Premium :	\$1,660.00															
COE Expiry Date :	11 Sep 2023															
Road Tax Expiry Date :	11 Sep 2018															
Inspection Due Date :	11 Sep 2018															
Intended Transfer Date :	14 Mar 2019															
CO2 Emission :	-															
CO Emission :	-															
HC Emission :	-															
NOx Emission :	-															
PM Emission :	-															
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use <a href="#">Enquire Road Tax Payable</a> for fee(s) payable.																
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.																
Amount Payable (From 12 Sep 2018 to 11 Mar 2019)																
	<table><tr><th>Amount Before GST (S\$)</th><th>GST Amount (S\$)</th><th>Amount After GST (S\$)</th></tr><tr><td>Transfer Fee :</td><td>25.00</td><td>-</td><td>25.00</td></tr><tr><td>Sub Total :</td><td></td><td></td><td>25.00</td></tr><tr><td>Nett Road Tax Amount (After Offsetting Over Payment) :</td><td>41.00</td><td>-</td><td>41.00</td></tr></table>	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)	Transfer Fee :	25.00	-	25.00	Sub Total :			25.00	Nett Road Tax Amount (After Offsetting Over Payment) :	41.00	-	41.00
Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)														
Transfer Fee :	25.00	-	25.00													
Sub Total :			25.00													
Nett Road Tax Amount (After Offsetting Over Payment) :	41.00	-	41.00													

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	05/03/2018 09:25
Date Of Accident	02/03/2018 18:00
Exact Location Of Accident	BLK 141 BISHAN ST 12 CARPARK BE7 M/CYCLE LOT 35
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBF1919M
<b>Insured/Policyholder</b>	
Name Of Registered Owner	NG CHOON TENG ANDY
NRIC No	S7827965F
Email Address	ANDY@ADSPRESS.COM.SG
Mobile Phone No	(LOCAL) +65-93881347
Alternative Phone No	OFFICE-93881347

### Vehicle Particulars

Manufacturer	VESPA
Model	GTS 300 SUPER-278CC
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

### Insurance Company

Name of Insurance Company	AUTO & GENERAL INSURANCE (SINGAPORE) PTE. LIMITED.
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	P20019991R00
Cover Note Number	

### Driver

Name of Driver	NG CHOON TENG ANDY
NRIC No	S7827965F
Date Of Birth	27/09/1978
Occupation	INDOOR
Date Of Driving Pass	23/12/1998
Driving Experience	19 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93881347
Fax Number	
Contact Number	OFFICE-93881347
Email Address	ANDY@ADSPRESS.COM.SG

Address	BLK 141 BISHAN STREET 12 #03-516
Postcode	570141
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	RAINING
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	10 UBI AVENUE 3
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO THE TRAFFIC ACCIDENT REPORT NO. T/20180303/7002 ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLN4978L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)



## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**



I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form, and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders

 02/07/2013 13:01


Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

   
Reporting Centre Personnel's Signature  
Name: Tan Chuan Lee  
NRIC/FIN No: G7715235R

### Sketch Plan #2

### SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Traffic Accular Report No. T/20180303/7002 attached.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

03/03/2018 13:01  
Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name: Kim Chock Lok  
NRIC/TIN No.: 9771535R





**SINGAPORE  
POLICE FORCE**



T/20180303/7002

Police Station Of Origin:  
Traffic Police Division HQ  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

1 of 3

Report No. T/20180303/7002

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 03/03/2018 10:27		Vide Report No.:	Station Diary No.:
<b>Informant's Particulars</b>			
Name of Informant: NG CHOON TENG, ANDY		Address: APT BLK 141 BISHAN STREET 12 #03-516 SINGAPORE 570141	
ID Type / ID No.: NRIC NO / S7827965F		Contact No.: Home/Office: Mobile: 93881347	
Nationality: SINGAPORE CITIZEN		Email: andy@e3nsecurity.com.sg	
Sex: Male	Age: 39	Date of Birth: 27/09/1978	Type of Informant: Vehicle Owner
Race: Chinese		Language: English	Institution / School Name:
Occupation: Administration manager		Driving Licence Information: Class: Date of Expiry:	

<b>General Information of the Accident</b>				
Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 02/03/2018 18:02	Type of Location: Car Park
Location:  BISHAN STREET 12  Blk 141 Bishan Street 12 Carpark BE7 (Surface Car Park), motorcycle LOT 35				
Weather: Drizzling		Road Surface: Wet	Road Speed Limit:	
Traffic Flow: Two Way		Traffic Control: Not Controlled	Traffic Volume: No Traffic	
Type of Collision: Moving Vehicle Against - Parked Vehicle			Anyone conveyed by ambulance: No	

<b>Details of Vehicle Involved</b>						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBF1919M	Motorcycle	VESPA	GTS 300 SUPER	White	Slightly Damaged	0
SLN4978L	Car	HONDA	VEZEL	Blue	No Damage	4

<b>Details of Vehicle Insurance</b>				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FBF1919M	AUTO & GENERAL INSURANCE (SINGAPORE) PTE. LIMITED	P20019991R00	12/09/2017	11/09/2018



**SINGAPORE  
POLICE FORCE**



T/20180303/7002

Police Station Of Origin:  
Traffic Police Division HQ  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

2 of 3

Report No. T/20180303/7002

**CONTINUATION OF REPORT**

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Vehicle Owner			
Name	NG CHOON TENG, ANDY	ID No.	S7827965F
Related Vehicle	FBF1919M (Motorcycle)	Contact No.	93881347
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 02 Mar 2018, 18:01:45 hours, one blue Honda vehicle with number plate SLN4978L reversed and collided into my parked motorcycle number plate FBF1919M and caused it to fell and sustained damages. A chinese male, spectacled, aged between 35 to 45, dark hair, wearing jeans and a brown printed floral shirt then proceeded to lift up my motorcycle and put it on side stand and then continue waited for 2 ladies and 2 children to board his vehicle and then left the scene. There was no note or contact left on my vehicle, nor did he check on my motorcycle damages. I have the whole incident captured on CCTV system.



**SINGAPORE  
POLICE FORCE**



T/20180303/7002

Police Station Of Origin:  
Traffic Police Division HQ  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

3 of 3

Report No. T/20180303/7002

**CONTINUATION OF REPORT**

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:  
Not applicable

Signature Of Interpreter:  
Not applicable

Officer In Charge Of Case:

Signature Of Informant.  
The identity of the person making this report has  
been authenticated by SingPass. No signature is  
required.

Date/Time:  
03/03/2018 10:27

Classification Of Case:

Authentication Stamp  
NP168

# PAN EURO BIKES PTE LTD

21 Moonstone Lane #01-01 Poh Leng Building Singapore 328462  
Tel: 62994929 Fax: 62994430 Email: paneurobikes@singnet.com.sg  
Biz/GST Reg: 200916151R

PAGE 1

TO: MOTOR CLAIMS DEPARTMENT  
CHINA TAIPING INS (S) PTE LTD

DATE: 06.03.2018

## ESTIMATED COST OF REPAIRS TO VESPA GTS 300ie SUPER

ENGINE NO : CHASSIS NO :  
VEHICLE NO : FBF 1919M ACCIDENT ON : 02.03.2018  
INSURED : NG CHOOON TENG ANDY

1 PC	LH MIRROR	cut	\$	38.00
1 PC	LH BRAKE LEVER	cut	\$	28.00
1 PC	HEADLAMP COVER	cut	\$	175.00
1 PC	LH BEADING, SILVER	cut	\$	45.00
1 PC	FRONT MUDGUARD	cut	\$	180.00
TOTAL			\$	466.00

LESS 10% \$ 46.60

SUB TOTAL \$ 419.40

### NETT ITEMS:

SEND BODY FOR WELD-KNOCKING REPAIR	\$	120.00	100
SEND NEW COVERS, REAR BOX AND BODY FOR PAINTING	\$	380.00	280
LABOUR CHARGE	\$	250.00	150
TOTAL	\$	1,169.40	530

### REMARKS:

Kindly send a surveyor down for an 3rd Party claim against your insured SLN 4978L.

Thank You.

Kin Wah: 9731-7133

ADD 7% GST

GRAND TOTAL

\$ 81.86

\$ 1,251.26

947.4

part buy part.

~~before~~

4Days

After paint photos.

Guo Qiang - 82880282

12/3/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**Veron Chen (LKKAuto)**

---

**From:** PanEuroBikes <paneurobikes@singnet.com.sg>  
**Sent:** Friday, 20 July 2018 5:45 PM  
**To:** Veron Chen (LKKAuto)  
**Subject:** RE: FBH 1919M-DOA: 2/3/18 (CHINA TAIPING)  
**Attachments:** image1.jpeg; image2.jpeg; image3.jpeg; image4.jpeg; image5.jpeg; image6.jpeg; image7.jpeg; image8.jpeg

Dear Veron,

Please find attached. I shall forward you the LOD and docs soon.

Best Regards,  
Kin Wah  
Pan Euro Bikes Pte Ltd  
Tel : +65 6299-4929  
Fax : +65 6299-4430  
Mobil : +65 9731-7133, +65 8121-2173  
Email : paneurobikes@singnet.com.sg

---

**From:** Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]  
**Sent:** Monday, July 02, 2018 4:03 PM  
**To:** paneurobikes@singnet.com.sg  
**Cc:** SUR  
**Subject:** RE: FBH 1919M-DOA: 2/3/18 (CHINA TAIPING)

Dear Kin Wah,

WITHOUT PREJUDICE

Offer finalize amount \$949.40 @ 4 working days.

Kindly confirmed and forward us resurvey photos.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Tuesday, 12 June 2018 3:28 PM  
**To:** 'paneurobikes@singnet.com.sg' <paneurobikes@singnet.com.sg>  
**Subject:** FW: FBH 1919M-DOA: 2/3/18 (CHINA TAIPING)

Dear Kin Wah,

Offer finalize amount \$949.40 @ 4 working days.

Kindly confirmed and forward us resurvey photos.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Veron Chen (LKKAuto)

**Sent:** Tuesday, 15 May 2018 5:03 PM

**To:** [paneurobikes@singnet.com.sg](mailto:paneurobikes@singnet.com.sg)

**Subject:** RE: FBH 1919M-DOA: 2/3/18 (CHINA TAIPING)

Dear Kin Wah,

Offer finalize amount \$949.40 @ 4 working days.

Kindly confirmed and forward us resurvey photos.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Mar 2018		09 Mar 2018 16:30 <a href="#">Edit Adj Rpt</a>	<b>S\$949.40</b> <a href="#">Edit Estimates</a>	<b>S\$949.40</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>



Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured: -, Co. Reg. No.: -									
Main Claimant: <b>NG CHOON TENG ANDY</b>									
Vehicle Reg. No.: <b>FBF1919M</b>		Date of Loss: 02/03/2018 00:00 - :59 [53 Months and 18 Days From LTA Reg Date (Man Yr)]							
Claim Type: <b>TP / SNM18D01271C02</b>		Policy/Cover Note No.: DMHCSN1733401700							
Vehicle Reg. No. (Insured): <b>SLN4978L</b>		Policy No. (Claimant):							
		Excess: S\$0.00							
Repairer: <b>Pan Euro Bikes Pte Ltd (HQ)</b> 21 Moonstone Lane #01-01 Poh Leng Building, 328462 Serangoon - Tel: 62994929									
Handling Insurer: <b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Irene Tay Hui Ping</b> - 638986192]									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... [Final Rpt due 20/03/2018]									
Adj Asg. Remarks: EST \$1251.26, CASE WITH SJE.									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

\*FBF1919M (SNM18D01271C02)  
[SLN4978L]  
TP  
NG CHOON TENG ANDY  
Mar 2 2018 12:00AM  
[-]  
Pan Euro Bikes Pte Ltd

Upload Documents   Upload Photos   Compose New Letter

View   View In Browser

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/07/18 17:18	General View	 Load PDF	
2	30/07/18 17:18	Reinspection Photo	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer
<small>Note: Remarks are private unless you show it to other parties.</small>

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118004650/GVD3E2

Date: 14/08/2018

## REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMHCSN1733401700

Claimant Vehicle  
No : FBF1919MInsured Vehicle  
No : SLN4978L

Date of Loss: 02/03/2018

Nature of Claim: TP

Claim  
No: SNM18D01271C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: FBF1919M

Make &amp; Model: VESPA GTS 300 SUPER, 278cc

Engine No: M454M1024245

Reg. Date: 12/09/2013 (Man. Year: 2012)

Chassis No: ZAPM4520000062503

Colour: White

Odometer: 8192 km

Engine Capacity: 278 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 120/70-12

Rear Tyre Size: 130/70-12

Front Left Side: Michelin 5 mm

Rear Left Side: Michelin 5 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	419.40	419.40	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	750.00	530.00	220.00	29.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>1,169.40</b>	<b>949.40</b>	<b>220.00</b>	<b>18.81</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	<b>81.86</b>	<b>66.46</b>	<b>15.40</b>	<b>18.81</b>
<b>Nett Amount (\$\$)</b>	<b>1,251.26</b>	<b>1,015.86</b>	<b>235.40</b>	<b>18.81</b>

## INSPECTION

Date of Assignment: 09/03/2018

Date Inspected: 12/03/2018 Inspected At:

Pan Euro Bikes Pte Ltd (HQ)  
21 Moonstone Lane #01-01 Poh Leng  
Building  
Singapore 328462

Estimated Period of Repair: 4.0 days

**Adjuster:** XING GUO QIANG

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 14 Aug 2018)	
<b>Parts:</b>	N/A	VESPA GTS 300 SUPER 278cc (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for FBF1919M)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH MIRROR	Cut	38.00 FL	*38.00 FL
2	1		*LH BRAKE LEVER	Cut	28.00 FL	*28.00 FL
3	1		*HEADLAMP COVER	Deformed	175.00 FL	*175.00 FL
4	1		*LH BEADING SILVER	Cut	45.00 FL	*45.00 FL
5	1		*FRONT MUDGUARD	Cut	180.00 FL	*180.00 FL
					<b>Sub Total (S\$)</b>	<b>466.00</b>
					<b>- List Item Discount on L Items 10.00/10.00% (S\$)</b>	<b>46.60</b>
					<b>Total Parts (S\$)</b>	<b>419.40</b>

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	SEND BODY FOR WELD-KNOCKING REPAIR	New	120.00	100.00
2	SEND NEW COVERS, REAR BOX AND BODY FOR PAINTING	New	380.00	280.00
3	LABOUR CHARGE	New	250.00	150.00
Gross Labour Cost (S\$)			<b>750.00</b>	<b>530.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >