

12/03/2018

ASS. REC. BY:

REF: CS/SMO18004652/Ktd3kz

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Melvin Yong

of SMO

Date/Time: 9/3/18 @ 6:17pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FBL 8670B

Insured: GBE 9936R

at Workshop m/s GA Motor

Tel: 6453 9903

of Blk 32, Sin Ming Drive # 01-331

Policy No:

Claim No: CMTD1800949/NSW

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 01/03/2018

CA / REV / REP. / REV 24 HRS ^{1wp?}

H.O.D. Endorsement:

Date/Time: 10:50am @ 12/3/18

Person Contacted: Tan

Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	FBL 8670B -x
	GBE 9936R
13/3-	Sent preli advise via email
31/5-	Confirm lump sum 2050 (Red: 1470, 41%)

ASS. REC. BY:

REF: Jomol

Kenneth

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD/TP/WS/TP RES/OD RES/EVA/INV/MV
 To inspect Vehicle No: _____
 at Workshop n/s City GA
 of _____
 Insured _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 04 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: FBL 8670B Yr Regn: 04, 17
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Traller or _____
 Make: Yamaha FBN150 c.c. 149
 Colour: Red / Grey A/C: Insured / Std / NI / NA
 Sp. Reading: 28315 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: MEIR6166-200213
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brake: Inorder / Jammed / Leaked / Burnt or _____
 Modl: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 100/80R17
 R: 140/60R17
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or MR F
 Front R/Bal. 3 mm Rear R/Bal. 4 mm
 L/Bal. _____ mm L/Bal. _____ mm
 D.O.A. 11/3/18 D.O.I. 12/3/18
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or o/s body
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>13/3</u>	<u>File pass to Catherine</u>

RECEIVED 9 MAY 2018

Date/Time, File Pass to? : Prell. Report
 : Final Report
11/3/18 Typist
 Date/Time, File Return to?

Days Of Repair: 4
 Resurvey No. of Trip: 1

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech Invs (\$)
 : Weekend (\$)

Survey Fee:	<u>250</u>
Transportation:	_____
S + RS St	_____
Photos	_____
Others	_____
TOTAL	<u>250</u>

Report Format: TP
 Lump Sum / I.B.I: (\$ 2050)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO18004652/K1d3

50 RAFFLES PLACE
#05-01/06
SINGAPORE LAND TOWERSINGAPORE 048623

Date : 12-03-2018



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBE 9936R	Veh. Inspected	FBL 8670B
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1800949/NSW	Excess (\$)	0.00
Assign From	MELVIN YONG	Assign Date	12/03/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	01/03/2018	Inspection Date	12/03/2018
Survey held at	GA MOTOR BLK 32 SIN MING DRIVE #01-331 SINGAPORE 575706		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Nivitha (LKK Auto)

From: Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>
Sent: Friday, 9 March 2018 6:17 PM
To: GA MOTOR; assignments@lkkauto.com; admin-d@lkkauto.com
Cc: Ngo, Sau Wei Shawn; Henry, Irene James
Subject: RE: accident involving GBE9936R&FBL8670B at Blk118 commonwealth crescent;
Claim No. : CMTD1800949/NSW

Our Claim Reference: CMTD1800949/NSW

Your Reference: FBL8670B

Dear Mr Tan,

We acknowledged receipt of your claim documents.

Please be informed that Mr Shawn Ngo is the handler of this case.

We have appointed LKK AUTO to conduct the survey.

Aside to LKK AUTO,

Please make arrangement to conduct the survey for FBL 8670B.

Best Regard

Melvin Ye

Claims Division

D: 6322 4667 | T: 6461 6555 | F: 6221 3302



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential

and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: GA MOTOR [mailto:gamotor@gmail.com]

Sent: Friday, 9 March, 2018 2:11 PM

To: Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>

Subject: Re: accident involving GBE9936R&FBL8670B at Blk118 commonwealth crescent; Claim No. : CMTD1800949/NSW

Hi, Melvin,

Please arrange Mr. Kenneth Kong (LKK Auto Consultants) for the pre-repair Survey

Thanks

On Fri, Mar 9, 2018 at 1:30 PM, Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg> wrote:

Our Reference: CMTD1800949/NSW

Your Reference: FBL8670B

Without Prejudice

Date: 9th March 2018

Attention:

GA MOTOR

Dear Mr Tan,

ACCIDENT INVOLVING GBE9936R & FBL8670B ON 01.03.2018

We refer to your Notice of Accident dated 09/03/2018.

Please be informed that Mr Shawn Ngo is the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Melvin Ye

Claims Division

D: 6322 4667 | T: 6461 6555 | F: 6221 3302



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: claimsreport

Sent: Friday, 9 March, 2018 10:37 AM

To: Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>

Cc: Ngo, Sau Wei Shawn <Shawn.Ngo@sompo.com.sg>

Subject: FW: accident involving GBE9936R&FBL8670B at Blk118 commonwealth crescent; Claim No. : CMTD1800949/NSW

Hi Melvin,

For your attention and necessary action please.

Best Regards

Raba'ah Mohd Ali

Claims Department

D: 6329 5215 | T: 6461 6555 | F: 6221 3147

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

 Please consider the environment before printing this email.

From: GA MOTOR [<mailto:gamotor@gmail.com>]

Sent: Friday, 9 March, 2018 10:26 AM

To: claimsreport <claimsreport@sompo.com.sg>

Subject: Re: accident involving GBE9936R&FBL8670B at Blk118 commonwealth crescent

Hi,

We require you to send a surveyor for a pre- repair inspection as highlighted in our earlier email 3 days ago. Please make the arrangements and inform us as soon as possible,

Thanks,



无病毒。 www.avg.com

On Tue, Mar 6, 2018 at 1:43 PM, GA MOTOR <gamotor@gmail.com> wrote:

attached documents for the claim of accident motorcycle FBL8670B

--

Best Regards,
Tan Sin Huat
GA MOTOR
BLK 32 SIN MING DRIVE
#01-331 SINGAPORE 575706

Tel: +65 64539903

Fax: +65 64539904

--

Best Regards,
Tan Sin Huat
GA MOTOR
BLK 32 SIN MING DRIVE
#01-331 SINGAPORE 575706

Tel: +65 64539903

Fax: +65 64539904

--

Best Regards,
Tan Sin Huat
GA MOTOR
BLK 32 SIN MING DRIVE
#01-331 SINGAPORE 575706

Tel: +65 64539903

Fax: +65 64539904

--
Best Regards,
Tan Sin Huat
GA MOTOR
BLK 32 SIN MING DRIVE
#01-331 SINGAPORE 575706

Tel: +65 64539903
Fax: +65 64539904

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Tuesday, 13 March 2018 3:03 PM
To: Admin-D (LKKAuto); 'Ye, Yong Kang Melvin'; assignments
Cc: 'Ngo, Sau Wei Shawn'; 'Henry, Irene James'; SUR
Subject: RE: accident involving GBE9936R&FBL8670B at Blk118 commonwealth crescent; Claim No. : CMTD1800949/NSW
Attachments: PRELI ADVISED FBL 8670B.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **FBL 8670B**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Monday, 12 March 2018 10:51 AM
To: 'Ye, Yong Kang Melvin' <melvin.ye@sompo.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Ngo, Sau Wei Shawn' <Shawn.Ngo@sompo.com.sg>; 'Henry, Irene James' <irene.henry@sompo.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: accident involving GBE9936R&FBL8670B at Blk118 commonwealth crescent; Claim No. : CMTD1800949/NSW

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ye, Yong Kang Melvin [<mailto:melvin.ye@sompo.com.sg>]
Sent: Friday, 9 March 2018 6:17 PM
To: GA MOTOR <gamotor@gmail.com>; assignments@lkkauto.com; admin-d@lkkauto.com
Cc: Ngo, Sau Wei Shawn <Shawn.Ngo@sompo.com.sg>; Henry, Irene James <irene.henry@sompo.com.sg>
Subject: RE: accident involving GBE9936R&FBL8670B at Blk118 commonwealth crescent; Claim No. : CMTD1800949/NSW

Our Claim Reference: CMTD1800949/NSW

Your Reference: FBL8670B

TC AUTOCLINIC PTE LTD
1 SIXTH LOK YANG ROAD
SINGAPORE 628099

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SJJ2645U

TOTAL LABOUR CHARGES	3410.00
TOTAL SPARE PARTS CHARGES	3177.97
GRAND TOTAL	6587.97 *

* All charges do not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: CMTD1800949/NSW

Date: 13/3/2018

Our Ref: CS/SMO18004652/Ktd3

The Motor Claims Department
SOMPO INSURANCE SINGAPORE PL

Without Prejudice

Dear Sirs/Mdm


PRELIMINARY ADVICE OF VEHICLE NO. FBL 8670B

Please be informed that we had conducted the inspection of the above mentioned vehicle on 13/3/2018 at the premises of M/s GA Motor and have the following to report: -

Workshop Estimate Amount	: S\$ <u>3,520.00</u>
Revised Estimate Amount	: S\$ <u>2,080.00</u>
"Check" Items Amount	: S\$ <u>835.00</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the o/s body portion.



Repair days: 4

Comments/ Present Status:

Damages Consistent.

Yours faithfully
Kenneth
Licensed Appraiser

TC AUTOCLINIC PTE LTD
 1 SIXTH LOR YANG ROAD
 SINGAPORE 638099

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SJJ8835U

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
26	REFLEX REFLECTOR ASSY-LH <i>SVC</i>	26565-EM00A	41.60	X	
27	REFLEX REFLECTOR ASSY-RH	26560-EM00A	41.60	X	
28	LAMP ASSY-REAR COMBI, RH TRUNK <i>SVC</i>	26550-EM01A	86.40	X	
29	LAMP ASSY-REAR COMBI, LH TRUNK <i>SVC</i>	26555-EM01A	86.40	X	
30	PACKING-LAMP, RH REAR <i>SVC</i>	26553-EM00A	12.10	X	
31	PACKING-LAMP, LH REAR <i>SVC</i>	26558-EM00A	12.10	X	
32	CLIP-RRAR COMBI LAMP #03.6DEACH XSPCD <i>NEC</i>	26398-EM00A	21.60	—	
33	LAMP ASSY-REAR COMBI, RH <i>OK</i>	26550-EM00A	172.90	—	
34	LAMP ASSY-REAR COMBI, LH <i>OK</i>	26555-EM00A	172.90	—	
SUB TOTAL			1329.00	2587.10	303.88
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			265.80	776.13	0.08
GRAND TOTAL			1063.20	1810.97	303.88
OVERALL TOTAL			3177.87		

LEGEND: REMARKS (OK) - APPROVED, REMARKS (X) - NOT APPROVED

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	01/03/2018 14:31
Date Of Accident	01/03/2018 13:10
Exact Location Of Accident	BLK 118 COMMONWEALTH CRESCENT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBL8670B
Insured/Policyholder	
Name Of Registered Owner	PAS AUTO PTE LTD
Co Reg No	201512120M
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-81498396
Alternative Phone No	OFFICE-64523938
Vehicle Particulars	
Manufacturer	YAMAHA
Model	FZN150
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5090595382
Cover Note Number	
Driver	
Name of Driver	ZAMERY BIN ADANAN
NRIC No	S7207967A
Date Of Birth	08/03/1972
Occupation	OUTDOOR
Date Of Driving Pass	08/02/1996
Driving Experience	22 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81498396
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address BLK 557 BEDOK NORTH STREET 3 #05-982
 Postcode 460557
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLIDED INTO PARKED VEHICLE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 0

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER STATEMENT (ATTENDED BY: JAMES NG)

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

Details of Witness 1

Name -
 Phone Number -
 Email Address

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBE9936R
 Vehicle Make/Model/Colour MIT FUSO CANTER
 Details Of Properties
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver LIM LAY HEE
 NRIC/Passport Number S0152784C
 Contact Number 81289430 / 62660644
 Address NO. 9 THIRD LOK YANG ROAD
 Postcode 628004
 Insurance Company Name
 Nature Of Damage

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for compliance with requirements under any regulations, laws or court orders.



PAS AUTO PTE LTD
Blk 32, Sin Ming Drive
#01-325 Singapore 575708
Tel: 0452 3938 Fax: 0452 7938



Policyholder's Signature
Date & Time:

01 MAR 2018

Driver's Signature
(If driver is not the policyholder)
Date & Time:

01 MAR 2018

Reporting Centre Personnel's Signature

Name: **NG WING KIN JAMES**
NRIC/FIN No.: **S7927881E**

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

When I just finish my lunch so I went to the motor parking lot I realize that my bike have fall with another motor. I was so shock; didn't know who has ~~been~~ hit my motor and this is first motor that hit ~~and~~ ^{my motor} ~~motor~~. Then a man came to me and told me that the lorry vehicle number so he ~~went~~ left. The driver come at a ~~approach~~ me and said that he had ~~been~~ reversed the lorry and ~~knocked~~ the first motor and my motor. I ask him to call his boss and he ~~said that he~~ ~~he~~ pass the hp to me and the boss said that ask me to make a accident report.

DECLARATION PAS AUTO PTE LTD

We declare the following particulars are true in every respect.
 #01-325 Singapore 575706
 Tel: 6452 3938 Fax: 6452 7936

Policyholder's Signature
 Date & Time:

01 MAR 2018

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

01 MAR 2018

Reporting Centre Personnel's Signature

Name: NG WING KIN JAMES
 NRIC/FIN No.: S7927881E



盛 摩 哆 GA MOTOR



Block 32, Sin Ming Drive, #01-331, Singapore 575706

TEL: 4539903, 4539904 FAX: 4539904

Importer & Exporter - New & Used Motorcycles. Spare Parts & Accessories.
Dealer of Honda, Yamaha, Suzuki and Vespa, etc. Repair & Service all motorcycles, scooters.

Date: 005-03-2018

Estimated repair list for the accident motorcycle Yamaha FZ 16 Vehicle No. FBL8670B

1 pc	Handle bar	Pr	\$110.00	✓
1 set	Handle balancer	Not/let	\$30.00	✓
1 set	Mirror	let	\$80.00	✓
1 pc	Brake lever	Pr	\$35.00	✓
1 pc	Tank cover (right)	Pr	Respray \$300.00	150/1m
1 pc	Side cover (right)	Pr	\$180.00	✓
2 pcs	Front fork inner tubes	TT/Pr	\$230.00	✓
1 set	Fork oil seal & fork oil	Pr	\$55.00	✓
2 pcs	Fork legs	TT	\$240.00	✓
1 pc	Bottom steering stem	Pr	\$250.00	✓
1 set	Steering cone & bearing	Pr	\$60.00	✓
1 pc	Brake padel	Pr	\$70.00	✓
1 pc	Clutch cover	Pr	\$280.00	✓
1 pc	Clutch gasket	Pr	\$25.00	✓
1 L	Engine oil	Pr	\$20.00	✓
1 set	Front footrest	Pr	\$70.00	✓
1 Set	Rear footrest	Pr	\$55.00	X
1 pc	Exhaust pipe	Pr	\$750.00	✓
	Spray Rear Box		\$300.00	150/1m
	Towing		\$30.00	✓
	Labour		\$350.00	150/1

Total: \$3520.00

Not Authorized
11 Sep 8 2 050h
Respray After Paint
4 days



Meneth

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO18004652/Ktd3e2	
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 08-05-2018	
		Code : SMO	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBE 9936R	Veh. Inspected	FBL 8670B
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1800949/NSW	Excess (\$)	0.00
Assign From	MELVIN YONG	Assign Date	09/03/2018
2. Vehicle Particulars & Condition			
Make & Model	YAMAHA FZN150	c.c	149
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	ME1RG1616G2002134	Colour	RED / GREY
Odometer	28315	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	100/80 R17	MRF	3 mm
L/H Front Tyre			mm
R/H Rear Tyre	140/60 R17	MRF	4 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	01/03/2018	Inspection Date	12/03/2018
Survey held at	GA MOTOR BLK 32 SIN MING DRIVE #01-331 SINGAPORE 575706		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBL 8670B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	HANDLE BAR	BENT	110.00	110.00
1	SET HANDLE BALANCER	DENTED / CUT	30.00	30.00
1	SET MIRROR	CUT	80.00	80.00
1	BRAKE LEVER	BENT	35.00	35.00
1	SIDE COVER (RIGHT)	DENTED	180.00	180.00
2	FRONT FORK INNER TUBES	TWISTED / BENT	230.00	230.00
1	SET FORK OIL SEAL & FORK OIL	NECESSARY	55.00	55.00
2	FORK LEGS	TWISTED	240.00	240.00
1	BOTTOM STEERING STEM	BENT	250.00	250.00
1	SET STEERING CONE & BEARING	NECESSARY	60.00	60.00
1	BRAKE PADEL	DENTED	70.00	70.00
1	CLUTCH COVER	DENTED	280.00	280.00
1	CLUTCH GASKET	NECESSARY	25.00	25.00
1	ENGINE OIL	NECESSARY	20.00	20.00
1	SET FRONT FOOTREST	DENTED	70.00	70.00
1	SET REAR FOOTREST	TO REPAIR SEE LABOUR	55.00	-
1	EXHAUST PIPE	DENTED	750.00	750.00
	LESS 10% DISCOUNT		-	-248.50
			2,540.00	2,236.50
<u>SPECIAL NETT ITEMS</u>				
1	TANK COVER (RIGHT)(SCRATCHED)(SN)	RESPRAY	300.00	100.00
			300.00	100.00
<u>LABOUR</u>				
	SPRAY REAR BOX.		300.00	150.00
	TOWING.		30.00	30.00
	LABOUR INCLUSIVE OF THE REPAIR OF SET REAR FOOTREST.		350.00	150.00
			-	-
			-	-
			680.00	330.00
GRAND TOTAL			3,520.00	2,666.50



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,050.00
---	--	--	-----------------

Report Ref No. CS/SMO18004652/Ktd3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.