

ASS. REC. BY:

REF: CS/SMO18004653/4vd3/12

Special Instruction:

Surveyor: MarcusASSIGNMENT (Office)From (Person): Irene Jamesof SMODate/Time: 12/3/18 @ 10:07am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKU 4025L

Insured:

GBE 1749S

at Workshop m/s

Fastech Auto

Tel:

6746 5405

of

1 Kaki Bkt Ave 6 # 01-16

Policy No:

Claim No:

CMTD1801021

Sum Insured:

Excess:

Make of Veh:

D.O.A. 6/3/18

(Client's Record)

CA / REV / REP. / REV 24 HRS

'wp'

H.O.D. Endorsement:

Date/Time: 10:34am 12/3/18

Person Contacted:

NancyVehicle: IN/OUT

Date/Time

Action/Instruction (✓) EstimateSKU 4025L-XGBE 1749S-X12/3/18Informed Irene pending est from repairer

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD ☒ TP ☒ WS ☒ TP RES ☒ OD RES ☒ EVA ☒ INV ☒ MV
 To Inspect Vehicle No: SKU 4025L
 at Workshop m/s: L.
 of: _____
 Insured: GS 17495
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 75
 IDAC Accident Report Consistent? : Yes or No
 G/A / PR Seen: 5 Consistent? : Yes or No
 Est. Repairs: 5 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SKU 4025L Yr Regn: 1, 13
 Type: ☒ M. Car / ☒ M. Cycle / ☒ Bus / ☒ Van / ☒ Lorry / ☒ Taxi / ☒ Prime Mover /
 Truck / Trailer or CA
 Make: BMW 316i c.c. 1598
 Colour: Grey A/C: ☒ Insured / ☒ Std / ☒ NI / ☒ NA
 Sp. Reading: 84028 T/Radio: ☒ Insured / ☒ Std / ☒ NI / ☒ NA
 Eng/No: _____
 C/No: WBA3A12040J719613
 Gen. Cond: ☒ Good / ☒ Fair / ☒ Poor / ☒ Burnt
 Steering: ☒ In order / ☒ Jammed / ☒ Leaked / ☒ Burnt or
 Brake: ☒ In order / ☒ Jammed / ☒ Leaked / ☒ Burnt or
 Modi: ☒ Nil / ☒ S/Rim / ☒ STD A/Rim or
 Tyre Size: F: _____ R: 225/45R18
 BS / ☒ DUN / ☒ EXNOVA / ☒ GY / ☒ FS / ☒ LIZA / ☒ MIC / ☒ OHTSU / ☒ PIR / ☒ SUMI /
 TOYO / YOKO or
 Front: 6 mm Rear: 6 mm
 R/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 6/3/18 D.O.I. 12/3/18
 Survey held at _____
 Des. of Damages: ☒ Frt / ☒ Rear / ☒ O/S / ☒ N/S / ☒ U/C / ☒ Rooftop or
Rear
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
20/3/18	have G/A LTA 60824 dep 12800 4hrs. 10 min.
22/3/18	confirm L/S & \$200 with Alan (Reel 10,072.27, 55%)
22/3/18	Email preli revised to Irene

RECEIVED 22 MAR 2018

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1)

Date/Time, File Return to?

2) 22/3 typist

Report Format: TPLump Sum / I.B.I. (\$) 8200pDays Of Repair: 5Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:

Transportation:

\$ + RS, \$

Photos

Others

TOTAL

450

Survey Department Check List (Case Handler)

Reference No.: CS | SMO | 800 4653 | Uvd3

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all information created by the assignment team are ACCURATE.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 22/3/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/201



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO18004653/Uvd3

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERS SINGAPORE 048623

Date : 12-03-2018



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBE 1749S	Veh. Inspected	SKU 4025L
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1801021	Excess (\$)	0.00
Assign From	IRENE JAMES	Assign Date	12/03/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	06/03/2018	Inspection Date	12/03/2018
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



Auto
Consultants
Pte Ltd

Company Registration No. 19960711

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564

Your ref: CMTD1801021

Our ref: CS/SMO18004653/Uvd3

Date: 22/3/2018

The Motor Claims Department
M/s SOMPO INSURANCE SINGAPORE PTE LTD

Dear Sir/Madam

PRELIMINARY ADVICE OF VEHICLE NO. SKU 4025L


We thank for your instruction on 12/3/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 12/3/2018 at the premises of M/s FASTECH AUTO PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$18,272.27
Revised Estimate Amount	: S\$8,200.00 (LUMP SUM)
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion



Comments/Present Status:
Damages Consistent

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 22 March 2018 9:39 AM
To: 'Henry, Irene James'
Cc: SUR
Subject: RE: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:SKU4025L
Attachments: SKU 4025L PRELI ADVISED.pdf

Dear Irene,

Enclosed preliminary revised of vehicle SKU 4025L
Date of survey: 12/3/2018
Number of days:5 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 13 March 2018 3:05 PM
To: 'Henry, Irene James' <irene.henry@sompo.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: RE: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:SKU4025L

Dear Irene,

Please be informed that we have inspected the vehicle SKU 4025L on 12/3/2018 .

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Monday, 12 March 2018 10:37 AM
To: 'Henry, Irene James' <irene.henry@sompo.com.sg>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:SKU4025L

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Henry, Irene James [<mailto:irene.henry@sompo.com.sg>]

Sent: Monday, 12 March 2018 10:07 AM

To: assignments <assignments@lkkauto.com>

Cc: Catherine Chong (LKK Auto) <admin-d@lkkauto.com>; Nancy Lam <nancy.lam@fastechauto.com.sg>

Subject: FW: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:SKU4025L

Our Claim Reference: CMTD1801021

Dear LKK AUTO,

Kindly assist to arrange to conduct motor survey of the mentioned vehicle (SKU 4025L)

Best Regards

Irene Henry

Claims Division

D: 6322 4618 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

From: Nancy Lam [<mailto:nancy.lam@fastechauto.com.sg>]

Sent: Monday, 12 March, 2018 9:58 AM

To: Henry, Irene James <irene.henry@sompo.com.sg>

Subject: RE: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:SKU4025L

Dear Sir

Please arrange LKK Auto Consultants to survey the car.

Regards,
Nancy Lam
Fastech Auto Pte Ltd
Tel: 6746 5405
Fax: 6745 8520

From: Henry, Irene James [mailto:irene.henry@sompo.com.sg]
Sent: Monday, March 12, 2018 9:57 AM
To: Nancy Lam <nancy.lam@fastechauto.com.sg>
Subject: RE: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:SKU4025L

Date: 12TH March 2018

Without Prejudice

BY EMAIL ONLY

Attention:

M/S FASTECH AUTO PTE LTD

Accident involving GBE 1749S & SKU 4025L on 06.03.2017

Dear Sir

We refer to your Notice of Accident dated 09/03/2017.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Ma Chin Fook (North area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Irene Henry

Claims Division

D: 6322 4618 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

From: Nancy Lam [<mailto:nancy.lam@fastechauto.com.sg>]

Sent: Friday, 9 March, 2018 5:17 PM

To: Claims - Motor Survey <MotorSurvey@sompo.com.sg>

Subject: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:SKU4025L

Hi Sir

My client claiming your insured GBE 1749S.

Please kindly arrange PRS for SKU 4025L .

Date of accident 06.03.2018

In accordance to APPENDIX C Pre-action Protocol for Non-Injury Motor Accident Cases of PRACTICE DIRECTIONS AMENDMENT NO. 1 OF 2016 paragraph 2.3, you are require to provide a list of at least 10 motor surveyors within 2 days of the notice.

Regards,

Nancy Lam

Fastech Auto Pte Ltd

Tel: 6746 5405

Fax: 6745 8520

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 13 March 2018 3:04 PM
To: 'Henry, Irene James'
Cc: SUR
Subject: RE: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:SKU4025L

Dear Irene,

Please be informed that we have inspected the vehicle SKU 4025L on 12/3/2018 .

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Monday, 12 March 2018 10:37 AM
To: 'Henry, Irene James' <irene.henry@sompo.com.sg>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:SKU4025L

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Henry, Irene James [<mailto:irene.henry@sompo.com.sg>]
Sent: Monday, 12 March 2018 10:07 AM
To: assignments <assignments@lkkauto.com>
Cc: Catherine Chong (LKK Auto) <admin-d@lkkauto.com>; Nancy Lam <nancy.lam@fastechauto.com.sg>
Subject: FW: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:SKU4025L

Our Claim Reference: CMTD1801021

Dear LKK AUTO,

Kindly assist to arrange to conduct motor survey of the mentioned vehicle (SKU 4025L)

Best Regards

Irene Henry

Claims Division

D: 6322 4618 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

From: Nancy Lam [<mailto:nancy.lam@fastechauto.com.sg>]

Sent: Monday, 12 March, 2018 9:58 AM

To: Henry, Irene James <irene.henry@sompo.com.sg>

Subject: RE: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:SKU4025L

Dear Sir

Please arrange LKK Auto Consultants to survey the car.

Regards,

Nancy Lam

Fastech Auto Pte Ltd

Tel: 6746 5405

Fax: 6745 8520

From: Henry, Irene James [<mailto:irene.henry@sompo.com.sg>]

Sent: Monday, March 12, 2018 9:57 AM

To: Nancy Lam <nancy.lam@fastechauto.com.sg>

Subject: RE: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:SKU4025L

Date: 12TH March 2018

Without Prejudice

BY EMAIL ONLY

Attention:

M/S FASTECH AUTO PTE LTD

Accident involving GBE 1749S & SKU 4025L on 06.03.2017

Dear Sir

We refer to your Notice of Accident dated 09/03/2017.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Ma Chin Fook (North area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Irene Henry

Claims Division

D: 6322 4618 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

From: Nancy Lam [<mailto:nancy.lam@fastechauto.com.sg>]
Sent: Friday, 9 March, 2018 5:17 PM
To: Claims - Motor Survey <MotorSurvey@sompo.com.sg>
Subject: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:SKU4025L

Hi Sir

My client claiming your insured GBE 1749S.

Please kindly arrange PRS for SKU 4025L .

Date of accident 06.03.2018

In accordance to APPENDIX C Pre-action Protocol for Non-Injury Motor Accident Cases of PRACTICE DIRECTIONS AMENDMENT NO. 1 OF 2016 paragraph 2.3, you are require to provide a list of at least 10 motor surveyors within 2 days of the notice.

Regards,
Nancy Lam
Fastech Auto Pte Ltd
Tel: 6746 5405
Fax: 6745 8520

Nivitha (LKK Auto)

From: Henry, Irene James <irene.henry@sompo.com.sg>
Sent: Monday, 12 March 2018 10:07 AM
To: assignments
Cc: Catherine Chong (LKK Auto); Nancy Lam
Subject: FW: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:SKU4025L

Our Claim Reference: CMTD1801021

Dear LKK AUTO,

Kindly assist to arrange to conduct motor survey of the mentioned vehicle (SKU 4025L)

Best Regards

Irene Henry

Claims Division

D: 6322 4618 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

From: Nancy Lam [mailto:nancy.lam@fastechauto.com.sg]
Sent: Monday, 12 March, 2018 9:58 AM
To: Henry, Irene James <irene.henry@sompo.com.sg>
Subject: RE: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:SKU4025L

Dear Sir

Please arrange LKK Auto Consultants to survey the car.

Regards,
Nancy Lam
Fastech Auto Pte Ltd
Tel: 6746 5405
Fax: 6745 8520

From: Henry, Irene James [mailto:irene.henry@sompo.com.sg]
Sent: Monday, March 12, 2018 9:57 AM
To: Nancy Lam <nancy.lam@fastechauto.com.sg>
Subject: RE: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:SKU4025L

Date: 12TH March 2018

Without Prejudice

BY EMAIL ONLY

Attention:

M/S FASTECH AUTO PTE LTD

Accident involving GBE 1749S & SKU 4025L on 06.03.2017

Dear Sir

We refer to your Notice of Accident dated 09/03/2017.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Ma Chin Fook (North area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards
Irene Henry
Claims Division



Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

From: Nancy Lam [<mailto:nancy.lam@fastechauto.com.sg>]
Sent: Friday, 9 March, 2018 5:17 PM
To: Claims - Motor Survey <MotorSurvey@sompo.com.sg>
Subject: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:SKU4025L

Hi Sir

My client claiming your insured GBE 1749S.

Please kindly arrange PRS for SKU 4025L .

Date of accident 06.03.2018

In accordance to APPENDIX C Pre-action Protocol for Non-Injury Motor Accident Cases of PRACTICE DIRECTIONS AMENDMENT NO. 1 OF 2016 paragraph 2.3, you are require to provide a list of at least 10 motor surveyors within 2 days of the notice.

Regards,
Nancy Lam
Fastech Auto Pte Ltd
Tel: 6746 5405
Fax: 6745 8520

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0556G
Vehicle Details	
Vehicle No.:	SKU4025L
Vehicle to be Exported:	No
Intended De-registration Date:	12 Mar 2018
Vehicle Make:	B.M.W.
Vehicle Model:	316I 1.6 AT D/AB 4DR ABS HID
Primary Colour:	Grey
Manufacturing Year:	2012
Engine No.:	A708J371N13B16A
Chassis No.:	WBA3A12040J719613
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$33,423.00
Original Registration Date:	31 Jan 2013
First Registration Date:	31 Jan 2013
Transfer Count:	1
Actual ARF Paid:	\$23,423.00 11711
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Jan 2023
PARF Rebate Amount:	\$16,396.00
Intended COE Rebate Details	
COE Expiry Date:	30 Jan 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$91,010.00
COE Rebate Amount:	\$44,428.00
Total Rebate Amount:	\$60,824.00

The information contained herein is correct as at 12 Mar 2018

OK



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)


Post an Advertisement

Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

New 5 Year Coe Renewal Toyota Altis 1.6A



\$2800 Downpayment Monthly.
From \$688 Onwards. Lowest
3.68%P.A@GV Cars Financing.
GV Credit Pte Ltd StarAd

HIN LUNG AUTO
 HoBee Group

30 years
 of car sale

One Stop Car Hub
 Finance, Insurance, Workshop
 New and Used Cars

 Browse by Category

 Sort by Date Posted 20 results/page

18 vehicles

bmw 316

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	bmw 316		Any	Any	2013	Any	Any	Any	Available
	BMW 3 Series 316i		\$90,800	\$13,360 /yr	27-Dec-2013	1,598 cc	36,000 km	Luxury	Available
Elegant White, One Owner Only, Low Mileage Done, Very Well Maintained, Drive Away With Minimum Down Payment, Flexible In-House Loan Packages Available.									
Prime Motor & Leasing									
Posted: 12-Mar-2018 Tags: 2013 BMW 316i, BMW 316i, BMW, 316i, Used BMW									
	BMW 3 Series 316i Sport		\$85,000	\$15,120 /yr	18-Jan-2013	1,598 cc	90,725 km	Luxury	Available
Road Tax Renewed, One Owner, High COE \$92,100, 316 Sports Model, All Servicing History Done At PML.									
Posted: 12-Mar-2018 Tags: 2013 BMW 316i, BMW 316i, BMW, 316i, Used BMW									
	BMW 3 Series 316i		\$81,800	\$13,360 /yr	29-Mar-2013	1,598 cc	-	Luxury	Available
Posted: 11-Mar-2018 Tags: 2013 BMW 316i, BMW 316i, BMW, 316i, Used BMW									
	BMW 3 Series 316i Sport		\$88,800	\$13,250 /yr	27-Sep-2013	1,598 cc	89,339 km	Luxury	Available
Graded B by STP									
1 Year Free Servicing! \$9K Down Payment! STA Certified Accident Free Quality Pre-owned With Low Mileage And Agent Service History For Peace Of Mind. 100% Loan Approval With Our Flexible In House Finan...									
Cosmo Automobiles									
Posted: 11-Mar-2018 Tags: 2013 BMW 316i, BMW 316i, BMW, 316i, Used BMW									
<div> <div>Car Buying</div> <div>Car Ownership</div> </div> <div> <div>Car Selling</div> <div>On The Move</div> </div> <div> <div>Car Aftermarket</div> <div>Lifestyle</div> </div> <div> <div>Buying a pre-owned car, but Unsure of its Condition?</div> <div>Get, STA Car Evaluation</div> </div>									
	BMW 3 Series 316i Sport		\$83,888	\$13,370 /yr	30-May-2013	1,598 cc	29,000 km	Luxury	Available
1 Owner Only! Sapphire Black! Super Low Mileage Done Only 29k Km! Well Kept And Maintained Regular, Like Brand New Condition!Low Down Payment, Low Monthly Repayment, High And Eazi Loan Can Be Arrange!									
Posted: 10-Mar-2018 Tags: 2013 BMW 316i, BMW 316i, BMW, 316i, Used BMW									
	BMW 3 Series 316i Sport		\$79,800	\$12,980 /yr	28-Mar-2013	1,598 cc	69,000 km	Luxury	Available
Only 1 Owner, Free 1 Year Warranty, Mint Condition! Call Now For Viewing. Trade In And Loans Available.									
Posted: 09-Mar-2018 Tags: 2013 BMW 316i, BMW 316i, BMW, 316i, Used BMW									
	BMW 3 Series 316i		\$88,800	\$13,190 /yr	26-Sep-2013	1,598 cc	49,000 km	Luxury	Available
New Brake Pad, Road Tax Till Sep 2018, Servicing From PML Accident Free! 3 Months Warranty From Our Inhouse Workshop Well Maintained By Previous Careful Owner. Bank Loan In House Loan Available, Trade...									

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/03/2018 18:32
Date Of Accident	06/03/2018 14:15
Exact Location Of Accident	CTE TUNNEL BEFORE CAIRNHILL EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKU4025L
Insured/Policyholder	
Name Of Registered Owner	TAN SIEW HWA
NRIC No	S1550556G
Email Address	TRANSIEWHWA@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97388053
Alternative Phone No	OFFICE-97388053

Vehicle Particulars

Manufacturer	BMW
Model	316I 1.6 AT D/AB 4DR ABS HID

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle?

NO

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

PRIVATE CAR

Insurance Company

Name of Insurance Company	DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MT/00398783
Cover Note Number	07/08/2017-06/08/2018

Driver

Name of Driver	LEONG LI XUE
NRIC No	S8338973G
Date Of Birth	30/11/1983
Occupation	INDOOR
Date Of Driving Pass	17/10/2003
Driving Experience	14 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90097618
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address

5 TAMPINES AVE
#06-08

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured CHILDREN

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance?

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 2

Passenger 1 NAME: : LOW REGIN

GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHMENT

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBE1749S

Vehicle Make/Model/Colour NISSAN NV 200

Details Of Properties

Vehicle Category COMMERCIAL VEHICLE

Name of Driver JUNID BIN ATAN

NRIC/Passport Number S1582006C

Contact Number 86153706

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 06/03/18 6.30pm

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

WAS DRIVING LANE 1 (OUTERMOST RIGHT) WHEN FRONT VEHICLE SLOWED DOWN.

I ALSO BRAKED SLIGHTLY TO SLOW DOWN, WHEN THE VEHICLE (GBE17498) KNOCKED INTO THE REAR OF MY VEHICLE.

STOPPED AND AUGMENTED TO TAKE PHOTOS AS PROVIDED.

You had been advised by workshop that in the event that you wish to claim against your own policy (OD claim), there is a **Fourteen (14) days clause** whereby the claim must be made within the stipulated timeframe from the day of occurrence.

Reporting Only
Claim OD
Claim TP
<input checked="" type="checkbox"/> Claim OD/TP at other workshop

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 06/03/18 6:30pm

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

GARAGE SketchPlanForm 93

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No:67452063/67467158 Fax No:67458520

not allocated
1/5 = 8200
12/3/18
5 day.

VEH: SKU4025L

QTY	PARTICULAR		AMOUNT
1PCS	BOOTLID	1288.35	\$1,418.32 ✓
1PCS	BOOTLID REAR LOGO		\$68.00 ✓
2PCS	BOOTLID REFLECTORS @\$335.00		\$670.00 X
1PCS	BOOTLID INNER LOCK	245.32	\$299.08 ✓
1PCS	BOOTLID WEATHERSTRIP	193.60	\$275.00 ✓
1PCS	BOOTLID INNER TRIM		\$288.02 X
1SET	BOOTLID INNER TRIM CLIPS		\$50.00 X
2PCS	TAILLAMPS @\$685.00	528.03 x 2 = 1056.06	\$1,370.00 ✓
2PCS	TAILLAMPS HOUSING PANELS @\$205.00		\$410.00 X
1PCS	REAR BUMPER	1043.23	\$1,658.00 ✓
1PCS	REAR BUMPER LOWER SPOILER	213.00	\$423.62 ✓
2PCS	REAR BUMPER REFLECTORS @\$62.00		\$124.00 X
4PCS	REAR BUMPER PDC SENSORS @\$225.00	215 x 2 = 430	\$900.00 2PCS
1PCS	REAR BUMPER PDC SENSOR WIRE BOARD		\$313.54 ✓
1PCS	REAR BUMPER TOP GUIDE		\$161.23 ✓
1PCS	REAR BUMPER REINFORCEMENT	566.01	\$745.00 ✓
2PCS	REAR BUMPER SIDE RETAINERS @\$89.20		\$178.40 ✓
1SET	REAR BUMPER CLIPS		\$50.00 ✓
1PCS	REAR END PANEL	880.11	\$1,018.57 ✓
1PCS	REAR END PANEL TOP GARNISH		\$223.11 ✓
1PCS	REAR EXHAUST W/CHROME	1250.35	\$1,380.00 ✓
1PCS	REAR EXHAUST HEAT SHIELD		\$266.00 ✓
2PCS	REAR EXHAUST MOUNTINGS @\$45.00		\$90.00 ✓
1PCS	REAR FENDER INNER TRIM N/S	282.32	\$348.15 ✓
1PCS	REAR FLOOR PANEL		\$1,081.23 X
1PCS	REAR FLOOR PANEL TOP BOARD		\$355.00 X
1PCS	REAR FENDER UNDER TRAY N/S	166.50	\$248.00 ✓
1PCS	REAR LICENCE PLATE W/HOLDER		\$50.00 X
1PCS	REAR END PANEL SEALANT		\$50.00 ✓
			\$14,512.27

TO CHECK WIRING

TO DISMENTLE & REPLACING REVERSE SENSOR

TO TRANSFER BOOTLID MECHANISM

9018.13
8113.61
\$80.00 30
\$80.00 50
\$120.00 60

TO DISMENTLE &REFIX SEAT,CUSHION UPHOLSTERY
TO DISMENTLE & REPLACING REAR EXHAUST
TO SPRAY RUST PROOFING
TO MOUNT VEHICLE ON CAR O-LINER
LABOUR FOR PANEL BEATING,CUT,WELD
STRAIGHTEN & REPLACING PARTS
TO PUTTY & SPRAY PAINTING

\$120.00 *80*
\$100.00 *80*
\$100.00 *60*
11 \$380.00 *X*
\$1,280.00 *800*
\$1,500.00 *1000*

TOTAL \$18,272.27

10273-61

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO18004653/Uvd3n2		
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 23-03-2018		
		Code : SMO		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBE 1749S	Veh. Inspected	SKU 4025L	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD1801021	Excess (\$)	0.00	
Assign From	IRENE JAMES	Assign Date	12/03/2018	
2. Vehicle Particulars & Condition				
Make & Model	B.M.W 316I (A)	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	WBA3A12040J719613	Colour	GREY	
Odometer	84028	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45 R18	PIRELLI	6 mm	
L/H Front Tyre	225/45 R18	PIRELLI	6 mm	
R/H Rear Tyre	225/45 R18	PIRELLI	6 mm	
L/H Rear Tyre	225/45 R18	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	06/03/2018	Inspection Date	12/03/2018	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKU 4025L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BOOTLID	DENTED / BUCKLED	1,418.32	1,288.35
1	BOOTLID REAR LOGO	NECESSARY	68.00	68.00
2	BOOTLID REFLECTORS @\$335.00	NOT NECESSARY	670.00	-
1	BOOTLID INNER LOCK	TWISTED	299.08	245.32
1	BOOTLID WEATHERSTRIP	TWISTED	275.00	193.60
1	BOOTLID INNER TRIM	NOT NECESSARY	288.02	-
1	SET BOOTLID INNER TRIM CLIPS	NOT NECESSARY	50.00	-
2	TAILLAMPS @\$685.00	CRACKED / DAMAGED	1,370.00	1,056.06
2	TAILLAMPS HOUSING PANELS @\$205.00	TO REPAIR SEE LABOUR	410.00	-
1	REAR BUMPER	DENTED / DEFORMED	1,658.00	1,043.23
1	REAR BUMPER LOWER SPOILER	DISTORTED	423.62	213.00
2	REAR BUMPER REFLECTORS @\$62.00	NOT NECESSARY	124.00	-
4	REAR BUMPER PDC SENSORS @\$225.00	SHORTED (2 PCS ONLY)	900.00	430.00
1	REAR BUMPER PDC SENSOR WIRE BOARD	TORN	313.54	313.54
1	REAR BUMPER TOP GUIDE	CRACKED	161.23	161.23
1	REAR BUMPER REINFORCEMENT	BENT	745.00	566.01
2	REAR BUMPER SIDE RETAINERS @\$89.20	CRACKED / BENT	178.40	178.40
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	50.00
1	REAR END PANEL	BADLY DENTED	1,018.57	880.11
1	REAR END PANEL TOP GARNISH	TWISTED	223.11	223.11
1	REAR EXHAUST W/CHROME	BENT / TWISTED	1,380.00	1,250.35
1	REAR EXHAUST HEAT SHIELD	BENT	266.00	266.00
2	REAR EXHAUST MOUNTINGS @\$45.00	NECESSARY	90.00	90.00
1	REAR FENDER INNER TRIM N/S	DEFORMED / TORN	348.15	282.32
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	1,081.23	-
1	REAR FLOOR PANEL TOP BOARD	NOT NECESSARY	355.00	-
1	REAR FENDER UNDER TRAY N/S	TWISTED	248.00	166.50
1	REAR LICENCE PLATE W/HOLDER	NOT NECESSARY	50.00	-
1	REAR END PANEL SEALANT	NECESSARY	50.00	50.00

Report Ref No. CS/SMO18004653/Uvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-	-901.51
			14,512.27	8,113.62
	LABOUR			
	TO CHECK WIRING.		80.00	30.00
	TO DISMENTLE & REPLACING REVERSE SENSOR.		80.00	50.00
	TO TRANSFER BOOTLID MECHANISM.		120.00	60.00
	TO DISMENTLE & REFIX SEAT,CUSHION UPHOLSTERY.		120.00	80.00
	TO DISMENTLE & REPLACING REAR EXHAUST.		100.00	80.00
	TO SPRAY RUST PROOFING.		100.00	60.00
	TO MOUNT VEHICLE ON CAR O-LINER.	NOT NECESSARY	380.00	-
	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF TAILLAMPS HOUSING PANELS AND REAR FLOOR PANEL.		1,280.00	800.00
	TO PUTTY & SPRAY PAINTING.		1,500.00	1,000.00
			3,760.00	2,160.00
	GRAND TOTAL		18,272.27	10,273.62
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				8,200.00

Report Ref No. CS/SMO18004653/Uvd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.