

ASS. REC. BY:

REF: CS/EQI18004654/Krd3

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Buzlin Ahmad

of EQI

Date/Time: 9/3/18 @ 3:52pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GQ 5994B

Insured:

at Workshop m/s

City Auto

Tel:

6453 1235

of Blk 160 Sin Ming Drive # 05-01

Policy No:

Claim No:

Sum Insured:

Excess:

\$ 500.00

Make of Veh:

D.O.A.

03/03/2018

(Client's Record)

CA / REV REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

9:25am @ 12/3/18

Person Contacted:

Vronica

Vehicle:

IN/OUT

Date/Time	Action/Instruction
	<p>(✓) Estimate</p> <p>GQ 5994B - NA/EQI17015262/k4</p> <p>D.O.A: 5/8/17</p>
15/3/18	<p>Sent preli thm email.</p> <p>Advise repair & inform repairer to proceed repair.</p>

SIN 117

EQI

ASSIGNMENT

Estimate No. _____ Date 12/3/18
 Estimated Cost _____
 TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No. GQ 5994 B
 at Workshop mis City Auto
 of Blk 160 Sin Ming # 05-01
 Insured _____
 Policy No. _____
 Claims No. _____
 Sum Insured _____ Excess \$500.00
 Client's Record _____
 Make of Car _____

Policy Condition _____
 Remark: The veh had commenced its repair at the time of inspection.
 Sal. or Market Value \$39k
 IDAC Accident Report _____ Consistent? Yes or No
 GIA RR Seen _____ Consistent? Yes or No
 Est. Repairs 06 days Res. Yes or No
 Lim Sum 10 MB % G/Vall. Yes or No
 CA / REP. / 24 HRS
 Date _____ Person Contacted _____ Vehicle IN / OUT

	
NS	O/S

Var No. GQ 5994 B Reg. 09 13
 Type M/Car M/Cycle Bus/Car Judo Taxi Prime Mover
 Truck Tractor _____
 Make Fiat ^M Doble ^M 1598
 Colour M. Brown A/C Insured Std. N/NA
 Seating 10808 T/Fold Insured Std. N/NA
 Eng No _____
 C No. EFA 26800008810614P
 Gen Cond Good Fair Poor Burnt
 Steering In order Jammed Leaked Burnt or
 Brake In order Jammed Leaked Burnt or
 Mod. S Rim / STD A Rim or
 Tyre Size F 205/60R16
 R. _____
 BS / DUN / EXNOVA / GY / FS LIZA / MIC / OHTSU / PIR / SLM
 TOYO / YOKO or Nexen
 Front _____ Rear _____
 R/Ba 5 --- R/Ba 8 ---
 L/Ba 5 --- L/Ba 8 ---
 D/OA 3/3/18 D/O 12/3/18
 Surveyed at _____
 Des of Damages Front Rear O/S N/S U/O Roofed or

The U/O / Chassis frame / Body Structure affected due to collision

Date Time Action / Instruction
13/3 File pass to Catherine

2:16 Lily & Good confirm Mr Quek
Red: \$4692.50, 371.

RECEIVED 22 JUN 2018

Date Time File Pass to: Prelim. Report
 Final Report
 Date Time File Return to: _____
 Report Format: OD
 LIME Sum MB: 8000

Days Of Repair: 6
 Resurvey No. of Trip: 2
 Add Fee: Site Insp \$ _____
 Meter \$ _____
 Tech \$ _____
 Equip \$ _____
 Surve Fee: 230
 Transport: _____
 Total: 230



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
EQ INSURANCE COMPANY LTD		Ref : CS/EQ18004654/Krd3	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 12-03-2018	
		Code : EQI	
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.		Veh. Inspected	GQ 5994B
Policy No.		Coverage (\$)	0.00
Claim No.	500.00	Excess (\$)	0.00
Assign From	BAZLIN AHMAD	Assign Date	12/03/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	12/03/2018	Inspection Date	12/03/2018
Survey held at	160 SIN MING DRIVE # 05-01		
Repairer	CITY AUTO PTE LTD		
5a. Remarks			
A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			

Nivitha (LKK Auto)

From: Shu Pei (LKKAuto) <shupe@lkkauto.com>
Sent: Friday, 9 March 2018 3:52 PM
To: assignments
Subject: FW: OD CLAIM SURVEY - GQ5994B
Attachments: GIA report.pdf; Estimate.pdf; GQ5994B 03.03.2018.pdf

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupe@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Bazlin Ahmad [<mailto:bazlin.ahmad@eqinsurance.com.sg>]
Sent: Friday, 9 March 2018 3:49 PM
To: cityauto@singnet.com.sg; Admin A <admin-a@lkkauto.com>
Cc: Janet Tan <janet.tan@eqinsurance.com.sg>
Subject: OD CLAIM SURVEY - GQ5994B

Dear Lkk

We refer to the above new assignment, please find below email and attachments for easy reference.

GQ5994B od excess is \$500.00 before GST.

Thank You.

Regards,
Lynn Ahmad
Executive | Claims

eqnsurance


EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110

did 65 6496 9881 | tel 65 6223 9433 ext 881 | fax 65 6223 4190

www.eqinsurance.com.sg

 A Member of Citystate

 you've got a friend

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of

From: City Auto [<mailto:cityauto@singnet.com.sg>]
Sent: Friday, March 9, 2018 2:54 PM
To: Janet Tan

Cc: Bazlin Ahmad

Subject: Arrange survey for GQ5994B

Dear Motor survey department,

Kindly arrange **LKK Auto Consultants Pte Ltd** survey on following vehicle :

OD survey

Our vehicle : GQ5994B

D.O.A : 03/03/2018

LOCATION : BLK 160, Sing Ming Drive, Sin Ming Auto City #05-01 Singapore 575722

Thank you.

Best Regards,

Vronica Law

City Auto Pte Ltd

Blk 8 Sin Ming Industrial Estate,

#01-60/62 Sin Ming Road,

Singapore 575643

Tel : 6453 1235

Fax : 6453 7944



Auto
Consultants
Pte Ltd

51 UBI AVE I, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: TBA

Date: 13 March 2018

Our Ref: CS/EQI18004654/Krd3

The Motor Claims Department
EQ INSURANCE COMPANY LTD

Dear Sir/Madam,


PRELIMINARY ADVICE OF VEHICLE NO. GQ 5994B

We thank you for the instruction on 09/03/2018

Please be informed that we had conducted the inspection of the abovementioned vehicle 12/03/2018 at the premises of m/s: CITY AUTO PTE LTD and have the following to report:-

Repairer's Estimate (Gross)	: <u>S\$ 12,692.50</u>
Revised Estimate Amount	: <u>S\$ 7,461.30</u>
"Check" Items (Estimated)	: <u>S\$ 4,642.20</u>
Total Repair Amount	: <u>S\$ 12,103.50</u>
Pre-Accident Value	: <u>S\$ 39,000.00</u>
COE/PARF value	: <u>S\$ 21,660.00</u>
Nett Value	: <u>S\$ 17,340.00</u>

Description of Damage:
The vehicle sustained damages
at the front portion.
We have not authorize repair.



Yours faithfully

KENNETH KONG
Automotive Assessor

Janice Lee (LKKAuto)

From: Janice Lee (LKKAuto)
Sent: Tuesday, March 13, 2018 1:04 PM
To: 'Bazlin Ahmad'
Cc: SUR
Subject: RE: OD CLAIM SURVEY - GQ5994B
Attachments: GQ 5994B .pdf

Dear Bazlin,

Enclosed preliminary revised for **GQ 5994B**.

We have not authorize repair.
Kindly sent us the claim number.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Monday, March 12, 2018 9:16 AM
To: 'Bazlin Ahmad' <bazlin.ahmad@eqinsurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: OD CLAIM SURVEY - GQ5994B

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Bazlin Ahmad [<mailto:bazlin.ahmad@eqinsurance.com.sg>]
Sent: Friday, 9 March 2018 3:49 PM
To: cityauto@singnet.com.sg; Admin A <admin-a@lkkauto.com>
Cc: Janet Tan <janet.tan@eqinsurance.com.sg>
Subject: OD CLAIM SURVEY - GQ5994B

Dear Lkk

Janice Lee (LKKAuto)

From: Bazlin Ahmad <bazlin.ahmad@eqinsurance.com.sg>
Sent: Thursday, March 15, 2018 9:22 AM
To: Janice Lee (LKKAuto)
Subject: EQ REF : DM18HO00621 - OD CLAIM SURVEY - GQ5994B

Dear Janice

Please proceed

Thank You.

Regards,
Lynn Ahmad
Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9881 | tel 65 6223 9433 ext 881 | fax 65 6223 4190
www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of it.

From: Janice Lee (LKKAuto) [mailto:JaniceLee@lkkauto.com]
Sent: Thursday, March 15, 2018 9:16 AM
To: Bazlin Ahmad
Subject: RE: OD CLAIM SURVEY - GQ5994B

Dear Lynn,

Kindly advice on the authorization.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: jannicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Janice Lee (LKKAuto)
Sent: Tuesday, March 13, 2018 1:04 PM

Janice Lee (LKKAuto)

From: Janice Lee (LKKAuto)
Sent: Thursday, March 15, 2018 9:47 AM
To: 'cityauto@singnet.com.sg'
Cc: SUR
Subject: GQ 5994B EQI DOA: 03.03.2018

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **GQ 5994B (excess \$500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: jannicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	7606W
Vehicle Details	
Vehicle No.:	GQ5994B
Vehicle to be Exported:	No
Intended De-registration Date:	13 Mar 2018
Vehicle Make:	FIAT
Vehicle Model:	DOBLO CARGO MAXI 1.6MJ DIESEL (MTA)
Primary Colour:	Purple
Manufacturing Year:	2013
Engine No.:	263A50007003924
Chassis No.:	ZFA26300006106149
Maximum Power Output:	-
Open Market Value:	\$21,470.00
Original Registration Date:	16 Sep 2013
First Registration Date:	16 Sep 2013
Transfer Count:	1
Actual ARF Paid:	\$1,074.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	15 Sep 2023
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$37,775.00
COE Rebate Amount:	\$21,660.00
Total Rebate Amount:	\$21,660.00

The information contained herein is correct as at 13 Mar 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/03/2018 18:03
Date Of Accident	03/03/2018 16:30
Exact Location Of Accident	PIE (TOWARDS TUAS BEFORE CTE) KALLANG
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GQ5994B
Insured/Policyholder	
Name Of Registered Owner	TOBA PADANG
Co Reg No	-
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98008646
Alternative Phone No	OFFICE-98008646

Vehicle Particulars

Manufacturer	FIAT
Model	-
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCPHQ17-007101
Cover Note Number	

Driver

Name of Driver	SIAU SIEW HWEE RAYMOND
NRIC No	S7906208A
Date Of Birth	23/02/1979
Occupation	INDOOR
Date Of Driving Pass	15/03/2003
Driving Experience	14 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98008646
Fax Number	
Contact Number	
EMail Address	NOEMAIL

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

TOBA PADANG
No. 30 Raffles Place, B1-01
Chevron House, S(048622)
Tel: 6532 7418 Fax: 6442 0238
ROC: 52807606W

Policyholder's Signature
Date & Time:

Raymond
Driver's Signature
(If driver is not the policyholder)
Date & Time:

5 MAR 2018 15:00H/L

[Signature]
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643
TEL: 6453 1235, 6452 0850 FAX: 6453 7944
24hrs Towing Services Tel: 9823 9898
Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

LKK

Estimate : QUOT201803-000238(00)

EQ INSURANCE COMPANY LIMITED

NO. 5
MAXWELL RD #17-00 SINGAPORE 069110
MND COMPLEX
SINGAPORE 069110
Attention: TOBA PADANG
Contact : 98008646

Fax No. : 62243903

Date : 09/03/2018
Vehicle No. : GQ5994B
Make/Model : FIAT DOBLO CARGO MAXI 1.6MJ
DIESEL (MTA)
Mileage (km) : 0
Chassis No. : ZFA26300006106149
Accident Date : 03/03/2018 00:00:00
Claim No. :
Reference : GQ5994B
Policy No. : DMCPHQ17-007101

FM
Not Authored
1.B.1
Resumy Bk paint
6days
Ex @ 500
Fax: 62564315

S/No	Particular	Quantity	Unit Price	Amount S\$
LIST ITEMS				
1	Front bumper	1.0	889.00	889.00 ✓
2	Front bumper side retainer	2.0	95.00	190.00 ✓
3	Front bumper sponge	1.0	225.00	225.00 ✓
4	Front bumper reinforcement	1.0	525.00	525.00 ✓
5	Front bumper towing cover	1.0	45.00	45.00 ✗
6	Front bumper logo	1.0	118.00	118.00 ✓
7	Front bumper upper grille	1.0	325.00	325.00 ✗
8	Front bumper lower grille	1.0	315.00	315.00 ✓
9	Headlamp	2.0	550.00	1,100.00 ✓
10	Headlamp lower bracket	2.0	95.00	190.00 ✗
11	Bonnet	1.0	950.00	950.00 ✓
12	Bonnet lock	1.0	210.00	210.00 ✗
13	Bonnet hinge	2.0	105.00	210.00 ✗
14	Support top panel	1.0	835.00	835.00 ✗
15	A/c condenser	1.0	695.00	695.00 ✓
16	A/c discharge pipe	1.0	355.00	355.00 ✗
17	A/c suction pipe	1.0	490.00	490.00 ✗
18	A/c liquid pipe	1.0	480.00	480.00 ✗
19	Radiator	1.0	685.00	685.00 ✓
20	Radiator air guide - upper	1.0	80.00	80.00 ✓
21	Radiator air guide - lower	1.0	80.00	80.00 ✗
22	Fan cowling	1.0	245.00	245.00 ✓
23	Fan motor assy	1.0	585.00	585.00 ✓
24	Foglamp cover (without foglamp type)	2.0	115.00	230.00 ✓
25	Turbo intercooler	1.0	650.00	650.00 ✓
26	Power steering cooler pipe	1.0	485.00	485.00 ✗
27	Power steering fluid	1.0	68.00	68.00 ✗
28	Front RH fender	1.0	495.00	495.00 ✓
29	Radiator air shroud - upper	1.0	225.00	225.00 ✓
List Total :				11,975.00
10% Discount S\$				1,197.50
				10,777.50

SPECIAL NET

CONTINUE NEXT PAGE



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643

TEL: 6453 1235, 6452 0850 FAX: 6453 7944

24hrs Towing Services Tel: 9823 9898

Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

Estimate : QUOT201803-000238(00)

Date : 09/03/2018

Vehicle No. : GQ5994B

Make/Model : FIAT DOBLO CARGO MAXI 1.6MJ
DIESEL (MTA)

Mileage (km) : 0

Chassis No. : ZFA26300006106149

Accident Date : 03/03/2018 00:00:00

Claim No. :

Reference : GQ5994B

Policy No. : DMCPHQ17-007101

EQ INSURANCE COMPANY LIMITED

NO. 5

MAXWELL RD #17-00 SINGAPORE 069110

MND COMPLEX

SINGAPORE 069110

Attention: TOBA PADANG

Contact : 98008646

Fax No. : 62243903

S/No	Particular	Quantity	Unit Price	Amount S\$
1	Front number plate	1.0	25.00	25.00
2	Front number plate casing	1.0	35.00	35.00
SPECIAL NET Total S\$:				60.00
LABOUR				
	*Air condenser	1.0	150.00	150.00
	*To check an re-wiring	1.0	55.00	55.00
	*To knock jackout damaged parts, panel beating,welding,align,refix and to renew accident parts	1.0	700.00	700.00
	*Spray painting on affected and replace parts	1.0	950.00	950.00
				1,855.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

E. & O.E.

Total S\$: 12,692.50

GST 7% S\$: 888.48

Amount Due S\$: 13,580.98

for CITY AUTO PTE LTD



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
EQ INSURANCE COMPANY LTD		Ref : CS/EQI18004654/Krd3e2	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 29-06-2018	
		Code : EQI	
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.		Veh. Inspected	GQ 5994B
Policy No.	DMCPHQ17-007101	Coverage (\$)	0.00
Claim No.		Excess (\$)	500.00
Assign From	BAZLIN AHMAD	Assign Date	09/03/2018
2. Vehicle Particulars & Condition			
Make & Model	FIAT DOBLO MAXI (A)	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	ZFA26300006106149	Colour	METALLIC BROWN
Odometer	10808	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/60 R16	NEXEN	5 mm
L/H Front Tyre	205/60 R16	NEXEN	5 mm
R/H Rear Tyre	205/60 R16	NEXEN	8 mm
L/H Rear Tyre	205/60 R16	NEXEN	8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	03/03/2018	Inspection Date	12/03/2018
Survey held at	160 SIN MING DRIVE # 05-01		
Repairer	CITY AUTO PTE LTD		
5a. Remarks			
A)THE MARKET VALUE IS S\$39,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GQ 5994B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	BUCKLED	889.00	889.00
2	FRONT BUMPER SIDE RETAINER @\$95.00	DISTORTED	190.00	190.00
1	FRONT BUMPER SPONGE	CRACKED	225.00	225.00
1	FRONT BUMPER REINFORCEMENT	BENT	525.00	525.00
1	FRONT BUMPER TOWING COVER	SERVICEABLE	45.00	-
1	FRONT BUMPER LOGO	MISSING	118.00	118.00
1	FRONT BUMPER UPPER GRILLE	SERVICEABLE	325.00	-
1	FRONT BUMPER LOWER GRILLE	BENT	315.00	315.00
2	HEADLAMP @\$550.00	MTG CRACKED	1,100.00	1,100.00
2	HEADLAMP LOWER BRACKET @\$95.00	SERVICEABLE	190.00	-
1	BONNET	BUCKLED	950.00	950.00
1	BONNET LOCK	TO REPAIR SEE LABOUR	210.00	-
2	BONNET HINGE @\$105.00	TO REPAIR SEE LABOUR	210.00	-
1	SUPPORT TOP PANEL	TO REPAIR SEE LABOUR	835.00	-
1	A/C CONDENSER	PUNCTURE	695.00	695.00
1	A/C DISCHARGE PIPE	SERVICEABLE	355.00	-
1	A/C SUCTION PIPE	SERVICEABLE	490.00	-
1	A/C LIQUID PIPE	SERVICEABLE	480.00	-
1	RADIATOR	PUNCTURE	685.00	685.00
1	RADIATOR AIR GUIDE - UPPER	CRACKED	80.00	80.00
1	RADIATOR AIR GUIDE - LOWER	SERVICEABLE	80.00	-
1	FAN COWLING	CRACKED	245.00	245.00
1	FAN MOTOR ASSY	JAMMED	585.00	585.00
2	FOGLAMP COVER (WITHOUT FOGLAMP TYPE) @\$115.00	DENTED	230.00	230.00
1	TURBO INTERCOOLER	PUNCTURE	650.00	650.00
1	POWER STEERING COOLER PIPE	SERVICEABLE	485.00	-
1	POWER STEERING FLUID	NOT NECESSARY	68.00	-
1	FRONT RH FENDER	BUCKLED	495.00	495.00
1	RADIATOR AIR SHROUD - UPPER	CRACKED	225.00	225.00

Report Ref No. CS/EQ118004654/Krd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-1,197.50	-820.20
			10,777.50	7,381.80
	SPECIAL NETT ITEMS			
1	FRONT NUMBER PLATE (SN) }	DENTED	25.00	45.00
1	FRONT NUMBER PLATE CASING (SN) }		35.00	-
			60.00	45.00
	LABOUR			
	AIR CONDENSER.		150.00	100.00
	TO CHECK AN RE-WIRING.		55.00	20.00
	TO KNOCK JACK OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW ACCIDENT PARTS. INCLUSIVE OF THE REPAIR OF BONNET LOCK, BONNET HINGE AND SUPPORT TOP PANEL.		700.00	550.00
	SPRAY PAINTING ON AFFECTED AND REPLACE PARTS.		950.00	800.00
			1,855.00	1,470.00
	GRAND TOTAL		12,692.50	8,896.80
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			8,000.00
	LESS EXCESS			-500.00
	NETT LIABILITY			7,500.00

Report Ref No. CS/EQ118004654/Krd3e2


KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS DRIVING ALONG PIE TOWARDS TUAS HEADING FOR CTE, I JUST LANE CHANGE TO LANE 4, DUE TO HEAVY TRAFFIC, I WAS TRAVELLING AT 40 KMH, AS I SLOWED DOWN, MY VEHICLE ROLLED FORWARD AND HIT THE VEHICLE IN FRONT OF ME.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

TOBA PADANG
 No. 30 Raffles Place, B1-01
 Cheong House, S(048622)
 Policy No. 527218 Fax: 6442 0238
 Tel: 6532 7218
 Date & Time ROC: 52807606W

Raymond

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

5 MAR 2018 1500HR.

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

Address -
 Postcode
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1 NAME: : PASSENGER
 GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

refer attached report.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLD739P
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver YEO PENG SOON
 NRIC/Passport Number S1201207A
 Contact Number 96412356
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)