

22/03/2001

ASS. REC. BY:

REF: CS/MSG18004663/K1/d3dz

Special Instruction:

Survivor:

Valvin

ASSIGNMENT (Office)

From (Person):

Katherine Wong

of

MSG

Date/Time: 2/3/01 @ 3:14pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHD 33311

Insured:

SKM 1493E

at Workshop m/s

Comfort Delgado

Tel:

624 8302

of

54 Lafayette Drive

Policy No:

80447560 QMX

Claim No:

552080

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

9/3/2008

CA / REV / REP. / REV 24 HRS

Wp

H.O.D. Endorsement:

Date/Time:

3:30pm @ 12/3/18

Person Contacted:

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SHD 33311 - CS/GW17000829/H11h3s2
	SKM 1493E - X

D.O.A: 8/11/17

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Mar 2018		12 Mar 2018 15:14 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	Lam Chee Mun, ID: S7288652F			[Created by insurer]	
Main Claimant:	Comfort Transportation Pte Ltd,			Co. Reg. No.: 199303821R	
Vehicle Reg. No.:	SHD3331J			Date of Loss:	09/03/2018 04:00 - :59
Claim Type:	TP			Policy/Cover Note No.:	80447560QMX
Vehicle Reg. No. (Insured):	SKM1493E			Policy No. (Claimant):	Coverage: 03/11/2017 - 02/11/2018
				Excess:	
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300				
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]				
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 13/03/2018]				

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18004663/K1td3

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 12-03-2018



Code : MSG

1. Policy Particulars : THIRD PARTY CLAIM

Insured Veh.	SKM 1493E	Veh. Inspected	SHD 3331J
Policy No.	80447560QMX	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	MERIMEN (KATHERINE WONG)	Assign Date	12/03/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	09/03/2018	Inspection Date	12/03/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

A member of **COMFORTDELGRO**

Date/Time: 12.03.2018 09:15

Page : 1

eam: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 3809778

JC NO. **305123848**

TOMER		REGN NO	MILEAGE
COMFORT TRANSPORTATION PTE LTD		SD3331J	
AS	7010045	MAKE	FUEL
TOMER NO	983 SIN MING DRIVE	HYUNDAI	E.....1/2.....F
RESS	Singapore SINGAPORE 575717	MODEL	DATE/TIME IN
	65508755	I-40	12.05.2015 08:00
(R)	(O)	YR OF MANU	TARGET DATE
(P)		21.07.2016	
COUNT CARD NO.		CHASSIS NO	COMPLETION DATE/TIME:
		41UMGU092116	

Accident Date: 09.03.2018
NATURE: 3P 09.03.18/B

JOB DESCRIPTION

/NO	LABOR CODE	DESCRIPTION
-----	------------	-------------

PACKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

wiedgement Slip

Exit Pass

SHD3331J

FZ MSIG

Vehicle No.: **SHD3331J**

of Service Advisor

Signature/Date

Name of Service Advisor

Date _____

returned to Service Reception upon collection

To be kept by Security Guard

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/03/2018 11:04
Date Of Accident	09/03/2018 04:00
Exact Location Of Accident	SIMS AVE X LOR 1 GEYLANG
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD3331J
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	

Driver

Name of Driver	CHEW KENG HWEE
NRIC No	S1374587J
Date Of Birth	17/11/1959
Occupation	OUTDOOR
Date Of Driving Pass	06/05/1977
Driving Experience	40 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 132 BEDOK NORTH STREET 2 #05-81
Postcode	460132
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKM1493E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	MUHAMMAD TAUFIQ
NRIC/Passport Number	
Contact Number	S8629190H
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	UNSURE
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

GIA:RMC SketchPlanForm_V3



Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 09 Mar 18 at about 0400HRS I stopped my taxi at the above junction waiting for the Traffic lights to turn green.

Suddenly a few seconds later a car SKM1493E came from behind hit the Rear portion of my taxi.

No pax on board my taxi. No injury at the point of the accident.

Enclosed is a video footage to support my claims.

DECLARATION



I/We declare the foregoing particulars are true in every respect.
COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SIAR/AC SketchPlanForm_V3



COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 3331J

DATE 9/3/2018 10:36

MAKE :

MODEL : HYUNDAI i40

Fauzy

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper			\$ 603.60	
	Rear Bumper Reinforcement			\$ 504.35	
	Rear Bumper Reinforcement Bracket (LH/RH)		\$ 180.00	\$ 360.00	
	Rear Bumper Side Bracket			\$ 49.00	
	Rear Bumper Clips			\$ 22.00	
	Rear Bumper Sponge			\$ 143.40	
	Rear Bumper Under Cover			\$ 225.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

COMFORTDELGRO ENGINEERING

Our Job Ref No : 305123848

Date : 19.03.2018

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : KALVIN

Vehicle Reg No. : SHD3331J

Date of Accident : 09.03.2018

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: MSIG — SKM1493E
2. The finalized amount shall be:

(a) Spare Parts after List discount		<u>\$680.48</u>
(b) Labour Charges		<u>\$720.00</u>
Total for Part-By-Part Repair Cost		<u>\$1,400.48</u>
(c.) Lumpsum Repair (if applicable)		
Total for Lumpsum repair cost after Less: <u>20%</u>		<u>\$0.00</u>
Final Lumpsum Repair cost		<u>\$0.00</u>
3. Estimated normal period for repairs: 2 working days.
4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : FAUZY BIN MOKHTAR

Tel : 62148319

Fax : 65468156

Signature : 

Name : Calvin

Date : 27/3/18

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305123848
REGN NO : SHD3331J
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 21.07.2016
DATE/TIME IN : 12.03.2018 08:00
ACCIDENT DATE : 09.03.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0579-G	I40VC COVER ASSY-RR BUMPE	1	603.60	20.00	482.88
0002 04-01-0103-0738-G	I40VC COVER-RR BUMPER LWR	1	225.00	20.00	180.00
0003 04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60

SUB-TOTAL : 680.48

JOB NATURE

0000 20-05	RENEW ADVERTISMENT REAR BUMPER	100.00
0001 20-05	RENEW ADVERTISMENT REAR FENDER LH	100.00
0002 20-05	RENEW ADVERTISMENT REAR FENDER RH	100.00
0003 L	PANEL BEATING	220.00
0004 L	SPRAY PAINTING CHARGE	180.00
0005 L	REMOVE/REFIX REVERSE SENSOR	20.00

SUB-TOTAL : 720.00

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305123848
REGN NO : SHD3331J
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 21.07.2016
DATE/TIME IN : 12.03.2018 08:00
ACCIDENT DATE : 09.03.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 1,400.48

MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Mar 2018		12 Mar 2018 15:14 Edit Adj Rpt	S\$1,400.48 Edit Estimates	S\$1,400.48 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:

Lam Chee Mun, ID: S7288652F

Main Claimant:

Comfort Transportation Pte Ltd, Co. Reg. No.: 199303821R

Vehicle Reg. No.:

SHD3331J

Claim Type:

TP / 552080

Vehicle Reg. No. (Insured):

SKM1493E

Repairer:

ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300

Handling Insurer:

MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KALVIN ANG WEI KUN] ... [Final Rpt due 11/04/2018]

Date of Loss:

09/03/2018 04:00 - :59

Policy/Cover Note No.:

80447560QMX
Coverage: 03/11/2017 - 02/11/2018

Policy No. (Claimant):

Excess:

[Created by Insurer]

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

























ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SHD3331J (552080)**
[SKM1493E]
TP
Comfort Transportation Pte Ltd
Mar 9 2018 4:00AM
[Lam Chee Mun]
ComfortDelGro Engineering Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View View In Browser		
Assessment Reports							1 per page		<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print
1	27/03/18 11:54	Adjuster Immediate Advice						Load HTM	
Photos/Images							3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print
1	12/03/18 17:47	General View						Load JPG	<input checked="" type="checkbox"/>
2	12/03/18 17:47	General View						Load JPG	<input checked="" type="checkbox"/>
3	12/03/18 17:47	General View						Load JPG	<input checked="" type="checkbox"/>
4	12/03/18 17:47	General View						Load JPG	<input checked="" type="checkbox"/>
5	12/03/18 17:47	General View						Load JPG	<input checked="" type="checkbox"/>
6	12/03/18 17:47	General View						Load JPG	<input checked="" type="checkbox"/>
7	12/03/18 17:47	General View						Load JPG	<input checked="" type="checkbox"/>
8	12/03/18 17:47	General View						Load JPG	<input checked="" type="checkbox"/>
9	12/03/18 17:47	General View						Load JPG	<input checked="" type="checkbox"/>
10	12/03/18 17:47	General View						Load JPG	<input checked="" type="checkbox"/>
11	12/03/18 17:47	General View						Load JPG	<input checked="" type="checkbox"/>
12	12/03/18 17:47	General View						Load JPG	<input checked="" type="checkbox"/>
13	12/03/18 17:47	General View						Load JPG	<input checked="" type="checkbox"/>
14	12/03/18 17:47	General View						Load JPG	<input checked="" type="checkbox"/>
15	12/03/18 17:47	General View						Load JPG	<input checked="" type="checkbox"/>
16	12/03/18 17:47	General View						Load JPG	<input checked="" type="checkbox"/>
17	12/03/18 17:47	General View						Load JPG	<input checked="" type="checkbox"/>
18	12/03/18 17:47	General View						Load JPG	<input checked="" type="checkbox"/>
19	12/03/18 17:47	General View						Load JPG	<input checked="" type="checkbox"/>
20	13/03/18 16:59	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>
21	13/03/18 16:59	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>
22	13/03/18 16:59	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>
Documentation							1 per page		<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)						Thumbnail	Print
1	12/03/18 14:29	Estimate - TP GIA report						Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	<input type="button" value="Reset"/>	<input type="button" value="Save"/>	<input type="button" value="Print"/>
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

^

∨

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18004663/K1TD3E2

Date: 28/03/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 80447560QMX

Claimant Vehicle No : SHD3331J

Insured Vehicle No : SKM1493E

Date of Loss: 09/03/2018

Nature of Claim: TP

Claim No: 552080

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHD3331J

Make & Model: HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)

Engine No: D4FDGU656525

Reg. Date: 21/07/2016 (Man. Year: 2016)

Chassis No: KMHLB41UMGU092116

Colour: Blue

Odometer: 177297 km

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size:

205/60 R16

Front Left Side: Hankook 7 mm

Rear Left Side:

Hankook 7 mm

Front Right Side: Hankook 7 mm

Rear Right Side:

Hankook 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,961.58	980.48	981.10	50.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	750.00	420.00	330.00	44.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,711.58	1,400.48	1,311.10	48.35
+ GST 7.00/7.00% (S\$)	189.81	98.03	91.78	48.35
Nett Amount (S\$)	2,901.39	1,498.51	1,402.88	48.35

INSPECTION

Date of Assignment: 12/03/2018

Date Inspected: 12/03/2018 Inspected At:

 ComfortDelGro Engineering Pte Ltd
 (Loyang)
 59 Loyang Drive
 Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: KALVIN ANG WEI KUN

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 28 Mar 2018)
Parts: 143 HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SHD3331J)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	603.60 FL	*603.60 FL
2	1		*REAR BUMPER REINFORCEMENT	Serviceable	504.35 FL	*- FL
3	2		*REAR BUMPER REINFORCEMENT BRACKET (LH/RH)	Serviceable	360.00 FL	*- FL
4	1		*REAR BUMPER SIDE BRACKET	Serviceable	49.00 FL	*- FL
5	1		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
6	1		*REAR BUMPER SPONGE	Serviceable	143.40 FL	*- FL
7	1		*REAR BUMPER UNDER COVER	Cut	225.00 FL	*225.00 FL
8	1		*REAR BUMPER REVERSE SENSOR	Serviceable	135.70 FS	*- FS
9	1		*REAR BUMPER ADVERTISEMENT LOGO	Necessary	100.00 FS	*100.00 FS
10	2		*REAR FENDER ADVERTISEMENT LOGO (LH/RH)	Necessary	200.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	2,343.05	1,150.60
- List Item Discount on L Items 20.00/20.00% (S\$)	381.47	170.12
Total Parts (S\$)	1,961.58	980.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	380.00	220.00
2	SPRAY PAINTING CHARGE	New	200.00	180.00
3	WIRING CHARGE	New	50.00	0.00
4	R/REFIX REVERSE SENSOR	New	120.00	20.00
Gross Labour Cost (\$\$)			750.00	420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >