

INS. CASE OWNER:

Nonstop | cc 6, A1618004665, Mea39

LKK IDAC

Surveyor: MAPUS

ASSIGNMENT

DOI: 12/2/18

Date / Time: 12/2/18

Registered in Merimen: 12/31/18

Pre-assign / CCU / FTE



Insured Vehicle No.: SPW 48956
 Name of Insured: TAN ZHONG CHYE
 Insured Tel No.: _____ HP: _____
 Excess Sec II :SS _____ D.O.A.: 2/2/18
 Is driver the owner? (YES / NO) Nature of Accident: _____
 If NO, Driver Name / Age: LIN GAI JUN SAGILA
 Driver Tel No.: 91177911 (VL: YES / NO)

Claim No.: 888105763366
 Policy No.: 200456279
 Make / Model: Infiniti Q50
 Place of Accident: MCOLE HIGHWAY 7200014
 KINTO Stamford
 OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO
 Insured Liability: % Final? Yes / No

SLQ 7714X



INSRS: Program
 WSP: _____
 Tel: _____
 Liability: _____
 RMKS: _____



INSRS: _____
 WSP: _____
 Tel: _____
 Liability: _____
 RMKS: _____



INSRS: _____
 WSP: _____
 Tel: _____
 Liability: _____
 RMKS: _____



INSRS: _____
 WSP: _____
 Tel: _____
 Liability: _____
 RMKS: _____

Date / Time	STAGE	DATE / PIC
14/3/18	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
15/3/18	Call OI: ASHER 4/4/18	
	After call ltr to OI:	
	Documentation Check List: Handler Typist	
	Notification ltr (if non-pickup)	<input type="checkbox"/>
	After call ltr to OI:	<input checked="" type="checkbox"/>
20/3/18	Authorisation To Act:	<input checked="" type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice: RYTE	<input type="checkbox"/>
	Towing Invoice:	<input type="checkbox"/>
20-4/18	LTA / GIA:	<input checked="" type="checkbox"/>
	Medical Bill:	<input type="checkbox"/>
	PIR:	<input type="checkbox"/>
	Mandate/Reject Instruction:	<input type="checkbox"/>
	LOD:	<input type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/>
	Others:	<input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: _____ Sent By: _____ Confirm by:

FINALIZATION Date/Time: 12.3.18 Confirm with: _____ Confirm by:

Repair Cost: 45 SS1,900 (3 days) Reduction: 48 % Email Call

FINAL SETTLEMENT Date/Time: 26.05.19 Confirm with: SPAREN Email Call

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 37 IF NO or B 28, Ass. Lia: _____

Repair Cost: 461 SS2,055.00 DID REPAIR ENDED TP

Loss of Rental (LOR): SS - (days)

Loss of Use (LOU): SS 400.00 (510 x 4 days)

Loss of Income (LOI): SS - (5 x days)

LOR only LOU only LOR + LOU LOR + LOI (Tick only one)

GIA/LTA Search: SS 7.49

Medical: SS -

Disbursement: SS - (e.g. Tow/ Independent)

Legal Cost: SS -

Total: SS 2,440.49 Global Sum SS: 2,440.00

FINAL PAYMENT Date/Time: 26.05.19 Confirm with: SPAREN Email Call

Payee 1: SS 2,440.00 Name 1: PERMAS ENGINEERING, 9 TONGKILAN, MEALD

Payee 2: (Strike if N.A.) SS Name 2: _____

Payee 3: (Strike if N.A.) SS Name 3: _____

31/4/19



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/AIG18004665/Uea3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 12-03-2018	
Code : AIG			
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKW 4895G	Veh. Inspected	SLQ 7714X
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	12/03/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	27/02/2018	Inspection Date	12/03/2018
Survey held at	PEGASUS ENGINEERING & TRADING PTE LTD 51 DEFU LANE 10 SINGAPORE 539216		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 539216 Officer in Charge : ALVIN LOW WAI LUN Tel : Email :	Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax :
--	--

To arrange 12/18
 CLK - Marcus
 12/03/18 @ 13250

Quotation No : QO18/02-1202	Quotation Date : 28/02/2018	Terms : 30 DAYS
Vehicle No : SLQ7714X	Chassis No : JM6BN22A8H0152995	Third Party Insurer :
Model : MAZDA 3	Date of Accident :	
Remarks : TP INSURER: AIG, TP INSURED VEHICLE NO: SKW4895G, DOA: 27.02.2018		

EM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)	
1	REAR BUMPER	1 <i>10/22</i>	1,075.0000	1,075.00	✓
2	REAR BUMPER REINFORCEMENT	1 <i>10</i>	538.0000	538.00	✓
3	REAR BUMPER REFLECTOR	2 <i>11</i>	51.0000	102.00	α
4	REAR BUMPER SIDE RETAINER	2 <i>37</i>	37.0000	74.00	✓
5	REAR BUMPER SIDE HOLDER	2 <i>11</i>	46.0000	92.00	X
6	REAR BUMPER SIDE HOLDER RIVETS	4 <i>9</i>	9.0000	36.00	✓
7	O/S REAR BUMPER TOW COVER	1 <i>M.S</i>	17.0000	17.00	✓
8	REAR BUMPER CENTRE BRACKET	1 <i>10</i>	10.0000	10.00	X
9	REAR BUMPER CLIPS	8 <i>5</i>	5.0000	40.00	✓
10	BOOTLID MAZDA 3 BADGE	1 <i>11</i>	54.0000	54.00	✓
11	BOOTLID CENTRE LOGO BADGE	1 <i>11</i>	75.0000	75.00	α
12	BOOTLID SKYACTIV BADGE	1 <i>11</i>	64.0000	64.00	X
13	LESS 20% (ITEM 1 - 12)	1	-435.4000	-435.40	
14	REAR BUMPER PARKING SENSOR	1 <i>450</i>	450.0000	450.00	2005.00
15	TO REINSTALL OF REAR BUMPER PARKING SENSOR.	1	120.0000	120.00	50
16	TO CHECK ELECTRICAL LIGHTING CONCERNED.	1	40.0000	40.00	20
17	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	1	600.0000	600.00	300
18	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	1	700.0000	700.00	400

CIF 0.00
Page 1 of 2

not allowed

1780
1424
2394

12/3/18

1780
1424
2394

2394

1915.00

1/5 \$1900

2394

when plus other repair confirmed with insurer.

23.05.2018.

(LKKAuto)

Asher

From

Se

T

Asher Sng (LKKAuto)
Tuesday, 27 March 2018 2:14 PM
'Pegasus Engineering'; claims2@pegasusengrg.com.sg
Vic (LKKAuto)
Subject: Accident Involving SLQ 7714X & SKW 4895G on 27/02/2018

WITHOUT PREJUDICE

Your Ref: SLQ 7714X
Our Ref: CC6/AIG18004665/Uea3

Dear Sir/Madam,

Accident Involving SLQ 7714X & SKW 4895G on 27/02/2018

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

In order to expedite the claim process, please forward all relevant documents for us (LKK) to proceed on negotiate settlement.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



PEGASUS

ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :
PEGASUS ENGINEERING & TRADING PTE LTD
 C/O 51 DEFU LANE 10
 539216
 Officer in Charge : ALVIN LOW WAI LUN
 Tel :
 Email :

Customer :
GRAB RENTALS PTE LTD
 18 SIN MING LANE
 #01-08 MIDVIEW CITY
 SINGAPORE 573960
 Attn :
 Tel :
 Fax :

*To arrange 12/03
 CLK - MRCG
 12/03/18 @ 1325H*

Quotation No : QO18/02-1202	Quotation Date : 28/02/2018	Terms : 30 DAYS
Vehicle No : SLQ7714X	Chassis No : JM6BN22A8H0152995	Third Party Insurer :
Model : MAZDA 3	Date of Accident :	
Remarks : TP INSURER: AIG, TP INSURED VEHICLE NO: SKW4895G, DOA: 27.02.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
1	REAR BUMPER	1 <i>10/pe</i>	1,075.0000	1,075.00 ✓
2	REAR BUMPER REINFORCEMENT	1	538.0000	538.00 ?
3	REAR BUMPER REFLECTOR	2 <i>11</i>	51.0000	102.00 ✗
4	REAR BUMPER SIDE RETAINER	2 <i>re</i>	37.0000	74.00 ✓
5	REAR BUMPER SIDE HOLDER	2 <i>11</i>	46.0000	92.00 ✗
6	REAR BUMPER SIDE HOLDER RIVETS	4 <i>re</i>	9.0000	36.00 ✓
7	O/S REAR BUMPER TOW COVER	1 <i>M.S</i>	17.0000	17.00 ✓
8	REAR BUMPER CENTRE BRACKET	1 <i>11</i>	10.0000	10.00 ✗
9	REAR BUMPER CLIPS	8 <i>re</i>	5.0000	40.00 ✓
10	BOOTLID MAZDA 3 BADGE	1 <i>11</i>	54.0000	54.00 ✓
11	BOOTLID CENTRE LOGO BADGE	1 <i>11</i>	75.0000	75.00 ✗
12	BOOTLID SKYACTIV BADGE	1 <i>11</i>	64.0000	64.00 ✗
13	LESS 20% (ITEM 1 - 12)	1	-435.4000	-435.40
14	REAR BUMPER PARKING SENSOR	1 <i>set</i>	450.0000 <i>shrd</i>	450.00 <i>2005.00</i>
15	TO REINSTALL OF REAR BUMPER PARKING SENSOR.	1	120.0000	120.00 <i>50</i>
16	TO CHECK ELECTRICAL LIGHTING CONCERNED.	1	40.0000	40.00 <i>20</i>
17	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	1	600.0000	600.00 <i>300</i>
18	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	1	700.0000	700.00 <i>400</i>

C/F 0.00
 Page 1 of 2

*Not Authorized
 12/3/18
 when plus other repair*



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 539216 Officer in Charge : ALVIN LOW WAI LUN Tel : Email :	Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax :
---	---

Quotation No : QO18/02-1202	Quotation Date : 28/02/2018	Terms : 30 DAYS
Vehicle No : SLQ7714X	Chassis No : JM6BN22A8H0152995	Third Party Insurer :
Model : MAZDA 3	Date of Accident :	
Remarks : TP INSURER: AIG, TP INSURED VEHICLE NO: SKW4895G, DOA: 27.02.2018		

EM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
				B/F 0.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Sub Total	3,651.60
GST(7.00%)	255.61
Total (SGD)	3,907.21

Please conduct the survey at
 Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216



MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01, SGX Centre 2, Singapore 068807
Tel +65 6827 7888, Fax +65 6827 7800
Co. Reg. No. 200412212G GST Reg. No. 20-041221G

Certificate of Insurance

ROAD TRANSPORT ACT 1987 (MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
(REPUBLIC OF SINGAPORE)
THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M. S. 400
Cars for Hire

COMMERCIAL VEHICLE - FLEET
Comprehensive

Certificate No. A 29069774 MKF

Excess : SGD2,000

1. Index Mark and Registration Number of Vehicle

SLQ7714X

2. Name of Policyholder

Grab Rentals 2 Pte. Ltd.

3. Effective Date of the Commencement of Insurance for the purposes of the Act

01/02/2018

4. Date of Expiry of Insurance

31/01/2019

5. Persons or Classes of Persons entitled to drive*

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use*

Use for the carriage of passengers or goods in connection with the Policyholder's business.

Use for social domestic and pleasure purposes.

The Policy does not cover

(1) Use for racing pace-making reliability trial or speed-testing.

(2) Use whilst drawing a trailer except the towing (other than for reward) of any one disabled mechanically propelled vehicle.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the Insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte. Ltd.

Approved Insurers

Chief Executive Officer



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC6/AIG18004665/Uea3

04 APRIL 2018

TAN THIAM CHYE
2 BUTTER WORTH LANE
#01-04
SINGAPORE 439445

Dear Sir/Madam,

ACCIDENT INVOLVING SKW 4895G AND SLQ 7714X ON 27/02/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Asher Sng
Case Handler
DID: 6841 6051
FAX: 6741 4108
Email: Ashersng@lkkauto.com

c.c. *AIG Asia Pacific Insurance Pte Ltd*
(Motor Claims Dept)

AUTHORIZATION TO ACT

TO: PEGASUS ENGINEERING & TRADING PTE LTD

FROM: OWNER OF VEHICLE NUMBER SLQ7714X

ACCIDENT INVOLVING skw4895G

ALONG/AT Stamford Road ON 27.02.2018

We hereby authorize you to act on our behalf in pursuance of our claim for all damages during the repair arising out of the above accident.

This letter serve as the 'AUTHORITY TO ACT'.

We also hereby authorize all agreed settlement payment be made in favour to PEGASUS ENGINEERING & TRADING PTE LTD.

Name : Grab Rentals 2 Pte Ltd

Co Reg No : 201701345N

Address : 18 Sin Ming Lane #01-08 Midview city Singapore 573960

Contact : 6655 0005

Date : 24.07.2018

Signature



Owner

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, **PEGASUS ENGINEERING & TRADING PTE LTD** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$2,440.00** (Global Sum) for vehicle no. **SLO 7714X** that was damaged pursuant to the accident which occurred on **27/02/2018** (date) along **STAMFORD ROAD** involving vehicle no/s **SKW 4895G**.

This is pursuant to the inspection conducted on **12/03/2018** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **GRAB RENTALS 2 PTE LTD** ("the third party claimant") of vehicle no. **SLO 7714X** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **SLO 7714X** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 27 (day) of March (month) 2019 (year)



CKS

Signed by appointed surveyor



Signed by "the workshop" (with chop)

"The contents of this document apply to vehicle damages only. All personal injuries and damages arising therefrom are excluded from the ambit and application of this document."



Grab Rentals 2 Pte Ltd
18 Sin Ming Lane
#01-08 Midview City
Singapore 573960

Vehicle Model : Mazda 3 Sedan 1.5
Vehicle No : SLQ7714X
Chassis No : JM6BN22A8H0152995

GST / ROC Company No : 201101753C

Third Party Insurer : AIG
Insured's Veh No : SKW4895G
Date of accident : 27.02.2018


Tax Invoice No : IV18/06-1084
Invoice Date : 25.06.2018

Pages : 1 of 1

DESCRIPTION	AMOUNT
TO LUMP SUM REPAIR AS RECOMMENDED BY SURVEYOR.	\$ 1,900.00
Sub Total	\$ 1,900.00
GST (7.00%)	\$ 133.00
Total	\$ 2,033.00

Cheques should be made payable to **PEGASUS ENGINEERING & TRADING PTE LTD**

PEGASUS ENGINEERING & TRADING PTE LTD


Authorised Signature (Company Stamp)

If you have enquiries concerning this invoice, please contact Mr. Alvin or Mr. Wee at Tel: (65) 6858 1846
Mailing Address : Pegasus Engineering@Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216
E-mail : claims@pegasusengrg.com.sg

Enquire Vehicle & Owner Information (Vehicle No. SKW4895G As At 27 Feb 2018 / 10:20:00)**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident
Law Firm Case No.: SLQ7714X

Current Owner Details

Owner ID Type: Singapore NRIC
Owner ID: S7009348J
Owner Name: TANTHAM CHYE
Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes
Registered Block/House No.: 2
Registered Street Name: BUTTERWORTH LANE
Registered Unit No.: # 01 - 04
Registered Building Name: -
Registered Postal Code: 439445

Current Vehicle Details

Vehicle No.: SKW4895G
Make Description/Model: INFINITI / Q50 2.0T PREMIUM A/T
Insurance Company Name: AIG ASIA PACIFIC INSURANCE PTE. LTD.

Thank you



Lee Ming Hui Kelvin has successfully logged out.
Your last login date and time was 28 Feb 2018, 09:49:51.
To return to ONE.MOTORING, please click [here](#)
For security reasons, please **CLEAR YOUR CACHE** after each session.

Session Transaction History

<u>S/No.</u>	<u>Asset Type</u>	<u>Asset ID</u>	<u>Asset Owner ID</u>	<u>Transaction Type</u>	<u>Transaction Amount(\$)</u>	<u>Log Date/Time</u>
1	Vehicle	SKW4E95G	-	18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49	28 Feb 2018 / 09:50:48



Our Ref: GR-ACC-2017-02

01 June 2017

Pagasus Engineering & Trading Pte Ltd
No. 51 Defu Lane 10
Singapore 539216

Mailing Address
18 Sin Ming Lane,
#01-08 Midview City,
Singapore 573960
Co. No. 201617200G

To whom it may concern,

Re: Vehicle Rental Rates for Loss of Rental Claims.

With regards to the above subject matter, we are pleased to inform you our Grab Rental rate for our various vehicles which are as follows:

S/No.	Make & Model	Daily Rental Rates (S\$)
01	Toyota Prius 1,798cc, 90kw, 120bhp, Automatic	\$ 79.95
02	Mazda 3 1.5 (A) Sedan	\$ 66.95
03	Nissan Qashqai 1.2L	\$78.95
04	Honda Vezel 1.5L	\$77.95
05	Honda Vezel 1.5L Hybrid	\$84.95
06	Toyota Vios 1.5L	\$68.95

Please note that the above stated rate is our daily rental rate to our drivers. For your necessary actions on third party accident claims on loss of rental.

Yours faithfully,


Tay Chee Wee
Grab Rental Pte Ltd

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	28 Feb 2018 Edit Reg		12 Mar 2018 00:00 Edit Adj Rpt	S\$1,900.00 Edit Estimates	S\$1,900.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	TAN THIAM CHYE , ID: S7009348J								
Main Claimant:	GRAB RENTALS 2 PTE LTD , Co. Reg. No.: 201701345N								
Vehicle Reg. No.:	SLQ7714X	Date of Loss:	27/02/2018 00:00 - :59 [7 Months and 6 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 8881057633SG	Policy/Cover Note No.:	2100436279 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKW4895G	Policy No. (Claimant):	A29069766MKF						
		Excess:							
Repairer:	Pegasus Engineering & Trading Pte Ltd (HQ) 51 DEFU LANE 10, 539216 Defu Lane - Tel: 68581846								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com								
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 21/03/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG (13/03/2018): Request To Upload TP GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLQ7714X (8881057633SG)
 [SKW4895G]
 TP
 GRAB RENTALS 2 PTE LTD
 Feb 27 2018 12:00AM
 [TAN THIAM CHYE]
 Pegasus Engineering & Trading Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View View in Browser	
Letters/Correspondences										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	(Draft)	Third Party Express Settlement - Payment Breakdown							Edit		
Assessment Reports										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)						Thumbnail	Print		
1	13/03/18 15:56	Accident Statement <small>From: SC - Reg. No: SKW4895G, Claimant: TAN THIAM CHYE</small>							Load HTML		
Photos/Images										3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	12/03/18 19:19	Chassis Number							Load JPG	<input checked="" type="checkbox"/>	
2	12/03/18 19:19	Odometer Reading							Load JPG	<input checked="" type="checkbox"/>	
3	12/03/18 19:19	General View							Load JPG	<input checked="" type="checkbox"/>	
4	12/03/18 19:19	General View							Load JPG	<input checked="" type="checkbox"/>	
5	12/03/18 19:19	General View							Load JPG	<input checked="" type="checkbox"/>	
6	12/03/18 19:19	General View							Load JPG	<input checked="" type="checkbox"/>	
7	12/03/18 19:19	General View							Load JPG	<input checked="" type="checkbox"/>	
8	12/03/18 19:19	General View							Load JPG	<input checked="" type="checkbox"/>	
9	12/03/18 19:19	General View							Load JPG	<input checked="" type="checkbox"/>	
10	12/03/18 19:19	General View							Load JPG	<input checked="" type="checkbox"/>	
11	12/03/18 19:19	General View							Load JPG	<input checked="" type="checkbox"/>	
12	12/03/18 19:19	General View							Load JPG	<input checked="" type="checkbox"/>	
13	12/03/18 19:19	General View							Load JPG	<input checked="" type="checkbox"/>	
14	12/03/18 19:19	General View							Load JPG	<input checked="" type="checkbox"/>	
15	12/03/18 19:19	General View							Load JPG	<input checked="" type="checkbox"/>	
16	12/03/18 19:19	General View							Load JPG	<input checked="" type="checkbox"/>	
17	12/03/18 19:19	General View							Load JPG	<input checked="" type="checkbox"/>	
18	12/03/18 19:19	General View							Load JPG	<input checked="" type="checkbox"/>	
19	12/03/18 19:19	General View							Load JPG	<input checked="" type="checkbox"/>	
20	12/03/18 19:19	General View							Load JPG	<input checked="" type="checkbox"/>	
21	23/05/18 18:10	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
22	23/05/18 18:10	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
23	23/05/18 18:10	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
24	23/05/18 18:10	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
25	23/05/18 18:10	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
26	23/05/18 18:10	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
27	23/05/18 18:10	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
28	23/05/18 18:10	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
Documentation										1 per page	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	14/03/18 11:03	TP ESTIMATE - MARKED		Load PDF
2	14/03/18 11:06	TP GIA REPORT		Load PDF
3	23/03/18 08:46	EMAIL TO AIG DD 230318		Load PDF
4	23/03/18 08:46	EMAIL TO OI DD 230318		Load PDF
5	04/04/18 17:20	LETTER TO OI		Load PDF
6	05/04/19 12:47	WORKSHOP INVOICE		Load PDF
7	05/04/19 12:47	AUTHORISATION TO ACT FORM		Load PDF
8	05/04/19 12:47	Release Voucher		Load PDF
9	05/04/19 12:47	RENTAL RATES		Load PDF
10	05/04/19 12:47	LTA SEARCH		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>(Note: Remarks are private unless you show it to other parties.)</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SKW4895G (Insd veh)	Model:	MAZDA 3 1.5 SEDAN EU6 (A)
	SLQ7714X (TP veh)		
Date of Accident:	27/02/2018		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	: \$		3,907.21
Final Repair Cost	: \$		2,440.00
Loss of Use	: \$		4.00 days at \$100.00 per day
Rental (if any)	: \$		days
LTA / GIA Search Fee	: \$		
Others:	: \$		
	: \$		
Final Settlement Sum (Global Sum)	: \$		2,440.00

Is Third Party Workshop GIA Registered? YES NO (Kindly indicate below)

A) For Non GIA Registered Workshop:	Agreed Liability ___100___(%)
B) For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: _____
BOLA Liability: _____(%)	Assessed Liability (*): _____(%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.	
Remarks _____	

Payment Instruction: Payee's Breakdown			
1)	Pegasus Engineering & Trading Pte Ltd	: \$	2,440.00
2)		: \$	
3)		: \$	
4)		: \$	

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

05 Apr
2019

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18004665/UEA3Q2
Date: 05/04/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100436279
Claimant Vehicle No : SLQ7714X	Insured Vehicle No :	SKW4895G
Date of Loss: 27/02/2018	Nature of Claim: TP	Claim No: 8881057633SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLQ7714X	Engine No:	P520444674
Make & Model:	MAZDA 3, 1.5 SEDAN EU6 (A)	Chassis No:	JM6BN22A8H0152995
Reg. Date:	21/07/2017 (Man. Year: 2017)	Odometer:	43501 km
Colour:	Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,191.60	1,624.00	567.60	25.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,460.00	770.00	690.00	47.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,651.60	2,394.00	1,257.60	34.44
Approved Total (Overridden) (S\$)		1,900.00		
	(S\$)	3,651.60	1,900.00	1,751.60
	+ GST 7.00/7.00% (S\$)	255.61	133.00	122.61
	Nett Amount (S\$)	3,907.21	2,033.00	1,874.21
	+ Loss of Use (4.0 x S\$100.00/day) (S\$)		400.00	
	+ Doc/Search Fee (S\$)		7.49	
	Nett Liability (S\$)		2,440.49	
	Global Sum Settlement (S\$)		2,440.00	

INSPECTION

Date of Assignment: 12/03/2018
Date Inspected: 12/03/2018 Inspected At:

Pegasus Engineering & Trading Pte Ltd
(HQ)
51 DEFU LANE 10
Singapore 539216

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented / Deformed	1,075.00 FL	*1,075.00 FL
2	1		*REAR BUMPER REINFORCEMENT	Dented	538.00 FL	*538.00 FL
3	2		*REAR BUMPER REFLECTOR	Not Necessary	102.00 FL	*- FL
4	2		*REAR BUMPER SIDE RETAINER	Necessary	74.00 FL	*74.00 FL
5	2		*REAR BUMPER SIDE HOLDER	Not Necessary	92.00 FL	*- FL
6	4		*REAR BUMPER SIDE HOLDER RIVETS	Necessary	36.00 FL	*36.00 FL
7	1		*O/S REAR BUMPER TOW COVER	Missing	17.00 FL	*17.00 FL
8	1		*REAR BUMPER CENTRE BRACKET	Not Necessary	10.00 FL	*- FL
9	8		*REAR BUMPER CLIPS	Necessary	40.00 FL	*40.00 FL
10	1		*BOOTLID MAZDA 3 BADGE	Not Necessary	54.00 FL	*- FL
11	1		*BOOTLID CENTRE LOGO BADGE	Not Necessary	75.00 FL	*- FL
12	1		*BOOTLID SKYACTIV BADGE	Not Necessary	64.00 FL	*- FL
13	1		*SET REAR BUMPER PARKING SENSOR	Shorted	450.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,627.00	1,980.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	435.40	356.00
Total Parts (\$\$)	2,191.60	1,624.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	120.00	50.00
2	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	40.00	20.00
3	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	600.00	300.00
4	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	700.00	400.00
Gross Labour Cost (S\$)			1,460.00	770.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >