

ASS. REC. BY:

REF: CS/FCI18004666/ T1vd3ⁿ² Special Instruction:

Surveyor: Tauhiah ASSIGNMENT (Office)

From (Person): Sitham of FCI Date/Time: 12/3/18 @ 11.32am

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLJ 6285K Insured: SHC 0472K

at Workshop m/s Tanaka Automotive Tel: 98385899

of 755 Choa chukang North 5

Policy No: _____ Claim No: D18000956MESH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 29/01/2018
(Client's Record)

CA / REV / REP. / REV 24 HRS lwp Insp: Miracle workz

Date/Time: 12:08pm @ 12/3/18 Person Contacted: Fanny H.O.D. Endorsement: _____

Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SLJ 6285K-X</u>
	<u>SHC 472K-CC3/AIG/11016484/H/a2a3a2 D.O.A: 10/1/2011</u>
<u>16/3/18</u>	<u>Email preli revised to FCI</u>
<u>18/4/18</u>	<u>LS \$3400 confirmed by email (Red 2488.02 429)</u>

Smith, Tanya

REF: FCI

ASSIGNMENT

Date 13/3/18

Ver No: BL 285K- 12/16

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLJ 6085K
at Worksite: Miracle Workz
18 Joh Guan Rd East #04-126

Type: M/Cycle Bus/Van/Truck/Trailer/Prime Mover
Truck/Trailer

Make: Toyota Equine
Color: white

Chassis No: 12735

Eng No: ZRR80 0080452

Gen Cond: Good Fair Poor Burnt

Steering: In order Jammed Leaked Burnt or

Brake: In order Jammed Leaked Burnt or

Mod: Nil STD A/R/H or

Tyre Size: F 195/65R15
R 14

BS/DUN/EXNOVA PS LIZA MIC CHTSL PR SLM
TOYO/YOKO

Front: R/Sa 6 --- L/Sa 6 ---

Wheel: L/Sa 6 --- R/Sa 6 ---

D/OA: --- D/O 13/3/18 @ pm

Surveyed at:

Des. of Damages: Fair O/S N/S U/O Referred

The U/O / Chassis/frame / Body Structure affected due to collision

Insured:

Policy No:


Claims No:

Sum Insured: Excess:

Claims Record:

Make of Van:

(Policy Condition)



Remark: The veh had commenced its repair at the time of inspection.

Sal. or Market Value:

OAD Accident Report: Consistent? Yes or No

GIA PR Seen: Consistent? Yes or No

Est. Repairs: days Rep: Yes or No

Sum Sum: % S Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted: Vehicle IN / OUT

Date Time Action / Instruction

w/s will e-mail GIA R estimate
HS \$3400, 5 days, e-mail to Fanny

RECEIVED 18 APR 2018

Date Time File Passed: Preli. Report
 Final Report

Days Of Repair: 5
Resurvey No. of Trip: 1

Date Time File Returned: 18/4 - typist

Add Fee: Site fee: \$
 Meter fee: \$
 Tech fee: \$
 Rep fee: \$

Report Format: CWS
L/Sa Sum: LS \$3400

140
50
50
51
291



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18004666/T1vd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 12-03-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 472K	Veh. Inspected	SLJ 6285K
Policy No.		Coverage (\$)	0.00
Claim No.	D18000956MFSH	Excess (\$)	0.00
Assign From	CWS (SITHARA)	Assign Date	12/03/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	29/01/2018	Inspection Date	
Survey held at	TANALA AUTOMOTIVE CONSULTANCY BLK 7 SIN MING IND EST SECTOR C #01-82 SINGAPORE 575642		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18000956MFSH

Our ref: CS/FC118004666/T1vd3

Date: 16/3/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Without Prejudice

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLJ 6285K


We thank you for your instruction on 12/3/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 13/3/2018 at the premises of M/s TANALA AUTOMOTIVE CONSULTANCY and have the following to report:-

Workshop Estimate Amount	: S\$5,888.02
Revised Estimate Amount	: S\$4,258.17
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

MOHAMAD TAUFIKH
M.MATAI, AMSAE-A
Automobile Assessor

MOTOR SURVEY ASSIGNMENT

Date	31-01-2018	Our Ref No. D18000956MFSH
Accident Date	29-01-2018	Claim Type. Third Party
Insured Vehicle	SHC0472K	Third Party Vehicle. SLJ6285K
Survey Location	755 CHOA CHU KANG NORTH 5	
Contact Person.	FANNY	
Contact No.	98385899/ 98385899	Fax No. 68636477
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TANALA AUTOMOTIVE CONSULTANCY	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/234538)



PRI Documents



Close



PRI Header Details

Claim No	D18000956MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & TANALA A
Workshop Name	TANALA AUTOMOTIVE CONSULTANCY (Contact Person : FANNY)	Survey Location & Contact Details	755 CHOA CHU KANG NORTH 5 Mobile: 98385899 , Phone: 98385899 , Fax: 6863647 EmailId: TANALA.MOTORING@GMAIL.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHC0472K	TP Vehicle No	SLJ6285K
PRI Recieved Date	09-03-2018 07:34:11 PM	Surveyor Appointed Date	12-03-2018 11:31:23 AM	Surveyor Accept Date	12-03-2018 0

Survey Report Upload

Surveyor Inspection Date *:	<input type="text"/>	Surveyor Report Date	12-03-2018	Upload Survey Report *:	<input type="button" value="Choose File"/>
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	<input type="text" value="Please Select Make"/>	Model	<input type="text" value="Please Select Model"/>	Year	<input type="text" value="Select Year"/>
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Veron Chen (LKKAuto)

From: Tanala <tanala.motoring@gmail.com>
Sent: Wednesday, 14 March 2018 10:35 AM
To: Taufikh (LKKAuto); SUR
Subject: Re: SURVEYOR APPOINTED; OUR REF : D18000956MFSH ; YOUR REF: SLJ6285K
Attachments: SLJ6285K_Estimate.pdf

Dear Sir/Madam,

Please find the attached estimate of SLJ6285K for your attention, please.

Thank You.

Regards,
Fanny
Tanala Automotive Consultancy

On Mon, Mar 12, 2018 at 11:31 AM, Claim Workflow System <cwsmotorclaims@msfirstcapital.com.sg> wrote:

Dear Sir/Madam

PRI Request For **SLJ6285K** Accident Involving **SHC0472K** On 29-01-2018 AT 15:30:00HRS.

Please find below details for your reference

- **Claim number** : D18000956MFSH
- **Insured vehicle number** : SHC0472K
- **Accident date** : 29-01-2018
- **Third-party vehicle number** : SLJ6285K
- **Assignment type** : WITHOUT PREJUDICE
- **Surveyor** : LKK AUTO CONSULTANTS PTE LTD
- **Officer-in-Charge** : SITHARA

PS: This is a system generated mail. Please do not reply to this mail.

Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

Veron Chen (LKKAuto)

From: Tanala <tanala.motoring@gmail.com>
Sent: Wednesday, 18 April 2018 11:39 AM
To: Taufikh (LKKAuto)
Cc: Veron Chen (LKKAuto)
Subject: Re: SURVEYOR APPOINTED; OUR REF : D18000956MFSH ; YOUR REF: SLJ6285K

Hi Taufikh,

We are agreeable to the COR (L/S) @ \$3,400/- and 5 working days.

Regards,
Fanny

On Tue, Apr 17, 2018 at 4:56 PM, Taufikh (LKK Auto) <taufikh@lkkauto.com> wrote:

Hi Fanny,

COR l/s \$3400 , 5 days.

Regards

Taufikh

Lkk Auto

From: Tanala [mailto:tanala.motoring@gmail.com]
Sent: Tuesday, 10 April 2018 9:50 PM
To: Taufikh (LKKAuto); SUR
Cc: Veron Chen (LKKAuto)

Subject: Re: SURVEYOR APPOINTED; OUR REF : D18000956MFSH ; YOUR REF: SLJ6285K

Dear Sir/Madam,

Kindly revert with adjustment to our estimate.

Regards,

Fanny

On Wed, Mar 28, 2018 at 3:48 PM, Tanala <tanala.motoring@gmail.com> wrote:

Dear Sir/Madam,

Kindly assist to finalize the repair costs, please.

Regards,

Fanny

On Wed, Mar 21, 2018 at 2:34 PM, Tanala <tanala.motoring@gmail.com> wrote:

Dear Sir/Madam,

Please find attached after repair photos for your attention.

Regards,

Fanny

On Fri, Mar 16, 2018 at 1:54 PM, Tanala <tanala.motoring@gmail.com> wrote:

Dear Veron,

GIA report attached as per your request.

Regards,

Fanny

On Fri, Mar 16, 2018 at 12:35 PM, Veron Chen (LKKAuto) <veronchen@lkkauto.com> wrote:

Dear Fanny,

Kindly forward us a copy of GIA report.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tanala [<mailto:tanala.motoring@gmail.com>]

Sent: Thursday, 15 March 2018 3:17 PM

To: Taufikh (LKKAuto) <Taufikh@lkkauto.com>; SUR <sur@lkkauto.com>

Subject: Re: SURVEYOR APPOINTED; OUR REF : D18000956MFSH ; YOUR REF: SLJ6285K

Dear Sir/Madam,

Attached photographs for your attention, please.

Regards,

Fanny

On Wed, Mar 14, 2018 at 10:34 AM, Tanala <tanala.motoring@gmail.com> wrote:

Dear Sir/Madam,

Please find the attached estimate of SLJ6285K for your attention, please.

Thank You.

Regards,

Fanny

Tanala Automotive Consultancy

On Mon, Mar 12, 2018 at 11:31 AM, Claim Workflow System <cwsmotorclaims@msfirstcapital.com.sg> wrote:

Dear Sir/Madam

PRI Request For **SLJ6285K** Accident Involving **SHC0472K** On 29-01-2018 AT 15:30:00HRS.

Please find below details for your reference

- **Claim number** : D18000956MFSH
- **Insured vehicle number** : SHC0472K
- **Accident date** : 29-01-2018
- **Third-party vehicle number** : SLJ6285K
- **Assignment type** : WITHOUT PREJUDICE
- **Surveyor** : LKK AUTO CONSULTANTS PTE LTD
- **Officer-in-Charge** : SITHARA

PS: This is a system generated mail. Please do not reply to this mail.

Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 16 March 2018 12:41 PM
To: 'Claim Workflow System'
Cc: SITHARA@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18000956MFSH/1, SLJ 6285K
Attachments: SLJ 6285K PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SLJ 6285K
Date of survey: 13/3/2018
Number of days:5 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Monday, 12 March 2018 4:53 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: SITHARA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18000956MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Monday, 12 March 2018 11:31 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SITHARA@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18000956MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

FIN G3279322W



Name
TANYA EKSTEEN



Date of Birth 25-10-1982 Sex F
Nationality SOUTH AFRICAN



TANYA EKSTEEN
Date of Birth 25 Oct 1982
Issue Date 12 Apr 2017
Valid Till 11/04/2022



002674596C

FA1596378

DEPENDANT'S PASS

Immigration Regulations

FIN G3279322W



MULTIPLE JOURNEY VISA ISSUED
Date of Issue 05-07-2016 Date of Expiry 23-05-2018



YOU ARE TO SURRENDER THIS CARD WHEN IT IS CANCELLED OR HAS EXPIRED, OR WHEN A NEW CARD IS ISSUED

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

EFFECTIVE DATE

Class 3

Motor cars with unladen weight =< 3000kg with =< 7 passengers, exclusive of driver; and other motor vehicles with unladen weight =< 2500kg

NP 428A



Licence No:G3279322W

CLASS 3 ~ 12 APR 2017

COPIES

Tanala Automotive Consultancy

My Mail Box 883230
 Singapore 919191
 ROB: 53240124K

Swee Seng Leasing Pte Ltd

21 Toh Guan Road East
 #03-02 Toh Guan Centre
 Singapore 608609
 Attn: Motor Claims Department

Estimate No : ES2018/0089
 Date : 13/03/2018
 Vehicle No : SLJ6285K
 Make/Model : Toyota / Esquire
 Date of Accident : 29/01/2018

S/N	Description	Qty	Unit Amount	Amount
<u>List Items</u>				
1	Rear Bumper	1	894.60	894.60 <i>de✓</i>
2	Reflector RH/LH, RR	2	158.85	317.70 <i>X 2 ✓</i>
3	Bumper Lower, RR	1	495.50	495.50 <i>de✓</i>
4	Bumper Chrome RH/LH, RR	2	195.50	391.00 <i>LH-R, RH-outer ✓</i>
5	Tail Boot	1	1,790.09	1,790.09 <i>bt ✓</i>
6	Inner Lock	1	368.40	368.40 <i>X 1 ✓</i>
7	Rear Body Weatherstrip	1	398.20	398.20 <i>X 1 ✓</i>
8	Esquire Logo	1	115.20	115.20 <i>new ✓</i>
			3490.89	4,770.69
			Less: 25%	(1,192.67)
				<u>2618.17</u> <i>3,578.02</i>
<u>Nett Items</u>				
1	Reverse Sensor	1 Set	250.00	250.00 <i>200 new ✓</i>
2	Rear Windscreen Sealant	1	60.00	60.00 <i>new ✓</i>
				<u>310.00</u> <i>260</i>
<u>Labour charges</u>				
	To dismantle/refit rear windscreen			150.00 <i>120</i>
	To panel beat/repair rear body			850.00 <i>600</i>
	To dismantle/replace above-mentioned parts			750.00 <i>600</i>
	To spray painting on affected areas			150.00 <i>30</i>
	To apply tuff kote			100.00 <i>30</i>
	To check wiring			
				<u>2,000.00</u> <i>1380</i>

Days of Repair: 7 days @ S\$150/day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Cheryl

Tanala Automotive Consultancy

16/3/18

4258.17
 4/S\$3400 #
 5 days
 TOTAL 5,888.02
 Tanakh 97495749
 'WP'
 13/3/18 @ 1pm
 5 days
 sw @ lkkarb.com



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18004666/T1vd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 19-04-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 472K	Veh. Inspected	SLJ 6285K	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18000956MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	12/03/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ESQUIRE	c.c	1986	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	ZRR800080432	Colour	WHITE	
Odometer	12735	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	GOODYEAR	6 mm	
L/H Front Tyre	195/65 R15	GOODYEAR	6 mm	
R/H Rear Tyre	195/65 R15	GOODYEAR	6 mm	
L/H Rear Tyre	195/65 R15	GOODYEAR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	29/01/2018	Inspection Date	13/03/2018	
Survey held at	TANALA AUTOMOTIVE CONSULTANCY BLK 7 SIN MING IND EST SECTOR C #01-82 SINGAPORE 575642			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLJ 6285K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED	894.60	894.60
2	REFLECTOR RH/LH,RR @\$158.85	NOT NECESSARY	317.70	-
1	BUMPER LOWER,RR	DEFORMED	495.50	495.50
2	BUMPER CHROME,RH/LH,RR @\$195.50	O/S CUT / N/S NOT NECESSARY	391.00	195.50
1	TAIL BOOT	BENT	1,790.09	1,790.09
1	INNER LOCK	NOT NECESSARY	368.40	-
1	REAR BODY WEATHERSTRIP	NOT NECESSARY	398.20	-
1	ESQUIRE LOGO	NECESSARY	115.20	115.20
	LESS 25% DISCOUNT		-1,192.67	-872.72
			3,578.02	2,618.17
SPECIAL NETT ITEMS				
1	SET REVERSE SENSOR (SN)	NOT WORKING	250.00	200.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	60.00	60.00
			310.00	260.00
LABOUR				
	TO DISMANTLE/REFIT REAR WINDSCREEN.		150.00	120.00
	TO PANEL BEAT/REPAIR REAR BODY.		850.00	600.00
	TO DISMANTLE/REPLACE ABOVE-MENTIONED PARTS.		750.00	600.00
	TO SPRAY PAINTING ON AFFECTED AREAS.		150.00	30.00
	TO APPLY TUFF KOTE.		100.00	30.00
	TO CHECK WIRING.		2,000.00	1,380.00
			5,888.02	4,258.17
GRAND TOTAL			5,888.02	4,258.17
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,400.00

Report Ref No. CS/FCI18004666/T1vd3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.