

INS. CASE OWNER:

cc3, ALG1800 4707, Kpa3

LKK:

IDAC:

Surveyor:

KSC

DOI:

ASSIGNMENT

12/3/18

Date / Time:

12/3/18

Registered in Merimen:

13/3/18

Pre-assign / CCU / FTE



Insured Vehicle No. : 8KS 7345D

Name of Insured :

Insured Tel No. :

HP:

Excess Sec II :S\$

D.O.A :

06/03/18

Is driver the owner? (YES / NO)

Nature of Accident :

If NO, Driver Name / Age :

Driver Tel No. :

(V/L: YES / NO)

Claim No. :

Policy No. :

Make / Model :

Place of Accident :

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability :

%

Final ? Yes / No

SHD 273m



INSRS:

WSP: Trans

Tel:

Liability: cas

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time	STAGE	DATE / PIC	
SHD 273m - NAT INC 10024643/01 : van. 4/1/10 8KS 7345D - X	Non-Reporting ltr (1st):		
	Non-Reporting ltr (2nd):		
	Non-Reporting ltr (Final):		
	Notification ltr (if non-pickup):		
	Call OI:		
	After call ltr to OI:		
	Documentation Check List:	Handler Typist	
	Notification ltr (if non-pickup)	☐	☐
	After call ltr to OI:	☐	☐
	Authorisation To Act:	☐	☐
	Release Voucher:	☐	☐
	Final Repair Bill:	☐	☐
	Car Rental Invoice:	☐	☐
	Towing Invoice	☐	☐
	LTA / GIA :	☐	☐
Medical Bill:	☐	☐	
PIR:	☐	☐	
Mandate/Reject Instruction:	☐	☐	
LOD	☐	☐	
Payment Breakdown Form:	☐	☐	
PRELIMINARY ADVICE Date/Time:	Sent By:	Post-Repair Photos: ☐	
		Others: ☐	
FINALIZATION Date/Time:	Confirm with:	Confirm by:	
Repair Cost: S\$	(days) Reduction: %	Email ☐ Call ☐	
FINAL SETTLEMENT Date/Time:	Confirm with:	Email ☐ Call ☐	
Final Liability: %	(Agreed / Assessed) BOLA S/N No. :	If NO or B 28, Ass. Lia :	
Repair Cost: S\$			
Loss of Rental (LOR): S\$	(days)		
Loss of Use (LOU): S\$	(\$ x days)		
Loss of Income (LOI): S\$	(\$ x days)		
LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐	[Tick only one]		
GIA/LTA Search	S\$		
Medical:	S\$	1) Claim status: Normal/Reject/Private Settle	
Disbursement:	S\$ (e.g. Tow/ Independent)	2) Report Format:	
Legal Cost	S\$	3) Survey fee:	
Total: S\$	Global Sum S\$:		
FINAL PAYMENT Date/Time:	Confirm with:	Email ☐ Call ☐	
Payee 1: S\$	Name 1:		
Payee 2: (Strike if N.A.) S\$	Name 2:		
Payee 3: (Strike if N.A.) S\$	Name 3:		

ASS. REC. BY:

REF:

A/G/

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

01 days

Res.: Yes or No

Lum Sum:

1.13.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SID 273m

Yr Regn:

02, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Renault Latitude

c.c. 1995

Colour

M. white 1R

A/C: Insured / Std / NI / NA

Sp. Reading

297175

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

VIFIABL15AUC. 282425

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Giti

Front

R/Bal.

7

mm

Rear

R/Bal.

8

mm

L/Bal.

7

mm

L/Bal.

8

mm

D.O.A.

6/3/18

D.O.I.

12/3/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

13/3

File pass to Catherine
\$1127.96

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trlp:

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$