

INS. CASE OWNER:

cc6, LOR1800 4715, Uja39v

LKK:

IDAC:

Surveyor:

Marius

DOI:

ASSIGNMENT

13/3/18

Date / Time:

13/3/18

Registered in Merimen:

13/3/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SUE 1165 G

Name of Insured:

LCRF P/L

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

9/3/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Mohammad Fairuz Bin Halid

Driver Tel No.:

90106639

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SUP 8527



INSRS:

WSP:

Tel:

Liability:

RMKS:

Pegasus

7/10/18



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

2/3
Joy

SUP 8527-X; SUE 1165 G-X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

JOY 21-3-18

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

X

After call ltr to OI:

X

Authorisation To Act:

X

Release Voucher:

X

Final Repair Bill:

X

Car Rental Invoice:

X

Towing Invoice:

X

LTA / GIA:

X

Medical Bill:

X

PIR:

X

Mandate/Reject Instruction:

X

LOD

X

Payment Breakdown Form:

X

Post-Repair Photos:

X

Others:

X

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

3/7/18

Confirm with:

Patricia

Email

Call

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No. : 28

If NO or B 28, Ass. Lia : 0%

Repair Cost:

GST

S\$

4,494.xx

Loss of Rental (LOR):

S\$

401.70

6

days)

x 66.95

3 VC. 01, 2ND.

Loss of Use (LOU):

S\$

-

(\$

x

days)

Loss of Income (LOI):

S\$

-

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$

7.49

Medical:

S\$

-

Disbursement:

S\$

-

(e.g. Tow/ Independent)

Legal Cost

S\$

-

Total:

S\$

4,903.19

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

4,903.19

Name 1:

PEGASUS ENGINEERING & TRADING PTE LTD

Payee 2: (Strike if N.A.)

S\$

X

Name 2:

X

Payee 3: (Strike if N.A.)

S\$

X

Name 3:

X

RECEIVED 03 JUL 2018

COPY SENT
3/7/18

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLP 58528at Workshop m/s Reposusof SLC 51656

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

CA / PR Seen: 9 Consistent? : Yes or NoEst. Repairs: 5 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

72006

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Date / Time Action / Instruction

13/3/18 confirmed L/S #4200 with willian.Veh No: SLP 58528 Yr Regn: 6, 17Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAMake: Toyota v. 05 C.C. 1496Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 55428 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MHF1329F.3102012112Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/50R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 9/3/18 D.O.I. 13/3/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Report Format : _____

Lump Sum / I.B.I. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS. \$ _____

Photos

Others

TOTAL

R (\$ 4,437.82/51%)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/LCR18004715/Uja3		
78 SHENTON WAY #08-16 CHARTIS BUILDINGS SINGAPORE 079120		Date : 13-03-2018		
		Code : LCR		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLE 5165G	Veh. Inspected	SLP 5852Z	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	13/03/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer		Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	09/03/2018	Inspection Date	13/03/2018	
Survey held at	PEGASUS ENGINEERING & TRADING PTE LTD 51 DEFU LANE 10 SINGAPORE 539216			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :

PEGASUS ENGINEERING & TRADING PTE LTD
C/O 51 DEFU LANE 10
539216

Officer in Charge : WEE TZE FAH
Tel :
Email :

Customer :

GRAB RENTALS PTE LTD
18 SIN MING LANE
#01-08 MIDVIEW CITY
SINGAPORE 573960

Attn :
Tel :
Fax :

Quotation No : QO18/03-1093

Quotation Date : 12/03/2018

Terms : 30 DAYS

Vehicle No : SLP5852Z

Chassis No : MHFB29F3102012112

Third Party Insurer :

Model : VIOS

Date of Accident :

Remarks : TP INSURER: AIG, INSURED'S VEH NO: SLE5165G, DATE OF ACCIDENT: 09.03.2018

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
1	BOOTLID	1	762.4700	762.47
2	BOOTLID LOCK	1	90.4000	90.40
3	BOOTLID LOCK STRICKER	1	18.5000	18.50
4	BOOTLID WEATHERSTRIP	1	188.8000	188.80
5	BOOTLID VIOS BADGE	1	44.1000	44.10
6	BOOTLID CENTRE BADGE	1	59.8000	59.80
7	BOOTLID E BADGE	1	39.4000	39.40
8	BOOTLID OUTER GARNISH	1	59.8000	59.80
9	BOOTLID INNER TRIM COVER	1	398.1000	398.10
10	BOOTLID INNER TRIM COVER CLIPS	6	4.3000	25.80
11	BOOTLID HINGE	2	79.8000	159.60
12	BOOTLID LOCK CABLE CLIPS	3	4.3000	12.90
13	REAR LICENSE PLATE LAMP	2	79.8000	159.60
14	REAR END PANEL	1	694.7000	694.70
15	REAR END PANEL INNER TRIM	1	234.3000	234.30
16	REAR END PANEL INNER CLIPS	4	4.3000	17.20
17	REAR LAMP	2	375.8000	751.60
18	REAR LAMP PANEL	2	238.9000	477.80
19	REAR LAMP CLIP HOLDER	4	9.5000	38.00
20	REAR BUMPER	1	504.9000	504.90
21	REAR BUMPER REINFORCEMENT	1	323.0000	323.00
22	REAR BUMPER SIDE RETAINER	2	116.3000	232.60
23	REAR BUMPER SIDE HOLDER	2	22.3000	44.60

C/F 0.00

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 539216 Officer in Charge : WEE TZE FAH Tel : Email :	Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax :
---	---

Quotation No : QO18/03-1093	Quotation Date : 12/03/2018	Terms : 30 DAYS
Vehicle No : SLP5852Z	Chassis No : MHFB29F3102012112	Third Party Insurer :
Model : VIOS	Date of Accident :	
Remarks : TP INSURER: AIG, INSURED'S VEH NO: SLE5165G, DATE OF ACCIDENT: 09.03.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00
24	REAR BUMPER CLIPS	8 <i>ur</i>	4.3000	34.40 ✓
25	REAR BUMPER END SPLASHIELD COVER	2 <i>11</i>	89.8000	179.60
26	REAR BUMPER REFLECTOR	2 <i>11</i>	130.5000	261.00
27	REAR LUGGAGE FLOOR TRIMBOARD	1 <i>70.11</i>	209.0000	209.00
28	REAR LUGGAGE FLOOR FOAM	1 <i>11</i>	75.0000	75.00
29	LESS 25% (ITEM 1 - 28)	1	-1,524.2400	-1,524.24
30	REAR LICENSE PLATE	1 <i>10</i>	80.0000	80.00
31	REAR BUMPER PARKING SENSOR	1 <i>1 set</i>	450.0000	450.00
32	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	1	1,050.0000	1,050.00
33	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	1	1,000.0000	1,000.00
34	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR	1	180.0000	180.00
35	TO RUST-PROOFING OF THE AFFECTED PORTION	1	220.0000	220.00
36	TO REINSTALL OF REAR BUMPER PARKING SENSOR	1	150.0000	150.00
37	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS, AND PERFORM WATER SEEPAGE TEST	1	160.0000	160.00
38	TO REPAIR AND REALIGN REAR EXHAUST BOX	1 <i>11</i>	150.0000	150.00
39	TO CHECK ELECTRICAL LIGHTING CONCERNED	1	60.0000	60.00

C/F 0.00

Page 2 of 3

2090

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 539216 Officer in Charge : WEE TZE FAH Tel : Email :	Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax :
---	---

Quotation No : QO18/03-1093	Quotation Date : 12/03/2018	Terms : 30 DAYS
Vehicle No : SLP5852Z	Chassis No : MHFB29F3102012112	Third Party Insurer :
Model : VIOS	Date of Accident :	
Remarks : TP INSURER: AIG, INSURED'S VEH NO: SLE5165G, DATE OF ACCIDENT: 09.03.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sub Total	8,072.73
GST(7.00%)	565.09
Total (SGD)	8,637.82

Please conduct the survey at
Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216



9A Lok Yang Singapore 628628
c/o 51 Defu Lane 10 Singapore 539216

Tel: 6858 1846 / HP 9628 6508
Fax: 6858 0877

Our Ref SM150032018
Your Ref SLF5165G

Date 21-06-2018

WITHOUT PREJUDICE

Claims Department -Executive In Charge
AIG Asia Pacific Insurance Pte Ltd

Dear Sir/Madam,

ACCIDENT INVOLVING SLP585JZ / SLF5165G / SLK9785J ON 09.03.2018

Refer to the above accident and please acknowledge receipt of this letter within 14 days.

It appears that the accident was caused by your insured. Enclosed documents to substantiate our client's property damaged claim as our client had authorized us to quantify, to act and to reach settlement within 6 weeks on their behalf: -

- ☒ Original Tax-invoice number 1V18/04-D33 ☐ police report / police result
☒ Certificate Of Insurance _____ ☐ Vehicle search result
☐ Letter from Grab ☒ Authorisation To Act - Hirer owner.
☒ Rental Tariff _____

*Survey under insurance instruction LKK

a)	Cost of repair (inclusive GST)	\$ <u>4,494.00</u>
b)	Vehicle Search fees / GIA fees / Police Report fees / Reporting fees	\$ <u>7.49</u>
c)	Loss of rental <u>6</u> days @ \$ <u>66.95</u>	\$ <u>401.70</u>
d)	Loss of earnings /rental fees _____ days @ \$ _____	\$ <u>-</u>
f)	Administrative charges to negotiate settlement (Waive if 100% offer made within acknowledge timeframe)	\$ <u>400.00</u>
	Total	\$ <u>5,303.19</u>

* Driver's injury and other losses exclude in this claim.

If you are agreeable to the above, please forward discharge voucher for our client's signature and payment issued directly to "Pegasus Engineering & Trading Pte Ltd" within 28 days.

Yours faithfully,

Sharon Orw

Email: claims@pegasusengrg.com.sg

Grab Rentals Pte Ltd
c/o 51 Defu Lane 10
Singapore 539216

Your Ref: CCB/HR/8004715/4: a3
Our Ref: SM150070018

23 June 2018

WITHOUT PREJUDICE

Motor Claims Department
AKR - LKR

Dear Sir/Madam

ACCIDENT INVOLVING SPS8527, SLE 51656 / KE9785J ON 09/03/2018

We refer to the above-mentioned accident.

We confirmed acceptance on your offer of S\$4903.19 in full and final settlement of our property damaged claim.

We hereby authorize that the said payment is to be issued in favour of Messrs PEGASUS ENGINEERING & TRADING PTE LTD within fourteen (14) days.

Your attention and prompt action in this matter is greatly appreciated.

Yours sincerely,



"The contents of this document apply to vehicle damages only. All personal injuries and damages arising therefrom are excluded from the ambit and application of this document."



MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01, SGX Centre 2, Singapore 068807
Tel +65 6827 7888, Fax +65 6827 7800
Co. Reg. No. 200412212G GST Reg. No. 20-041221G

Certificate of Insurance

ROAD TRANSPORT ACT 1987 (MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
(REPUBLIC OF SINGAPORE)
THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M.Z.400
Cars for Hire

COMMERCIAL VEHICLE - FLEET Comprehensive

Certificate No. A 29069766 MKF

Excess : SGD2,000

1. Index Mark and Registration Number of Vehicle
SLP5852Z

2. Name of Policyholder
Grab Rentals Pte. Ltd.

3. Effective Date of the Commencement of Insurance for the purposes of the Act
01/02/2018

4. Date of Expiry of Insurance
31/01/2019

5. Persons or Classes of Persons entitled to drive*

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use*

Use for the carriage of passengers or goods in connection with the Policyholder's business.

Use for social domestic and pleasure purposes.

The Policy does not cover

(1) Use for racing pace-making reliability trial or speed-testing.

(2) Use whilst drawing a trailer except the towing (other than for reward) of any one disabled mechanically propelled vehicle.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the Insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte. Ltd.
Approved Insurers

Chief Executive Officer

Joy Irene (LKKAUTO)

From: Joy Irene (LKKAUTO)
Sent: Wednesday, 21 March 2018 4:34 PM
To: 'Eileen, May Hwee Yap'
Cc: Admin A; Vivian Lau (LKKAUTO)
Subject: ACCIDENT INVOLVING SLE 5165G(AIG) & SLP 5852Z & OTHERS ON 09/03/2018 (18:30) ALONG SEMBAWANG ROAD

21 MARCH 2018

LION CITY RENTALS PTE LTD

Policy Holder

Your Ref: SLE 5165G
Our Ref: CC3/LCR18004715/Uja3

Dear Sir/Madam,

ACCIDENT INVOLVING SLE 5165G(AIG) & SLP 5852Z & OTHERS ON 09/03/2018 (18:30) ALONG SEMBAWANG ROAD

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

We have received a claim from **SLP 5852Z** against your insurance policy.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please call us if you have further queries.

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

AUTHORIZATION TO ACT

TO: PEGASUS ENGINEERING & TRADING PTE LTD

FROM: OWNER OF VEHICLE NUMBER SLP58527

ACCIDENT INVOLVING SL5165G.

ALONG/AT Sembawang Road ON 09.03.2018

We hereby authorize you to act on our behalf in pursuance of our claim for all damages during the repair arising out of the above accident.

This letter serve as the 'AUTHORITY TO ACT'.

We also hereby authorize all agreed settlement payment be made in favour to **PEGASUS ENGINEERING & TRADING PTE LTD.**

Name : Grab Rentals Pte Ltd

Co Reg No : 201617200G

Address : 18 Sin Ming Lane #01-08 Midview City Singapore 573960

Contact : 6655 0005

Date : 14.06.2018.

Signature



Owner

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, **PEGASUS ENGINEERING & TRADING PTE LTD** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$4,494.00** (Repair Cost), **S\$401.70** (Loss of Rental) **S\$7.49** (Disbursement) for vehicle no. **SLP 5852Z** that was damaged pursuant to the accident which occurred on **09/03/2018** (date) along **SEMBAWANG ROAD** (location) involving vehicle no/s **SLE 5165G**. This is pursuant to the inspection conducted on **13/03/2018** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **GRAB RENTALS PTE LTD** ("the third party claimant") of vehicle no. **SLP 5852Z** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **SLP 5852Z** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 03 (day) of July (month) **2018** (year)



Signed by appointed surveyor



Signed by "the workshop" (with chop)

"The contents of this document apply to vehicle damages only. All personal injuries and damages arising therefrom are excluded from the ambit and application of this document."



Grab Rentals Pte Ltd
18 Sin Ming Lane
#01-08 Midview City
Singapore 573960

GST / ROC Company No : 201101753C

Third Party Insurer : AIG
Insured's Veh No : SLE5165G
Date of accident : 09.03.2018

Tax Invoice No : IV18/04-1233
Invoice Date : 30.04.2018

Vehicle Model : Toyota Vios 1.5E CVT
Vehicle No : SLP5852Z
Chassis No : MHFB29F3102012112

Pages : 1 of 1

DESCRIPTION	AMOUNT
TO LUMP SUM REPAIR AS RECOMMENDED BY SURVEYOR.	\$ 4,200.00
Sub Total	\$ 4,200.00
GST (7.00%)	\$ 294.00
Total	\$ 4,494.00

Cheques should be made payable to **PEGASUS ENGINEERING & TRADING PTE LTD**

PEGASUS ENGINEERING & TRADING PTE LTD


Authorised Signature (Company Stamp)

If you have enquiries concerning this invoice, please contact Mr. Alvin or Mr. Wee at Tel: (65) 6858 1846
Mailing Address : Pegasus Engineering@Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216
E-mail : claims@pegasusengrg.com.sg



Our Ref: GR-ACC-2017-02

01 June 2017

Pagasus Engineering & Trading Pte Ltd
No. 51 Defu Lane 10
Singapore 539216

Mailing Address
18 Sin Ming Lane,
#01-08 Midview City,
Singapore 573960
Co. No. 201617200G

To whom it may concern,

Re: Vehicle Rental Rates for Loss of Rental Claims.

With regards to the above subject matter, we are pleased to inform you our Grab Rental rate for our various vehicles which are as follows:

S/No.	Make & Model	Daily Rental Rates (S\$)
01	Toyota Prius 1,798cc, 90kw, 120bhp, Automatic	\$ 79.95
02	Mazda 3 1.5 (A) Sedan	\$ 66.95
03	Nissan Qashqai 1.2L	\$78.95
04	Honda Vezel 1.5L	\$77.95
05	Honda Vezel 1.5L Hybrid	\$84.95
06	Toyota Vios 1.5L	\$66.95

Please note that the above stated rate is our daily rental rate to our drivers. For your necessary actions on third party accident claims on loss of rental.

Yours faithfully,

Tay Chee Wee
Grab Rental Pte Ltd

Enquire Vehicle & Owner Information (Vehicle No. SLE5165G As At 09 Mar 2018 / 18:20:00)

Law Firm Search Details

Search Reason: Insurance claim in relation to traffic accident
Law Firm Case No.: SLP5852Z

Current Owner Details

Owner ID Type: Company
Owner ID: 201624597K
Owner Name: LCRF PTE LTD
Registered Address Type: Private Residential (non-Condo Apt / non-House)
Registered Block/House No.: 60
Registered Street Name: ANSON ROAD
Registered Unit No.: # 11-01
Registered Building Name: MAPLETREE ANSON
Registered Postal Code: 079914

Current Vehicle Details

Vehicle No.: SLE5165G
Make Description/Model: TOYOTA / SIENNA 1.5G CVT ABS D/AIRBAG 2WD SDR
Insurance Company Name: AIG ASIA PACIFIC INSURANCE PTE. LTD.

Thank you



Lee Ming Hui Kelvin has successfully logged out.
Your last login date and time was 12 Mar 2018, 15:47:19.
To return to ONE MOTORING, please click [here](#)
For security reasons, please **CLEAR YOUR CACHE** after each session.

Session Transaction History

<u>S/No.</u>	<u>Asset Type</u>	<u>Asset ID</u>	<u>Asset Owner ID</u>	<u>Transaction Type</u>	<u>Transaction Amount(\$)</u>	<u>Log Date/Time</u>
1	Vehicle	5LE5165G	-	18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49	12 Mar 2018 / 15:48:02

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Mar 2018 Edit Reg		13 Mar 2018 00:00 Edit Adj Rpt	S\$4,200.00 Edit Estimates	S\$4,200.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	LCRF PTE LTD, Co. Reg. No.: 201624597K								
Main Claimant:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G								
Vehicle Reg. No.:	SLP5852Z	Date of Loss:	09/03/2018 00:00 - :59 [8 Months and 25 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 6915204648SG	Policy/Cover Note No.:	0999994757						
Vehicle Reg. No. (Insured):	SLE5165G	Policy No. (Claimant):	A29069766MKF						
		Excess:							
Repairer:	Pegasus Engineering & Trading Pte Ltd (HQ) 51 DEFU LANE 10, 539216 Defu Lane - Tel: 68581846								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Boyogan, Joane] Joane.Boyogan@aig.com								
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 22/03/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG (14/03/2018): Request To Upload TP GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLP5852Z (6915204648SG)
[SLE5165G]
TP
GRAB RENTALS PTE LTD
Mar 9 2018 12:00AM
[LCRF PTE LTD]
Pegasus Engineering & Trading Pte Ltd

Upload Documents	Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser
------------------	---------------	--------------------	--------------	--------------	--

Letters/Correspondences				1 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
1	(Draft)	LKK Auto Consultants Pte Ltd (HQ)			<input checked="" type="checkbox"/>
		Third Party Express Settlement – Payment Breakdown		Edit	

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder			Thumbnail	Print
1	13/03/18 18:48	LKK Auto Consultants Pte Ltd (HQ)			<input checked="" type="checkbox"/>
		Odometer Reading		Load JPG	<input checked="" type="checkbox"/>
2	13/03/18 18:48				<input checked="" type="checkbox"/>
		General View		Load JPG	<input checked="" type="checkbox"/>
3	13/03/18 18:48				<input checked="" type="checkbox"/>
		Chassis Number		Load JPG	<input checked="" type="checkbox"/>
4	13/03/18 18:48				<input checked="" type="checkbox"/>
		General View		Load JPG	<input checked="" type="checkbox"/>
5	13/03/18 18:48				<input checked="" type="checkbox"/>
		General View		Load JPG	<input checked="" type="checkbox"/>
6	13/03/18 18:49				<input checked="" type="checkbox"/>
		General View		Load JPG	<input checked="" type="checkbox"/>
7	13/03/18 18:49				<input checked="" type="checkbox"/>
		General View		Load JPG	<input checked="" type="checkbox"/>
8	13/03/18 18:49				<input checked="" type="checkbox"/>
		General View		Load JPG	<input checked="" type="checkbox"/>
9	13/03/18 18:49				<input checked="" type="checkbox"/>
		General View		Load JPG	<input checked="" type="checkbox"/>
10	13/03/18 18:49				<input checked="" type="checkbox"/>
		General View		Load JPG	<input checked="" type="checkbox"/>
11	13/03/18 18:49				<input checked="" type="checkbox"/>
		General View		Load JPG	<input checked="" type="checkbox"/>
12	13/03/18 18:49				<input checked="" type="checkbox"/>
		General View		Load JPG	<input checked="" type="checkbox"/>
13	13/03/18 18:49				<input checked="" type="checkbox"/>
		General View		Load JPG	<input checked="" type="checkbox"/>
14	13/03/18 18:49				<input checked="" type="checkbox"/>
		General View		Load JPG	<input checked="" type="checkbox"/>
15	13/03/18 18:49				<input checked="" type="checkbox"/>
		General View		Load JPG	<input checked="" type="checkbox"/>
16	13/03/18 18:49				<input checked="" type="checkbox"/>
		General View		Load JPG	<input checked="" type="checkbox"/>
17	13/03/18 18:49				<input checked="" type="checkbox"/>
		General View		Load JPG	<input checked="" type="checkbox"/>
18	13/03/18 18:49				<input checked="" type="checkbox"/>
		General View		Load JPG	<input checked="" type="checkbox"/>
19	13/03/18 18:49				<input checked="" type="checkbox"/>
		General View		Load JPG	<input checked="" type="checkbox"/>
20	13/03/18 18:49				<input checked="" type="checkbox"/>
		General View		Load JPG	<input checked="" type="checkbox"/>
21	13/03/18 18:49				<input checked="" type="checkbox"/>
		General View		Load JPG	<input checked="" type="checkbox"/>
22	13/03/18 18:49				<input checked="" type="checkbox"/>
		General View		Load JPG	<input checked="" type="checkbox"/>
23	13/03/18 18:49				<input checked="" type="checkbox"/>
		General View		Load JPG	<input checked="" type="checkbox"/>
24	13/03/18 18:49				<input checked="" type="checkbox"/>
		General View		Load JPG	<input checked="" type="checkbox"/>
25	13/03/18 18:49				<input checked="" type="checkbox"/>
		General View		Load JPG	<input checked="" type="checkbox"/>
26	13/03/18 18:49				<input checked="" type="checkbox"/>
		General View		Load JPG	<input checked="" type="checkbox"/>
27	13/03/18 18:49				<input checked="" type="checkbox"/>
		General View		Load JPG	<input checked="" type="checkbox"/>
28	13/03/18 18:49				<input checked="" type="checkbox"/>
		General View		Load JPG	<input checked="" type="checkbox"/>
29	13/03/18 18:49				<input checked="" type="checkbox"/>
		General View		Load JPG	<input checked="" type="checkbox"/>
30	13/03/18 18:49				<input checked="" type="checkbox"/>
		General View		Load JPG	<input checked="" type="checkbox"/>
31	13/03/18 18:49				<input checked="" type="checkbox"/>
		General View		Load JPG	<input checked="" type="checkbox"/>
32	13/03/18 18:49				<input checked="" type="checkbox"/>
		General View		Load JPG	<input checked="" type="checkbox"/>
33	13/03/18 18:49				<input checked="" type="checkbox"/>
		General View		Load JPG	<input checked="" type="checkbox"/>
34	13/03/18 18:49				<input checked="" type="checkbox"/>
		General View		Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	13/03/18 18:49	General View	Load JPG	<input checked="" type="checkbox"/>
36	13/03/18 18:49	General View	Load JPG	<input checked="" type="checkbox"/>
37	13/03/18 18:49	General View	Load JPG	<input checked="" type="checkbox"/>
38	13/03/18 18:49	General View	Load JPG	<input checked="" type="checkbox"/>
39	13/03/18 18:49	General View	Load JPG	<input checked="" type="checkbox"/>
40	13/03/18 18:49	General View	Load JPG	<input checked="" type="checkbox"/>
41	13/03/18 18:49	General View	Load JPG	<input checked="" type="checkbox"/>
42	13/03/18 18:49	General View	Load JPG	<input checked="" type="checkbox"/>
43	13/03/18 18:49	General View	Load JPG	<input checked="" type="checkbox"/>
44	13/03/18 18:49	General View	Load JPG	<input checked="" type="checkbox"/>
45	13/03/18 18:49	General View	Load JPG	<input checked="" type="checkbox"/>
46	13/03/18 18:49	General View	Load JPG	<input checked="" type="checkbox"/>
47	13/03/18 18:49	General View	Load JPG	<input checked="" type="checkbox"/>
48	13/03/18 18:49	General View	Load JPG	<input checked="" type="checkbox"/>
49	13/03/18 18:49	General View	Load JPG	<input checked="" type="checkbox"/>
50	13/03/18 18:49	General View	Load JPG	<input checked="" type="checkbox"/>
51	13/03/18 18:49	General View	Load JPG	<input checked="" type="checkbox"/>
52	13/03/18 18:49	General View	Load JPG	<input checked="" type="checkbox"/>
53	13/03/18 18:49	General View	Load JPG	<input checked="" type="checkbox"/>
54	13/03/18 18:49	General View	Load JPG	<input checked="" type="checkbox"/>
55	13/03/18 18:49	General View	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	19/03/18 11:27	TP ESTIMATE - MARKED	Load PDF	
2	19/03/18 11:28	TP GIA REPORT	Load PDF	
3	21/03/18 16:36	LETTER TO LCRF	Load PDF	
4	05/07/18 09:00	WORKSHOP INVOICE	Load PDF	
5	05/07/18 09:00	AUTHORISATION TO ACT FORM	Load PDF	
6	05/07/18 09:00	Release Voucher	Load PDF	
7	05/07/18 09:00	RENTAL RECEIPT	Load PDF	
8	05/07/18 09:01	LTA SEARCH	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	14/03/18 14:56	OI GIA report	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLE5165G (Insd veh)	Model:	TOYOTA VIOS 1.5 E (A)
	SLP5852Z (TP veh)		
Date of Accident:	09/03/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	8,637.82
Final Repair Cost	:	\$	4,494.00
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	401.70 6 days
LTA / GIA Search Fee	:	\$	7.49
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	4,903.19
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)			
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability ____ 100 ____ (%)	
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes/ No BOLA Scenario No: ____	
BOLA Liability: ____ (%)		Assessed Liability (*): ____ 0 ____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Pegasus Engineering & Trading Pte Ltd	:	\$ 4,903.19
2)		:	\$
3)		:	\$
4)		:	\$

JOANNE LEE KHANG MIN

05 Jul
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/LCR18004715/UJA3Q2

Date: 05/07/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994757
Claimant Vehicle No : SLP5852Z **Insured Vehicle No :** SLE5165G
 Date of Loss: 09/03/2018 Nature of Claim: TP Claim No: 6915204648SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLP5852Z**
 Make & Model: TOYOTA VIOS, 1.5 E (A) Engine No: 2NRX160116
 Reg. Date: 12/06/2017 (Man. Year: 2017) Chassis No: MHFB29F3102012112
 Colour: Grey Odometer: 55428 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/50 R16 Rear Tyre Size: 195/50 R16
 Front Left Side: Bridgestone 7 mm Rear Left Side: Bridgestone 7 mm
 Front Right Side: Bridgestone 7 mm Rear Right Side: Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,102.73	3,400.55	1,702.18	33.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,970.00	1,850.00	1,120.00	37.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,072.73	5,250.55	2,822.18	34.96
Approved Total (Overridden) (S\$)		4,200.00		
(S\$)	8,072.73	4,200.00	3,872.73	47.97
+ GST 7.00/7.00% (S\$)	565.09	294.00	271.09	47.97
Nett Amount (S\$)	8,637.82	4,494.00	4,143.82	47.97
+ Car Rental (6.0 x S\$66.95/day) (S\$)		401.70		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		4,903.19		

INSPECTION

Date of Assignment: 13/03/2018
 Date Inspected: 13/03/2018 Inspected At: Pegasus Engineering & Trading Pte Ltd (HQ)

51 DEFU LANE 10
Singapore 539216

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented / Buckled	762.47 FL	*762.47 FL
2	1		*BOOTLID LOCK	Twisted	90.40 FL	*90.40 FL
3	1		*BOOTLID LOCK STRICKER	Not Necessary	18.50 FL	*- FL
4	1		*BOOTLID WEATHERSTRIP	Twisted	188.80 FL	*188.80 FL
5	1		*BOOTLID VIOS BADGE	Necessary	44.10 FL	*44.10 FL
6	1		*BOOTLID CENTRE BADGE	Necessary	59.80 FL	*59.80 FL
7	1		*BOOTLID E BADGE	Necessary	39.40 FL	*39.40 FL
8	1		*BOOTLID OUTER GARNISH	Repair	59.80 FL	*- FL
9	1		*BOOTLID INNER TRIM COVER	Not Necessary	398.10 FL	*- FL
10	6		*BOOTLID INNER TRIM COVER CLIPS	Not Necessary	25.80 FL	*- FL
11	2		*BOOTLID HINGE	Repair	159.60 FL	*- FL
12	3		*BOOTLID LOCK CABLE CLIPS	Not Necessary	12.90 FL	*- FL
13	2		*REAR LICENSE PLATE LAMP	Not Necessary	159.60 FL	*- FL
14	1		*REAR END PANEL	Badly Dented	694.70 FL	*694.70 FL
15	1		*REAR END PANEL INNER TRIM	Twisted	234.30 FL	*234.30 FL
16	4		*REAR END PANEL INNER CLIPS	Not Necessary	17.20 FL	*- FL
17	2		*REAR LAMP	Cracked	751.60 FL	*751.60 FL
18	2		*REAR LAMP PANEL	Repair	477.80 FL	*- FL
19	4		*REAR LAMP CLIP HOLDER	Not Necessary	38.00 FL	*- FL
20	1		*REAR BUMPER	Dented / Deformed	504.90 FL	*504.90 FL
21	1		*REAR BUMPER REINFORCEMENT	Bent	323.00 FL	*323.00 FL
22	2		*REAR BUMPER SIDE RETAINER	Bent	232.60 FL	*232.60 FL
23	2		*REAR BUMPER SIDE HOLDER	Bent	44.60 FL	*44.60 FL
24	8		*REAR BUMPER CLIPS	Necessary	34.40 FL	*34.40 FL
25	2		*REAR BUMPER END SPLASHIELD COVER	Not Necessary	179.60 FL	*- FL
26	2		*REAR BUMPER REFLECTOR	Not Necessary	261.00 FL	*- FL
27	1		*REAR LUGGAGE FLOOR TRIMBOARD	Torn	209.00 FL	*209.00 FL
28	1		*REAR LUGGAGE FLOOR FOAM	Not Necessary	75.00 FL	*- FL
29	1		*REAR LICENSE PLATE	Dented	80.00 FS	*40.00 FS
30	1		*SET REAR BUMPER PARKING SENSOR	Shorted	450.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,626.97	4,454.07
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,524.24	1,053.52
Total Parts (\$\$)	5,102.73	3,400.55

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	1,050.00	800.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,000.00	800.00
3	TO REMOVE AND REFIT INTERIOR FITTINGS ,TRIMMINGS ,GARNISH AND OTHER ,TO ENABLE REPAIR	New	180.00	60.00
4	TO RUST-PROOFING OF THE AFFECTED PORTION	New	220.00	60.00
5	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	150.00	50.00
6	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS ,AND PERFORM WATER SEEPAGE TEST	New	160.00	60.00
7	TO REPAIR AND REALIGN REAR EXHAUST BOX	New	150.00	0.00
8	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	60.00	20.00
Gross Labour Cost (S\$)			2,970.00	1,850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >