

ASS. REC. BY:

REF: CS3/CTI18004720/Gd3-1 Special Instruction:

range 8 days

Survivor:

Mehmen

ASSIGNMENT (Office)

From (Person):

Sharon Hen

of

CTI

Date/Time:

12/3/18 @ 3.22pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLB 5136G

Insured:

SFV 7399S

at Workshop m/s

N-51 Automotive

Tel:

6842 0051

of

Blk 2, Kaki Bkt #01-17/18

Policy No:

DMHC SN 3068011700

Claim No:

SNM18 001298

Sum Insured:

Excess:

Make of Veh:

D.O.A.

9/3/18

(Client's Record)

CA / REV / REP. / REV 24 HRS wpt

H.O.D. Endorsement:

Date/Time:

10:47am @ 13/3/18

Person Contacted:

Subriker

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

SLB 5136G-X

SFV 7399S-X

Dismantle: 15/3/2018

PRS Xone. REF: CTI

# ASSIGNMENT

From: Date: 13/3/18

Estimated Cost:

OD (TP) NS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No: SLB 5136G  
at Workshop No: N-51 Automotive  
Blk 2, Kaki Bkt # 01-17 / 18

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

Client's Record:

Make of Ver:

(Policy Condition)

Remark: The van had commenced its repair at the time of inspection.

NS	O/S

Sal. or Market Value:

DAD Accident Report: Consistent? Yes or No

DIA PR Seen: Consistent? Yes or No

Est. Repairs: days Res: Yes or No

Lim Sum: % B Val: Yes or No

CA / REV / REP. / 24 HRS (w/p)

Date: Person Contacted:

Vehicle IN / OUT

Date Time Action Instruction

\* Repair Estimate : S\$ 9000-10,000

\* 8 days

RECEIVED 21 MAY 2018

Date Time File Pass/PT

☐

Preli. Report

☐

Final Report

Date Time File Return/PT

1

Add Fee:

☐  
☐  
☐  
☐

Site Fee: \$

Interim: \$

Final: \$

45-47: \$

Days Of Repair: 8

Resurvey No. of Trip: 1

Survey Fee

Transport:

149-150

Report Format

PRS

Lim Sum: \$

150

150

SLB 5136G 12 Apr 2016

Type: VCB / M / C / B / S / Van / Lorry / Taxi / Private Motor

Truck / Trailer:

Make: Honda Vezel 1496

Color: Silver

So. Reg. No: 155892

Engine:

C/V: RU1111.3085

Gen. Cond: Good Fair Poor Burnt

Steering: In order Jammed / Leaked / Burnt or

Brake: In order Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / A/Rim or

Tyre Size: F 25/60 R16  
R 11

BS / DUN / EXNOVA / GY / PS / LIZA / MIC / CHSU / PR / SUM  
TOYO / YOKO or

Front:

Rear:

F.Ba: 6 -- R.Ba: 6 --

L.Ba: 6 -- R.Ba: 6 --

D.O.A: 13-03-18

Surveyed at: W/S 4:50pm

Des. of Damages: Fr. Rear O/S NS UO Roofed or

O/S RA

The UO / Chassis/frame / Body Structure affected due to collision

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Mar 2018		12 Mar 2018 15:22 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	TWINCAR LEASING PTE LTD		
Vehicle Reg. No.:	SLB5136G	Date of Loss:	09/03/2018 00:00 - :59
Claim Type:	TP / SNM18D01298C02	Policy/Cover Note No.:	DMHCSN3068011700
Vehicle Reg. No. (Insured):	SFV7399S	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	N-51 Automotive Pte Ltd (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel: 68420051		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Sharon Han - 63896]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 21/03/2018]		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SLB5136G		
Vehicle Type :	Z11 - Private Hire (Chauffeur) Station Wagon/Jeep/Land Rover		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	HONDA		
Vehicle Model :	VEZEL 1.5X CVT ABS D/AIRBAG 2WD		
Chassis No. :	RU11113085		
Propellant :	Petrol		
Engine No. :	L15B4033091		
Engine Capacity :	1496 cc		
Maximum Power Output :	96.0 kW ( 128 bhp )		
Maximum Laden Weight :	1465 kg		
Unladen Weight :	1190 kg		
Year Of Manufacture :	2016		
Original Registration Date :	12 Apr 2016		
Lifespan Expiry Date :	-		
COE Category :	A - Car up to 1600cc & 97kW (130bhp)		
Quota Premium :	\$56,001.00		
COE Expiry Date :	11 Apr 2026		
Road Tax Expiry Date :	11 Oct 2018		
PARF Eligibility Expiry Date :	11 Apr 2026		
Inspection Due Date :	11 Apr 2019		
Intended Transfer Date :	14 Mar 2018		
CO2 Emission :	117.00 (g/km)		
CEV/VES Rebate Utilised Amount :	\$10,000.00		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use <a href="#">Enquire Road Tax Payable</a> for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	3046C
<b>Vehicle Details</b>	
Vehicle No.:	SLB5136G
Vehicle to be Exported:	No
Intended De-registration Date:	21 May 2018
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT ABS D/AIRBAG 2WD
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	L15B4033091
Chassis No.:	RU11113085
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$19,627.00
Original Registration Date:	12 Apr 2016
First Registration Date:	12 Apr 2016
Transfer Count:	0
Actual ARF Paid:	\$9,627.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Apr 2026
PARF Rebate Amount:	\$7,220.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	11 Apr 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$56,001.00
COE Rebate Amount:	\$44,189.00
<b>Total Rebate Amount:</b>	<b>\$51,409.00</b>

The information contained herein is correct as at 21 May 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	12/03/2018 10:16
Date Of Accident	09/03/2018 21:35
Exact Location Of Accident	ECP TOWARDS SHEARES AVE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLB5136G
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TWINCAR LEASING PTE LTD
Co Reg No	201533046C
Email Address	SALES@N51.COM.SG
Mobile Phone No	(LOCAL) +65-83802233
Alternative Phone No	OFFICE-68420051

### Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL-1.5 X CVT (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE HIRE

### Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	SD17V11639/VPZ/R02
Cover Note Number	

### Driver

Name of Driver	KARUNAKARAN S/O RAMACHANDRAN
NRIC No	S8440238I
Date Of Birth	11/12/1984
Occupation	OUTDOOR
Date Of Driving Pass	15/03/2013
Driving Experience	4 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81116374
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 675 HOUGANG AVE 8, #02-597
Postcode	530675
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

### General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN GENDER: : MALE

### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

### Circumstances of Accident

REFER TO ATTACHED SKETCH PLAN

### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SFV7399S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

**DETAILS OF INJURED PERSON 1**

Name	KARAUNAKARAN S/O RAMACHANDRAN
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SLB5136G
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	



## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:



Driver's Signature  
(if driver is not the policyholder)  
Date & Time:



Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# Sketch Plan #2

## SKETCH PLAN

VEHICLE A - SLB 5136 G  
VEHICLE B - SPV 7399 S



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS DRIVING TOWARD SHEARS AVE. I WAS ON THE THIRD LANE.
WHILE DRIVING STRAIGHT AHEAD ON THE LANE OF GOING TOWARDS MCE (AGE) CENTRAL BLVD. SUDDENLY A VEHICLE SWERVED INTO MY LANE FROM THE CHEROKEE CUTTING THROUGH FROM THE 2nd LANE WHICH HEADING TOWARDS SHEARS AVE.
ALIGHTED FROM MY VEHICLE AND REALIZED A VEHICLE DRIVING (SPV 7399 S) CUT THROUGH THE CHEROKEE FROM THE 2nd LANE HEADING TOWARDS SHEARS, CUT ON MY LANE AND CAUSED THE ACCIDENT.
VEHICLE A - SLB 5136 G
VEHICLE B - SPV 7399 S

## DECLARATION

I/We declare the above particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NIC/FIN No.:

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Mar 2018		12 Mar 2018 15:22 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All																				
<div>CLAIM SUBFOLDER DETAILS <span>[Created by insurer]</span></div> <div> <div>Insured: -, Co. Reg. No.: -</div> <div> <div>Main Claimant: <b>TWINCAR LEASING PTE LTD</b></div> <div> <div>Vehicle Reg. No.: <b>SLB5136G</b></div> <div>Date of Loss: 09/03/2018 00:00 - :59 [22 Months and 25 Days From LTA Reg Date (Man Yr)]</div> </div> <div>Claim Type: <b>TP / SNM18D01298C02</b></div> <div> <div>Vehicle Reg. No. (Insured): <b>SFV7399S</b></div> <div>Policy/Cover Note No.: DMHCSN3068011700</div> </div> <div> <div>Policy No. (Claimant):</div> <div>Excess: S\$0.00</div> </div> </div> <div> <div>Repairer: <b>N-51 Automotive Pte Ltd (HQ)</b> BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel: 68420051</div> <div> <div>Handling Insurer: <b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Sharon Han</b> - 63896]</div> <div>Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b>] ... <b>[Final Rpt due 21/03/2018]</b></div> </div> <div>Adj Asg. Remarks: NO EST, CASE W/O SJE.</div> </div> <div> <div>ASSOCIATED MAIL RECEIVED</div> <div>There are no mail for this case.</div> </div> <div> <div>ALL ASSOCIATED TASKS</div> <div> <div>View All</div> <div>Search Tasks</div> <div>Create New Task</div> <div>Complete</div> </div> <table border="1"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table> </div> </div>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								

## Claim Documents

**\*SLB5136G (SNM18D01298C02)**  
[SFV73995]

TP  
TWINCAR LEASING PTE LTD  
Mar 9 2018 12:00AM  
[-]  
N-51 Automotive Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View <input type="button" value="View in Browser"/>	
						3 per page	<input checked="" type="checkbox"/>
<b>Photos/Images</b>						Thumbnail	Print
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Load PDF
1	21/05/18 10:16	General View					Load PDF
2	21/05/18 10:16	Photographs of Damaged Parts					
						1 per page	<input checked="" type="checkbox"/>
<b>Documentation</b>						Thumbnail	Print
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)					Load PDF
1	12/03/18 15:22	PRS					

## Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT118004720/GD3E2  
Date: 22/05/2018

### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSN3068011700  
Claimant Vehicle No: SLB5136G Insured Vehicle No: SFV7399S  
Date of Loss: 09/03/2018 Nature of Claim: TP Claim No: SNM18D01298C02

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLB5136G Engine No: L15B4033091  
Make & Model: HONDA VEZEL, 1.5 (A) Chassis No: RU11113085  
Reg. Date: 12/04/2016 (Man. Year: 2016) Odometer: 155892 km  
Colour: Silver  
Engine Capacity: 1496 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16  
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm  
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 12/03/2018  
Date Inspected: 13/03/2018 Inspected At: N-51 Automotive Pte Ltd (HQ)  
BLK 2 KAKI BUKIT, #01-17/18 KAKI  
BUKIT AUTOHUB  
Singapore 417921

Estimated Period of Repair: 8.0 days

Adjuster: XING GUO QIANG

Manager: Nivitha Govindasamy

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.

B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$9,000.00 -\$10,000.00

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 22 May 2018)
<b>Parts:</b>	M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLB5136G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >