

ASS. SEC. BY:

REF:

CS / EQ118004723 / KH02

Special Instruction:

Surveyor:

KMN20

ASSIGNMENT (Office)

Munim

From (Person):

Bazlin Ahmad

of

EQ1

Date/Time:

13/03/2018 1:51pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBA 51113

Insured:

at Workshop m/s

Cheng Hoe Motor

Tel:

6755 6142

of

Blk T019 Yishun Ind Park A #01-374

Policy No:

DMCPH017-004876

Claim No:

Sum Insured:

Excess:

\$500.00

Make of Veh:

(Client's Record)

D.O.A. 11.03.2018

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

13/03/2018

2:40pm

Person Contacted:

June

Vehicle IN / LOUT

Date/Time

Action/Instruction (✓) Estimate

GBA 51113 - x

FIS 11/2/834501 Confirm E&amp;P (Red. 1100 : 24%)

ASS. REC. BY:

REF:

EQ1

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

☒ TP / WS / TP RES / QD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

 Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

Consistent? : Yes or No

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

GBA 5911J

Yr Regn:

CP, 07

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Isuzu TFR

c.c.

2499

Colour

Multi Colour

A/C:

Insured / Std / NI / NA

Sp. Reading

362476

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MPA TFR 86H7.4568035

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim or

Tyre Size:

F: 175/70R15

Chas R: Yany

215/70R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

R/Bal.

6

mm

Rear

R/Bal.

9

mm

L/Bal.

6

mm

L/Bal.

9

mm

D.O.A.

11/3/18

D.O.I.

13/3/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

14/3

File pass to Catherine

RECEIVED

Date/Time, File Pass to?

10/15 Typist

Date/Time, File Return to?



: Prell. Report



: Final Report

Days Of Repair:

6

Resurvey No. of Trip:

Survey Fee:

160

Transportation:

S + RS SI

Photos

Others

TOTAL

160

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Report Format :

OD

Lump Sum / I.B.I. (\$

3450




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD		Ref : CS/EQI18004723/Ktb		
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEX SINGAPORE 069110		Date : 13-03-2018		
		Code : EQI		
<b>1. Policy Particulars :- OWN DAMAGE</b>				
Insured Veh.	Veh. Inspected		GBA 5911J	
Policy No. DMCPHQ17-004876	Coverage (\$)		0.00	
Claim No.	Excess (\$)		500.00	
Assign From MERIMEN (BAZLIN AHMAD)	Assign Date		13/03/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	c.c		0	
Engine No. HIDDEN	Year of Reg.			
Chassis No.	Colour			
Odometer -	Steering			
Brakes	Modification			
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date 11/03/2018	Inspection Date		13/03/2018	
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761			
<b>5a. Remarks</b>				
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				

## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Mar 2018 12:35 Sendback Est	13 Mar 2018 12:42 S\$3,871.50	13 Mar 2018 13:51 Assign				<b>New Assignment</b> Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

## CLAIM SUBFOLDER DETAILS

Insured:	DA PAOLO GROUP PTE LTD, Co. Reg. No.: 198905296C		
Vehicle Reg. No.:	GBA5911J	Date of Loss:	11/03/2018 06:00 - :59
Claim Type:	OD	Policy/Cover Note No.:	DMCPHQ17-004876 (Comprehensive) Coverage: 07/09/2017 - 06/09/2018
		Excess:	S\$500.00
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142		
Handling Insurer:	EQ Insurance Company Ltd (HQ) - Tel: 6223 9433 ... [Handled by Bazlin Ahmad]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 22/03/2018]		
Driver/Custodian:	ZULKAFFI BIN YUNOS (29 / Male), NRIC: S8827139D		
Adj Asg. Remarks:	OD EXCESS \$500		

## ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

## ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)



# CHENG HOE MOTOR PTE LTD

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel : 67556142 Fax : 67557719

Email: chmotor@singnet.com.sg

INSURER: EQ Insurance Company Ltd (HQ)

## PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD EQ
Policy No:	DMCPHQ17-004876	Date of Loss:	11/03/2018
Vehicle Reg. No.:	GBA5911J	Driveable?	
Driver Age/Info:	29 / MALE	Party At Fault:	DRIVER
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	DA PAOLO GROUP PTE LTD		
Driver:	ZULKAFFI BIN YUNOS		
Make/Model:	ISUZU TFR86HDR, 2.5 D (M)	Vehicle Reg. Date:	07/09/2007
Vehicle Colour:	WHITE		
Engine No:	EX5885	Chassis No:	MPATFR86H7H568035
Odometer:	0 KM		
Paint Type:			<i>Not handled</i>
Total Loss?	NO		<i>11 Sep 87</i>
Est. Duration of Repair (day)	<i>7-6 days</i>		<i>Recovery After Repair</i>
			<i>Ex 8500h</i>
Present Location:	CHENG HOE MOTOR PTE LTD (YISHUN)		

## COST OF CLAIMS

	Amount
Parts	1,851.50
Miscellaneous Items	20.00
Labour	2,000.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>3,871.50</b>
<b>+ GST 7.00% (S\$)</b>	<b>271.01</b>
<b>Nett Amount (S\$)</b>	<b>4,142.51</b>

This claim is handled by: JUNE PHUA LIAN HUA

Generated using Merimen e-Claims Internet Estimation & Adjusting System

**REPAIR DETAILS****Reference**

**Part Source:** (Last Synchronised: 13 Mar 2018)  
**Parts:** N/A ISUZU TFR86HDR 2.5 D (M) (Model not available in database)  
**Labour:** Repairer's (Price-denominated Standard List)  
**Print Code:** Cheng Hoe Motor Pte Ltd/GBA5911J/13/03/2018 12:42  
**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 pc frt bumper	Br 0.00	0.00	*543.00 F ✓
2	1		*1 pc frt bumper lh side retainer	D, Y 0.00	0.00	*4.00 F —
3	1		*2 pcs frt bumper clip @2/pce	Br 0.00	0.00	*4.00 F ✓
4	1		*1 pc frt lh door protector	Br 0.00	0.00	*38.00 F ✓
5	1		*1 pc lh headlamp	CM 0.00	0.00	*259.00 F —
6	1		*1 pc frt lh fender	Br 0.00	0.00	*299.00 F —
7	1		*1 pc frt lh fender inner shield	D, Y 0.00	0.00	*50.00 F —
8	1		*1 pc frt lh side mirror	Br 0.00	0.00	*380.00 F —
9	1		*1 pc frt lh fender lamp	Br 0.00	0.00	*33.00 F ✓
Sub Total (\$\$)						1,610.00
+ Margin on L,N Items 15.00% (\$\$)						241.50
Total Parts (\$\$)						1,851.50

F=Franchise part.

Cheng Hoe Motor Pte Ltd/GBA5911J/13/03/2018 12:42. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

**Estimates on Miscellaneous Items**

No	Qty	Particulars	Amount
1	1	1 pc frt lh door sticker	Me 20.00 ✓
Sub Total (\$\$)			20.00

**Estimates on Labour**

No	Particulars	Lab.Type	Amount
1	1) To panel beating	New	800.00
2	2) To putty and respray painting on affected areas	New	1,200.00
Gross Labour Cost (\$\$)			2,000.00

Cheng Hoe Motor Pte Ltd/GBA5911J/13/03/2018 12:42. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

&lt; END OF ESTIMATES &gt;

**REPAIR DETAILS**

GBA5911J

supp 1

**Reference****Part Source:** (Last Synchronised: 28 Apr 2018)**Parts:** N/A ISUZU TFR86HDR 2.5 D (M) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Cheng Hoe Motor Pte Ltd/GBA5911J/28/04/2018 14:16**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT LH DOOR	0.00	0.00	*590.00F
F=Franchise part.						
Sub Total (\$\$)						590.00
+ Margin on L,N Items 15.00% (\$\$)						88.50
Total Parts (\$\$)						678.50

Cheng Hoe Motor Pte Ltd/GBA5911J/28/04/2018 14:16. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

**Estimates on Miscellaneous Items**

There are no new miscellaneous items selected.

**Estimates on Labour**

There are no labour items selected.

Cheng Hoe Motor Pte Ltd/GBA5911J/28/04/2018 14:16. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

&lt; END OF ESTIMATES &gt;

## Enquire PARF/COE Rebate for Registered Vehicle

## Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 5296C

## Vehicle Details

Vehicle No.: GBA5911J

Vehicle to be Exported: No

Intended De-registration  
Date: 12 Mar 2018

Vehicle Make: ISUZU

Vehicle Model: TFR86HSR

Primary Colour: White

Manufacturing Year: 2007

Engine No.: EX5885

Chassis No.: MPATFR86H7H568035

Maximum Power Output: -

Open Market Value: \$17,728.00

Original Registration Date: 07 Sep 2007

First Registration Date: 07 Sep 2007

Transfer Count: 0

Actual ARF Paid: \$0.00

## Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry  
Date: -

PARF Rebate Amount: \$0.00

## Intended COE Rebate Details

COE Expiry Date: 31 Aug 2022

COE Category: C - Goods Vehicle &amp; Bus

COE Period(Years): 5

PQP Paid: \$17,920.00

COE Rebate Amount: \$16,012.00

Total Rebate Amount: \$16,012.00

## Message

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 12 Mar 2018



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	12/03/2018 14:33
Date Of Accident	11/03/2018 06:00
Exact Location Of Accident	CANBERRA LINK
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBA5911J
<b>Insured/Policyholder</b>	
Name Of Registered Owner	DA PAOLO GROUP PTE LTD
Co Reg No	198905296C
Email Address	ADMIN@DAPAOLO.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-64796522

### Vehicle Particulars

Manufacturer	ISUZU
Model	TFR86HSR
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	

Vehicle Category	COMMERCIAL VEHICLE
------------------	--------------------

### Insurance Company

Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCPHQ17-004876
Cover Note Number	07/09/17 - 06/09/18

### Driver

Name of Driver	ZULKAFFI BIN YUNOS
NRIC No	S8827139D
Date Of Birth	31/07/1988
Occupation	OUTDOOR
Date Of Driving Pass	05/02/2009
Driving Experience	9 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-88083506
Fax Number	
Contact Number	
Email Address	ADMIN@DAPAOLO.COM.SG

**SKETCH PLAN**

VEHICLE NO.: G8A 59113  
 INSURER : EQ  
 DATE & TIME: 11/3/18 6pm

**IMPORTANT NOTICE**

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

**da paolo**

Da Paolo Group Pte Ltd  
 80 Club Street, Singapore 069448  
 Tel: 6479 6522 ROC No: 198705296C

Policyholder's Signature  
 Date & Time:

Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

(YS) 09/03/18  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Mar 2018 12:35	13 Mar 2018 12:42	13 Mar 2018 13:51	<b>S\$3,450.00</b>	<b>S\$3,450.00</b>		<b>Pending for Survey Report</b>
	<a href="#">Sendback Est</a>	<b>S\$3,871.50</b>	<a href="#">Edit Adj Rpt</a>	<a href="#">Edit Estimates</a>	<a href="#">View Rpt</a>		<a href="#">Cancel Case</a>
Supp #1	28 Apr 2018 14:14	28 Apr 2018 14:16	28 Apr 2018 14:17			(Combined)	<b>Combined with Main</b> <a href="#">Uncombine Suppl.</a>
		<b>S\$678.50</b>					

<b>Main</b>	<b>Reference</b>	<b>Claim Details</b>	<b>Documents</b>	<b>Show All</b>
-------------	------------------	----------------------	------------------	-----------------

#### CLAIM SUBFOLDER DETAILS

Insured:	DA PAOLO GROUP PTE LTD, Co. Reg. No.: 198905296C		
Vehicle Reg. No.:	GBA5911J	Date of Loss:	11/03/2018 06:00 - :59 [126 Months and 4 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD	Policy/Cover Note No.:	DMCPHQ17-004876 (Comprehensive) Coverage: 07/09/2017 - 06/09/2018
		Excess:	S\$500.00
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142		
Handling Insurer:	EQ Insurance Company Ltd (HQ) - Tel: 6223 9433 ... [Handled by Bazlin Ahmad]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 22/03/2018]		
Driver/Custodian:	ZULKAFFI BIN YUNOS (29 / Male), NRIC: S8827139D		
Adj Asg. Remarks:	OD EXCESS \$500		

#### ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

#### ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

GBA5911J  
OD  
Mar 11 2018 6:00AM  
[DA PAOLO GROUP PTE LTD]  
Cheng Hoe Motor Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

**View** View in Browser

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
1	13/03/18 12:42	Repairer Estimates	Load HTM	
2	28/04/18 14:17	Repairer Estimates Suppl. #1	Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	10/05/18 10:01	General View	Load JPG	<input checked="" type="checkbox"/>
2	10/05/18 10:01	General View	Load JPG	<input checked="" type="checkbox"/>
3	10/05/18 10:01	General View	Load JPG	<input checked="" type="checkbox"/>
4	10/05/18 10:01	General View	Load JPG	<input checked="" type="checkbox"/>
5	10/05/18 10:01	General View	Load JPG	<input checked="" type="checkbox"/>
6	10/05/18 10:01	General View	Load JPG	<input checked="" type="checkbox"/>
7	10/05/18 10:01	General View	Load JPG	<input checked="" type="checkbox"/>
8	10/05/18 10:01	General View	Load JPG	<input checked="" type="checkbox"/>
9	10/05/18 10:01	General View	Load JPG	<input checked="" type="checkbox"/>
10	10/05/18 10:01	General View	Load JPG	<input checked="" type="checkbox"/>
11	10/05/18 10:01	General View	Load JPG	<input checked="" type="checkbox"/>
12	10/05/18 10:01	General View	Load JPG	<input checked="" type="checkbox"/>
13	10/05/18 10:01	General View	Load JPG	<input checked="" type="checkbox"/>
14	10/05/18 10:01	General View	Load JPG	<input checked="" type="checkbox"/>
15	10/05/18 10:01	General View	Load JPG	<input checked="" type="checkbox"/>
16	10/05/18 10:01	General View	Load JPG	<input checked="" type="checkbox"/>
17	10/05/18 10:01	General View	Load JPG	<input checked="" type="checkbox"/>
18	10/05/18 10:01	General View	Load JPG	<input checked="" type="checkbox"/>
19	10/05/18 10:01	General View	Load JPG	<input checked="" type="checkbox"/>
20	10/05/18 10:01	General View	Load JPG	<input checked="" type="checkbox"/>
21	10/05/18 10:01	General View	Load JPG	<input checked="" type="checkbox"/>
22	10/05/18 10:01	General View	Load JPG	<input checked="" type="checkbox"/>
23	10/05/18 10:01	General View	Load JPG	<input checked="" type="checkbox"/>
24	10/05/18 10:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
25	10/05/18 10:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
26	10/05/18 10:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
1	13/03/18 12:41	E-filed GIA report	Load PDF	
2	13/03/18 12:42	Driver's Driving License	Load JPG	<input checked="" type="checkbox"/>

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	16/05/18 10:03	Supplementary	Load PDF	

Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	<a href="#">Reset</a>	<a href="#">Save</a>	<a href="#">Print</a>
There are no document checklists configured.			

<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>
<div></div>
<b>Show Remarks To:</b> <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

EQ Insurance Company Ltd  
5 Maxwell Road, #17-00 Tower Block, MND Complex  
Singapore 069110

Our File No: CS/EQ118004723/KTBE2

Date: 16/05/2018

**REFERENCE**

Insured/Claimant: DA PAOLO GROUP PTE LTD Policy No: DMCPHQ17-004876  
Date of Loss: 11/03/2018 Nature of Claim: OD Claim No: N/A

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **GBA5911J**  
Make & Model: ISUZU TFR86HDR, 2.5 D (M) Engine No: EX5885  
Reg. Date: 07/09/2007 (Man. Year: 2007) Chassis No: MPATFR86H7H568035  
Colour: Multi-colour Odometer: 362476 km  
Engine Capacity: 2499 cc  
Market Value/New Car Price: S\$22,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

**CONDITION OF TYRES**

Front Tyre Size: 215/70 R15 Rear Tyre Size: 215/70 R15  
Front Left Side: CHAO YANG 6 mm Rear Left Side: CHAO YANG 9 mm  
Front Right Side: CHAO YANG 6 mm Rear Right Side: CHAO YANG 9 mm

The above values represent the remaining tyre treads depth

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,530.00	2,530.00	0.00	0.00
Miscellaneous Items	20.00	20.00	0.00	0.00
Labour	2,000.00	1,750.00	250.00	12.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,550.00</b>	<b>4,300.00</b>	<b>250.00</b>	<b>5.49</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,450.00</b>		
<b>- Excess (S\$)</b>	0.00	500.00	-500.00	
<b>(S\$)</b>	4,550.00	2,950.00	1,600.00	35.16
<b>+ GST 7.00/7.00% (S\$)</b>	318.51	206.50	112.01	35.17
<b>Nett Amount (S\$)</b>	<b>4,868.51</b>	<b>3,156.50</b>	<b>1,712.01</b>	<b>35.16</b>

**INSPECTION**

Date of Assignment: 13/03/2018 Present Location: Cheng Hoe Motor Pte Ltd (Yishun)  
Date Inspected: 13/03/2018 Inspected At: Blk 1019 #01-374/382, Yishun Industrial Park A  
Singapore 768761  
Estimated Period of Repair: 6.0 days

**Adjuster:** KENNETH KONG

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** (Last Synchronised: 16 May 2018)  
**Parts:** N/A ISUZU TFR86HDR 2.5 D (M) (Model not available in database)  
**Labour:** Repairer's (Price-denominated Standard List)  
**Print Code:** (Unsubmitted, no print-code for GBA5911J)  
**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*1 pc frt bumper (WCP)	Buckled	543.00 F	*543.00 F
2	1		*1 pc frt bumper lh side retainer (WCP)	Distorted	4.00 F	*4.00 F
3	1		*2 pcs frt bumper clip @2/pce (WCP)	Necessary	4.00 F	*4.00 F
4	1		*1 pc frt lh door protector (WCP)	Necessary	38.00 F	*38.00 F
5	1		*1 pc lh headlamp (WCP)	Cracked	259.00 F	*259.00 F
6	1		*1 pc frt lh fender (WCP)	Bent	299.00 F	*299.00 F
7	1		*1 pc frt lh fender inner shield (WCP)	Distorted	50.00 F	*50.00 F
8	1		*1 pc frt lh side mirror (WCP)	Broken	380.00 F	*380.00 F
9	1		*1 pc frt lh fender lamp (WCP)	Broken	33.00 F	*33.00 F
<b>Supplementary #1</b>						
10	1		*FRT LH DOOR (WCP)	Bent	590.00 F	*590.00 F

F=Franchise part.

<b>Sub Total (\$\$)</b>	<b>2,200.00</b>	<b>2,200.00</b>
<b>+ Margin on L,N Items 15.00/15.00% (\$\$)</b>	<b>330.00</b>	<b>330.00</b>
<b>Total Parts (\$\$)</b>	<b>2,530.00</b>	<b>2,530.00</b>

Report was unsubmitted during this print-out.



**Recommended Miscellaneous Items**

No	Qty	Particulars	Repairer's	Amount
<b><u>Miscellaneous Items</u></b>				
1	1	1 pc frt lh door sticker (NECESSARY)	20.00	20.00
<b>Sub Total (S\$)</b>			<b>20.00</b>	<b>20.00</b>

**Recommended Labour**

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	1) To panel beating	New	800.00	700.00
2	2) To putty and respray painting on affected areas	New	1,200.00	1,050.00
<b>Gross Labour Cost (S\$)</b>			<b>2,000.00</b>	<b>1,750.00</b>

Report was unsubmitted during this print-out.
---

&lt; END OF ESTIMATES &gt;